

# NEWYORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation  
Operation Maintenance and Monitoring Review Report  
Period covered by -- 2003

Site / Spill Number : 336037		Site Name: Macbeth Kollmorgen		Class: 04	
Program Lead: Hazardous Waste Program			OM&M Funding Source: Responsible Party		
Start Date : 03/01/1995		ACT			
Annual IC/EC Certification :					
DEC Inspection Date: 11/01/2002		--- Last Date of DEC Inspection			
Report Used for Evaluation: private well sampling report by NYSDEC & NYSDOH					
ROD Compliance ? NO		Consent order/Decree Compliance ? NO			
LongTerm Monitoring(effectiveness of remedy): No		Frequency:		Act. Date: / /	
Treatment System(Monitoring performance of remedy): No		Frequency:		Pln. Date: / / #wells : 0	
PROBLEM STATUS : 99A		----- None			
Evaluation : The Remedy is performing properly and is effective.					
Comments\ Changes\ Attachments: 2003: Private wells sampled around site showed only trace amounts (below detection limit) of contaminants associated with site, except for #14 steel road where carbon filters are used. Results of quarterly sampling at MW-12 & potable water supply are not being sent to NYSDEC in a timely manner. Recommendations: Continue quaterly sampling as required at potable water supply #14 Steel Rd, and MW-12. Also, resume sampling quarterly as requested at MW-13.					
ROD/Consent Order Modifications?		NO			
reclassification recommended :		None			
Contaminant of concern OU		Contaminant of concern		Media/Receptor	
01		TOLUENE (F005)			
01		XYLENE			
01		TETRACHLOROETHYLENE			
01		TRICHLOROETMYLENE			
01		CARBON TETRACHLORIDE			
Remedies OU		Remedies		Size of Treatment	
01		No Action		Date in Place / / Remedy Effective Yes	
01		Waterline Extension		/ / Yes	

Next Review 02/07/2004			Priority: 2		
Project Manager Bendell			Reviewer: Pergadia		
Signature		Date		Signature	
Name		Region or Bureau		Telephone	