APPENDIX K GEOTECHNICAL TESTING REPORTS





= E. TETZ & SONS, INC. ==

130 CROTTY ROAD • MIDDLETOWN, NY 10941 (845) 692-4486 • FAX (845) 692-6938



September 12, 2012

Attention: Ben Entact, LLC. 1010 Executive Court Suite 280 Westmart, IL 60559

Via Fax: 972-550-7464

To Whom It May Concern:

Please be advised that to the best of my knowledge all materials delivered to the R.S.R. site in the Town of Wallkill, Orange County, New York are of virgin origin and contain no contaminants and are clean and free of anything but natural material. Following is a list of our approved locations:

<u>Site</u>	DEC Permit #
Bloomingburg	3-4840-00033/00003
Summitville	3-4840-00082/00001
Slate Hill	3-3356-00015/00005
Chester	3-3322-00037/00004
Mongaup Valley	3-4846-00120/00013

Do not hesitate to contact me should you require any additional information (Cell 845-283-2380).

Halfry Kiernan

Bobby Kierman Sales Representative E. Tetz & Sons, Inc.



08/29/2009 13:42

8454951398

ADVANCE TESTING CO

PAGE 02/09



Advance

3348 Route 208, Campbell Hall, NY 10916 Phone: 845-496-1600 Fax: 845-496-1398

25 Hathom Road, Enfield, NH 63748

42 Day Farm Road, West Stockheidge, MA 01266

Clients	E. Tetz and Sons	Projects	Quality Control
Material	Item 4 Pine	Project Number:	090011
Source	Chester Quarry	Lab Nimber:	09-06778
Date Sampled:	8/19/2009	Sampled By:	Client
Date Tested:	8/21/2009	Tasted By:	K. Harris

	سنتحوب ويستفين ويبهالنهوب الحورب	والمراجع والمتحارب والمتحا
CIPATIATION (CIPS/PAN)	ALYSIS) OF SOIL OR AGGRE	
	UNITEDIDI DE DOMO ON VIVINA	
Tent Mathematics A TAN SIA	24. C136. C117. AALBOYO YOU THAT	7(
	WE CAN A CAS I LEGAL ST TO THE TAX I	

Lab Number Se	emple Type Sampling	
09-0677B	Man 4 Fine Stock	pile NYSDOT 554.01 M-Backfill

Sleva Slate		%	%	Spec. %
75.7T	inches .	Rotsined	Pendus	Pam
100.II mm	4*	0.0	100.0	100
75.0 mm	34	0.0	100.6	
63.0 may	2 I/2"	0,0	100.0	
54.0 mm	2"	0.0	100.0	
27.5 may	1 1/2"	0.0	100.0	
24.4 mm	1,	0.9	99.1	
19.8 mm	3/4"	7.5	91,6	
12.5 mm	1/2"	14.2	77.4	
4.) mm	1/4"	23.4	54.0	30-100
4.75 Was	#4	7,3	46.7	
2,00 mm	#19	17.6	29.1	
GLESS STEEL	430	10.7	18,4	
\$-500 mm	#30	7.8	15.6	
\$.426 mm	#40	2.1	13.5	0-60
\$.150 mm	#160	4.5	9.0	
9.076 Mm	#200	2.0	7.0	0-15
Pas		7.0		

Comments:

Test results comply with specification. Minus #200 by wast-sieve method.


Report Reviewed By:

25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

CLIENT:	E. Tetz and Sous		PROJECT NO.:	90011
PROJECT:			LAB NUMBER:	12-0665
TEST METHOD:			Method: C	
SOIL ID NUMBER:	16			
ITEM:	Item 4			
SOURCE:	E. Tetz and Sons			
SOIL DESCRIPTION:	Mod Gray Crush	ed Shale:69% Gravel; 23%	Sand; 8% Silt	
DATE SAMPLED:	7/31/2012	SAMPLED BY:	Client	
DATE TESTED:	7/31/2012	TESTED BY:	Justin Rademacher	

REPORT OF MOISTURE DENSITY RELATIONSHIP



Individua	Individual Test Points			
Percent	Dry			
Moisture	Density			
2.6	132.0			
4.9	142.0			
7,5	140,3			
10.3	134.4			

Uncorrected Maximum Dry Density;	142.5	lb/cu. ft.
Uncorrected Optimum Moisture Content:	5.7	%
Percent Oversize Particles:	28.7	%
Specific Gravity of Oversize:	2.76	

Corrected* Maximum Dry Density: 149.9 lb/cu. ft. Corrected* Opt. Moisture Content:

Corrected for oversize, when oversize particles exceed 5% of sample.

Report Reviewed By-

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

Citanti	E. Tetz and Sons	Project:	Quality Congol
Material:	3/8" Stone	Project Number:	090011
Source:	E. Tels: Bloomingburg	Lah Number:	10-0639F
Date Sampled:	7/30/2010	Sampled By:	Client
Date Tested:	8/2/2010	Tested By:	John Brinsfild

GRADATION (SIEVE AVALYSIS) OF SOIT, OF A	
Control of the second of the s	POMPO72/34 A)
The Land of the State of the St	4040 4-11
Test Methodich: ASTN/ DATA CIDE, C177; AASHTO TIE	1.46/6 A S I

Lab Number	Sample Type	Sampking Location	Specification
10-0639F	3/8" Stone	Stockpile	

Slave Stre		%	9%	Spec. %
THE .	Laches	Retained	Passipp	Pass
15.7 mm	3/4"	0.0	100.0	
12.6 mm	1/2"	3,4	96.6	
9.5 mm	3/8"	37.1	59.5	
6.3 mm	1/49 5	30.7	8.8	
475 mm	44	5.0	3.8	
2.94 mm	#8	7.3_	1.5	
Pas		1,5		

				ļ <u>-</u> -

Comments:

Report Reviewed By:

Ernily J. Rodriguez

HERY COPY



= E. TETZ & SONS, INC. ==

130 CROTTY ROAD • MIDDLETOWN, NY 10941 (845) 692-4486 • FAX (845) 692-6638



September 12, 2012

Attention: Ben Entact, LLC. 1010 Executive Court Suite 280 Westmart, IL 60559

Via Fax: 972-550-7464

To Whom It May Concern:

Please be advised that to the best of my knowledge all materials delivered to the R.S.R. site in the Town of Wallkill, Orange County, New York are of virgin origin and contain no contaminants and are clean and free of anything but natural material. Following is a list of our approved locations:

<u>Site</u>	DEC Permit #
Bloomingburg	3-4840-00033/00003
Summitville	3-4840-00082/00001
Slate Hill	3-3356-00015/00005
Chester	3-3322-00037/00004
Mongaup Valley	3-4846-00120/00013

Do not hesitate to contact me should you require any additional information (Cell 845-283-2380).

Halfry Kilmon

Bobby Kiernan Sales Representative E. Tetz & Sons, Inc.

p.1

Tetz Asphalt

845-344-4160



3348 Route 208, Campbell Hall, NY 10916 Phone: 845 496-1600 Fax: 845-496-1398

25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

	E. Tetz and Sons	Project:	Quality Control
Client:	Bedding Layer	Project Number:	090011
Material:	Bloomingburg	Lab Number:	12-0830
Source:	Stockpile	Item Number:	Protective Layer Soil
Location:	9/21/2012	Sampled By:	Client
Date Sampled:	9/26/2012	Tested By:	John Brinsfield

Report of Hydraulic Conductiv	ty (Constant Head Permeability)
Test Method: ASTM	02434, AASHTO T215

Permeability Test Conditions	
Laboratory Recompacted Density of Sample:	Moderate
Compaction, Percent of Maximum Dry Density (%):	N/A
Moisture Content During Recompaction (%):	5.0

Sample diameter (cm):

11.20

Area (cm²):

Piezometer Spacing, L (cm):

	" .	٠.			-				
	Tail Level	Hend Level	Head (cm)	Volume (Q)	Time (1) sec	Q/At	₩.L	"C	k=(Q/At)/(b/L)
1	·	26.2	6.4	500	60	8.46E-02	0.56	21.1	1.47E-01
1	19.8	26.2		530	60	8.97E-02	0.66	21.1	1.31E-01
١	20.4	28.0	7.6	535	60	9.06E-02	0.71	21.1	1,24E-01
Ī	20.5	28.6	8.1	545	60	9.23E-02	0.77	21.1	1.17E-01
١	20.7	29.5	8.8		60	9.56E-02	0.82	21.1	1.13E-01
]	21.0	30.4	9.4	565	60	9.82E-02	0.85	21.1	1,1315-01
·	21.3	31.0	9.7	580		3.020-02		1	
1	13	1	4	1	, ,				

98.5

Permeability Test Results

Coefficient of Permeability @ 20°C (68°F):

1.24E-01 cm/sec

Project Specification:

1.00E-03 cm/sec

Notes:

1. Permeability values obtained under field conditions will be influenced by compaction density and moisture content, compaction equipment used, variations in material, preparation methods, subgrade conditions, weather, and other factors. 2. Changes in head level between test increments may differ from the specified 0.5cm, in order to accurately assess the

laminar flow regime. 3. Test results are corrected to standard temperature (20°C / 68°F).

Comments: Test result complies with specification

Emily J. Kodeiguez

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.

Lab Number

12-0830

Sep 27 12 11:19a

Tetz Asphalt



3348 Route 208, Campbell Hall, NY 10916 Phone: 845-496-1600 Fax: 845-496-1398

25 Hathort Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

	1014		
	Proje	ct:	Quality Control
Client: E. Tetz and Sons		ct Number:	090011
Item: Bedding Layer		Number:	12-0830
Source: Bioomingourg		led By:	Client
Date Sampled: 9/21/2012		d By:	John Brinsfield
Date Tested: 9/25/2012			

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Sample Type Sampling Location Specification

Stockpile

Sieve Size		%	%	Spec. %
mm	Inches	Retained	Passing .	Pass
100.0 mm	4 ⁿ	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	0.001	
19.0 mm	3/4"	0.8	99.2	<u> </u>
12.5 mm	1/2"	1.3	97.9	
6.3 mm	1/4"	34.3	63.6	
4.75 mm	#4	7.7	55.9	
2,00 mm	#10	12.6	33.3	
0.850 mm	#20	10,6	22.7	
0.600 mm	#30	2.7	20.0	
0.425 mm	#40	2.5	17.5	
0.150 mm	#100	6.2	11.3	
0.130 mm	#200	2.7	8.6	
Pan	11200	8.6		

Comments:

Minus #200 by wash-sieve method.

ENTACT

Report Reviewed By:

rily J. Rodriguez

p.3

Sep 27 12 11:19a

Tetz Asphalt



42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7 Harpursville, NY 13787

	Quality Control
Clients E. Tetz and Sons Proje	14 Number: 090011
CREATE TOYER	(12.0020
Lab	Milliott
Source: Bloomingburg Item	Rumber.
	Client
Date Sampled: 9/21/2012 Test	el By: Emily Rodriguez
Date Tested: 9/26/2012	
The second	

Report for Unified	E-3 Classification
Deport for Unitied	Son Classification
Kehore to	4 73407
Test Method:	ASTM DZ4b/
I est Memodi	

USCS Group Symbol:

SW-SM

USCS Group Name:

Well graded sand with silt and gravel.

Specifications: SW-SM or SP-SM

Comments: Test result complies with specification

Emily J. Rodriguez

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.

p.1

Sep 27 12 11:19a

Tetz Asphalt



3348 Route 208, Campbell Hall, NY 10916 Phone: 845-496-1600 Fax: 845-496-1398 25 Hathorn Road, Enfield, NH 03748 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

	E. Tetz and Sons		Project:	Quality Control
Client:	Bedding Layer		Project#:	090011
Material:	Bloomingburg		Lab No.:	12-0830
Source:	Stockpile		Item Number:	RSR, Middletown NY
Location:	9/21/2012	1	Sampled By:	Client
Date Sampled:	9/25/12	\top	Tested By:	John Brinsfield
Date Tested:	912371,2	+		

REPORT OF ATTERBERG LIMITS TEST RESULTS

1	REPOR	IUFALLERD	10,100	
1		TEST METHOD:	ASTM	D4318; LL Method B
Į,				
	·			Specification
ľ	Lab Number:	12-0830		Specification
ħ	Liquid Limit:			
ŀ	Plastic Limit:			
ł	Plasticity Index:			

Notes:

The soil characteristics of this sample do not allow for the liquid limit

or plastic limit to be determined. Therefore, the plasticity index for the

sample is 'non-plastic.'

Sample was air-dried

Comments:

Emily

Report Reviewed By

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Bedding Layer	Project Number:	120361
Source:	E. Tetz and Sons Bloomingburg	Lab Number:	12-0916
Date Sampled:	10/17/2012	Sampled By:	Client
Date Tested:	10/17/2012	Tested By:	John Brinsfield

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
12-0916	Bedding Layer	Stockpile	

Sieve	e Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	100
12.5 mm	1/2"	0.2	99.8	
6.3 mm	1/4"	25.7	74.1	
4.75 mm	#4	6.4	67.7	
2.00 mm	#10	21.3	46.4	
0.850 mm	#20	13.5	32.9	
0.600 mm	#30	3.8	29.1	
0.425 mm	#40	4.6	24.5	
0.150 mm	#100	12.0	12.5	
0.075 mm	#200	4.2	8.3	
Pan		8.3		

Emily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 0374842 Day Farm Road, West Stockbridge, MA 012661813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Material:	Bedding Layer	Project #:	120361
Source:	E. Tetz and Sons Bloomingburg	Lab No.:	12-0916
Location:	Stockpile	Item Number:	Bedding Layer
Date Sampled:	10/17/2012	Sampled By:	Client
Date Tested:	10/19/12	Tested By:	John Brinsfield

REPORT OF ATTERBERG LIMITS TEST RESULTS
TEST METHOD: ASTM D4318; LL Method B

Lab Number:	12-0916	Specification
Liquid Limit:	Non-Plastic	
Plastic Limit:	24	
Plasticity Index:	Non-Plastic	

Notes: Values shown are percent moisture.

Customary procedure is to round results to the nearest whole number.

Sample was air-dried

Comments: Material was tested on the minus #200

Report Reviewed By:

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.



1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project	RSR, Middletown, NY
Material:	Bedding Layer	Project Number:	120361
Source:	E. Tetz and Sons Bloomingburg	Lab Number:	12-0916
Location:	Stockpile	Item Number:	Bedding Layer
Date Sampled:	10/17/2012	Sampled By:	Client
Date Tested:	10/23/2012	Tested By:	Emily Rodriguez

Report for Unific	ed Soil Classification
Test Method:	ASTM D2487

USCS Group Symbol: SW

Well Graded Sand USCS Group Name:

Specifications: SW, SM, SC, ML, or CL

Comments: Test result complies with specification

Report Reviewed By:

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer	Project Number:	120361
Source:	E. Tetz, Bloomingburg, NY	Lab Number:	12-1027A
Date Sampled:	11/30/2012	Sampled By:	Client
Date Tested:	12/4/2012	Tested By:	Jared Vassell

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
12-1027A	Protective Soil Layer	Containment Cell	Protective Soil Layer
Client ID No.:	PSL-01		

Sieve	e Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	4.7	95.3	
6.3 mm	1/4"	30.3	65.0	
4.75 mm	#4	9.7	55.3	
2.00 mm	#10	19.4	35.9	
0.850 mm	#20	12.0	23.9	
0.600 mm	#30	3.0	20.9	
0.425 mm	#40	3.3	17.6	
0.150 mm	#100	8.0	9.6	
0.075 mm	#200	2.9	6.7	5-100
Pan		6.7		

Emily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer	Project Number:	120361
Source:	E. Tetz, Bloomingburg, NY	Lab Number:	12-1027B
Date Sampled:	11/30/2012	Sampled By:	Client
Date Tested:	12/4/2012	Tested By:	Jared Vassell

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Lab Number Sample Type		Specification	
12-1027B	Protective Soil Layer	Containment Cell	Protective Soil Layer	
Client ID No.:	PSL-02			

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	2.7	97.3	
6.3 mm	1/4"	22.6	74.7	
4.75 mm	#4	9.1	65.6	
2.00 mm	#10	26.1	39.5	
0.850 mm	#20	17.0	22.5	
0.600 mm	#30	3.3	19.2	
0.425 mm	#40	2.9	16.3	
0.150 mm	#100	6.8	9.5	
0.075 mm	#200	2.5	7.0	5-100
Pan		7.0		

Ernily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 0374842 Day Farm Road, West Stockbridge, MA 012661813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Material:	Protective Soil Layer (PSL-02)	Project Number:	120361
Source:	Metro Recycling and Crushing	Lab Number:	12-1027B
Location:	Containment Cell	Client ID No.	PSL-02
Date Sampled:	11/30/2012	Sampled By:	Client
Date Tested:	12/6/2012	Tested By:	John Brinsfield

Report of Hydraulic Conductivity (Constant Head Permeability)
Test Method: ASTM D2434, AASHTO T215

Permeability Test Conditions			
Laboratory Recompacted Density of Sample (PCF):	123.7		
Moisture Content During Recompaction (%):	4.8		

Sample diameter (cm): 11.20 Area (cm²): 98.5 Piezometer Spacing, L (cm): 11.43

Tail Level	Head Level	Head (cm)	Volume (Q) mL	Time (t) sec	Q/At	h/L	°C	k=(Q/At)/(h/L)
9.8	28.0	18.2	170	60	2.88E-02	1.59	21.1	1.76E-02
10.0	29.0	19.0	180	60	3.05E-02	1.66	21.1	1.78E-02
10.1	30.1	20.0	190	60	3.22E-02	1.75	21.1	1.79E-02
10.2	32.0	21.8	210	60	3.56E-02	1.91	21.1	1.81E-02
10.4	33.2	22.8	220	60	3.72E-02	1.99	21.1	1.82E-02
1.2	31.0	29.8	200	60	3.39E-02	2.61	21.1	1.26E-02

Permeability Test Results

Coefficient of Permeability @ 20° C (68° F): **k20** = **1.79E-02** cm/sec

Notes:

- 1. Permeability values obtained under field conditions will be influenced by compaction density and moisture content, compaction equipment used, variations in material, preparation methods, subgrade conditions, weather, and other factors.
- 2. Changes in head level between test increments may differ from the specified 0.5cm, in order to accurately assess the laminar flow regime.
- 3. Test results are corrected to standard temperature (20°C / 68°F).

Comments: The final trial shows a decrease in k value that indicates turbulent flow conditions; the consistent values determined in the previous trials indicate laminar flow conditions. The final trial result is not included in the average.

Specifications not available at time of testing.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-03)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1043A
Date Sampled:	12/6/2012	Sampled By:	Client
Date Tested:	12/11/2012	Tested By:	John Brinsfield

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Lab Number Sample Type		Specification
12-1043A	Protective Soil Layer (PSL-03)	Stockpile	

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	3.1	96.9	
6.3 mm	1/4"	22.3	74.6	
4.75 mm	#4	5.8	68.8	
2.00 mm	#10	21.2	47.6	
0.850 mm	#20	19.3	28.3	
0.600 mm	#30	5.9	22.4	
0.425 mm	#40	4.9	17.5	
0.150 mm	#100	8.2	9.3	
0.075 mm	#200	2.6	6.7	
Pan		6.7		

Emily J. Rodriguez

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 0374842 Day Farm Road, West Stockbridge, MA 012661813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Material:	Protective Soil Layer (PSL-05)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1043C
Location:	Stockpile	Item Number:	PSL-03
Date Sampled:	12/8/2012	Sampled By:	Client
Date Tested:	12/12/2012	Tested By:	John Brinsfield

Report of Hydraulic Conductivity (Constant Head Permeability)		
Test Method: ASTM D2434, AASHTO T215		

Permeability Test Conditions	
Laboratory Recompacted Density of Sample (PCF):	135.0
Moisture Content During Recompaction (%):	3.7

Sample diameter (cm): 11.20 Area (cm²): 98.5 Piezometer Spacing, L (cm): 11.43

Tail Level	Head Level	Head (cm)	Volume (Q) mL	Time (t) sec	Q/At	h/L	°C	k=(Q/At)/(h/L)
11.7	32.4	20.7	790	60	1.34E-01	1.81	21.1	7.19E-02
11.7	33.0	21.3	200	60	3.39E-02	1.86	21.1	1.77E-02
11.8	34.0	22.2	210	60	3.56E-02	1.94	21.1	1.78E-02
11.8	35.2	23.4	215	60	3.64E-02	2.05	21.1	1.73E-02
11.9	36.0	24.1	220	60	3.72E-02	2.11	21.1	1.72E-02
12.0	37.2	25.2	225	60	3.81E-02	2.20	21.1	1.68E-02

Permeability Test Results

Coefficient of Permeability @ 20° C (68° F): **k20** = **2.65E-02** cm/sec

Notes:

- 1. Permeability values obtained under field conditions will be influenced by compaction density and moisture content, compaction equipment used, variations in material, preparation methods, subgrade conditions, weather, and other factors.
- 2. Changes in head level between test increments may differ from the specified 0.5cm, in order to accurately assess the laminar flow regime.
- 3. Test results are corrected to standard temperature (20°C / 68°F).

Comments: No Specifications available at time of testing.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-04)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1043B
Date Sampled:	12/8/2012	Sampled By:	Client
Date Tested:	12/11/2012	Tested By:	John Brinsfield

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
12-1043B	Protective Soil Layer (PSL-04)	Stockpile	

Sieve	e Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	4.4	95.6	
6.3 mm	1/4"	27.8	67.8	
4.75 mm	#4	5.9	61.9	
2.00 mm	#10	20.5	41.4	
0.850 mm	#20	17.7	23.7	
0.600 mm	#30	4.5	19.2	
0.425 mm	#40	3.7	15.5	
0.150 mm	#100	6.9	8.6	
0.075 mm	#200	2.2	6.4	
Pan		6.4		

Emily J. Rodriguez

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-05)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1043C
Date Sampled:	12/8/2012	Sampled By:	Client
Date Tested:	12/11/2012	Tested By:	John Brinsfield

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
12-1043C	Protective Soil Layer (PSL-05)	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	2.7	97.3	
6.3 mm	1/4"	25.9	71.4	
4.75 mm	#4	3.6	67.8	
2.00 mm	#10	19.2	48.6	
0.850 mm	#20	20.1	28.5	
0.600 mm	#30	5.5	23.0	
0.425 mm	#40	4.7	18.3	
0.150 mm	#100	8.4	9.9	
0.075 mm	#200	2.6	7.3	
Pan		7.3		

Emily J. Rodriguez

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-06)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1062A
Date Sampled:	12/11/2012	Sampled By:	Client
Date Tested:	12/18/2012	Tested By:	Jared Vassell

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification	
12-1062A	Protective Soil Layer (PSL-06)	Containment Cell	Protective Soil Layer	

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	100
12.5 mm	1/2"	2.2	97.8	
6.3 mm	1/4"	19.3	78.5	
4.75 mm	#4	10.3	68.2	
2.00 mm	#10	25.8	42.4	
0.850 mm	#20	21.7	20.7	
0.600 mm	#30	4.3	16.4	
0.425 mm	#40	3.0	13.4	
0.150 mm	#100	4.9	8.5	
0.075 mm	#200	1.5	7.0	5-100
Pan		7.0		

Emily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-07)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1062B
Date Sampled:	12/13/2012	Sampled By:	Client
Date Tested:	12/18/2012	Tested By:	Jared Vassell

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification	
12-1062B	Protective Soil Layer (PSL-07)	Containment Cell	Protetive Soil Layer	

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	100
12.5 mm	1/2"	3.6	96.4	
6.3 mm	1/4"	19.4	77.0	
4.75 mm	#4	4.4	72.6	
2.00 mm	#10	22.2	50.4	
0.850 mm	#20	24.5	25.9	
0.600 mm	#30	5.5	20.4	
0.425 mm	#40	4.0	16.4	
0.150 mm	#100	6.4	10.0	
0.075 mm	#200	1.3	8.7	5-100
Pan		8.7		

Emily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Material:	Protective Soil Layer (PSL-07)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1062B
Location:	Containment Cell	Item Number:	Protective Soil Layer
Date Sampled:	12/13/2012	Sampled By:	Client
Date Tested:	12/19/2012	Tested By:	John Brinsfield

Report of Hydraulic Conductivity (Constant Head Permeability)		
Test Method: ASTM D2434, AASHTO T215		

Permeability Test Conditions				
Laboratory Recompacted Density of Sample (PCF):	102.0			
Moisture Content During Recompaction (%):	3.4			

Sample diameter (cm): 11.20 Area (cm²): 98.4 Piezometer Spacing, L (cm): 11.43

Tail Level	Head Level	Head (cm)	Volume (Q) mL	Time (t) sec	Q/At	h/L	°C	k=(Q/At)/(h/L)
13.6	25.9	12.3	210	60	3.56E-02	1.08	21.1	3.22E-02
14.0	26.9	12.9	226	60	3.83E-02	1.13	21.1	3.30E-02
14.1	27.5	13.4	230	60	3.90E-02	1.17	21.1	3.24E-02
14.2	28.0	13.8	230	60	3.90E-02	1.21	21.1	3.14E-02
14.5	28.5	14.0	236	60	4.00E-02	1.22	21.1	3.18E-02
14.5	29.5	15.0	242	60	4.10E-02	1.31	21.1	3.04E-02

Permeability Test Results

Coefficient of Permeability @ 20° C (68° F): k20 = 3.19E-02 cm/sec Project Specification: 1.00E-03 cm/sec

Notes:

- 1. Permeability values obtained under field conditions will be influenced by compaction density and moisture content, compaction equipment used, variations in material, preparation methods, subgrade conditions, weather, and other factors.
- 2. Changes in head level between test increments may differ from the specified 0.5cm, in order to accurately assess the laminar flow regime.
- 3. Test results are corrected to standard temperature (20°C / 68°F).

Comments:

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.

Emily J. Kodriguez



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR, Middletown, NY
Item:	Protective Soil Layer (PSL-08)	Project Number:	120361
Source:	E. Tetz Bloomingburg, NY	Lab Number:	12-1062C
Date Sampled:	12/15/2012	Sampled By:	Client
Date Tested:	12/18/2012	Tested By:	Jared Vassell

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
12-1062C	Protective Soil Layer (PSL-08)	Containment Cell	Protective Soil Layer

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	100
12.5 mm	1/2"	2.8	97.2	
6.3 mm	1/4"	19.4	77.8	
4.75 mm	#4	7.6	70.2	
2.00 mm	#10	24.3	45.9	
0.850 mm	#20	20.5	25.4	
0.600 mm	#30	4.6	20.8	
0.425 mm	#40	3.8	17.0	
0.150 mm	#100	7.1	9.9	
0.075 mm	#200	2.3	7.6	5-100
Pan		7.6		

Emily J. Rodriguez

Comments: Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Subgrade	Project Number:	140125
Source:	ORI	Lab Number:	14-0333A
Date Sampled:	5/8/2014	Sampled By:	Client
Date Tested:	5/19/2014	Tested By:	Brian Kolodziejczyk

DADATION (CIEVE ANALYCI	STOR SOLL OF ACCORCATE	
MADATION (SIEVE ANALISI	S) OF SOIL OR AGGREGATE	
Test Method(s): ASTM D422, C136	, C117; AASHTO 188, T27, T11	
	•	GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0333A	Subgrade	Stockpile	

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
i				
109.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.5	99.5	
6.3 mm	1/4"	0.5	99.0	
4.75 mm	#4	0.6	98.4	
2.00 mm	#10	3.5	94.9	
0.850 mm	#20	6.4	88.5	
0.600 mm	#30	3.6	84.9	
0.425 mm	#40	3.0	81.9	
0.150 mm	#100	7.7	74.2	
0.075 mm	#200	5.6	68.6	
Pan		68.6		

J. Rodriguez

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Subgrade	Project Number:	140125
Source:	ORI	Lab Number:	14-0333A
Location:	Stockpile	Item Number:	No Specification Available
Date Sampled:	5/8/2014	Sampled By:	Client
Date Tested:	5/16/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition			
Test Method: AASHTO T267			

Inorganic Content:	77.7	%	(Sand, silt, clay, etc.)
Organic Content:	22.3	%	
Specification:			

Comments:

No specifications available at time of testing.

Report Reviewed By:

Rodriguez

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Habitat Sub-grade	Project Number:	140125
Source:	On Site Topsoil	Lab Number:	14-0758C
Location:	Stockpile	Item Number:	No Specification Available
Date Sampled:	8/19/2014	Sampled By:	Client
Date Tested:	8/20/2014	Tested By:	Donald Leisure

	Report	of pH of Soil				
To To	est Method: A	STM D4972 Method A				
pH Test Result:	7.5	(in Distilled Water)				
	N/A	(In Calcium Chloride Solution)				
Specification Comments:						
No specifications available at time of testing.						
E	mily	J. Rodriguez				



Date Sampled/Received: 04 Jun. 13 / 06 Jun. 13

Organic Recycling Inc. (Tappan)

Jessie Te

117A Route 303

Tappan

NY 10983

Product Identification Compost

ORI- Compost

COMPOST TECHNICAL DATA SHEET

LABORATORY: Soil Control Lab; 42 Hangar Way; Watsonville, CA 95076 tel: 831.724.5422 fax: 831.724.3188				
Compost Parameters	Reported as (units of measure)	Test Results	Test Results	
Plant Nutrients:	%, weight basis	Not reported	Not reported	
Moisture Content	%, wet weight basis	51.7		
Organic Matter Content	%, dry weight basis	44.6		
pН	units	8.07		
Soluble Salts (electrical conductivity EC 3)	dS/m (mmhos/cm)	1.7		
Particle Size or Sieve Size	maxium aggregate size, inches	0.38		
Stability Indicator (respirometry)	-	Stability Rating:	
CO ₂ Evolution mg CO ₂ -C/g OM/day		2,1	Stable	
	mg CO ₂ -C/g TS/day	0.96	Stable	
Maturity Indicator (bioassay)				
Percent Emergence	average % of control	100.0		
Relative Seedling Vigor	average % of control	100.0		
Select Pathogens	PASS/FAIL: per US EPA Class A standard, 40 CFR § 503.32(a)	Pass	Fecal coliform	
		Pass	Salmonella	
Trace Metals			As,Cd,Cr,Cu,Pb,Hg	
	standard, 40 CFR § 503.13, Tables 1 and 3.	Pass .	Mo,Ni,Se,Zn	

Participants in the US Composting Council's Seal of Testing Assurance Program have shown the commitment to test their compost products on a prescribed basis and provide this data, along with compost end use instructions, as a means to better serve the needs of their compost customers.

Laboratory Group:	Jun.13 A	Laboratory Number: 3060226-1/1
Analyst: Assaf Sadeh	Clay Solet	www.compostlab.com



Date Sampled/Received: 04 Jun. 13 / 06 Jun. 13

Organic Recycling Inc. (Tappan)

Jessie Te

117A Route 303

Tappan

NY 10983

Product Identification Compost

ORI- Compost

COMPOST TECHNICAL DATA SHEET

LABORATORY: Soil Control Lab; 42 Hangar Way; Watsonville, CA 95076 tel: 831.724.5422 fax: 831.724.3188				
Compost Parameters Reported as (units of measure)		Test Results	Test Results	
Plant Nutrients:	%, weight basis	%, wet weight basis	%, dry weight basis	
Nitrogen	Total N	0.76	1.6	
Phosphorus	P ₂ O ₅	0.23	0.48	
Potassium	K ₂ O	0.31	0.66	
Calcium	Ca	1.2	2.6	
Magnesium	Mg	0.33	0.68	
Moisture Content	%, wet weight basis	51.7		
Organic Matter Content	%, dry weight basis	44.6		
рН	units	8.07		
Soluble Salts (electrical conductivity EC 3)	dS/m (mmhos/cm)	1.7		
Particle Size or Sieve Size	% under 9.5 mm, dw basis	100,0		
Stability Indicator (respirometry)	-	Stability Rating:	
CO ₂ Evolution	mg CO ₂ -C/g OM/day	2.1 Stable		
	mg CO ₂ -C/g TS/day	0.96		
Maturity Indicator (bioassay)				
Percent Emergence	average % of control	100.0		
Relative Seedling Vigor	average % of control	100.0		
Select Pathogens	PASS/FAIL: per US EPA Class A standard, 40 CFR § 503.32(a)	Pass . Fecal coliform		
		Pass	Salmonella	
Trace Metals	PASS/FAIL: per US EPA Class A standard, 40 CFR § 503.13,	Pass	As,Cd,Cr,Cu,Pb,Hg	
	Tables 1 and 3.	1 433	Mo,Ni,Se,Zn	

Participants in the US Composting Council's Seal of Testing Assurance Program have shown the commitment to test their compost products on a prescribed basis and provide this data, along with compost end use instructions, as a means to better serve the needs of their compost customers.

Laboratory Group:	Jun.13 A	Laboratory Number: 3060226-1/1
Analyst: Assaf Sadeh	Clay Sobel	www.compostlab.com

TEL: 831-724-5422 FAX: 831-724-3188 www.compostlab.com

SOIL CONTROL LAB

WAISONVILLE CAUFORNIA 95076 USA

Account #: 3060226-1/1-7581 Group: Jun.13 A #37 Reporting Date: June 17, 2013

Organic Recycling Inc. (Tappan)

117A Route 303 Tappan, NY 10983 Attn: Jessie Te

Date Received:

Zinc (Zn):

06 Jun. 13 **ORI- Compost** 3060226 - 1/1

Sample Identification: Sample ID #:

				. <u></u>			
Nutrients	Dry wt.	As Rcvd.	units	Stability Indica			Biologically
Total Nitrogen:	1.6	0.76	%	CO2 Evolution		Respirometery	Available C
Ammonia (NH ₄ -N):	310	150	mg/kg	mg CO ₂ -C/g ON	//day	2.1	19
Nitrate (NO ₃ -N):	3.0	1.4	mg/kg	mg CO₂-C/g TS	/day	0.96	8.5
Org. Nitrogen (OrgN):	1.6	0.77	%	Stability Rati	ing	stable	unstable
Phosphorus (as P ₂ O ₅):	0.47	0.23	%		_		
Phosphorus (P):	2100	1000	mg/kg				
Potassium (as K₂O):	0.66	0.32	%	Maturity Indica	itor: Cucum	ber Bioassay	
Potassium (K):	5500	2600	mg/kg	Compost:Vermi	culite(v:v)	1:1	1:3
Calcium (Ca):	2.6	1.2	%	Emergence (%)	1	100	100
Magnesium (Mg):	0.68	0.33	%	Seedling Vigor	(%)	100	100
Sulfate (SO ₄ -S):	31	15	mg/kg	Description of	of Plants	healthy	healthy
Boron (Total B):	30	14	mg/kg	,		•	-
Moisture:	0	51.7	%				
Sodium (Na):	0.046	0.022	%	Pathogens	Results	Units	Rating
Chloride (CI):	0.11	0.053	%	Fecal Coliform	< 2.0	MPN/g	pass
pH Value:	NA	8.07	unit	Salmonella	< 3	MPN/4g	pass
Bulk Density :	22	46	lb/cu ft	Date Tested: 06 J	un. 13	•	•
Carbonates (CaCO ₃):	30	15	lb/ton				
Conductivity (EC5):	1.7	NA	mmhos/cm				
Organic Matter:	44.6	21.6	%	Inerts	% by weight	/(+	
Organic Carbon:	26.0	13.0	%	Plastic	< 0.5		
Ash:	55.4	26.8	%	Glass	< 0.5		
C/N Ratio	17	17	ratio	Metal	< 0.5		
Agindex	> 10	> 10	ratio	Sharps	ND		
Metals	Dry wt.	EPA Limit	units	Size & Volume	Distribution	1	-
Aluminum (AI)	6400	-	mg/kg	ММ	% by weight	% by volume	BD g/cc
Arsenic (As):	4.4	41	mg/kg	> 50	0.0	0.0	0.00
Cadmium (Cd):	< 1.0	39	mg/kg	25 to 50	0.0	0.0	0.00
Chromium (Cr):	16	1200	mg/kg	16 to 25	0.0	0.0	0.00
Cobalt (Co)	4.8	-	mg/kg	9.5 to 16	0.0	0.0	0.00
Copper (Cu):	45	1500	mg/kg	6.3 to 9.5	3.5	3.2	0.66
Iron (Fe):	12000	-	mg/kg	4.0 to 6.3	8.4	9.4	0.54
Lead (Pb):	61	300	mg/kg	2.0 to 4.0	18.1	20.9	0.51
Manganese (Mn):	630	4=	mg/kg	< 2.0	69.9	66.5	0.63
Mercury (Hg):	< 1.0	17 75	mg/kg	Bulk Density Description:<.35 Light Materials, .3560 medium weight materials, >.60 Heavy Materials			
Molybdenum (Mo):	2.1 12	75 420	mg/kg	mulbern vocc.	weight mate		
Nickel (Ni): Selenium (Se):	< 1.0	420 36	mg/kg			100	t: Assaf Sadeh
	< 1.0	30	mg/kg			Jan Maria	Solet

*Sample was received and handled in accordance with TMECC procedures.

2800

130

mg/kg

Clay Sodel

Account No.: 3060226 - 1/1 - 7581 Group: Jun.13 A No. 37 Date Received Sample i.d. Sample I.d. No. 06 Jun. 13 ORI- Compost 1/1 3060226

INTERPRETATION:

Page one of three

Is Your Compost Stable?

Respiration Rate	Biodegradation Rate of Your Pile
2.1 mg CO2-C/ g OM/day	+++++++ Stable > <moderately unstable=""><high for="" mulch<="" td=""></high></moderately>
Biologically Available Carbo	on (BAC) Optimum Degradation Rate
g OM/day	< Stable > < Moderately Unstable> < Unstable > < High For Mulch
ls Your Compost Mature?	
AmmoniaN/NitrateN ratio	
100 Ratio	VeryMature> <
Ammonia N ppm	
310 mg/kg dry wt,	VeryMature > < Immature
Nitrate N ppm	
3.0 mg/kg dry wt.	++ < immature > < Mature
pH value	
8.07 units	+++++++++++++++++++++++++++++++++++++
Cucumber Emergence	ADDRESSOR N
100.0 percent	Immature >I Mature
ls Your Compost Safe Red	garding Health?
Fecal Coliform	
< 1000 MPN/g dry wt.	+++++++ < Safe > < High Fecal Coliform
Salmonella	
Less than 3 /4g dry wt.	+++++++ <safe_ (none:defected)=""> < High Selmonella Count(> 3 per 4 grams)</safe_>
Metals US EPA 503	++++++
Pass dry wt.	<al> All:Metals Pass None of more Metals: Fall </al>
Does Your Compost Prov	ide Nutrients or Organic Matter?
Nutrients (N+P2O5+K2O)	
2.7 Percent	+++++++++++++++++++++++++++++++++++++
dry wt. Agindex (Nutrients / Sodium	
15 Ratio	***************************************
Plant Available Nitrogen (P/	
6 lbs/ton	********
wet wt.	Low Nitrogen Provider> < Average Nitrogen Provider > < Ligh Nitrogen Provider
17 Ratio	+++++++++++++++++++++++++++++++++++++
Soluble Available Nutrients	
1.7 mmhos/cm	++++++++ SioRelease> < Average Nument Release Rate
dry wt. Lime Content (CaCO3)	SCREEGES NOTING INTERIOR CONT. STATE AND AND INCOME.
30 Lbs/ton	Cow SI Average SI High Lime Content (as CaCO3)
dry wt. What are the physical pro	
Percent Ash	Rei iles di 1dai collibosti
55.4 Percent	++++++
dry wt. Sieve Size % > 6.3 MM (0.25	
3.5 Percent	+++++++++++++++++++++++++++
dry wt.	All Uses > < Size May Restrict Uses for Potting mix and Golf Courses

Account No.: Date Received 06 Jun. 13 3060226 - 1/1 - 7581 Sample i.d. ORI- Compost

Group: Jun.13 A No. 37 Sample I.d. No. 1/1 3060226

INTERPRETATION:

is Your Compost Stable?

Page two of three

Respiration Rate

2.1 Low: Good for all uses mg CO2-C/g OM/day

The respiration rate is a measurement of the biodegradation rate of the organic matter in the sample (as received). The respiration rate is determined by measuring the rate at which CO2 is released under optimized moisture and temperature conditions.

Biologically Available Carbon

19 High-for mulch

mg CO2-C/g OM/day

Biologically Available Carbon (BAC) is a measurement of the rate at which CO2 is released under optimized moisture, temperature, porosity, nutrients, pH and microbial conditions. If both the RR and the BAC test values are close to the same value, the pite is optimized for composting. If both values are high the compost pile just needs more time. If both values are low the compost has stabilized and should be moved to curing. BAC test values that are higher than RR indicate that the compost pile has stalled. This could be due to anaerobic conditions, lack of available nitrogen due to excessive air converting ammonia to the unavailable nitrate form, lack of nitrogen or other nutrients due to poor choice of feedstock, pH value out of range, or microbes rendered non-active.

Is Your Compost Mature?

AmmoniaN:NitrateN ratio 100 immature

Ammonia N p	pm
310	mature
Nitrate N ppm	1
3.0	immature
pH value	
8.07	mature

Composting to stabilize carbon can occur at such a rapid rate that sometimes phytotoxins remain in the compost and must be neutralized before using in high concentrations or in high-end uses. This step is called curing. Typically ammonia is in excess with the break-down of organic materials resulting in an increase in pH. This combination results in a loss of volatile ammonia (it smells). Once this toxic ammonia has been reduced and the pH drops, the microbes convert the ammonia to nitrates. A low ammonia + high nitrate score is indicative of a mature compost, however there are many exceptions. For example, a compost with a low pH (<7) will retain ammonia, while a compost with high lime content can lose ammonia before the organic fraction becomes stable. Composts must first be stable before curing indicators apply.

Cucumber Bloassay

100.0 Percent

Cucumbers are chosen for this test because they are salt tolerant and very sensitive to ammonia and organic acid toxicity. Therefore, we can germinate seeds in high concentrations of compost to

measure phytotoxic effects without soluble salts being the limiting factor. Values above 80% for both percent emergence and vigor are indicative of a well-cured compost. Exceptions include very high salts that affect the cucumbers, excessive concentrations of nitrates and other nutrients that will be in range when formulated to make a growing media. In addition to testing a 1:1 compost: vermiculite blend, we also test a diluted 1:3 blend to indicate a more sensitive toxicity level.

Is Your Compost Safe Regarding Health?

Fecal Coliform

< 1000 / g dry wt. Fecal coliforms can survive in both aerobic and anaerobic conditions and is common in all initial compost piles. Most human pathogens occur from fecal matter and all fecal matter is loaded in fecal coliforms. Therefore fecal coliforms are used as an indicator to determine if the chosen method for pathogen reduction (heat for compost) has met the requirements of sufficient temperature, time and mixing. If the fecal coliforms are reduced to below 1000 per gram dry wt. it is assumed all others pathogens are eliminated. Potential problems are that fecal coliform can regrow during the curing phase or during shipping. This is because the conditions are now more favorable for growth than during the composting process.</p>
Salmonella Bacteria

Less than 3 3 / 4g dry wt. Salmonella is not only another indicator organism but also a toxic microbe. It has been used in the case of biosolids industry to determine adequate pathogen reduction.

Metals

Pass The ten heavy metals listed in the EPA 503 regulations are chosen to determine if compost can be applied to ag land and handled without toxic effects. Most high concentrations of heavy metals are derived from woodwaste feedstock such as chrome-arsenic treated or lead painted demolition wood. Biosolids are rarely a problem.

Does Your Compost Provide Nutrients or Organic Matter?

Nutrients (N+P2O5+K2O)

2.7 Average nutrient content

This value is the sum of the primary nutrients Nitrogen, Phosphorus and Potassium. Reported units are consistent with those found on fertilizer formulations. A sum greater than 5 is indicative of a compost with high nutrient content, and best used to supply nutrients to a receiving soil. A sum below 2 indicates low nutrient content, and is best-used to improve soil structure via the addition of organic matter. Most compost falls between 2 and 5.

Account No.:

3060226 - 1/1 - 7581

Jun.13 A No. 37 Group:

Date Received

06 Jun. 13

Sample i.d.

ORI- Compost

Sample I.d. No. 1/1

Page three of three

3060226

INTERPRETATION:

AgIndex (Nutrients/Na+CI)

High nutrient ratio Composts with low AgIndex values have high concentrations of sodium and/or chloride compared to nutrients. Repeated use of a compost with a low AgIndex (< 2) may result in sodium and/or chloride acting as the limiting factor compared to nutrients, governing application rates. These composts may be used on well-draining soils and/or with salt-tolerant plants. Additional nutrients form another source may be needed if the application rate is limited by sodium or chloride. If the Agindex is above 10, nutrients optimal for plant growth will be available without concern of sodium and/or chloride toxicity. Composts with an AgIndex of above 10 are good for increasing nutrient levels for all soils. Most composts score between 2 and 10. Concentrations of nutrients, sodium, and chloride in the receiving soil should be considered when determining compost application rates. The AgIndex is a product of feedstock quality. Feedstock from dairy manure, marine waste, industrial wastes, and halophytic plants are likely to produce a finished compost with a low Agindex. Plant Available Nitrogen (lbs/ton)

- Average N Provider Plant Available Nitrogen (PAN) is calculated by estimating the release rate of Nitrogen from the organic fraction of the compost. This estimate is based on information gathered from the BAC test and measured ammonia and nitrate values. Despite the PAN value of the compost, additional sources of Nitrogen may be needed during he growing season to offset the Nitrogen demand of the microbes present in the compost. With ample nutrients these microbes can further breakdown organic matter in the compost and release bound Nitrogen. Nitrogen demand based on a high C/N ratio is not considered in the PAN calculation because additional Nitrogen should always be supplemented to the receiving soil when composts with a high C/N ratio are applied. C/N Ratio
- Indicates immaturity As a guiding principal, a C/N ratio below 14 indicates maturity and above 14 indicates immaturity, however, there are many exceptions. Large woodchips (>6.3mm), bark, and redwood are slow to breakdown and therefore can result in a relatively stable product while the C/N ratio value is high. Additionally, some composts with chicken manure and/or green grass feedstocks can start with a C/N ratio below 15 and are very unstable. A C/N ratio below 10 supplies Nitrogen, while a ratio above 20 can deplete Nitrogen from the soil. The rate at which Nitrogen will be released or used by the microbes is indicated by the respiration rate (BAC). If the respiration rate is too high the transfer of Nitrogen will not be controlable. Soluble Nutrients & Salts (EC5 w/w dw - mmhos/cm)
- This value refers to all soluble ions including nutrients, sodium, chloride and some 1.7 Average salts soluble organic compounds. The concentration of salts will change due to the release of salts from the organic matter as it degrades, volatilization of ammonia, decomposition of soluble organics, and conversion of molecular structure. High salts + high AgIndex is indicative of a compost high in readily available nutrients. The application rate of these composts should be limited by the optimum nutrient value based on soil analysis of the receiving soil. High Salts + low AgIndex is indicalive of a compost low in nutrients with high concentrations of sodium and/or chloride. Limit the application rate according to the toxicity level of thesodium and/or chloride. Low salts indicates that the compost can be applied without risking salt toxicity, is likely a good source of organic matter, and that nutrients will release slowly over time.

Lime Content (lbs. per ton)

Compost high in lime or carbonates are often those produced from chicken manure (layers) High lime content ash materials, and lime products. These are excellent products to use on a receiving soil where lime has been recommended by soil analysis to raise the pH. Composts with a high lime content should be closely considered for pH requirements when formulating potting mixes.

Physical Properties

Percent Ash

- Average ash content Ash is the non-organic fraction of a compost. Most composts contain approximately 50% 55.4 ash (dry weight basis). Compost can be high in ash content for many reasons including: excess minerilzation(old compost), contamination with soil base material during turning, poor quality feedstock, and soil or mineral products added. Finding the source and reducing high ash content is often the fastest means to increasing nutrient quality of a compost. Particle Size % > 6.3 MM (0.25")
- Large particles may restrict use for potting soils, golf course topdressings, seed-starter 3.5 May restrict use mixes, and where a fine size distribution is required. Composts with large particles can still be used as excellent additions to field soils, shrub mixes and mulches.

Particle Size Distribution

Each size fraction is measured by weight, volume and bulk density. These results are particularly relevent with decisions to screen or not, and if screening, which size screen to use. The bulk density indicates if the fraction screened is made of light weight organic material or heavy mineral material. Removing large mineral material can greatly improve compost quality by increasing nutrient and

organia contactitations.		
Appendix:		
	Estimated available nutrients for use whe	n calculating application rates
Plant Available Nitrogen (PAN) calculations:		lbs/ton (As Rcvd.)
PAN = (X * (organic N)) + ((NH4-N) + (NO3-N))		
X value = If BAC < 2 then X = 0.1	Plant Available Nitrogen (PAN)	6.3
If BAC =2.1 to 5 then X = 0.2	Ammonia (NH4-N)	0.30
If BAC =5.1 to 10 then X = 0.3	Nitrate (NO3-N)	0.00
If BAC > 10 then X = 0.4	Available Phosphorus (P2O5*0.64)	2.9
Note: If C/N ratio > 15 additional N should be applied.	Available Polassium (K2O)	6.3



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Compost #1	Project Number:	140125
Source:	ORI	Lab Number:	14-0553B
Date Sampled:	6/30/2014	Sampled By:	Client
Date Tested:	7/1/2014	Tested By:	Michael Trim

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0553B	Compost #1	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	100
6.3 mm	1/4"	7.2	92.8	
4.75 mm	#4	6.6	86.2	
2.36 mm	#8	8.7	77.5	
1.18 mm	#16	13.2	64.3	85-100
0.600 mm	#30	15.4	48.9	
0.425 mm	#40	7.8	41.1	
0.300 mm	#50	7.1	34.0	
0.150 mm	#100	8.8	25.2	
0.075 mm	#200	4.8	20.4	
Pan		20.4		

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

Emily J. Rodriguez

PDF

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY	
Material:	Compost #1	Project Number:	140125	
Source:	ORI	Lab Number:	14-0553B	
Location:	Stockpile	Item Number:	Compost	
Date Sampled:	6/30/2014	Sampled By:	Client	
Date Tested:	7/1/2014	Tested By:	John Brinsfield	

Report of Organic Content of Soils by Loss on Ignition				
Test Method	: AASHTO T267			

Inorganic Content: _	46.1	_%	(Sand, silt, clay, etc.)
Organic Content:	53.9	%	

Specification: 25-100

Comments:

Test results comply with specifications.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project: RSR E7976, Middletown, NY		
Item:	Compost #2	Project Number:	140125	
Source:	ORI	Lab Number:	14-0553C	
Date Sampled:	6/30/2014	Sampled By:	Client	
Date Tested:	Tested: 7/1/2014 Tested By: Michael Trim		Michael Trim	

 GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification	
14-0553C	Compost #2	Stockpile		

Sieve Size		%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	100
6.3 mm	1/4"	15.2	84.8	
4.75 mm	#4	4.0	80.8	
2.36 mm	#8	12.7	68.1	
1.18 mm	#16	12.4	55.7	85-100
0.600 mm	#30	14.4	41.3	
0.425 mm	#40	6.3	35.0	
0.300 mm	#50	5.7	29.3	
0.150 mm	#100	7.4	21.9	
0.075 mm	#200	3.6	18.3	
Pan		18.3		

J. Rodriguez

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Compost #2	Project Number:	140125
Source:	ORI	Lab Number:	14-0553C
Location:	Stockpile	Item Number:	Compost
Date Sampled:	6/30/2014	Sampled By:	Client
Date Tested:	7/1/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition		
Test Method:	AASHTO T267	

Inorganic Content:	51.3	<u>%</u>	(Sand, silt, clay, etc.)
Organic Content:	48.7	%	

Specification: 25-100

Comments:

Test results comply with specifications.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Compost #3	Project Number:	140125
Source:	ORI	Lab Number:	14-0589B
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	Liam Foody

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0589B	Compost #3	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	_ 3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	100
4.75 mm	#4 c	0.5	99.5	
2.00 mm	#10	0.3	99.2	
1.18 mm	#16	1.5	97.7	85-100
0.600 mm	#30	17.3	80.4	
0.425 mm	#40	15.7	64.7	
0.250 mm	#60	19.7	45.0	
0.150 mm	#100	17.6	27.4	
0.075 mm	#200	8.7	18.7	
Pan		18.7		

Comments:

Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

PDF



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Compost #3	Project Number:	140125
Source:	ORI	Lab Number:	14-0589B
Location:	Stockpile	Item Number:	
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition				
Test Method:	AASHTO T267			

Inorganic Content:	41.3	%	(Sand, silt, clay, etc.
Organic Content:	58.7	%	

Specification: 25-100

Comments:

Test results comply with specifications.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Upland Topsoil	Project Number:	140125
Source:	ORI	Lab Number:	14-0553A
Date Sampled:	6/30/2014	Sampled By:	Client
Date Tested:	7/1/2014	Tested By:	Michael Trim

<u>-</u>	GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
	Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0553A	Upland Topsoil	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	100
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	85-100
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	
6.3 mm	1/4"	5.1	94.9	65-100
4.75 mm	#4	3.8	91.1	
2.00 mm	#10	4.2	86.9	
0.850 mm	#20	5.7	81.2	
0.600 mm	#30	3.4	77.8	
0.425 mm	#40	4.7	73.1	
0.150 mm	#100	19.7	53.4	
0.075 mm	#200	10.7	42.7	20-40
Pan		42.7		

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Upland Topsoil	Project Number:	140125
Source:	ORI	Lab Number:	14-0553A
Location:	Stockpile	Item Number:	NYSDOT 713-01
Date Sampled:	6/30/2014	Sampled By:	Client
Date Tested:	7/1/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition			
Test Method: AASHTO T267			

Inorganic Content:	91.6	%	(Sand, silt, clay, etc.)
Organic Content:	8.4	%	

Specification: 10% Minimum

Comments: Test result does not comply with specification

Cruly J. Kodriguez

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Upland Topsoil #2	Project Number:	140125
Source:	ORI	Lab Number:	14-0589A
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	Liam Foody

GRADATION	(SIEVE ANALYSIS) OF SOIL OR A	AGGREGATE
Test Method	(s): ASTM D422, C136, C117; AASHTO T	88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0589A	Upland Topsoil #2	Stockpile	NYSDOT 713-01

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	100
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	85-100
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	
6.3 mm	1/4"	3.3	96.7	65-100
4.75 mm	#4	2.9	93.8	
2.00 mm	#10	10.3	83.5	
0.850 mm	#20	15.7	67.8	
0.600 mm	#30	7.2	60.6	
0.425 mm	#40	7.4	53.2	
0.150 mm	#100	20.3	32.9	,
0.075 mm	#200	9.4	23.5	20-40
Pan		23.5		

Comments:

Test results comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Upland Topsoil #2	Project Number:	140125
Source:	ORI	Lab Number:	14-0589A
Location:	Stockpile	Item Number:	NYSDOT 713-01
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition			
Test Method: AASHTO T267			

Inorganic Content:	80.2	%	(Sand, silt, clay, etc.)
Organic Content:	19.8	%	

Specification: 10% Minimum

Comments:

Test results comply with specifications.

Report Reviewed By:



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Upland Topsoil	Project Number:	140125
Source:	On Site Topsoil	Lab Number:	14-0758B
Location:	Stockpile	Item Number:	No Specification Available
Date Sampled:	8/19/2014	Sampled By:	Client
Date Tested:	8/20/2014	Tested By:	Donald Leisure

	Report of p	H of Soil
	Test Method: ASTM	
pH Test Result:_	7.0	(in Distilled Water)
_	N/A	(In Calcium Chloride Solution)
Specification		
Comments:		

No specifications available at time of testing.

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Item:	Upland Topsoil	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-7
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/8/2014	Tested By:	Liam Foody

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE	
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11	

Lab Number	Sample Type	Sampling Location	Specification
14-0706-7	Upland Topsoil	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	2.8	97.2	
6.3 mm	1/4"	13.3	83.9	
4.75 mm	#4	2.4	81.5	
2.00 mm	#10	9.9	71.6_	
0.850 mm	#20	10.2	61.4	
0.600 mm	#30	4.0	57.4	
0.425 mm	#40	4.6	52.8	
0.150 mm	#100	15.9	36.9	
0.075 mm	#200	6.5	30.4	
Pan		30.4		

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Material:	Topsoil (3:1)	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-2
Location:	Stockpile	Item Number:	No Specificaitons Available
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/5/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition	
Test Method: AASHTO T267	

Inorganic Content: Organic Content:	90	% %	(Sand, silt, clay, etc.)
Specification:			

Report Reviewed By:

Comments:



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Material:	Topsoil 3:1	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-7
Location:	Stockpile	Item Number:	No Specificaitons Available
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/7/2014	Tested By:	John Brinsfield

	Report of p	H of Soil	
Test Method: ASTM D4972 Method A			
pH Test Result:	7.2	(in Distilled Water)	
	N/A	(In Calcium Chloride Solution)	
Specification			

No specifications available at time of testing.

Ernily J. Rodriguez

Report Reviewed By:

Comments:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Granular Material	Project Number:	140125
Source:	ORI	Lab Number:	14-0553D
Date Sampled:	6/30/2014	Sampled By:	Client
Date Tested:	7/1/2014	Tested By:	Michael Trim

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE	
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11	

Lab Number	Sample Type	Sampling Location	Specification
14-0553D	Granular Material	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.1	99.9	
4.75 mm	#4 c	5.8	94.1	
2.00 mm	#10	14.7	79.4	
1.18 mm	#16	6.9	72.5	100
0.600 mm	#30	13.3	59.2	
0.425 mm	#40	9.5	49.7	85-100
0.250 mm	#60	16.5	33.2	40-100
0.150 mm	#100	13.9	19.3	
0.075 mm	#200	12.5	6.8	5-10
Pan		6.8		

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Granular Material #2	Project Number:	140125
Source:	ORI	Lab Number:	14-0589C
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	Liam Foody

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE	
Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11	

Lab Number	Sample Type	Sampling Location	Specification
14-0589C	Granular Material #2	Stockpile	

Sieve	Size	%	%	Spec. %
mm	Inches	Retained	Passing	Pass
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"	0.0	100.0	
4.75 mm	#4 c	0.0	100.0	
2.00 mm	#10	0.1	99.9	
1.18 mm	#16	3.0	96.9	100
0.600 mm	#30	14.8	82.1	
0.425 mm	#40	11.6	70.5	40-100
0.250 mm	#60	18.8	51.7	
0.150 mm	#100	17.3	34.4	
0.075 mm	#200	13.5	20.9	5-10
Pan		20.9		

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

Ernily J. Rodriguez This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Granular Material #2	Project Number:	140125
Source:	ORI	Lab Number:	14-0589C
Location:	Stockpile	Item Number:	NYSDOT 713-01
Date Sampled:	7/9/2014	Sampled By:	Client
Date Tested:	7/11/2014	Tested By:	John Brinsfield

Report of Organic Content of	Soils by Loss on Ignition
Test Method: AA	ASHTO T267

99.1	%	(Sand, silt, clay, etc.)
0.9	%	

Comments:

No specifications available at time of testing.

Report Reviewed By:

Nodruguer



3348 Route 208, Campbell Hall, NY 10916

12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Wetland Topsoil	Project Number:	140125
Source:	ORI	Lab Number:	14-0333B
Location:	Stockpile	Item Number:	No Specification Available
Date Sampled:	5/8/2014	Sampled By:	Client
Date Tested:	5/16/2014	Tested By:	John Brinsfield

Report of Organic Content of Soils by Loss on Ignition						
	Test Method: AASHTO T267					
Inorganic Content:	83.3	%	(Sand, silt, clay, etc.)			

Specification:

Organic Content: 16.7

Comments:

No specifications available at time of testing.

Report Reviewed By:



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Material:	Wetland Topsoil	Project Number:	140125
Source:	On Site Topsoil	Lab Number:	14-0758A
Location:	Stockpile	Item Number:	No Specification Available
Date Sampled:	8/19/2014	Sampled By:	Client
Date Tested:	8/20/2014	Tested By:	Donald Leisure

Report of pH of Soil				
	Test Method: ASTM	D4972 Method A		
pH Test Result:	6.6	(in Distilled Water)		
_	N/A	(In Calcium Chloride Solution)		
Specification				
Comments:				

No specifications available at time of testing.

Emily J. Rodriguez

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Item:	Wetland Topsoil	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-6
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/8/2014	Tested By:	Liam Foody

GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE
 Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
14-0706-6	Wetland Topsoil	Stockpile	

Sieve	Sieve Size		%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	0.0	100.0	
19.0 mm	3/4"	0.0	100.0	
12.5 mm	1/2"_	16.8	83.2	
6.3 mm	1/4"	13.0	70.2	
4.75 mm	#4	1.4	68.8	
2.00 mm	#10	7.4	61.4	
0.850 mm	#20	8.5	52.9	
0.600 mm	#30	2.8	50.1	
0.425 mm	#40	3.4	46.7	
0.150 mm	#100	10.2	36.5	
0.075 mm	#200	6.0	30.5	
Pan		30.5		

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



Comments:

3348 Route 208, Campbell Hall, NY 10916 Phone: 845-496-1600 Fax: 845-496-1398

12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Material:	Topsoil 3:2	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-6
Location:	Stockpile	Item Number:	No Specificaitons Available
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/7/2014	Tested By:	John Brinsfield

Report of Organic Conten	nt of Soils by Loss on Ignition	\Box
	AASHTO T267	

Inorganic Content: Organic Content:	86 15	%	(Sand, silt, clay, etc.)
Specification:			

Report Reviewed By:

Crnily J. Rodriguez



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	5 L Enterprises	Project:	RSR Middletown, NY
Material:	Topsoil 3:2	Project Number:	140475
Source:	5L Enterprises	Lab Number:	14-0706-6
Location:	Stockpile	Item Number:	No Specificaitons Available
Date Sampled:	8/4/2014	Sampled By:	Client
Date Tested:	8/7/2014	Tested By:	John Brinsfield

Report of pH of Soil				
	Test Method: ASTM	D4972 Method A		
pH Test Result:	7.4	(in Distilled Water)		
	N/A	(In Calcium Chloride Solution)		
Specification				
Comments:	RE .			

Report Reviewed By:



25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Commoon Fill	Project Number:	140125
Source:	E. Tetz	Lab Number:	14-0689
Date Sampled:	7/30/2014	Sampled By:	Client
Date Tested:	7/31/2014	Tested By:	Michael Trim

GRADATION (SIEVE A)	NALYSIS) OF SOIL	OR AGGREGATE	
 Test Method(s): ASTM D	0422, C136, C117; AASH	TO T88, T27, T11	

Lab Number	Sample Type	Sampling Location	Specification
14-0689	Commoon Fill	Stockpile	

Sieve Size		0 ∕₀	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	1.0	99.0	
19.0 mm	3/4"	0.0	99.0	
12.5 mm	1/2"	0.5	98.5	
6.3 mm	1/4"	1.9	96.6	
4.75 mm	#4	0.6	96.0	90-100
2.00 mm	#10	1.5	94.5	
0.850 mm	#20	1.4	93.1	
0.600 mm	#30	0.6	92.5	
0.425 mm	#40	0.9	91.6	55-80
0.150 mm	#100	3.3	88.3	
0.075 mm	#200	8.1	80.2	60-80
Pan		80.2		

Comments:

Test results do not comply with specification

Minus #200 by wash-sieve method.

Report Reviewed By:

Emily J. Rodriguez This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



3348 Route 208, Campbell Hall, NY 10916

Phone: 845-496-1600 Fax: 845-496-1398

25 Hathorn Road, Enfield, NH 03748

42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project:	RSR E7976, Middletown, NY
Item:	Common Fill	Project Number:	140125
Source:	5L Enterprise	Lab Number:	15-1171
Date Sampled:	10/15/2015	Sampled By:	Client
Date Tested:	10/21/15	Tested By:	Aaron Taddeo

ABLAT MOTOL OF C	OIL OD ACCDECATE	
ANALYSIS) OF S	UILUK AUURKUATE	
	012 011110 01120 01112	
D.400 C105 C115 1	A CARTE O TROO TROO TO A	
-D422, C136, C117: A	ASHTU 188. 127. TTI	
		ANALYSIS) OF SOIL OR AGGREGATE D422, C136, C117; AASHTO T88, T27, T11

Lab Number	Sample Type	Sampling Location	Specification
15-1171	Common Fill	Stockpile	

Sieve Size		%	%	Spec. %
mm	Inches	Retained	Passing	Pass
100.0 mm	4"	0.0	100.0	
75.0 mm	3"	0.0	100.0	
63.0 mm	2 1/2"	0.0	100.0	
50.0 mm	2"	0.0	100.0	
37.5 mm	1 1/2"	0.0	100.0	
25.0 mm	1"	3.2	96.8	
19.0 mm	3/4"	1.8	95.0	
12.5 mm	1/2"	4.0	91.0	
6.3 mm	1/4"	7.1	83.9	
4.75 mm	#4	2.8	81.1	
2.00 mm	#10	7.0	74.1	
0.850 mm	#20	6.9	67.2	
0.600 mm	#30	3.2	64.0	
0.425 mm	#40	4.1	59.9	
0.150 mm	#100	14.3	45.6	
0.075 mm	#200	7.3	38.3	
Pan		38.3		

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.



42 Day Farm Road, West Stockbridge, MA 01266

1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project	RSR E7976, Middletown, NY
Material:	Common Fill	Project Number:	140125
Source:	5L Enterprise	Lab Number:	15-1171
Location:	Stockpile	Item Number:	No specifications available.
Date Sampled:	10/15/2015	Sampled By:	Client
Date Tested:	10/22/2015	Tested By:	Emily Rodriguez

	Report for Unified	I Soil Classification	
	Test Method:	ASTM D2487	

USCS Group Symbol:

SC

USCS Group Name:

Clayey Sand with Gravel

Specifications:

Comments:

Report Reviewed By:

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.

Emily J. Rodriguez



12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787

Client:	Entact Inc.	Project: RSR E7976, Middletown, NY
Material:	Common Fill	Project #: 140125
Source:	5L Enterprise	Lab No.: 15-1171
Location:	Stockpile	Item Number: No specifications available.
Date Sampled:	10/15/2015	Sampled By: Client
Date Tested:	10/20/15	Tested By: Jonathan Valle

REPORT OF ATTERBERG LIMITS TEST RESULTS
TEST METHOD: ASTM D4318; LL Method B

Lab Number:	15-1171	Specification
Liquid Limit:	23	
Plastic Limit:	16	
Plasticity Index:	7	

Notes:

Values shown are percent moisture.

Customary procedure is to round results to the nearest whole number.

Comments:

Report Reviewed By:

This report shall not be reproduced, except in full, without the written permission of Advance Testing Company, Inc.