

APPENDICES

**APPENDIX A PHOTOGRAPHS OF THE LITTLE FALLS PONDS PROPERTY FROM NON-
EMERGENCY INTERIM REMEDIAL MEASURE WORK PLAN (JUNE 2009)**





Plate 1: Waste recyclables pile adjacent to Former Town Pumping Well #1



Plate 2: Waste pile of recyclables dumped by others around trees – Little Falls Pond Property



Plate 3: Example of waste pile material – Little Falls Pond property.



Plate 4 Condition of Former Town Pumping Well Building #1.



Plate 5: Culvert discharging into Little Falls Pond #2 – shows waste refuse.



Plate 6: Example of debris in Little Falls Pond #2.