

**NEWYORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION**

Division of Environmental Remediation  
Operation Maintenance and Monitoring Review Report  
Period covered by -- 2003

<b>Site / Spill Number :</b> 344001		<b>Site Name:</b> Clarkstown Town		<b>Class:</b> 02	
<b>Program Lead:</b> Hazardous Waste Program			<b>OM&amp;M Funding Source:</b> Responsible Party		
<b>Start Date :</b> 01/01/2001		<b>ACT</b>			
<b>Annual IC/EC Certification :</b>					
<b>DEC Inspection Date:</b> 07/10/2002		--- Last Date of DEC Inspection			
<b>Report Used for Evaluation:</b> 1st quarter 2002					
<b>ROD Compliance ?</b> YES		<b>Consent order/Decree Compliance ?</b> YES			
<b>LongTerm Monitoring(effectiveness of remedy):</b> Yes		<b>Frequency:</b> Quarterly		<b>Act. Date:</b> / /	
<b>Treatment System(Monitoring performance of remedy):</b> No		<b>Frequency:</b>		<b>Pln. Date:</b> / / <b>#wells :</b> 0	
<b>PROBLEM STATUS :</b> ----- None					
<b>Evaluation :</b> The Remedy is performing properly and is effective.					
<b>Comments/ Changes/ Attachments:</b> 10/02: Resurface access road between compost facility and entrance without disturbing settlement plates will be completed soon. Settlement plates to be protected by manhole covers. Model airplane aerodrome runway extended.					
<b>ROD/Consent Order Modifications?</b> NO					
<b>Reclassification recommended :</b> None					
<b>Contaminant of concern</b> OU		<b>Contaminant of concern</b>		<b>Media/Receptor</b>	
01		TETRACHLOROETHYLENE			
<b>Remedies</b> OU		<b>Remedies</b>		<b>Size of Treatment</b>	<b>Date in Place</b> <b>Remedy Effective</b>
01		6 NYCRR Part 360 Cap			/ / Yes
01		Leachate Recovery			/ / Yes

<b>Next Review</b> 10/16/2003			<b>Priority:</b> 0		
<b>Object Manager</b>			<b>Reviewer:</b> Pergadia		
<b>Signature</b>		<b>Date</b>	<b>Signature</b>		<b>Date</b>
<b>Name</b>	<b>Region or Bureau</b>	<b>Telephone</b>	<b>Name</b>	<b>Region or Bureau</b>	<b>Telephone</b>