

Historic

H/ltH Dept
Sampling

POUND RIDGE SAMPLING SUMMARY
SCOTTS CORNERS
Sampling Results Available as of 7-08-97
Health Department Sampling Only

FEB 24 2000

BUREAU OF
HAZARDOUS SITE CONTROL
DIVISION OF HAZARDOUS
WASTE REMEDIATION

7 Westchester Avenue 3-28-95 No Contamination Found
Tom Sangermans

15 Westchester Avenue 11-28-95 No Contamination Found
Anita DeGiacomo

16 Westchester Avenue 3-7-95 No Contamination Found
Nina Scuderl

22 Westchester Avenue 2-14-95 No Contamination Found
Stewart Simon 10-17-95 No Contamination Found

34 Westchester Avenue 2-14-95 No Contamination Found
Curry And Hovis

35 Westchester Avenue 2-14-95 No Contamination Found
Pound Ridge Vet

39 Westchester Avenue 10-17-95 No Contamination Found
Bender

54 Westchester Avenue 2-14-95 19ppb MTBE

Hunter Travel Service
Body Sculpture by Susan 4-4-95 20ppb MTBE

56 Westchester Avenue 2-14-95 21ppb MTBE
J. Brown Interiors

57 Westchester Avenue 1-26-95 4.9ppb MTBE

U. S. Post Office
Trinity Corners 2-14-95 2.5ppb MTBE
Shopping Center

60 Westchester Avenue 8-18-94 6.6ppb MTBE
Country Treasures

65 Westchester Avenue Antiques and Tools Joan Silbersher	8-18-94	34ppb .59ppb	MTBE 1,1-Dichloroethane
	2-8-95	.57ppb 300ppb	1,1-Dichloroethane MTBE Other Purgeable Compounds
	2-14-95	.84ppb 330ppb	1,1-Dichloroethane MTBE Other Purgeable Compounds

66 Westchester Avenue Shell Station	8-18-94	13ppb 1.2ppb 1.3ppb	MTBE 1,1-Dichloroethane Toluene
	2-8-95	120ppb 1.8ppb .63ppb	MTBE 1,1-Dichloroethane 1,1,1-Trichloroethene Other Purgeable Compounds

67 Westchester Avenue The Country Shopper	8-18-94	15ppb .54ppb	MTBE Chloroform
	2-8-95	560ppb	MTBE
	2-14-95	450ppb	MTBE Other Purgeable Compounds

68 Westchester Avenue Chubby's Hardware	8-18-94	3300ppb	MTBE
		52ppb	Benzene
		2ppb	Chlorobenzene
		.68	1,4-Dichlorobenzene
		.51	Naphthalene
		3.8	1,1-Dichloroethane
		1.3	Cis-1,2-Dichloroethene
		1.5	Trichloroethene
		.51	O-Xylene
	2-1-95	3500ppb	MTBE
		2.6	1,1-Dichloroethane
		1.2	Tetrachloroethene
			Other Purgeable compounds

Prefilter	2-8-95	3500ppb	MTBE
		1.4ppb	Benzene
		.92ppb	Chlorobenzene
		.60	1,3-Dichlorobenzene
		.97	Tetrachloroethene
		3.0	1,1-Dichloroethane
		.54	Cis-1,2-Dichloroethene
		.68	Trichloroethene
			Other Purgeable Compounds
Midfilter	2-8-95	No Contamination Found	
69 Westchester Avenue The Orange Cherry	8-18-94	25ppb	MTBE
70 Westchester Avenue Di Nardo's Restaurant	2-18-94	1.5ppb	MTBE
Dora Landry Antiques	8-18-94	41ppb	MTBE
	2-8-95	29ppb	MTBE
71 Westchester Avenue The Wine Connection	2-3-94	No Contamination Found	
	8-18-94	10ppb	MTBE
	2-8-95	9.4ppb	MTBE
72 Westchester Avenue Pound Ridge Cleaners Moreno's Residence	7-1-93	1.3ppb	Tetrachloroethene
		4.6ppb	MTBE
Postfilter	2-3-94	6.8ppb	Tetrachloroethene
		4.9ppb	MTBE
	2-22-94	5.6ppb	Tetrachloroethene
		4.3ppb	MTBE
Prefilter	5-9-94	2.0ppb	Tetrachloroethene
		250ppb	MTBE
Midfilter		.55ppb	Tetrachloroethene
		48ppb	Dichlorodifluoromethane
Postfilter		No Contamination Found	

Prefilter	8-18-94	4.6ppb 530ppb 1.4ppb .5ppb	Tetrachloroethene MTBE Toluene Benzene
Midfilter		460ppb 7.7ppb	MTBE Dichlorodifloromethane
Postfilter		2.3ppb	Dichlorodifloromethane
Prefilter	2-1-95	3.0ppb 400ppb	Tetrachloroethene MTBE Other Purgeable Compounds
Postfilter	2-8-95	600ppb 44ppb	MTBE Dichlorodifloromethane
Prefilter	2-14-95	7.4ppb 320ppb	Tetrachloroethene MTBE Other Purgeable Compounds
Midfilter		600ppb	MTBE Other Purgeable Compounds
Postfilter		830ppb	MTBE Other Purgeable Compounds
73 Westchester Avenue	8-18-95	4.7ppb	MTBE
Kulhanek and Plan	2-8-95	6.3ppb	MTBE
NatWest Bank			
74 Westchester Avenue	2-8-95	120ppb	MTBE
Travel Agency			
77 Westchester Avenue	2-18-94	.6ppb	Toluene
Texaco Station		15.2ppb	MTBE
	8-18-94	1.8ppb	MTBE
	2-8-95	7.9ppb	MTBE
78 Westchester Avenue	2-3-94	10ppb	MTBE
The Deli	8-22-94	5.6ppb	MTBE
	2-8-95	8.4ppb	MTBE (Before/After)
		8.0ppb	MTBE (After)

79 Westchester Avenue	8-22-94	No Contamination Found
Houlihan/Lawerence	2-8-95	No Contamination Found
	4-20-95	No Contamination Found
	3-20-96	<.5ppb Chloroform
	2-28-97	7.2ppb MTBE

80 Westchester Avenue	2-3-94	No Contamination Found
Scotts Corners	8-22-95	2.0ppb 1,4-Dichlorobenzene
Fire Station		1.1ppb MTBE
	2-8-95	1.6ppb MTBE
	4-20-95	No Contamination Found
	3-20-96	No Contamination Found
	2-28-97	1.8ppb MTBE

Pond located behind the Fire Station
3-16-95

81 Westchester Avenue	8-22-94	No Contamination Found
Tony Woolner Designer	3-20-96	<.5ppb Chloroform
	5-1-97	11ppb MTBE

83 Westchester Avenue	8-22-94	No Contamination Found
Preferred Realty	2-14-95	No Contamination Found
The Corner Store	4-20-95	No Contamination Found
Albano Electric	3-20-96	No Contamination Found
	2-28-97	2.5 ppb MTBE

85 Westchester Avenue	8-22-94	No Contamination Found
Moon Struck Pizza	3-20-96	No Contamination Found

87 Westchester Avenue	8-22-94	No Contamination Found
Scotts Corner Service	2-8-95	No Contamination Found
Station	2-21-95	No Contamination Found

89 Westchester Avenue	2-21-95	2.5ppb Dichlorodifloromethane
Ambulance Corp.		Presoftener
	2-21-95	2.9ppb Dichlorodifloromethane
		Postsoftener

97 Westchester Avenue	3-16-95	No Contamination Found
Gelfand		

County Market	4-20-95	No Contamination Found	
469 Westchester Avenue			
8 Trinity Lane	1-26-95	1.3ppb	Chloroform
Len	2-8-95	2.4ppb	Chloroform
		1.2ppb	MTBE
10 Trinity Lane	1-26-95	4.2ppb	MTBE
Santulli	2-8-95	3.8ppb	MTBE
14 Trinity Lane	1-26-95	10ppb	MTBE
Scofield	2-8-95	7.6ppb	MTBE (Before Softener)
	2-8-95	8.2ppb	MTBE (After Softener)
18 Trinity Lane	1-26-95	2.1ppb	1,1-Dichloroethane
Laird		1.2ppb	1,1,1-Trichloroethene
		11ppb	MTBE
22 Trinity Lane	1-26-95	4.8ppb	1,1-Dichloroethane
Janiga		1.1ppb	1,1,1-Trichloroethene
		440ppb	MTBE
		.90ppb	Cis-1,2-Dichloroethene
	2-1-95	4.1ppb	1,1-Dichloroethane
		1.2ppb	1,1,1-Trichloroethene
		410ppb	MTBE
		.97ppb	Cis-1,2-Dichloroethene
			Other Purgeable Compounds
Before Filter	2-8-95	4.1ppb	1,1-Dichloroethane
		1.1ppb	1,1,1-Trichloroethene
		460ppb	MTBE
		.89ppb	Cis-1,2-Dichloroethene
			Other Purgeable Compounds
Between Filters	2-8-95		No Contamination Found
Before Filter	7-26-95	380ppb	MTBE
Between Filters	7-26-95	330ppb	MTBE
		35ppb	Chloroform
		2.7ppb	Bromodichloromethane
Post Filters	7-26-95		No Contamination Found

25 Trinity Lane Wade	1-26-95	4.6ppb 260ppb	1,1-Dichloroethane MTBE
	2-1-95	6.2ppb 1.3ppb 310ppb	1,1-Dichloroethane 1,1,1-Trichloroethene MTBE Other Purgeable Compounds
Prefilter	8-2-95	1.6ppb 42ppb	1,1-Dichloroethane MTBE
Midfilter	8-2-95	72ppb	MTBE
Postfilter	8-2-95	No Contamination Detected	
26 Trinity Lane Levine	1-26-95	8.4ppb 2.0ppb .57ppb 1.7ppb .87ppb 1.0ppb 1.0ppb 7200ppb 4.9ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene Tetrachloroethene Benzene Sec-Butyl Benzene 1,2-Dichlorobenzene 1,4-Dichlorobenzene MTBE Chlorobenzene Other Purgeable Compounds
(Kitchen Tap)	2-1-95	14ppb 3.6ppb .91ppb 2.0ppb 1.4ppb 1.6ppb 1.6ppb 7200ppb 7.4ppb 1.2ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene Tetrachloroethene Benzene Sec-Butyl Benzene 1,2-Dichlorobenzene 1,4-Dichlorobenzene MTBE Chlorobenzene 1,1,1-Trichloroethene Other Purgeable Compounds
(First tap after pump)	2-1-95	8.1ppb 2.1ppb .56ppb 1.4ppb .91ppb 1.0ppb 1.1ppb 6800ppb 5.0ppb .71ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene Tetrachloroethene Benzene Sec-Butyl Benzene 1,2-Dichlorobenzene 1,4-Dichlorobenzene MTBE Chlorobenzene 1,1,1-Trichloroethene Other Purgeable Compounds

(Shower Hot Water) (NYSDOH)	2-2-95	5.9ppb 1.9ppb .7ppb .7ppb 3.4ppb .5ppb 3500ppb 44ppb 23ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene 1,2-Dichlorobenzene 1,4-Dichlorobenzene Chlorobenzene 1,1,1-Trichloroethene MTBE Acetone 4-Methyl-2-Pentanone
(Shower Basin Hot Water) (NYSDOH)	2-2-95	1.5ppb 0.6ppb 1.0ppb 2000ppb 67ppb 10ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene Chlorobenzene MTBE Acetone 4-Methyl-2-Pentanone
(Kitchen Hot Water) (NYSDOH)	2-2-95	7.3ppb 2.4ppb .8ppb .8ppb 4.3ppb .6ppb 6800ppb 92ppb 35ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene 1,2-Dichlorobenzene 1,4-Dichlorobenzene Chlorobenzene 1,1,1-Trichloroethene MTBE Acetone 4-Methyl-2-Pentanone
(Boiled Water) (NYSDOH)	2-2-95	2.4ppb 0.9ppb 1.5ppb 2700ppb 40ppb 13ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene Chlorobenzene MTBE Acetone 4-Methyl-2-Pentanone
(Kitchen Tap)	2-3-95	160ppb	MTBE
(PreSoftener)	2-3-95		No Contamination Found
(Kitchen Tap)	2-14-95	96ppb	MTBE
(Prefilter)	4-4-95	Sampled	Filtering System
	4-4-95	6.6ppb 1.8ppb 1.0ppb .92ppb 4.1ppb 5700ppb .70ppb .95ppb	1,1-Dichloroethane Cis-1,2-Dichloroethene 1,2-Dichlorobenzene 1,4-Dichlorobenzene Chlorobenzene MTBE Trichloroethene Benzene

(Between Filters 1&2)	4-4-95	12ppb	MTBE
(Between Filters 2&3)	4-4-95	No Contamination Found	
(After Filters Kitchen)	4-4-95	No Contamination Found	
(Prefilter)	6-16-95	Sampled Filtering System	
	6-16-95	6.6ppb	1,1-Dichloroethane
		1.5ppb	Cis-1,2-Dichloroethene
		.90ppb	1,2-Dichlorobenzene
		1.1ppb	1,4-Dichlorobenzene
		6.7ppb	Chlorobenzene
		6800ppb	MTBE
		.69ppb	Benzene
		1.0ppb	Sec-butyl Benzene
(Between Filters 1&2)	6-16-95	9100ppb	MTBE
(Between Filters 2&3)	6-16-95	56ppb	MTBE
(After Filters Kitchen)	6-16-95	No Contamination Found	
(After Filters Outside)	5-1-97	No Contamination Found	
6 Lower Trinity Pass Brown, Charlie	1-26-95	26ppb	MTBE
10 Lower Trinity Pass Seymour	1-26-95	15ppb	MTBE
		.76ppb	1,1,1-Trichloroethene
Prefilter	2-14-95	7.4ppb	MTBE
		.62ppb	1,1-Dichloroethene
		.73ppb	1,1,1-Trichloroethene
Midfilter	2-14-95	No Contamination Found	
Postfilter	2-14-95	No Contamination Found	
15 Lower Trinity Pass Thom	12-20-95	3.5ppb	MTBE 12-20 Sampled by Thom
		.43ppb	1,1,1-Trichloroethene
		.47ppb	1,1-Dichloroethene
	1-26-95	4.3ppb	MTBE
	2-8-95	3.2ppb	MTBE
Postfilter only	6-16-95	No Contamination Detected	

17 Lower Trinity Pass Dunne	1-26-95	2.2ppb	MTBE
	2-8-95	No Contamination Found	
22 Lower Trinity Pass Huges, Kit	2-24-95	No Contamination Found	
	4-20-95	No Contamination Found	
23 Lower Trinity Pass Tomaselli	1-26-95	No Contamination Found	
24 Lower Trinity Pass Post, Katherine	2-24-95	No Contamination Found	
26 Lower Trinity Pass Joaquim, Felice	4-20-95	3.8 ppb	1,2-Dichlorobenzene
		.63 ppb	1,3-Dichlorobenzene
		3.0 ppb	1,4-Dichlorobenzene
	4-28-95	4.5 ppb	1,2-Dichlorobenzene
		.70 ppb	1,3-Dichlorobenzene
		3.6 ppb	1,4-Dichlorobenzene
		.94 ppb	Chlorobenzene
		.55 ppb	1,2,4-Trichlorobenzene
	3-20-96	4.0 ppb	1,2-Dichlorobenzene
		.80 ppb	1,3-Dichlorobenzene
		3.0 ppb	1,4-Dichlorobenzene
		1.4 ppb	Chlorobenzene
		.5 ppb	1,2,4-Trichlorobenzene
	2-28-97	2.8 ppb	1,2-Dichlorobenzene
		2.7 ppb	1,4-Dichlorobenzene
		1.6 ppb	Chlorobenzene
27 Lower Trinity Pass Russell, Roberta	2-21-95	No Contamination Found	
	4-20-95	No Contamination Found	
	3-20-96	No Contamination Found	
	2-28-97	No Contamination Found	
31 Lower Trinity Pass Albanese	11-28-95	No Contamination Found	
33 Lower Trinity Pass Traynor	11-28-95	No Contamination Found	
35 Lower Trinity Pass Braun, Sherry	4-20-95	1.0 ppb	MTBE
	4-28-95	1.3 ppb	MTBE
	7-26-95	1.4 ppb	MTBE

37 Lower Trinity Pass Vinci, Marsha	4-20-95	No Contamination Found	
44 Lower Trinity Pass Schiffman, Jill	6-5-95	No Contamination Found	
46 Lower Trinity Pass Nieburg, Herb	3-7-95	No Contamination Found	
47 Lower Trinity Pass Boyajain, Eli	6-5-95 10-17-95 5-1-97	No Contamination Found No Contamination Found No Contamination Found	
18 Pine Drive Paula Cappa	2-14-95 1-31-96	No Contamination Found No Contamination Found	
20 Pine Drive Freid	1-31-96	No Contamination Found	
22 Pine Drive Goldsmith	1-31-96	No Contamination Found	
32 Pine Drive Marty Kramer	4-20-95 4-28-95 6-5-95 2-13-96	34 ppb 6.7 ppb .8 ppb .95 ppb	Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane Trichlorofluoromethane
38 Pine Drive Peter Auellino	3-28-95 2-13-96	No Contamination Found No Contamination Found	
44 Pine Drive Joe Peloso	2-14-95 2-13-96	No Contamination Found No Contamination Found	
34 Hemlock Hill Kingman, Linda	3-16-95	No Contamination Found	
1 Sellecks Walk Edythe Harris	2-14-95 10-17-95 3-20-96	No Contamination Found No Contamination Found No Contamination Found	

15 Sellecks Walk Egan	3-16-95	No Contamination Found	
4 Trinity Pass Sheldon Satin Inc	2-21-95	370ppb	MTBE
		.92ppb	1,1-Dichloroethene
		Other Purgeable Compounds	
Resample	2-27-95	370ppb	MTBE
		.83ppb	1,1-Dichloroethene
		.62ppb	Chlorobenzene
7 Trinity Pass	2-21-95	No Contamination Found	
Ms. Brooks Hallocks	4-20-95	No Contamination Found	
	3-20-96	No Contamination Found	
	2-28-97	Trace 1,4-Dichlorobenzene	
10-12 Trinity Pass	2-21-95	1.1ppb	MTBE
A.C. & Son Excavations			
Clarkson	7-26-95	Trace	MTBE
		Trace	Trichlorofluoromethane
	10-17-95	No Contamination Found	
	3-20-96	No Contamination Found	
	2-28-97	no contamination Found	
15 Trinity Pass	2-27-95	1.5ppb	MTBE
Murphy, Rita	10-17-95	1.4ppb	Chloromethane
	2-28-97	No Contamination Found	
16 Trinity Pass	2-21-95	2.0ppb	MTBE
Hoffman, Jean			
17 Trinity Pass	3-16-95	No Contamination Found	
Bastis, Lori	2-20-95	No Contamination Found	
	10-17-95	1.2 ppb	Chloroform
	3-20-96	.5 ppb	Chloroform
20 Trinity Pass	3-7-95	No Contamination Found	
Johnston, E.	4-20-95	No Contamination Found	
	3-20-96	No Contamination Found	
	2-28-97	No Contamination Found	
21 Trinity Pass	3-16-95	No Contamination Found	
Blake			

23 Trinity Pass 3-16-95 No Contamination Found
Webber

25 Trinity Pass 2-27-95 No Contamination Found
Slivka, Mark

26 Trinity Pass 3-7-95 No Contamination Found
Healy

27 Trinity Pass 3-16-95 No Contamination Found
Powers, Roberts

29 Trinity Pass 3-16-95 1.3ppb MTBE
Goscilo

30 Trinity Pass 3-28-95 No Contamination Found
Fire Department House

31 Trinity Pass 3-7-95 3.8ppb MTBE
Richmond

3-16-95 1.6ppb MTBE

33 Trinity Pass 4-4-95 No Contamination Found
Berger, Max

35 Trinity Pass 3-28-95 No Contamination Found
Seton

36 Trinity Pass 3-28-95 No Contamination Found
Buzzeo, Louis

51 Trinity Pass 6-5-95 No Contamination Found
Burnbaum, Martha

3 Rolling Meadow Lane 3-28-95 No Contamination Found
Petch, John

5 Rolling Meadow Lane 11-28-95 No Contamination Found
King

6 Rolling Meadow Lane Lachowicz, Mary-Ellen	3-28-95 No Contamination Found 10-17-95 No Contamination Found
7 Rolling Meadow Lane Smith, Silas	3-28-95 No Contamination Found 10-17-95 No contamination Found
15 Rolling Meadow Lane April, Laurie	3-7-95 .6ppb Toluene (Possibly caused by recent varnishing) 3-16-95 No Contamination Found
16 Rolling Meadow Lane Aminoff, Melvin & Ruth	3-28-95 No Contamination Found
17 Rolling Meadow Lane Frankel	11-28-95 No Contamination Found
22 Rolling Meadow Lane Corrao	11-28-95 No Contamination Found
27 Rolling Meadow Lane Fopeanon, James	3-7-95 No Contamination Found
28 Rolling Meadow Lane Niewieroski, Stan	3-16-95 No Contamination Found
30 Rolling Meadow Lane Becker	10-17-95 No Contamination Found
32 Rolling Meadow Lane Diane (O'Conner) Miele	3-28-95 .55ppb Chloroform
39 Rolling Meadow Lane Karns	3-28-95 No Contamination Found
22 Woodland Road Fusco	3-28-95 No Contamination Found

86 Fancher Road Bria, John	3-28-95	No Contamination Found	
6 Kinicut Road Hecht	4-4-95	No Contamination Found	
33 Laurel Road Horowitz	6-16-95	18 ppb Chloroform .63 ppb Sec-Butylbenzene Otherpurgeable Compounds	
	7-7-95	2.8 PPB Chloroform	
Pound Ridge Motors Route 172 and Route 137	4-20-95	No Contamination Found	
Pound Ridge Nursery Route 172 and Route 137	4-20-95	5.9 ppb Tetrachloroethene 2.7 ppb Methyl T-Butyl Ether	
	8-16-95	8.9 ppb Tetrachloroethene 4.8 ppb Methyl T-Butyl Ether .60 ppb 1,1-Dichloroethane .77 ppb Cis-1,2-Dichloroethane	
	10-17-95	16 ppb Tetrachloroethene 5.2 ppb Methyl T-Butyl Ether 1.2 ppb Cis-1,2-Dichloroethane	
Post Filter	3-20-96	>.5 ppb Tetrachloroethene	
Marshall Oil Company Route 124	4-20-95	No Contamination Found	

DATE: 03/26/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 07799051
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

Recent
DEC Sampling

APPROVAL: QSS
QC: PK
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 2ND FILTER 0958H 03/17/99 G

ULI I.D.: 07799054*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL KEY	FILE#
EPA Method 503.1 with MTBE					
Benzene	BDL	0.5ug/l	03/20/99	VA4286	
Trichloroethene	BDL	0.5ug/l	03/20/99	VA4286	
Toluene	BDL	0.5ug/l	03/20/99	VA4286	
Tetrachloroethene	BDL	0.5ug/l	03/20/99	VA4286	
Ethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
m-Xylene and p-Xylene	BDL	0.5ug/l	03/20/99	VA4286	
Chlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
4-Isopropyltoluene	BDL	0.5ug/l	03/20/99	VA4286	
o-Xylene	BDL	0.5ug/l	03/20/99	VA4286	
Isopropylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
Styrene	BDL	0.5ug/l	03/20/99	VA4286	
n-Propylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
tert-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
2-Chlorotoluene	BDL	0.5ug/l	03/20/99	VA4286	
4-Chlorotoluene	BDL	0.5ug/l	03/20/99	VA4286	
Bromobenzene	BDL	0.5ug/l	03/20/99	VA4286	
sec-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,3,5-Trimethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,4-Trimethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,4-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,3-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
n-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,2-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
Hexachlorobutadiene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,4-Trichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
Naphthalene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,3-Trichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
MTBE	BDL	2ug/l	03/20/99	VA4286	

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 03/26/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 07799051
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *QSS*
QC: *PF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 1ST FILTER 1002H 03/17/99 G

ULI I.D.: 07799055*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL	KEY	FILE#
EPA Method 503.1 with MTBE						
Benzene	BDL	0.5ug/l	03/20/99		VA4286	
Trichloroethene	BDL	0.5ug/l	03/20/99		VA4286	
Toluene	BDL	0.5ug/l	03/20/99		VA4286	
Tetrachloroethene	BDL	0.5ug/l	03/20/99		VA4286	
Ethylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
m-Xylene and p-Xylene	BDL	0.5ug/l	03/20/99		VA4286	
Chlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
4-Isopropyltoluene	BDL	0.5ug/l	03/20/99		VA4286	
o-Xylene	BDL	0.5ug/l	03/20/99		VA4286	
Isopropylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
Styrene	BDL	0.5ug/l	03/20/99		VA4286	
n-Propylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
tert-Butylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
2-Chlorotoluene	BDL	0.5ug/l	03/20/99		VA4286	
4-Chlorotoluene	BDL	0.5ug/l	03/20/99		VA4286	
Bromobenzene	BDL	0.5ug/l	03/20/99		VA4286	
sec-Butylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
1,3,5-Trimethylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
1,2,4-Trimethylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
1,4-Dichlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
1,3-Dichlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
n-Butylbenzene	BDL	0.5ug/l	03/20/99		VA4286	
1,2-Dichlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
Hexachlorobutadiene	BDL	0.5ug/l	03/20/99		VA4286	
1,2,4-Trichlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
Naphthalene	BDL	0.5ug/l	03/20/99		VA4286	
1,2,3-Trichlorobenzene	BDL	0.5ug/l	03/20/99		VA4286	
MTBE	BDL	2ug/l	03/20/99		VA4286	

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 03/26/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 07799051
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: AS
QC: PF
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT BEFORE FILTERS 1006H 03/17/99 G

ULI I.D.: 07799056*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL KEY	FILE#
EPA Method 503.1 with MTBE					
Benzene	BDL	0.5ug/l	03/20/99	VA4286	
Trichloroethene	BDL	0.5ug/l	03/20/99	VA4286	
Toluene	BDL	0.5ug/l	03/20/99	VA4286	
Tetrachloroethene	0.7ug/l	0.5ug/l	03/20/99	VA4286	
Ethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
m-Xylene and p-Xylene	BDL	0.5ug/l	03/20/99	VA4286	
Chlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
4-Isopropyltoluene	BDL	0.5ug/l	03/20/99	VA4286	
o-Xylene	BDL	0.5ug/l	03/20/99	VA4286	
Isopropylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
Styrene	BDL	0.5ug/l	03/20/99	VA4286	
n-Propylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
tert-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
2-Chlorotoluene	BDL	0.5ug/l	03/20/99	VA4286	
4-Chlorotoluene	BDL	0.5ug/l	03/20/99	VA4286	
Bromobenzene	BDL	0.5ug/l	03/20/99	VA4286	
sec-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,3,5-Trimethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,4-Trimethylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,4-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,3-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
n-Butylbenzene	BDL	0.5ug/l	03/20/99	VA4286	
1,2-Dichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
Hexachlorobutadiene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,4-Trichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
Naphthalene	BDL	0.5ug/l	03/20/99	VA4286	
1,2,3-Trichlorobenzene	BDL	0.5ug/l	03/20/99	VA4286	
MTBE	BDL	2ug/l	03/20/99	VA4286	

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

4/1 H.D.D

Fair Lawn (N.J.)

DATE: 08/06/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 20399090
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *Q/S*
QC: *EF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 2ND FILTER 1330H 07/21/99 G

ULI I.D.: 20399125*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	07/31/99	VA4508
Trichloroethene	BDL	0.5ug/l	07/31/99	VA4508
Toluene	BDL	0.5ug/l	07/31/99	VA4508
Tetrachloroethene	BDL	0.5ug/l	07/31/99	VA4508
Ethylbenzene	BDL	0.5ug/l	07/31/99	VA4508
m-Xylene and p-Xylene	BDL	0.5ug/l	07/31/99	VA4508
Chlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
4-Isopropyltoluene	BDL	0.5ug/l	07/31/99	VA4508
o-Xylene	BDL	0.5ug/l	07/31/99	VA4508
Isopropylbenzene	BDL	0.5ug/l	07/31/99	VA4508
Styrene	BDL	0.5ug/l	07/31/99	VA4508
n-Propylbenzene	BDL	0.5ug/l	07/31/99	VA4508
tert-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4508
2-Chlorotoluene	BDL	0.5ug/l	07/31/99	VA4508
4-Chlorotoluene	BDL	0.5ug/l	07/31/99	VA4508
Bromobenzene	BDL	0.5ug/l	07/31/99	VA4508
sec-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4508
1,3,5-Trimethylbenzene	BDL	0.5ug/l	07/31/99	VA4508
1,2,4-Trimethylbenzene	BDL	0.5ug/l	07/31/99	VA4508
1,4-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
1,3-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
n-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4508
1,2-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
Hexachlorobutadiene	BDL	0.5ug/l	07/31/99	VA4508
1,2,4-Trichlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
Naphthalene	BDL	0.5ug/l	07/31/99	VA4508
1,2,3-Trichlorobenzene	BDL	0.5ug/l	07/31/99	VA4508
MTBE	BDL	2ug/l	07/31/99	VA4508

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 08/06/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 20399090
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *Q/S*
QC: *PE*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 1ST FILTER 1334H 07/21/99 G

ULI I.D.: 20399126*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	07/31/99	VA4511
Trichloroethene	BDL	0.5ug/l	07/31/99	VA4511
Toluene	BDL	0.5ug/l	07/31/99	VA4511
Tetrachloroethene	BDL	0.5ug/l	07/31/99	VA4511
Ethylbenzene	BDL	0.5ug/l	07/31/99	VA4511
m-Xylene and p-Xylene	BDL	0.5ug/l	07/31/99	VA4511
Chlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
4-Isopropyltoluene	BDL	0.5ug/l	07/31/99	VA4511
o-Xylene	BDL	0.5ug/l	07/31/99	VA4511
Isopropylbenzene	BDL	0.5ug/l	07/31/99	VA4511
Styrene	BDL	0.5ug/l	07/31/99	VA4511
n-Propylbenzene	BDL	0.5ug/l	07/31/99	VA4511
tert-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4511
2-Chlorotoluene	BDL	0.5ug/l	07/31/99	VA4511
4-Chlorotoluene	BDL	0.5ug/l	07/31/99	VA4511
Bromobenzene	BDL	0.5ug/l	07/31/99	VA4511
sec-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4511
1,3,5-Trimethylbenzene	BDL	0.5ug/l	07/31/99	VA4511
1,2,4-Trimethylbenzene	BDL	0.5ug/l	07/31/99	VA4511
1,4-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
1,3-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
n-Butylbenzene	BDL	0.5ug/l	07/31/99	VA4511
1,2-Dichlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
Hexachlorobutadiene	BDL	0.5ug/l	07/31/99	VA4511
1,2,4-Trichlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
Naphthalene	BDL	0.5ug/l	07/31/99	VA4511
1,2,3-Trichlorobenzene	BDL	0.5ug/l	07/31/99	VA4511
MTBE	BDL	2ug/l	07/31/99	VA4511

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 08/06/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 20399090
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT BEFORE FILTERS 1338H 07/21/99 G

ULI I.D.: 20399127*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	07/30/99	VA4505
Trichloroethene	BDL	0.5ug/l	07/30/99	VA4505
Toluene	BDL	0.5ug/l	07/30/99	VA4505
Tetrachloroethene	4ug/l	0.5ug/l	07/30/99	VA4505
Ethylbenzene	BDL	0.5ug/l	07/30/99	VA4505
m-Xylene and p-Xylene	BDL	0.5ug/l	07/30/99	VA4505
Chlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
4-Isopropyltoluene	BDL	0.5ug/l	07/30/99	VA4505
o-Xylene	BDL	0.5ug/l	07/30/99	VA4505
Isopropylbenzene	BDL	0.5ug/l	07/30/99	VA4505
Styrene	BDL	0.5ug/l	07/30/99	VA4505
n-Propylbenzene	BDL	0.5ug/l	07/30/99	VA4505
tert-Butylbenzene	BDL	0.5ug/l	07/30/99	VA4505
2-Chlorotoluene	BDL	0.5ug/l	07/30/99	VA4505
4-Chlorotoluene	BDL	0.5ug/l	07/30/99	VA4505
Bromobenzene	BDL	0.5ug/l	07/30/99	VA4505
sec-Butylbenzene	BDL	0.5ug/l	07/30/99	VA4505
1,3,5-Trimethylbenzene	BDL	0.5ug/l	07/30/99	VA4505
1,2,4-Trimethylbenzene	BDL	0.5ug/l	07/30/99	VA4505
1,4-Dichlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
1,3-Dichlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
n-Butylbenzene	BDL	0.5ug/l	07/30/99	VA4505
1,2-Dichlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
Hexachlorobutadiene	BDL	0.5ug/l	07/30/99	VA4505
1,2,4-Trichlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
Naphthalene	BDL	0.5ug/l	07/30/99	VA4505
1,2,3-Trichlorobenzene	BDL	0.5ug/l	07/30/99	VA4505
MTBE	5ug/l	2ug/l	07/30/99	VA4505

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

6034 Corporate Drive • E. Syracuse, NY 13057-1017
(315) 437 0255 Fax 437 1209

Fax 437 1209 Spill# 94-12600 Pin#94023

Syracuse

DATE: 10/18/99

Recent
DEC Sampling

Upstate Laboratories, Inc.
Analysis Results
Report Number: 27099055
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *C/S*
QC: *PE*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 2ND FILTER 1523H 09/24/99 G

ULI I.D.: 27099103*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	10/08/99	VOC102
Trichloroethene	BDL	0.5ug/l	10/08/99	VOC102
Toluene	BDL	0.5ug/l	10/08/99	VOC102
Tetrachloroethene	BDL	0.5ug/l	10/08/99	VOC102
Ethylbenzene	BDL	0.5ug/l	10/08/99	VOC102
m-Xylene and p-Xylene	BDL	0.5ug/l	10/08/99	VOC102
Chlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
4-Isopropyltoluene	BDL	0.5ug/l	10/08/99	VOC102
o-Xylene	BDL	0.5ug/l	10/08/99	VOC102
Isopropylbenzene	BDL	0.5ug/l	10/08/99	VOC102
Styrene	BDL	0.5ug/l	10/08/99	VOC102
n-Propylbenzene	BDL	0.5ug/l	10/08/99	VOC102
tert-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102
2-Chlorotoluene	BDL	0.5ug/l	10/08/99	VOC102
4-Chlorotoluene	BDL	0.5ug/l	10/08/99	VOC102
Bromobenzene	BDL	0.5ug/l	10/08/99	VOC102
sec-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102
1,3,5-Trimethylbenzene	BDL	0.5ug/l	10/08/99	VOC102
1,2,4-Trimethylbenzene	BDL	0.5ug/l	10/08/99	VOC102
1,4-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
1,3-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
n-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102
1,2-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
Hexachlorobutadiene	BDL	0.5ug/l	10/08/99	VOC102
1,2,4-Trichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
Naphthalene	BDL	0.5ug/l	10/08/99	VOC102
1,2,3-Trichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102
MTBE	BDL	2ug/l	10/08/99	VOC102

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 10/18/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 27099055
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PE*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 1ST FILTER 1527H 09/24/99 G

ULI I.D.: 27099104*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL KEY	FILE#
EPA Method 503.1 with MTBE					
Benzene	BDL	0.5ug/l	10/08/99	VOC102	
Trichloroethene	BDL	0.5ug/l	10/08/99	VOC102	
Toluene	BDL	0.5ug/l	10/08/99	VOC102	
Tetrachloroethene	BDL	0.5ug/l	10/08/99	VOC102	
Ethylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
m-Xylene and p-Xylene	BDL	0.5ug/l	10/08/99	VOC102	
Chlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
4-Isopropyltoluene	BDL	0.5ug/l	10/08/99	VOC102	
o-Xylene	BDL	0.5ug/l	10/08/99	VOC102	
Isopropylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
Styrene	BDL	0.5ug/l	10/08/99	VOC102	
n-Propylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
tert-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
2-Chlorotoluene	BDL	0.5ug/l	10/08/99	VOC102	
4-Chlorotoluene	BDL	0.5ug/l	10/08/99	VOC102	
Bromobenzene	BDL	0.5ug/l	10/08/99	VOC102	
sec-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
1,3,5-Trimethylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
1,2,4-Trimethylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
1,4-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
1,3-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
n-Butylbenzene	BDL	0.5ug/l	10/08/99	VOC102	
1,2-Dichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
Hexachlorobutadiene	BDL	0.5ug/l	10/08/99	VOC102	
1,2,4-Trichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
Naphthalene	BDL	0.5ug/l	10/08/99	VOC102	
1,2,3-Trichlorobenzene	BDL	0.5ug/l	10/08/99	VOC102	
MTBE	3ug/l	2ug/l	10/08/99	VOC102	

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 10/18/99

Upstate Laboratories, Inc.
Analysis Results
Report Number: 27099055
Client I.D.: NYSDC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT BEFORE FILTERS 1531H 09/24/99 G

ULI I.D.: 27099105*

Matrix: Water

PARAMETERS	RESULTS	DET.	LIMIT	DATE	ANAL	KEY	FILE#
EPA Method 503.1 with MTBE							
Benzene	BDL	0.5ug/l		10/08/99		VOC	103
Trichloroethene	BDL	0.5ug/l		10/08/99		VOC	103
Toluene	BDL	0.5ug/l		10/08/99		VOC	103
Tetrachloroethene	BDL	0.5ug/l		10/08/99		VOC	103
Ethylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
m-Xylene and p-Xylene	BDL	0.5ug/l		10/08/99		VOC	103
Chlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
4-Isopropyltoluene	BDL	0.5ug/l		10/08/99		VOC	103
o-Xylene	BDL	0.5ug/l		10/08/99		VOC	103
Isopropylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
Styrene	BDL	0.5ug/l		10/08/99		VOC	103
n-Propylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
tert-Butylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
2-Chlorotoluene	BDL	0.5ug/l		10/08/99		VOC	103
4-Chlorotoluene	BDL	0.5ug/l		10/08/99		VOC	103
Bromobenzene	BDL	0.5ug/l		10/08/99		VOC	103
sec-Butylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
1,3,5-Trimethylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
1,2,4-Trimethylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
1,4-Dichlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
1,3-Dichlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
n-Butylbenzene	BDL	0.5ug/l		10/08/99		VOC	103
1,2-Dichlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
Hexachlorobutadiene	BDL	0.5ug/l		10/08/99		VOC	103
1,2,4-Trichlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
Naphthalene	BDL	0.5ug/l		10/08/99		VOC	103
1,2,3-Trichlorobenzene	BDL	0.5ug/l		10/08/99		VOC	103
MTBE	5ug/l	2ug/l		10/08/99		VOC	103

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

Spill# 94-12600, Pin# 94023

AFL —

DATE: 01/06/00

Recent
DEC Sampling

Upstate Laboratories, Inc.
Analysis Results
Report Number: 33399037
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PE*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 2ND FILTER 1517H 11/30/99 G

ULI I.D.: 33599143*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	12/06/99	VA4705
Trichloroethene	BDL	0.5ug/l	12/06/99	VA4705
Toluene	BDL	0.5ug/l	12/06/99	VA4705
Tetrachloroethene	BDL	0.5ug/l	12/06/99	VA4705
Ethylbenzene	BDL	0.5ug/l	12/06/99	VA4705
m-Xylene and p-Xylene	BDL	0.5ug/l	12/06/99	VA4705
Chlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
4-Isopropyltoluene	BDL	0.5ug/l	12/06/99	VA4705
o-Xylene	BDL	0.5ug/l	12/06/99	VA4705
Isopropylbenzene	BDL	0.5ug/l	12/06/99	VA4705
Styrene	BDL	0.5ug/l	12/06/99	VA4705
n-Propylbenzene	BDL	0.5ug/l	12/06/99	VA4705
tert-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705
2-Chlorotoluene	BDL	0.5ug/l	12/06/99	VA4705
4-Chlorotoluene	BDL	0.5ug/l	12/06/99	VA4705
Bromobenzene	BDL	0.5ug/l	12/06/99	VA4705
sec-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705
1,3,5-Trimethylbenzene	BDL	0.5ug/l	12/06/99	VA4705
1,2,4-Trimethylbenzene	BDL	0.5ug/l	12/06/99	VA4705
1,4-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
1,3-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
n-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705
1,2-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
Hexachlorobutadiene	BDL	0.5ug/l	12/06/99	VA4705
1,2,4-Trichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
Naphthalene	BDL	0.5ug/l	12/06/99	VA4705
1,2,3-Trichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705
MTBE	BDL	2ug/l	12/06/99	VA4705

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 01/06/00

Upstate Laboratories, Inc.
Analysis Results
Report Number: 33399037
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT AFTER 1ST FILTER 1521H 11/30/99 G

ULI I.D.: 33599144*

Matrix: Water

PARAMETERS

RESULTS

DET. LIMIT DATE ANAL KEY FILE#

EPA Method 503.1 with MTBE

Benzene	BDL	0.5ug/l	12/07/99	VA4705
Trichloroethene	BDL	0.5ug/l	12/07/99	VA4705
Toluene	BDL	0.5ug/l	12/07/99	VA4705
Tetrachloroethene	BDL	0.5ug/l	12/07/99	VA4705
Ethylbenzene	BDL	0.5ug/l	12/07/99	VA4705
m-Xylene and p-Xylene	BDL	0.5ug/l	12/07/99	VA4705
Chlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
4-Isopropyltoluene	BDL	0.5ug/l	12/07/99	VA4705
o-Xylene	BDL	0.5ug/l	12/07/99	VA4705
Isopropylbenzene	BDL	0.5ug/l	12/07/99	VA4705
Styrene	BDL	0.5ug/l	12/07/99	VA4705
n-Propylbenzene	BDL	0.5ug/l	12/07/99	VA4705
tert-Butylbenzene	BDL	0.5ug/l	12/07/99	VA4705
2-Chlorotoluene	BDL	0.5ug/l	12/07/99	VA4705
4-Chlorotoluene	BDL	0.5ug/l	12/07/99	VA4705
Bromobenzene	BDL	0.5ug/l	12/07/99	VA4705
sec-Butylbenzene	BDL	0.5ug/l	12/07/99	VA4705
1,3,5-Trimethylbenzene	BDL	0.5ug/l	12/07/99	VA4705
1,2,4-Trimethylbenzene	BDL	0.5ug/l	12/07/99	VA4705
1,4-Dichlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
1,3-Dichlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
n-Butylbenzene	BDL	0.5ug/l	12/07/99	VA4705
1,2-Dichlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
Hexachlorobutadiene	BDL	0.5ug/l	12/07/99	VA4705
1,2,4-Trichlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
Naphthalene	BDL	0.5ug/l	12/07/99	VA4705
1,2,3-Trichlorobenzene	BDL	0.5ug/l	12/07/99	VA4705
MTBE	5ug/l	2ug/l	12/07/99	VA4705

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 01/06/00

Upstate Laboratories, Inc.
Analysis Results
Report Number: 33399037
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *QFS*
QC: *PF*
Lab I.D.: 10170

POUND RIDGE CLEANERS
SPIGOT BEFORE FILTERS 1525H 11/30/99 G

ULI I.D.: 33599145*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL KEY	FILE#
EPA Method 503.1 with MTBE					
Benzene	BDL	0.5ug/l	12/07/99		VA4705
Trichloroethene	BDL	0.5ug/l	12/07/99		VA4705
Toluene	BDL	0.5ug/l	12/07/99		VA4705
Tetrachloroethene	4ug/l	0.5ug/l	12/07/99		VA4705
Ethylbenzene	BDL	0.5ug/l	12/07/99		VA4705
m-Xylene and p-Xylene	BDL	0.5ug/l	12/07/99		VA4705
Chlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
4-Isopropyltoluene	BDL	0.5ug/l	12/07/99		VA4705
o-Xylene	BDL	0.5ug/l	12/07/99		VA4705
Isopropylbenzene	BDL	0.5ug/l	12/07/99		VA4705
Styrene	BDL	0.5ug/l	12/07/99		VA4705
n-Propylbenzene	BDL	0.5ug/l	12/07/99		VA4705
tert-Butylbenzene	BDL	0.5ug/l	12/07/99		VA4705
2-Chlorotoluene	BDL	0.5ug/l	12/07/99		VA4705
4-Chlorotoluene	BDL	0.5ug/l	12/07/99		VA4705
Bromobenzene	BDL	0.5ug/l	12/07/99		VA4705
sec-Butylbenzene	BDL	0.5ug/l	12/07/99		VA4705
1,3,5-Trimethylbenzene	BDL	0.5ug/l	12/07/99		VA4705
1,2,4-Trimethylbenzene	BDL	0.5ug/l	12/07/99		VA4705
1,4-Dichlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
1,3-Dichlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
n-Butylbenzene	BDL	0.5ug/l	12/07/99		VA4705
1,2-Dichlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
Hexachlorobutadiene	BDL	0.5ug/l	12/07/99		VA4705
1,2,4-Trichlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
Naphthalene	BDL	0.5ug/l	12/07/99		VA4705
1,2,3-Trichlorobenzene	BDL	0.5ug/l	12/07/99		VA4705
MTBE	7ug/l	2ug/l	12/07/99		VA4705

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

DATE: 01/06/00

Upstate Laboratories, Inc.
Analysis Results
Report Number: 33399037
Client I.D.: NYSDEC-REGION 3
Sampled by: ULI

APPROVAL: *CJS*
QC: *PE*
Lab I.D.: 10170

POUND RIDGE CLEANERS
ULI TRIP BLANK 11/30/99

ULI I.D.: 33599104*

Matrix: Water

PARAMETERS	RESULTS	DET. LIMIT	DATE	ANAL KEY	FILE#
EPA Method 503.1 with MTBE					
Benzene	BDL	0.5ug/l	12/06/99	VA4705	
Trichloroethene	BDL	0.5ug/l	12/06/99	VA4705	
Toluene	BDL	0.5ug/l	12/06/99	VA4705	
Tetrachloroethene	BDL	0.5ug/l	12/06/99	VA4705	
Ethylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
m-Xylene and p-Xylene	BDL	0.5ug/l	12/06/99	VA4705	
Chlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
4-Isopropyltoluene	BDL	0.5ug/l	12/06/99	VA4705	
o-Xylene	BDL	0.5ug/l	12/06/99	VA4705	
Isopropylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
Styrene	BDL	0.5ug/l	12/06/99	VA4705	
n-Propylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
tert-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
2-Chlorotoluene	BDL	0.5ug/l	12/06/99	VA4705	
4-Chlorotoluene	BDL	0.5ug/l	12/06/99	VA4705	
Bromobenzene	BDL	0.5ug/l	12/06/99	VA4705	
sec-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
1,3,5-Trimethylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
1,2,4-Trimethylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
1,4-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
1,3-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
n-Butylbenzene	BDL	0.5ug/l	12/06/99	VA4705	
1,2-Dichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
Hexachlorobutadiene	BDL	0.5ug/l	12/06/99	VA4705	
1,2,4-Trichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
Naphthalene	BDL	0.5ug/l	12/06/99	VA4705	
1,2,3-Trichlorobenzene	BDL	0.5ug/l	12/06/99	VA4705	
MTBE	BDL	2ug/l	12/06/99	VA4705	

BDL = Below Detectable Limits.

* Spill 9412600 PIN 94023

12/8 HDD

Fax 437 1209 Spill# 94-12600, Pin# 94023

Syracuse Rochester Buffalo Albany Binghamton Fair Lawn (NJ)