

New York State Department of Environmental Conservation
Division of Environmental Remediation
Remedial Bureau C, 11th Floor



Alexander B. Grannis
Commissioner

DAILY INSPECTION REPORT

Site Code #: 360054	Date: March 18, 2010	Report #:
----------------------------	-----------------------------	------------------

Site Name: One Commerce Park

Location: Wall Street, Valhalla, Town of Mt Pleasant, Westchester Co.

PRP Proj. Mgr.: Dan Smith/Rich Baldwin

DEC Proj. Mgr.: K. Maiurano

Consultant Proj. Mgr.: N/A

Proj. Contr.: N/A

Site Phone & Fax: N/A

	AM	PM
Weather	Clear	Clear
Temperature	~55-60	~60-65
Wind Direction	calm	calm

Description of work performed by contr. this report period:

Installation of MW-3 - Intermediate

Discussions/comments regarding visitors, contractor and/or engineer:

Rich Baldwin and Rob on site for Apex., driller (Ken) and helper (Anthony) from Land, Air, Water Environmental Services

MW-3: Hit refusal at 44', WP calls for 55'. (MW-1 and MW-2 hit rock at 54'). Discussed with Rich Baldwin. Agreed to install intermediate well here by filling bottom of hole with 7' of sand, 2' bentonite, 6" sand and setting well there.

Will move across median to lower parking area to try to drill to 55' for deep well.

Sampling and Analyses:

none

Health & Safety:

Level of protection: Normal.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Site Representative: Karen Maiurano

Date: March 22, 2010

Representative's signature: *Karen Maiurano*