



**DAILY INSPECTION REPORT**

<b>Site Code #:</b> 360054	<b>Date:</b> March 16, 2010	<b>Report #:</b>
----------------------------	-----------------------------	------------------

**Site Name:** One Commerce Park  
**Location:** Wall Street, Valhalla, Town of Mt Pleasant, Westchester Co.  
**PRP Proj. Mgr.:** Dan Smith/Rich Baldwin  
**DEC Proj. Mgr.:** K. Maiurano  
**Consultant Proj. Mgr.:** N/A  
**Proj. Contr.:** N/A  
**Site Phone & Fax:** N/A

	AM	PM
<b>Weather</b>	Clear	Clear
<b>Temperature</b>	~55-60	~60-65
<b>Wind Direction</b>	calm	calm

**Description of work performed by contr. this report period:**

Installation of MW-1 – deep  
 Equip decon  
 Mobilization to MW-2 location  
 Installation of of MW-2 shallow

**Discussions/comments regarding visitors, contractor and/or engineer:**

Rich Baldwin on site for Apex., driller (Ken) and helper (Anthony) from Land, Air, Water Environmental Services

MW-1 deep: drilled to 55', screened 50' - 55'. (rock at 54').

**Sampling and Analyses:**

none

**Health & Safety:**

Level of protection: Normal.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Site Representative: Randy Whitcher**

**Date: March 26, 2010**

**Representative's signature: *Randy Whitcher***