
New Scotland Avenue 401031

Monitoring Well Inventory, 9/12/2005

Photos with Notes

Photo

Description



Photo left. MW-8 599981
4722729, MW-8S 599981
4722729



Photo left. MW-8 series wells.
These two wells have been
destroyed and I don't know
which was which.



Photo left. MW-11S 599968
4722716.



Photo left. MW-11S. Note that
MW11S lettering is scratched
into the concrete.



Photo left. Looking through the trees towards MW-11S.



Photo left. We'd like to locate a well in the green shrubs, center of the picture. The location is to be between the curb and the fence, not too deep into the shrubs, closer to the curb than the fence. The shot shows that there are overhead wires to keep clear of and there likely is a buried electric line to the light pole.