


New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services



Alexander B. Grannis
Commissioner

DAILY INSPECTION REPORT

Site Code #: 4-11-014	Date: 7/21/08	Report #: 4
------------------------------	----------------------	--------------------

Site Name: Former Bouchard Junkyard
Location: Town of New Lebanon
Contr. Proj. Mgr.: Dave MacDougall
DEC Proj. Mgr.: Michael Mason
Consultant Proj. Mgr.: James Magda
Proj. Contr.: D.A. Collins Environmental Services
Site Phone & Fax:

	AM	PM
Weather	Not on Site	Sunny
Temperature		85
Wind Direction		Southwest

Description of work performed by contr. this report period:

Contractor continued excavating non TSCA soil and hauling off site .
23-24 loads hauled out today

Dust suppression continued on site and on Rte 20 by wetting down driving surfaces with water truck.

Description of inspections performed by engr. this report period:

Observed:

- Excavating and hauling non-TSCA soils
- Dust suppression

Discussions/comments regarding visitors, contractor and/or engineer: None

Change Orders: None

Sampling and Analyses: None

Major Issues	Description & Reason
None	

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from:

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Pick up truck	1				Contr. Engineer	1			
Dozer					Contr. Safety	1			
Track Hoe	1				Foreman	1			
Loader	1				Superintendent	1			
Water Truck	1				Operator	2			
Roller					Laborer	4			
Tandem Dump		6			Teamster	1	6		

Site Representative: Kristopher Keenan
Representative's signature:

Date: 7/21/08

Photo Log



Truck receiving non TSCA soil



Non TSCA Stockpile



RCRA TSCA Stockpile



TSCA Stockpile



Rte. 20 - Roadway Wet down with water truck



Rte. 20 - Roadway wet down with water truck