


New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services



Alexander B. Grannis
Commissioner

DAILY INSPECTION REPORT

Site Code #: 4-11-014	Date: 7/28/08	Report #: 5
------------------------------	----------------------	--------------------

Site Name: Former Bouchard Junkyard
Location: Town of New Lebanon
Contr. Proj. Mgr.: Dave MacDougall
DEC Proj. Mgr.: Michael Mason
Consultant Proj. Mgr.: James Magda
Proj. Contr.: D.A. Collins Environmental Services
Site Phone & Fax:

	AM	PM
Weather	Not on Site	Sunny
Temperature		81
Wind Direction		Southwest

Description of work performed by contr. this report period:

D.A. Collins:
- Excavating old entrance/exit road (grid J6/K6) to a depth of 1 foot.
- Loading out non-TSCA soil stockpiled at west end of project (Area 4)
- Dust suppression continued on site and on Rte 20 by wetting down driving surfaces with water truck.

Jointa Galusha LLC (Sub):
- Cutting down and chipping trees at west end of site

Description of inspections performed by engr. this report period:

Observed:
- Loading out non-TSCA soil
- Dust suppression
- Tree removal

Discussions/comments regarding visitors, contractor and/or engineer: None

Change Orders: None

Sampling and Analyses: None

Major Issues	Description & Reason
None	

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from:

Subcontractor	Activity	Hours Worked
(1)Jointa Galusha	Tree removal/chipping	

Equipment	P	1	2	3	Personnel	P	1	2	3
Pick up truck	1				Contr. Engineer				
Dozer					Contr. Safety	1			
Track Hoe	2				Foreman	1	1		
Loader	1				Superintendent	1			
Water Truck	1				Operator	3	3		
Roller					Laborer		1		
Tandem Dump					Teamster				
tree shear		1							
log skidder		1							
chipper		1							

Site Representative: Kristopher Keenan
Representative's signature:

Date: 7/28/08

Photo Log



Looking West - Excavating grid J6/K6



Looking West - Galusha removing trees at west end of site



Looking West - Galusha chipping trees



Dust Suppression

