

DATE: Wednesday 11/02/11

REPORT NO. 111102

PAGE NO. 1 OF 2

PROJECT NO. 3153

LOGBOOK NO. 10 PAGES 096-099

DAILY FIELD ACTIVITY REPORT

PROJECT	Former Bouchard Junkyard	WEATHER	TIME	TEMP.	PRECIP.	WIND (MPH)	WIND (DIR)
LOCATION	Town of New Lebanon, NY	clear	1040 AM	42 °F	None	Calm	N/A
ATTACHMENTS	Photo Log, Photos	clear	1300 PM	50 °F	None	Calm	N/A

SITE CONDITIONS: Clear and Sunny, No Precipitation; Scattered patches of snow

WORK GOAL FOR DAY: Wetland Inspection

PERSONNEL ON SITE:

NAME	AFFILIATION	ARRIVAL TIME	DEPART TIME
Jack Kuhn	D&B Engineering	1040	1300

EQUIPMENT ON SITE:

TYPE	MODEL	TYPE	MODEL

HEALTH & SAFETY:

PPE REQUIRED: ☒ LEVEL D ☐ LEVEL C ☐ LEVEL B ☐ LEVEL A **HASP? YES**

SITE SAFETY OFFICER: None

H & S NOTES: Site work was performed in Level D PPE.

DATE: 11/02/11

REPORT NO. 111102

PAGE NO. 2 OF 2

PROJECT NO. 3153

DAILY FIELD ACTIVITY REPORT

DESCRIPTION OF WORK PERFORMED AND OBSERVED

D&B Engineering arrived on-site to inspect the restored wetland area at the former Bouchard Junkyard site. During the inspection, D&B documented observations of the remediated area, including a listing of dominant plant species and an assessment of invasive species within the wetland area.

Vegetation within the remediated wetland area continues to be well established and appears in good condition. The dominant plant specie within the wetland is cattail. The entire wetland area is inundated with water, however, recent work to clear debris and improve drainage along Rt. 20 has lowered the water level within the wetland by several feet. Survivability of plantings installed within the restored area is the same as previously documented during the September 2011 inspection; no additional mortality was observed.

After the site inspection was completed, D&B departed from the site.

Concerns: No concerns were observed.

Future Work: No work schedule at this time.

PREPARED BY (OBSERVER)

PRINT NAME: Jack Kuhn

SIGNATURE:

REVIEWED BY

PRINT NAME: James Magda

SIGNATURE:

☒ ADDITIONAL SHEETS USED

☒ emailed draft / final to NYSDEC – date:

☐ hardcopy to NYSDEC – date:

PHOTOGRAPHIC LOG
November 2, 2011
D&B JOB NO. 3153
FORMER BOUCHARD JUNKYARD SITE
TOWN OF NEW LEBANON, NEW YORK

PHOTO	DATE	TIME	DESCRIPTION
PB 20001	11/2/2011	11:00	View to southeast showing wetland area from monitoring well #4
PB 20002	11/2/2011	11:04	View to northeast showing wetland area from monitoring well #4
PB 20003	11/2/2011	11:05	View to northeast showing wetland area from data point #1
PB 20004	11/2/2011	11:07	View to southeast showing wetland area from data point #1
PB 20005	11/2/2011	11:28	View to north showing wetland area from southwest corner of wetland
PB 20006	11/2/2011	11:30	View to southeast showing wetland area from northwest corner of wetland
PB 20007	11/2/2011	11:30	View to east showing rip-rap area entering wetland
PB 20008	11/2/2011	11:54	View to west showing wetland area from data point #3
PB 20009	11/2/2011	12:00	View to south showing wetland area from data point #4
PB 20010	11/2/2011	12:01	View to southeast showing wetland area from data point #4
PB 20011	11/2/2011	12:04	View to north from corner of gravel parking area
PB 20012	11/2/2011	12:07	View to north showing wetland area from south side of wetland



PB020001.JPG



PB020002.JPG



PB020003.JPG



PB020004.JPG



PB020005.JPG



PB020006.JPG



PB020007.JPG



PB020008.JPG



PB020009.JPG



PB020010.JPG



PB020011.JPG



PB020012.JPG