

**New York State - Department of Environmental Conservation
Division of Environmental Remediation
Periodic Review Evaluation Report**

Period covered by -- 2009-10

Site Code: 413010	Site Name: West Well and Parking Area (Amphenol)	Class: 02		
Program Lead: State Superfund Program	Site Management Funding Source: Responsible Party (RP)			
Start Date: 02/01/1988	ACT			
IC/EC Certification: Received	Received Date:	Accept Date: 03/30/2010		
DEC Inspection Date: 07/23/2009	--- Last Date of DEC Inspection			
Report Used for Evaluation: Longterm Monitoring, Inspection				
ROD Compliance? Yes				
Long Term Monitoring (effectiveness of remedy): Yes	Frequency: Quarterly			
Treatment System (Monitoring performance of remedy): Yes	Frequency: Quarterly	Number of Wells: 4		
Problem Status:				
Comments/Changes/Attachments: The 1988 Consent Order was modified in 05/2009 to address the migration of PCBs from the portion of the Village of Sydney's sanitary sewer line that runs underneath the Amphenol Facility, and to address the clean up and removal of PCBs found at the Village POTW.				
ROD/Consent Order Modifications? No				
Site reclassification recommended: No				
Contaminant of concern	OU	Media/Receptor		
TRICHLOROETHYLENE (F001)	01	gw/soil		
1,1,1-TRICHLOROETHANE (F001)	01	gw/soil		
PCBS (B007)	01	gw/soil		
CADMIUM (D006)	01	gw/soil		
CHROMIUM (D007)	01	gw/soil		
Evaluation: The Remedy is performing properly and is effective.				
Remedies	OU	Site of Treatment	Date in Place	Remedy Effective
Air Stripper	01	XX	03/14/1988	Yes
Other Pump & Treat	01	XX	03/14/1988	Yes

Next Review: 05/16/2011	Priority: 01
Project Manager: JRSTRANG	Reviewer: CXONEILL
Signature: <i>John Strang</i> Date: 03/30/2010	Signature: <i>[Signature]</i> Date: 03/30/2010
Name: JOHN STRANG Region or Bureau: DER REG. 4 Telephone: 518 357-2390	Name: CHRIS O'NEILL Region or Bureau: DER REG. 4 Telephone: 518 357-2394