

Appendix B

Representative Photographs



(Photo # 4-23-5) April 23, 2001 – Staging area after clearing and grubbing and silt fencing was installed. View toward the northeast.



(Photo # 4-23-13) April 23, 2001 – Staging area and MRP Spoil Banks after clearing and grubbing and silt fencing was installed. Original location of house trailer on the Spoil Banks. View toward the south.



(Photo # 4-23-14) April 23, 2001 – Existing conditions at LLA. View toward the northeast.



(Photo # 5-16-7) May 16, 2001 – Set up of the office trailers, parking area, and staging area. View toward the west.



(Photo # 5-24-5) May 24, 2002 – Existing conditions at NWDD. View toward the east.



(Photo # 6-6-MVC-004F) June 6, 2001 – Clearing and grubbing completed at the NWDD; silt and construction fencing installed; excavation limits surveyed, staked, and marked with a string line. View toward the northeast.



(Photo # 6-6-MVC-005F) June 6, 2001 – Clearing and grubbing completed at the NWDD; silt and construction fencing installed; excavation limits surveyed, staked, and marked with a string line. View toward the southeast.



(Photo # 6-6-MVC-010F) June 6, 2001 – Construction of the passive temporary diversion ditch north of the NWDD. View toward the west.



(Photo # 6-14-5) June 14, 2001 – MRP prior to dewatering and excavation activities. View toward the northwest.



(Photo # 6-14-6) June 14, 2001 – Pre-excavation conditions at MRP Spoil Banks. Clearing and grubbing completed. Excavation limits surveyed and staked. View toward the west.



(Photo # 6-14-12) June 14, 2001 – Installation of piping in the temporary passive diversion ditch north of MRP.
View toward the west.



(Photo # 6-20-5) June 20, 2001 – Real-time verification of a one foot excavation in the east end of the NWDD.



(Photo # 6-20-10) June 20, 2001 – Completion of a one foot excavation in the east end of the NWDD. View toward the west.



(Photo # 6-28-1) June 28, 2001 – Completion of a two foot excavation in the NWDD. Additional completed areas of excavation in the NWDD are shown in the background. View toward the east.



Photo # 7-10-MVC-001F
July 10, 2001 – Dewatering of MRP; upper soft materials. View toward the south.



(Photo # 7-18-3) July 18, 2001 – Excavation of 1 foot of material from a 6-foot by 6-foot area in NWDD to address NYSDEC post-excavation sampling results.



(Photo # 7-19-1) July 19, 2001 – Beginning excavation at the MRP Spoil Banks. View toward the northwest.



(Photo # 7-23-1) July 23, 2001 – Completion of excavation at a 4-, 5-, and 7-foot depths at the MRP Spoil Banks. View toward the west.



(Photo # 8-8-13) August 8, 2001 – Excavation of the south side of MRP. View toward the east.



(Photo # 8-14-7) August 14, 2001 – Excavation of MRP upper soft materials to the underlying clay layer. View toward the northeast.



(Photo # 9-5-4) September 5, 2001 – Excavations of from 6-foot by 6-foot areas on the MRP Spoil Banks to address NYSDEC post-excavation soil sampling results.



(Photo # 9-10-1) September 10, 2001 – Excavation completed at MRP. View toward the southeast.



(Photo # 9-17-4) September 17, 2001 – Excavation at LLA. View toward the northeast.



(Photo # 9-19-3) September 19, 2001 – Installation of a geotextile to act as a marking layer in the base of excavations. View toward the southwest.



(Photo # 9-24-2) September 24, 2001 – Backfilling MRP and MRP Spoil Banks. View toward the southwest.



(Photo # 10-1-2) October 1, 2001 – Completion of excavation at the LLA. View toward the northeast.



(Photo # 10-22-2) October 22, 2001 – Permanent diversion ditch inlet. View toward the northeast.



(Photo # 11-5-2) November 5, 2001 – Backfilled and graded MRP; rip-rap installed in the permanent diversion ditch. View towards the northeast.



(Photo # 11-21-10) November 21, 2001 – Topsoil installed in the LLA. View toward the southeast.



(Photo # 11-21-8) November 21, 2001 – Topsoil installed in the NWDD; planting of the wetlands. View toward the north.



(Photo # 11-21-13) November 21, 2001 – Topsoil and planting completed in the NWDD. View toward the east.