

Appendix F

Equipment Wipe Sampling Laboratory Analytical Data Sheets

Appendix F

General Electric Company Mead Road Pond Area Interim Remedial Measures Completion Report

Summary of Equipment Wipe Sampling Results

Sample ID	Sample Date	Total PCB (ug/100cm ²)
Dozer Blade	08/15/01	<1
Dozer Track	08/15/01	<1
Bucket #1	08/17/01	<1
Bucket #2	08/17/01	<1
Bucket	08/24/01	<1
Track	08/24/01	<1
Tire	09/14/01	<1
Dump	09/14/01	<1
L-Track	09/18/01	<1
L-Bucket	09/18/01	<1
K-Bucket	09/19/01	<1
K-Tread	09/19/01	<1
Excav. 690 Bucket	10/03/01	<1
Excav. 690 Track	10/03/01	<1
239156 Front Valve	10/09/01	<1
239156 Wall	10/09/01	<1
239345 Front Valve	10/09/01	<1
239345 Wall	10/09/01	<1
254102 Front Valve	10/09/01	<1
254102 Wall	10/09/01	<1
7124 Front Valve	10/09/01	<1
7124 Wall	10/09/01	<1

Notes:

1. "Valve" and "wall" samples from frac tanks. All other samples from earth-moving equipment.



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Dozer Blade

AES sample #: 010816 C01

Samples taken by: T.Makein

MATRIX: Wipe

Date Sampled: 08/15/01

Date sample received: 08/16/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB	EPA-8082	<1	ug/ 100cm2	KF-PCBAI26	08/16/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Dozer Track

AES sample #: 010816 C02

Samples taken by: T.Makein

MATRIX: Wipe

Date Sampled: 08/15/01

Date sample received: 08/16/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTE/BK REF</u>	<u>TEST DATE</u>
PCB	EPA-8082	<1	ug/ 100cm2	KF-PCBA126	08/16/01

APPROVED BY: 
Report date: 01/28/02



314 North Pearl Street
Albany, New York 12207
518-434-4546/434-0891 FAX

Wipe area = 100 cm²

A full service analytical research laboratory offering solutions to environmental concerns

CHAIN OF CUSTODY RECORD

CLIENT NAME <i>Clean Harbors</i>	PROJECT NAME (Location) <i>Dewey Loeffel</i>	SAMPLERS: (Names) <i>Thom MAKein</i>
ADDRESS	PO NUMBER <i>EV327267</i>	SAMPLER'S (Signature) <i>Thom MAKein</i>

AES SAMPLE NUMBER	CLIENT SAMPLE IDENTIFICATION & LOCATION	DATE SAMPLED	TIME A = a.m. P = p.m.	SAMPLE TYPE			NUMBER OF CONT'S	ANALYSIS REQUIRED
				MATRIX	COMP	GRAB		
<i>010116 col</i>	<i>Dozer Blade</i>	<i>8/15</i>		<i>A</i> <i>wipe</i>	<i>X</i>		<i>1</i>	<i>PCB</i>
<i>col</i>	<i>Dozer Track</i>	<i>8/15</i>		<i>A</i> <i>wipe</i>	<i>X</i>		<i>1</i>	<i>PCB</i>
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				
				<i>A</i>				
				<i>P</i>				

Turnaround Time: <i>24 hrs</i>	Laboratory Approval:
--------------------------------	----------------------

Relinquished by: (Signature)	Received by: (Signature)	Date/Time
Relinquished by: (Signature) <i>Rosend Custer</i>	Received by: (Signature)	Date/Time
Relinquished by: (Signature)	Received by: (Signature)	Date/Time
Dispatched by: (Signature)	Date/Time	Received for Laboratory by: <i>M.L.</i>
Method of Shipment:	Send Report To: <i>PAUL PUCK</i>	Date/Time <i>8/16/01 7:55 am</i>
		Client Phone No.: <i>766-0993</i>

The Laboratory reserves the right to return hazardous samples to the client or may levy an appropriate fee per container for disposal.

WHITE - Lab Copy

YELLOW - Sampler Copy

PINK - Generator Copy

Adirondack Environmental Services, Inc.

FAX 766 6494

0211181



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Bucket #1

AES sample #: 010817AL01

Samples taken by: Client

MATRIX: Wipe

Date Sampled: 08/17/01

Date sample received: 08/17/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Bucket #2

AES sample #: 010817AL02

Samples taken by: Client

MATRIX: Wipe

Date Sampled: 08/17/01

Date sample received: 08/17/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI27	08/17/01



314 North Pearl Street
Albany, New York 12207
518-434-4546/434-0891 FAX

CHAIN OF CUSTODY RECORD

A full service analytical research laboratory offering solutions to environmental concerns

Client Name: Clean Harbors		Address: 30 Bank Rd Glenmont, NY 12077	
Send Report To: Paul PUKL		Project Name (Location): Davey Loeffel	
Client Phone No: 766-0993		PO Number: EN327267	
Client Fax No: 766-6494		Samplers: (Names)	
		Samplers: (Signature)	

AES Sample Number	Client Sample Identification & Location	Date Sampled	Time A.M. P.M.	Sample Type			Number of Con'ts	Analysis Required
				Matrix	Comp	Grb		
010&17AW1	Bucket #1	8/17	A	wipe	X	1	PCB	
AW2	Bucket #2	8/17	P	wipe	X	1	PCB	
AW3	Effluent #3	8/17	A	H2O	X	1	PCB	
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					

Turnaround Time Request: ☐ 1 Day ☐ 3 Day ☒ Normal ☐ 2 Day ☐ 5 Day		Special Instructions/Remarks: wipe samples are 100 cm²	
CC Report To: Roland Austin			
Relinquished by: (Signature)		Received by: (Signature)	
Relinquished by: (Signature)		Received for Laboratory by: [Signature]	
		Date/Time: 8/17/01 4:00	

TEMPERATURE Ambient or Chilled	PROPERLY PRESERVED Y N	RECEIVED WITHIN HOLDING TIMES Y N
Notes: _____	Notes: _____	Notes: _____

WHITE - Lab Copy

YELLOW - Sampler Copy

PINK - Generator Copy

Adirondack Environmental Services, Inc.

231590 **B**



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Bucket

AES sample #: 010824 Z01

Samples taken by: Client

MATRIX: Wipe

Date Sampled: 08/24/01

Date sample received: 08/24/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01



Experience is the solution


314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.
CLIENT'S SAMPLE ID: Track
AES sample #: 010824 Z02

Samples taken by: Client
MATRIX: Wipe

Date Sampled: 08/24/01
Date sample received: 08/24/01
Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI29	08/24/01

APPROVED BY: 
Report date: 01/28/02



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Tire

AES sample #: 010914AT01

Samples taken by: Client

MATRIX: Wipe

Date Sampled:

Date sample received: 09/14/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Dump

AES sample #: 010914AT02

Samples taken by: Client

MATRIX: Wipe

Date Sampled:

Date sample received: 09/14/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI28	09/14/01

Client Name: Clean Harbors		Address: 32 Bask Rd Germant NY	
Send Report To: Paul RKK		Project Name (Location): Dewey Lottel	Samplers: (Names)
Client Phone No: 766-0993		PO Number: EV327269	Samplers: (Signature)
Client Fax No: 766-6494			

AES Sample Number	Client Sample Identification & Location	Date Sampled	Time A=a.m. P=p.m.	Sample Type			Number of Cont's	Analysis Required
				Matrix	Comp	Orb		
010914 ATO1	TIRE	8/14	A	wipe	x	1	PCB wipe *	
ATO2	Dump	8/14	A	wipe	x	1	PCB wipe	
			P					
ATO3	Topsoil	8/14	A	soil			* *	
ATO4	Clay Sand	8/14	A	soil			* *	
ATO5	Silt	8/14	A	soil			* *	
			P					
ATO6	Frac #2	8/14	A	H ₂ O	x	2	PCB, TSS	
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					

Turnaround Time Request: ☒ 1 Day ☐ 3 Day ☐ Normal ☐ 2 Day ☒ 5 Day		Special Instructions/Remarks: → ASAP on wipes, H₂O 5 Days on soils ** pH, organic content, nitrogen, Phosphorus Potassium, Calcium	
CC Report To:		Received by: (Signature) Rosebud Austin	
Relinquished by: (Signature) Rosebud Austin		Received for Laboratory by: M. L. P.	
Relinquished by: (Signature)		Date/Time 8/14 4/19/01 435	

TEMPERATURE Ambient or Chilled Notes: _____	PROPERLY PRESERVED Y N Notes: _____	RECEIVED WITHIN HOLDING TIMES Y N Notes: _____
--	--	---

WHITE - Lab Copy

YELLOW - Sampler Copy

PINK - Generator Copy

Adirondack Environmental Services, Inc.

23267



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: L-Track

AES sample #: 010918AY01

Samples taken by: Client

MATRIX: Wipe

Date Sampled: 09/18/01

Date sample received: 09/18/01

Location: N/A
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01



Experience is the solution


314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.
CLIENT'S SAMPLE ID: L-Bucket
AES sample #: 010918AY02

Samples taken by: Client
MATRIX: Wipe

Date Sampled: 09/18/01
Date sample received: 09/18/01
Location: N/A
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI39	09/18/01

APPROVED BY: 
Report date: 01/28/02



314 North Pearl Street
Albany, New York 12207
518-434-4546/434-0891 FAX

CHAIN OF CUSTODY RECORD

A full service analytical research laboratory offering solutions to environmental concerns

Client Name: Clean Harbors		Address: 30 Park Rd Glenmont, NY						
Send Report To: Paul RKL		Project Name (Location)		Samplers: (Names)				
Client Phone No: 766-0993		PO Number: EN307269		Samplers: (Signature)				
Client Fax No: 766-6494								
AES Sample Number	Client Sample Identification & Location	Date Sampled	Time A=a.m. P=p.m.	Sample Type			Number of Cont's	Analysis Required
				Matrix	Comp	Grab		
	HA TRACK K-BUCKET	9/18 9/18	A P	W.P.C W.P.C	X X	1 1	PCB PCB	* *
010918AY01	L-Track	9/18	A	W.P.C	X	1	PCB	*
AY02	L-Bucket	9/18	A	W.P.C	X	1	PCB	*
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					

Turnaround Time Request: ☒ 1 Day ☐ 3 Day ☐ Normal ☐ 2 Day ☐ 5 Day		Special Instructions/Remarks * 2 hr turnaround - see Tra At 11:00 AM	
CC Report To:			
Relinquished by: (Signature) Rosario Austin		Received by: (Signature) JS Miller	Date/Time 9/18/01 19:00
Relinquished by: (Signature) Rosario Austin		Received for Laboratory by: JS Miller	Date/Time 9/18/01 19:00
TEMPERATURE Ambient or Chilled Notes: _____	PROPERLY PRESERVED ☒ Y ☐ N Notes: _____	RECEIVED WITHIN HOLDING TIMES ☒ Y ☐ N Notes: _____	

WHITE - Lab Copy

YELLOW - Sampler Copy

PINK - Generator Copy

Adirondack Environmental Services, Inc.

232772



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.
CLIENT'S SAMPLE ID: K-Bucket
AES sample #: 010919BJ01

Samples taken by: Client
MATRIX: Wipe

Date Sampled: 09/19/01
Date sample received: 09/19/01
Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.
CLIENT'S SAMPLE ID: K-Tread
AES sample #: 010919BJ02

Samples taken by: Client
MATRIX: Wipe

Date Sampled: 09/19/01
Date sample received: 09/19/01
Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI40	09/19/01



314 North Pearl Street
Albany, New York 12207
518-434-4546/434-0891 FAX

CHAIN OF CUSTODY RECORD

A full service analytical research laboratory offering solutions to environmental concerns

Client Name: Clean Harbors	Address: 32 Bay Rd Glenmont NY	
Send Report To: Paul P. K.	Project Name (Location): Dwight Lottel	Samplers: (Names)
Client Phone No: 766-0993	PO Number: EW 327269	Samplers: (Signature)
Client Fax No: 766-6494		

AES Sample Number	Client Sample Identification & Location	Date Sampled	Time A=a.m. P=p.m.	Sample Type			Number of Cont's	Analysis Required
				Matrix	Comp	Grab		
010919B101	K - Bucket	9/19	A	wipe		X	1	PCB wipe
B102	K - Tread	9/19	A	wipe		X	1	PCB wipe
			P					
			A					
B103	Frag # 3	9/19	A	H2O		X	2	TSS, PCB
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					
			A					
			P					

Turnaround Time Request: ☒ 1 Day ☐ 3 Day ☐ Normal ☐ 2 Day ☐ 5 Day		Special Instructions/Remarks → 24 hrs	
CC Report To:			
Relinquished by: (Signature)		Received by: (Signature)	Date/Time
Relinquished by: (Signature)		Received for Laboratory by:	Date/Time: 9/19/01 4:45
TEMPERATURE Ambient or Chilled Notes: _____	PROPERLY PRESERVED Y N Notes: _____	RECEIVED WITHIN HOLDING TIMES Y N Notes: _____	

WHITE - Lab Copy

YELLOW - Sampler Copy

PINK - Generator Copy

Adirondack Environmental Services, Inc.

232849



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Excav. 690 Bucket

AES sample #: 011003BI01

Samples taken by: T.MaKein

MATRIX: Wipe

Date Sampled:

10/03/01

Date sample received: 10/03/01

Location: Dewey Loeffel
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: Excav. 690 Track

AES sample #: 011003BI02

Samples taken by: T.MaKein

MATRIX: Wipe

Date Sampled:

Date sample received: 10/03/01

Location: Dewey Loeffel

grab

10 c 2

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KS-PCBAI45	10/03/01

APPROVED BY:

Stephen K...

Report date: 01/28/02

022108



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 239156 Front Valve

AES sample #: 011010AF01

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCEAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 239156 Wall

AES sample #: 011010AF02

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill

grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 239345 Front Valve

AES sample #: 011010AF03

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTE/BK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 239345 Wall

AES sample #: 011010AF04

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 254102 Front Valve

AES sample #: 011010AF05

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 254102 Wall

AES sample #: 011010AF06

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891

CLIENT: Clean Harbors, Inc.

CLIENT'S SAMPLE ID: 7124 Front Valve

AES sample #: 011010AF07

Samples taken by: Thom MaKein

MATRIX: Wipe

Date Sampled: 10/09/01

Date sample received: 10/10/01

Location: Dewey Landfill
grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • 800-848-4983 • (518) 434-4546 • Fax (518) 434-0891


CLIENT: Clean Harbors, Inc.
CLIENT'S SAMPLE ID: 7124 Wall
AES sample #: 011010AF08

Date Sampled: 10/09/01

Date sample received: 10/10/01

Samples taken by: Thom MaKein Location: Dewey Landfill
MATRIX: Wipe grab

<u>PARAMETER PERFORMED</u>	<u>METHOD</u>	<u>RESULT</u>	<u>UNITS</u>	<u>NOTEBOOK REF</u>	<u>TEST DATE</u>
PCB-1016	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1221	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1232	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1242	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1248	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1254	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01
PCB-1260	EPA-8082	<1 ug/	100cm2	KF-PCBAI47	10/10/01

APPROVED BY: 
Report date: 01/28/02

