11
ENE
< 1/8
0.013 mi.
67 ft.

WASTE MGT @ FRIENDLYS RT 4 TROY RD
9 TROY RD RT 4
EAST GREENBUSH, NY

NY Spills **S102242595**
N/A

Relative:
Higher

Actual:
256 ft.

SPILLS:

Facility ID:	9603307
DER Facility ID:	111897
Facility Type:	ER
Site ID:	129820
DEC Region:	4
Spill Date:	6/10/1996
Spill Number/Closed Date:	9603307 / 6/10/1996
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	6/10/1996
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	6/10/1996
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/10/1996
Spill Record Last Update:	7/20/2012
Spiller Name:	Not reported
Spiller Company:	WASTE MGT
Spiller Address:	12 WING ST
Spiller City,St,Zip:	FORT EDWARD, NY
Spiller Company:	001
Contact Name:	CHRIS JONES
Contact Phone:	(518) 477-4010
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"
Remarks:	worn hose blew causing spill onto the pavementclean up done with speedidry

Material:

Site ID:	129820
Operable Unit ID:	1030854
Operable Unit:	01
Material ID:	349561
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	2
Resource Affected:	Not reported
Oxygenate:	False

WASTE MGT @ FRIENDLYS RT 4 TROY RD (Continued) **S102242595**

Tank Test:

B12 **NAT GRID TRANSFORMER COLUMBIA TNPK RT 20 NIMO** **NY Spills** **S108057827**
NW **591A COLUMBIA TNPK RT 9 & 20** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.026 mi.
137 ft. **Site 1 of 2 in cluster B**

Relative:
Lower

Actual:
251 ft.

SPILLS:

Facility ID:	0603371
DER Facility ID:	316166
Facility Type:	ER
Site ID:	366082
DEC Region:	4
Spill Date:	6/27/2006
Spill Number/Closed Date:	0603371 / 6/28/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	6/27/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/27/2006
Spill Record Last Update:	6/22/2011
Spiller Name:	BARBRA SCHEURER [SP] BARBARA SCHEURER
Spiller Company:	POLE #152 (NIMO NAT GRID)
Spiller Address:	591 A COLUMBIA TURNPIKE
Spiller City,St,Zip:	EAST GREENBUSH, NY
Spiller Company:	999
Contact Name:	BARBRA SCHEURER [SP]
Contact Phone:	(518) 433-3696
DEC Memo:	non-pcb. closed
Remarks:	transformer failure

Material:

Site ID:	366082
Operable Unit ID:	1124041
Operable Unit:	01
Material ID:	2113523
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No

NAT GRID TRANSFORMER COLUMBIA TNPK RT 20 NIMO (Continued) **S108057827**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

C13 **SHERWIN-WILLIAMS CO THE** **RCRA NonGen / NLR** **1000131727**
SSE **JCT US 20 & US 4** **FINDS** **NYD063785687**
< 1/8 **EAST GREENBUSH, NY** **NY MANIFEST**
0.027 mi.
143 ft. **Site 1 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: SHERWIN-WILLIAMS CO THE
Facility address: JCT US 20 & US 4
EAST GREENBUSH, NY 12061
EPA ID: NYD063785687
Mailing address: GREENBUSH FAIR SHPG PLZA
EAST GREENBUSH, NY 12061
Contact: H WILLIAMS JR
Contact address: GREENBUSH FAIR SHPG PLZA
EAST GREENBUSH, NY 12061
Contact country: US
Contact telephone: (212) 555-1212
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: THE SHERWIN-WILLIAMS CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE SHERWIN-WILLIAMS CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: SHERWIN-WILLIAMS CO THE
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: SHERWIN-WILLIAMS CO THE
Classification: Not a generator, verified

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/29/2010
Date achieved compliance: 05/13/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/13/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 04/29/2010
Date achieved compliance: 01/18/2011
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/13/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 04/29/2010
Date achieved compliance: 05/13/2010
Violation lead agency: State

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/13/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 04/29/2010
Date achieved compliance: 12/28/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/13/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/09/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 01/18/2011
Evaluation lead agency: State

Evaluation date: 04/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 12/28/2010
Evaluation lead agency: State

Evaluation date: 04/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 05/13/2010
Evaluation lead agency: State

Evaluation date: 04/29/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 05/13/2010
Evaluation lead agency: State

FINDS:

Registry ID: 110008004033

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD063785687
Country:	USA
Mailing Name:	SHERWIN-WILLIAMS CO THE
Mailing Contact:	ANTHONY CIPOLLA
Mailing Address:	596 COLUMBIA TPKE SUITE 13
Mailing Address 2:	Not reported
Mailing City:	EAST GREENBUSH
Mailing State:	NY
Mailing Zip:	12061
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	518-477-7177

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-19
Trans1 Recv Date:	2009-03-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	192.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001528485FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 2009-03-19
Trans1 Recv Date: 2009-03-19
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-03-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD063785687
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: Not reported
Quantity: 192.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 6.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001528485FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 2009-03-19
Trans1 Recv Date: 2009-03-19
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-03-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD063785687
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: Not reported
Quantity: 192.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 6.0

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001528485FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-12-09
Trans1 Recv Date:	2009-12-09
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-12-09
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	176.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	003188592FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Trans2 State ID:	Not reported
Generator Ship Date:	2009-12-09
Trans1 Recv Date:	2009-12-09
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-12-09
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CW - Wooden boxes
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	003188592FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-08-27
Trans1 Recv Date:	2009-08-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-08-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	520.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002498346FLE
Import Ind:	N

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2010-09-29
Trans1 Recv Date:	2010-09-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-10-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	003186545FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	RIR000508457
Trans2 State ID:	Not reported
Generator Ship Date:	22-Mar-2013 00:00:00
Trans1 Recv Date:	22-Mar-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	22-Mar-2013 00:00:00
Part A Recv Date:	Not reported

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	805
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	006501946FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	RIR000508457
Trans2 State ID:	Not reported
Generator Ship Date:	22-Mar-2013 00:00:00
Trans1 Recv Date:	22-Mar-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	22-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	006501946FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-28
Trans1 Recv Date:	2012-02-28
Trans2 Recv Date:	2012-03-02
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	9.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005155176FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-28
Trans1 Recv Date:	2012-02-28
Trans2 Recv Date:	2012-03-02
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Quantity:	750.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	CW - Wooden boxes
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005155176FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-28
Trans1 Recv Date:	2012-02-28
Trans2 Recv Date:	2012-03-02
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	9.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005155176FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-28
Trans1 Recv Date:	2012-02-28
Trans2 Recv Date:	2012-03-02
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	750.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	CW - Wooden boxes
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005155176FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-19
Trans1 Recv Date:	2009-03-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	192.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

SHERWIN-WILLIAMS CO THE (Continued) **1000131727**

Year:	2009
Manifest Tracking Num:	001528485FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-08-27
Trans1 Recv Date:	2009-08-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-08-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063785687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	520.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002498346FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

C14 **VALLEY OIL RT 9 & 20 @ RT 4 COLUMBIA TNPK** **NY Spills** **S102962743**
SSE **600 COLUMBIA TNPK RT 9 & 20@ RT 4 (TROY RD)** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.033 mi.
173 ft. **Site 2 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

SPILLS:

Facility ID:	9009584
DER Facility ID:	118800
Facility Type:	ER
Site ID:	138953
DEC Region:	4
Spill Date:	12/3/1990
Spill Number/Closed Date:	9009584 / 7/25/2005
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	12/4/1990
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	12/4/1990
Spill Record Last Update:	7/20/2012
Spiller Name:	KAREN O'CONNOR
Spiller Company:	MID VALLEY OIL CITGO
Spiller Address:	P.O. BOX 519
Spiller City,St,Zip:	E. GREENBUSH, NY 12061-0519
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	SEE EDOCs; SPILL #9501352, 0202590, 0312567, 0403380. PBS 4-066079MD TO KDG 8/98.6/14/99: A MODIFIED REMEDIAL PROPOSAL IS DUE IN EARLY JULY 1999. CONCENTRATIONS ARE EXTREMELY HIGH IN MW-3. (KG)8/7/01: A SEASONAL REMEDIATION SYSTEM HAS BEEN INSTALLED WHICH CONSISTS OF PUMPING FROM TWO TANK PIT WELLS AND REINJECTING AFTER TREATMENT INTO A THIRD. THE CONCENTRATIONS APPEAR TO BE DECREASING. (KG)7/25/05: The XTRA-Mart USTs have been removed along with corresponding contaminated soil. Some contaminated soil remains associated with a previous generation of USTs at a different location on the site. XTRA-Mart does not own the site and has sufficiently remediated their problem. The property owner is responsible for the remaining contamination which will be handled under spill #0403380. (KG)
Remarks:	CONT. SOIL FOUND PREPARING FOR TANK TEST, WILL DEWATER THRU CARBON, STORE CONT. SOIL ON POLY. 12/12-1 TANK REMOVED, 2 A-I-P, 3 PASSED TEST TO REMAIN IN USE. 12/18-OK TO VENT ON SITE, 5 MWS.

Material:

Site ID:	138953
Operable Unit ID:	946617
Operable Unit:	01

VALLEY OIL RT 9 & 20 @ RT 4 COLUMBIA TNPK (Continued) **S102962743**

Material ID:	429795
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	138953
Operable Unit ID:	946617
Operable Unit:	01
Material ID:	2096591
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	138953
Spill Tank Test:	1537983
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

C15 **NIMO TRANSFORMER COLUMBIA TNPK RT 4@RT 9&RT 20 NAT** **NY Spills** **S108130848**
SSE **RT 4 @ RT 9 & RT 20 COLUMBIA TNPK @ TROY RD** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.034 mi.
177 ft. **Site 3 of 13 in cluster C**

Relative:
Higher

Actual:
261 ft.

SPILLS:

Facility ID:	0606755
DER Facility ID:	319996
Facility Type:	ER
Site ID:	370146
DEC Region:	4
Spill Date:	9/12/2006
Spill Number/Closed Date:	0606755 / 9/20/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	weblain
Referred To:	Not reported

NIMO TRANSFORMER COLUMBIA TNPK RT 4@RT 9&RT 20 NAT (Continued) **S108130848**

Reported to Dept:	9/12/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/12/2006
Spill Record Last Update:	8/2/2012
Spiller Name:	DOUG GNIEWEK
Spiller Company:	POLE#4 (NIMO NAT GRID)
Spiller Address:	RTV 4 & AND RT 9&20
Spiller City,St,Zip:	EAST GREENBUSH, NY
Spiller Company:	999
Contact Name:	DOUG GNIEWEK
Contact Phone:	(518) 356-6471
DEC Memo:	non-pcb oil. cleaned.
Remarks:	A BUSHING BROKE HWILE MOVING A TRANSFORMER: 1 QUART AND ALL CLEANED UP: NOPN PCB AND DRIVEWAY ONLY

Material:

Site ID:	370146
Operable Unit ID:	1127972
Operable Unit:	01
Material ID:	2117581
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C16 **CITGO RT 9 & RT 20 @ RT 4 COLUMBIA TNPK** **NY Spills** **S102960873**
SSE **COLUMBIA TNPK RT 9 & 20 @ RT 4 (TROY RD)** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.034 mi.
178 ft. **Site 4 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

SPILLS:

Facility ID:	9501352
DER Facility ID:	306553
Facility Type:	ER
Site ID:	279030
DEC Region:	4
Spill Date:	5/2/1995
Spill Number/Closed Date:	9501352 / 9/19/1996
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response.

CITGO RT 9 & RT 20 @ RT 4 COLUMBIA TNPK (Continued) **S102960873**

	Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	DOMAGALA
Referred To:	Not reported
Reported to Dept:	5/2/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/4/1995
Spill Record Last Update:	7/20/2012
Spiller Name:	THOMAS MICHAEL
Spiller Company:	MID VALLEY OIL CITGO
Spiller Address:	PO BOX 4092
Spiller City,St,Zip:	NEW WINDSOR, NY 12553-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	PBS 4-066079; 9009584, 0202590, 0312567, 0403380.
Remarks:	FOUND CONT. SOIL @ WO TANK PULL.

Material:

Site ID:	279030
Operable Unit ID:	1012103
Operable Unit:	01
Material ID:	369958
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C17 **XTRAMART 1419 - EAST GREENBOSH** **RCRA NonGen / NLR 1001493718**
SSE **600 COLUMBIA TNPK** **FINDS NYU005001581**
< 1/8 **EAST GREENBUSH, NY 12061**
0.041 mi.
218 ft. **Site 5 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	XTRAMART 1419 - EAST GREENBOSH
Facility address:	600 COLUMBIA TNPK
	EAST GREENBUSH, NY 12061
EPA ID:	NYU005001581
Mailing address:	PO BOX 4092

XTRAMART 1419 - EAST GREENBOSH (Continued) **1001493718**

NEW WINDSOR, NY 12553
Contact: Not reported
Contact address: PO BOX 4092
NEW WINDSOR, NY 12553
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (914) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (914) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: XTRAMART 1419 - EAST GREENBOSH
Classification: Not a generator, verified

Date form received by agency: 08/11/1999

XTRAMART 1419 - EAST GREENBOSH (Continued) **1001493718**

Facility name: XTRAMART 1419 - EAST GREENBOSH
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/30/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004568833

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C18 **FORMER CITGO RT 20 COLUMBIA TNPK** **NY Spills** **S106470529**
SSE **600 COLUMBIA TNPK RT 20** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.041 mi.
218 ft. **Site 6 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

SPILLS:
Facility ID: 0403380
DER Facility ID: 257123
Facility Type: ER
Site ID: 129896
DEC Region: 4
Spill Date: 6/11/2004
Spill Number/Closed Date: 0403380 / 9/9/2009
Spill Cause: Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4224
Investigator: AJKOKOCK
Referred To: Not reported
Reported to Dept: 6/29/2004
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/29/2004
Spill Record Last Update: 6/22/2011

FORMER CITGO RT 20 COLUMBIA TNPK (Continued) **S106470529**

Spiller Name:	CHARLES POST
Spiller Company:	FORMER CITGO
Spiller Address:	600 COLUMBIA TURNPIKE
Spiller City,St,Zip:	EAST GREENBUSH, NY
Spiller Company:	001
Contact Name:	CHARLES POST
Contact Phone:	(518) 584-5122
DEC Memo:	PBS 4-066079; 9009584 (Edocs), 9501352, 0202590, 0312567, 04033805/12/08 - FOIL 08/13211/10/08 - 08/3582009-09-09 Site characterization work and soil removeal is sufficient to achive no further action required. File closed.
Remarks:	OLDER GENERATION OF DISPENSING LINES ON WESTERN SIDE OF PROPERTY ALONG RT. 9 &20: PID 150PPM, ORIGINAL SPILL ENGINEER AWARE OF CONDITION: FORMER MID VALLEY OIL CO. GAS STATION:

Material:

Site ID:	129896
Operable Unit ID:	885624
Operable Unit:	01
Material ID:	490967
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B19 **EDR US Hist Auto Stat** **1015563692**
WNW **591 COLUMBIA TPKE** **N/A**
< 1/8 **EAST GREENBUSH, NY 12061**
0.047 mi.
249 ft. **Site 2 of 2 in cluster B**

Relative: EDR Historical Auto Stations:
Higher

Name:	GRAND PREMIER TIRE & BATTERY
Year:	2011
Address:	591 COLUMBIA TPKE

Actual:
254 ft.

Name:	GRAND PREMIER TIRE & BATTERY
Year:	2012
Address:	591 COLUMBIA TPKE

C20 **NIMO SUBSTATION RT 9 & 20@ RT 4 COLUMBIA TNPK** **NY Spills** **S102962770**
SSE **COLUMBIA TNPK RT 9 & 20@ RT 4 SUBSTATION (TROY RD)** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.054 mi.
283 ft. **Site 7 of 13 in cluster C**

Relative:
Higher

Actual:
261 ft.

SPILLS:

Facility ID:	9108835
DER Facility ID:	226564
Facility Type:	ER
Site ID:	279029
DEC Region:	4
Spill Date:	11/19/1991
Spill Number/Closed Date:	9108835 / 11/21/1991
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	11/19/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	11/19/1991
Cleanup Meets Std:	True
Last Inspection:	11/19/1991
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/21/1991
Spill Record Last Update:	7/20/2012
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"09/28/95: This is additional information about material spilled from the translation of the old spill file: TRANSFORMER OIL?.
Remarks:	BREAKER EXPLODED, SM FIRE OUT, 4 DRUMS OIL RECOVERED, ~100GAL LEFT ON STONE, LITTLE PENETRATION, CLEANING SATISFACTORILY.

Material:

Site ID:	279029
Operable Unit ID:	959047
Operable Unit:	01
Material ID:	420946
Material Code:	0016A
Material Name:	NON PCB OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

NIMO SUBSTATION RT 9 & 20@ RT 4 COLUMBIA TNPK (Continued) **S102962770**

Tank Test:

C21
SSE
< 1/8
0.054 mi.
283 ft.

Relative: Higher

Actual: 261 ft.

CITGO COLUMBIA TNPK RT 9 & RT 20 @ RT 4 **NY Spills** **S106004444**
COLUMBIA TNKP RT 9 & 20 RT 4 (TROY RD) **N/A**
EAST GREENBUSH, NY

Site 8 of 13 in cluster C

SPILLS:

Facility ID:	0202590
DER Facility ID:	215034
Facility Type:	ER
Site ID:	263806
DEC Region:	4
Spill Date:	6/11/2002
Spill Number/Closed Date:	0202590 / 10/10/2002
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	6/11/2002
CID:	396
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/11/2002
Spill Record Last Update:	8/2/2012
Spiller Name:	[MID VALLEY OIL]
Spiller Company:	UNKNOWN " CITGO
Spiller Address:	COLUMBIA TNKP/RT4
Spiller City,St,Zip:	EAST GREENBUSH", ZZ
Spiller Company:	001
Contact Name:	BARB SCHEURER
Contact Phone:	(518) 433-3696
DEC Memo:	6-11-02 Called Barb Scheurer of NIMO -(518)433-3696NIMO encountered strong odor of petroleum across from Citgo while digging in their right of way. NIMO loaded all the contamination onto a dump truck. Dump truck is located at EPS property. Nimo will sample and dispose of properly. rjs 9009584, 9501352, 0312567, 0403380 PBS 4-06607910/10/02: KG contacted NIMO and they have taken the contaminated soil they generated to ESMI. The contamination was encountered in the right of way adjacent to the Xtra Mart Site. This site is being investigated under Spill #9009584. This spill number will be closed. (KG)
Remarks:	while diging [SP] in the right-a-way..a petrolium [SP] odor was detected in the ground.

Material:

Site ID:	263806

CITGO COLUMBIA TNPK RT 9 & RT 20 @ RT 4 (Continued) **S106004444**

Operable Unit ID:	855678
Operable Unit:	01
Material ID:	520437
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C22 **EAST GREENBUSH CITGO RT 20 COLUMBIA TNPK** **NY Spills** **S106382676**
SSE **600 COLUMBIA TNPK RT 9 & 20** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.054 mi.
283 ft. **Site 9 of 13 in cluster C**

Relative:
Higher

Actual:
261 ft.

SPILLS:

Facility ID:	0312567
DER Facility ID:	353459
Facility Type:	ER
Site ID:	318986
DEC Region:	4
Spill Date:	1/30/2004
Spill Number/Closed Date:	0312567 / 5/21/2004
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	2/11/2004
CID:	406
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/11/2004
Spill Record Last Update:	6/22/2011
Spiller Name:	STEVE MCGINCHEY
Spiller Company:	MID VALLEY OIL CITGO
Spiller Address:	1 SOUTH WATER ST.
Spiller City,St,Zip:	NEWBURGH, NY 12550
Spiller Company:	001
Contact Name:	STEVE MCGINCHEY
Contact Phone:	(845) 561-4000 108
DEC Memo:	PBS 4-066079; 9009584, 9501352, 0202590, 0403380This spill will be

EAST GREENBUSH CITGO RT 20 COLUMBIA TNPK (Continued) **S106382676**

investigated under Spill #9009584. (KG)
Remarks: While monitoring site noted water via the veeder root electronic tank gauging system . Pumped all the tanks down and all tanks at this site have been taken out of service temporarily.

Material:

Tank Test:
Site ID: 318986
Spill Tank Test: 1528971
Tank Number: 1,3&5
Tank Size: 4000
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

C23 **GOLDSTEIN ISUZU INC** **RCRA NonGen / NLR** **1000192757**
SSE **601 COLUMBIA TNPK** **FINDS** **NYD155313810**
< 1/8 **EAST GREENBUSH, NY** **NY AST**
0.062 mi. **NY MANIFEST**
327 ft. **Site 10 of 13 in cluster C**

Relative: Higher

Actual: 260 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: GOLDSTEIN ISUZU INC
Facility address: 601 COLUMBIA TNPK
EAST GREENBUSH, NY 12061
EPA ID: NYD155313810
Mailing address: COLUMBIA TNPK
EAST GREENBUSH, NY 12061
Contact: Not reported
Contact address: COLUMBIA TNPK
EAST GREENBUSH, NY 12061
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: GOLDSTEIN ENTERPRISES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: GOLDSTEIN ENTERPRISES
Owner/operator address: NOT REQUIRED

GOLDSTEIN ISUZU INC (Continued) **1000192757**

NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: GOLDSTEIN ISUZU INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: GOLDSTEIN ISUZU INC
Classification: Not a generator, verified

Date form received by agency: 04/03/1987
Facility name: GOLDSTEIN ISUZU INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004384719

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AST:
Region: STATE
DEC Region: 4

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Site Status:	Active
Facility Id:	4-600365
Program Type:	PBS
UTM X:	605849.21271999995
UTM Y:	4717044.4365699999
Expiration Date:	2016/08/21
Site Type:	Other

Affiliation Records:

Site Id:	37699
Affiliation Type:	On-Site Operator
Company Name:	MICHAELS AUTO PLAZA 920 CORP.
Contact Type:	Not reported
Contact Name:	MICHAEL RUBINCHUK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 689-0266
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	8/21/2006

Site Id:	37699
Affiliation Type:	Emergency Contact
Company Name:	MICHAEL RUBINCHUK
Contact Type:	Not reported
Contact Name:	MICHAEL RUBINCHUK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 495-9526
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	8/21/2006

Site Id:	37699
Affiliation Type:	Facility Owner
Company Name:	MICHAEL RUBINCHUK
Contact Type:	PRESIDENT
Contact Name:	MICHAEL RUBINCHUK
Address1:	103 VAN SCHOICK AVE.
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12209
Country Code:	001
Phone:	(518) 495-9526
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Date Last Modified: 5/17/2011

Site Id: 37699
Affiliation Type: Mail Contact
Company Name: MICHAELS AUTO PLAZA 920 CORP.
Contact Type: Not reported
Contact Name: EUGENE RUBINCHUK
Address1: 601 COLUMBIA TPKE
Address2: Not reported
City: EAST GREENBUSH
State: NY
Zip Code: 12061
Country Code: 001
Phone: (518) 869-0266
EMail: MICHAELSAUTOPLAZA@AOL.COM
Fax Number: Not reported
Modified By: RJSCHOWE
Date Last Modified: 8/21/2006

Tank Info:

Tank Number: 1
Tank Id: 95853
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/01/1994
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JDUTBERG
Last Modified: 05/17/2011
Material Name: Used Oil (Heating, On-Site Consumption)

Tank Number: 2
Tank Id: 239332
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/10/2010
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JDUTBERG
Last Modified:	05/17/2011
Material Name:	Used Oil (Heating, On-Site Consumption)

Tank Number:	3
Tank Id:	239333
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/10/2010
Capacity Gallons:	350
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JDUTBERG
Last Modified:	05/17/2011
Material Name:	Used Oil (Heating, On-Site Consumption)

NY MANIFEST:
EPA ID: NYD155313810

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Country:	USA
Mailing Name:	GOLDSTEIN ISUZU INC
Mailing Contact:	GOLDSTEIN ISUZU INC
Mailing Address:	601 COLUMBIA TPKE
Mailing Address 2:	Not reported
Mailing City:	EAST GREENBUSH
Mailing State:	NY
Mailing Zip:	12061
Mailing Zip4:	1693
Mailing Country:	USA
Mailing Phone:	518-477-2671

Document ID:	CTC0119368
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	G65142CT
Trans2 State ID:	Not reported
Generator Ship Date:	871104
Trans1 Recv Date:	871104
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	871105
Part A Recv Date:	871201
Part B Recv Date:	871113
Generator EPA ID:	NYD155313810
Trans1 EPA ID:	VAD980831580
Trans2 EPA ID:	Not reported
TSDF ID:	CTD072138969
Waste Code:	F003 - UNKNOWN
Quantity:	00070
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

Document ID:	CTB0087170
Manifest Status:	Completed copy
Trans1 State ID:	G54385CT
Trans2 State ID:	Not reported
Generator Ship Date:	870617
Trans1 Recv Date:	870617
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870619
Part A Recv Date:	870702
Part B Recv Date:	870625
Generator EPA ID:	NYD155313810
Trans1 EPA ID:	VAD980831580
Trans2 EPA ID:	Not reported
TSDF ID:	CTD072138969
Waste Code:	F003 - UNKNOWN
Quantity:	00105
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Specific Gravity:	100
Year:	87
EPA ID:	NYD981495112
Country:	USA
Mailing Name:	GOLDEN FORD BODY SHOP
Mailing Contact:	CHARLES MERRITT
Mailing Address:	601A COLUMBIA TPKE
Mailing Address 2:	Not reported
Mailing City:	EAST GREENBUSH
Mailing State:	NY
Mailing Zip:	12061
Mailing Zip4:	1603
Mailing Country:	USA
Mailing Phone:	518-477-2671
Document ID:	CTC0119368
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	G65142CT
Trans2 State ID:	Not reported
Generator Ship Date:	871104
Trans1 Recv Date:	871104
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	871105
Part A Recv Date:	871201
Part B Recv Date:	871113
Generator EPA ID:	NYD155313810
Trans1 EPA ID:	VAD980831580
Trans2 EPA ID:	Not reported
TSDF ID:	CTD072138969
Waste Code:	F003 - UNKNOWN
Quantity:	00070
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87
Document ID:	CTB0087170
Manifest Status:	Completed copy
Trans1 State ID:	G54385CT
Trans2 State ID:	Not reported
Generator Ship Date:	870617
Trans1 Recv Date:	870617
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870619
Part A Recv Date:	870702
Part B Recv Date:	870625
Generator EPA ID:	NYD155313810
Trans1 EPA ID:	VAD980831580
Trans2 EPA ID:	Not reported
TSDF ID:	CTD072138969
Waste Code:	F003 - UNKNOWN
Quantity:	00105

GOLDSTEIN ISUZU INC (Continued) **1000192757**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

C24 **GOLDSTEIN USED CARS RT 9 & 20 @ RT 4 COLUMBIA TNPK** **NY Spills** **S102115930**
SSE **601 COLUMBIA TNPK RT 9 & 20 @ RT 4 (TROY RD)** **N/A**
< 1/8 **EAST GREENBUSH, NY**
0.062 mi.
327 ft. **Site 11 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

SPILLS:

Facility ID:	9413938
DER Facility ID:	105370
Facility Type:	ER
Site ID:	121391
DEC Region:	4
Spill Date:	1/19/1995
Spill Number/Closed Date:	9413938 / 2/8/1995
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	1/19/1995
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	1/20/1995
Cleanup Meets Std:	True
Last Inspection:	1/20/1995
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/8/1995
Spill Record Last Update:	7/20/2012
Spiller Name:	Not reported
Spiller Company:	GOLDSTEIN USED CARS
Spiller Address:	601 COLUMBIA TNPK
Spiller City,St,Zip:	EAST GREENBUSH, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"
Remarks:	ECO FOUND WASTE OIL TANKS OVERFLOWING. 1/20-BLAIN @ SITE, GOLDSTEIN HI RED CORELLIS TO REMOVE & STOCKPILE CONT. SOIL, CLEANED.

Material:

Site ID:	121391
Operable Unit ID:	1007508
Operable Unit:	01
Material ID:	553850
Material Code:	0022

GOLDSTEIN USED CARS RT 9 & 20 @ RT 4 COLUMBIA TNPK (Continued) **S102115930**

Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C25 **GOLDEN FORD INC** **RCRA NonGen / NLR 1000186402**
SSE **601-A COLUMBIA TNPK** **FINDS NYD981495112**
< 1/8 **EAST GREENBUSH, NY**
0.062 mi.
327 ft. **Site 12 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GOLDEN FORD INC
Facility address:	601-A COLUMBIA TNPK EAST GREENBUSH, NY 12061
EPA ID:	NYD981495112
Mailing address:	COLUMBIA TNPK EAST GREENBUSH, NY 12061
Contact:	Not reported
Contact address:	COLUMBIA TNPK EAST GREENBUSH, NY 12061
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	GOLDSTEIN ENTERPRISES
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	GOLDSTEIN ENTERPRISES
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

GOLDEN FORD INC (Continued) **1000186402**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: GOLDEN FORD INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: GOLDEN FORD INC
Classification: Not a generator, verified

Date form received by agency: 08/12/1986
Facility name: GOLDEN FORD INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004407482

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C26 **EDR US Hist Auto Stat** **1015568640**
SSE **601 COLUMBIA TPKE** **N/A**
< 1/8 **EAST GREENBUSH, NY 12061**
0.063 mi.
331 ft. **Site 13 of 13 in cluster C**

Relative:
Higher

Actual:
260 ft.

EDR Historical Auto Stations:

Name: MICHALS AUTO PLAZA CORP
Year: 2005
Address: 601 COLUMBIA TPKE

Name: MICHAELS AUTO PLAZA 9 20 CORP

(Continued) **1015568640**

Year: 2008
Address: 601 COLUMBIA TPKE

D27 **WARREN TIRE** **NY AST** **A100350499**
SSE **608 COLUMBIA TURNPIKE** **N/A**
< 1/8 **EAST GREENBUSH, NY 12061**
0.086 mi.
454 ft. **Site 1 of 5 in cluster D**

Relative:
Higher

Actual:
263 ft.

AST:

Region:	STATE
DEC Region:	4
Site Status:	Active
Facility Id:	4-601344
Program Type:	PBS
UTM X:	605906.46800999995
UTM Y:	4716972.2720900001
Expiration Date:	2015/06/10
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	435942
Affiliation Type:	On-Site Operator
Company Name:	WARREN TIRE
Contact Type:	Not reported
Contact Name:	GENE GARHARTT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-7635
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG
Date Last Modified:	6/5/2013

Site Id:	435942
Affiliation Type:	Mail Contact
Company Name:	WARREN TIRE
Contact Type:	Not reported
Contact Name:	ROBERT W KELLOGG
Address1:	4 HIGHLAND AVE
Address2:	Not reported
City:	QUEENSBURY
State:	NY
Zip Code:	12804
Country Code:	001
Phone:	(518) 792-0316
EMail:	BKUSNA88@WARRENTIRESVC.COM
Fax Number:	Not reported
Modified By:	tesperbe
Date Last Modified:	6/10/2010

Site Id:	435942
Affiliation Type:	Emergency Contact
Company Name:	ROBERT KELLOGG

WARREN TIRE (Continued) **A100350499**

Contact Type:	Not reported
Contact Name:	BOB KELLOGG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 792-0316
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	7/25/2013

Site Id:	435942
Affiliation Type:	Facility Owner
Company Name:	ROBERT KELLOGG
Contact Type:	PRESIDENT
Contact Name:	ROBERT W KELLOGG
Address1:	4 HIGHLAND AVE
Address2:	Not reported
City:	QUEENSBURY
State:	NY
Zip Code:	12804
Country Code:	001
Phone:	(518) 792-0316
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG
Date Last Modified:	6/5/2013

Tank Info:

Tank Number:	1
Tank Id:	234848
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/09/2007

WARREN TIRE (Continued) **A100350499**

Capacity Gallons:	180
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	tesperbe
Last Modified:	06/10/2010
Material Name:	Motor Oil

Tank Number:	2
Tank Id:	234851
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/09/2007
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	tesperbe
Last Modified:	06/10/2010
Material Name:	Used Oil (Heating, On-Site Consumption)

Tank Number:	3
Tank Id:	234853
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

WARREN TIRE (Continued) **A100350499**

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/09/2007
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	tesperbe
Last Modified:	06/10/2010
Material Name:	Used Oil (Heating, On-Site Consumption)

D28 **EDR US Hist Auto Stat** **1015573144**
SSE **608 COLUMBIA TPKE** **N/A**
< 1/8 **EAST GREENBUSH, NY 12061**
0.086 mi.
454 ft. **Site 2 of 5 in cluster D**

Relative: EDR Historical Auto Stations:
Higher

Name:	WARRENS TIRE SVC CTR INC
Year:	2010
Address:	608 COLUMBIA TPKE

Actual:
263 ft.

Name:	WARREN TIRE SVCE CENTER INC
Year:	2011
Address:	608 COLUMBIA TPKE

D29 **SMITH'S TIRE SERVICE** **NY UST** **U002169597**
SSE **608 COLUMBIA TURNPIKE** **NY HIST UST** **N/A**
< 1/8 **EAST GREENBUSH, NY 12061**
0.086 mi.
454 ft. **Site 3 of 5 in cluster D**

Relative: UST:
Higher

Id/Status:	4-600337 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	4
Expiration Date:	N/A
UTM X:	605941.77596
UTM Y:	4716930.5757099995
Site Type:	Other

Actual:
263 ft.

Affiliation Records:

Site Id:	37671
Affiliation Type:	Facility Owner
Company Name:	CEDAR HOLDING ASSOCIATES

SMITH'S TIRE SERVICE (Continued) **U002169597**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	222 GRAND AVENUE
Address2:	Not reported
City:	ENGLEWOOD
State:	NJ
Zip Code:	07631
Country Code:	001
Phone:	(201) 569-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	37671
Affiliation Type:	Mail Contact
Company Name:	CEDAR HOLDING ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	222 GRAND AVENUE
Address2:	Not reported
City:	ENGLEWOOD
State:	NJ
Zip Code:	07631
Country Code:	001
Phone:	(201) 569-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	37671
Affiliation Type:	On-Site Operator
Company Name:	SMITHS TIRE SERVICE
Contact Type:	Not reported
Contact Name:	WAYNE KELLOGG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-7635
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	37671
Affiliation Type:	Emergency Contact
Company Name:	CEDAR HOLDING ASSOCIATES
Contact Type:	Not reported
Contact Name:	GENE GARHARTT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

SMITH'S TIRE SERVICE (Continued) **U002169597**

Zip Code:	Not reported
Country Code:	001
Phone:	(518) 465-2047
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	95630
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None

HIST UST:

PBS Number:	4-600337
SPDES Number:	Not reported
Emergency Contact:	GENE GARHARTT
Emergency Telephone:	(518) 465-2047
Operator:	WAYNE KELLOGG
Operator Telephone:	(518) 477-7635
Owner Name:	CEDAR HOLDING ASSOCIATES
Owner Address:	222 GRAND AVENUE
Owner City,St,Zip:	ENGLEWOOD, NJ 07631
Owner Telephone:	(201) 569-8500
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	CEDAR HOLDING ASSOCIATES
Mailing Address:	222 GRAND AVENUE
Mailing Address 2:	Not reported

SMITH'S TIRE SERVICE (Continued) **U002169597**

Mailing City,St,Zip:	ENGLEWOOD, NJ 07631
Mailing Contact:	Not reported
Mailing Telephone:	(201) 569-8500
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3824
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/27/1995
Expiration Date:	03/27/2000
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	EAST GREENBUSH
County Code:	38
Town or City:	24
Region:	4

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	FIBERGLASS COATED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

E30
NE
< 1/8
0.086 mi.
456 ft.

GENET SCHOOL RT 4 (TROY RD)
RT 4 GENET MIDDLE SCHOOL (TROY RD)
EAST GREENBUSH, NY

NY Spills **S107408068**
N/A

Site 1 of 2 in cluster E

Relative:
Higher

Actual:
260 ft.

SPILLS:

Facility ID:	9203796
DER Facility ID:	421061
Facility Type:	ER
Site ID:	317164
DEC Region:	4
Spill Date:	7/1/1992
Spill Number/Closed Date:	9203796 / 4/13/1993
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	7/1/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	2/28/1993
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/3/1992
Spill Record Last Update:	7/20/2012
Spiller Name:	Not reported
Spiller Company:	E. GREENBUSH SCHOOLS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN/O'BRIEN"
Remarks:	FOUND CONT. SOIL PREPING FOR TANK TEST, STOCKPILING. SEE 9207394.

Material:

Site ID:	317164
Operable Unit ID:	971179
Operable Unit:	01
Material ID:	411571
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

GENET SCHOOL RT 4 (TROY RD) (Continued) **S107408068**

Tank Test:

E31
NE
< 1/8
0.086 mi.
456 ft.

Relative:
Higher

Actual:
260 ft.

GENET MIDDLE SCHOOL RT 4 (TROY RD)
RT 4 GENET MIDDLE SCHOOL (TROY RD)
EAST GREENBUSH, NY

Site 2 of 2 in cluster E

NY Spills **S109208673**
N/A

SPILLS:

Facility ID:	9207394
DER Facility ID:	421061
Facility Type:	ER
Site ID:	317165
DEC Region:	4
Spill Date:	9/25/1992
Spill Number/Closed Date:	9207394 / 10/30/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	9/25/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/1/1992
Spill Record Last Update:	7/20/2012
Spiller Name:	PAUL DALEY
Spiller Company:	E. GREENBUSH SCHOOLS
Spiller Address:	ADMINISTRATION CENTER
Spiller City,St,Zip:	EAST GREENBUSH, NY 12061-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"10/03 Located a letter from Lebanon Valley in PBS file stating that the tanks had been removed, and soil taken to Sand Lake Landfill. Didn't include disposal receipts, but S.L. landfill was notoriously bad about that. closed no folder11/03 Letter sent to NYSHD; cc'd school. Does HD have any addt'l concerns? otherwise, stays closed
Remarks:	FOUND CONT. SOIL @ TANK PULL, O'BRIEN NOTIFIED, SEE 9203796.

Material:

Site ID:	317165
Operable Unit ID:	971028
Operable Unit:	01
Material ID:	408034
Material Code:	0003A

GENET MIDDLE SCHOOL RT 4 (TROY RD) (Continued) **S109208673**

Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D32 **RITE AID #1051** **NY MANIFEST** **S112141495**
SSE **614-616 COLUMBIA TNPK** **N/A**
1/8-1/4 **EAST GREENBUSH, NY 12061**
0.132 mi.
695 ft. **Site 4 of 5 in cluster D**

Relative:
Higher

Actual:
269 ft.

NY MANIFEST:

EPA ID:	NYR000189977
Country:	USA
Mailing Name:	RITE AID #1051
Mailing Contact:	RITE AID
Mailing Address:	614-616 COLUMBIA TNPK
Mailing Address 2:	Not reported
Mailing City:	EAST GREENBUSH
Mailing State:	NY
Mailing Zip:	12061
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	518-479-4230

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	20-Jun-2013 00:00:00
Trans1 Recv Date:	20-Jun-2013 00:00:00
Trans2 Recv Date:	24-Jun-2013 00:00:00
TSD Site Recv Date:	03-Jul-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	005534078FLE
Import Ind:	N

RITE AID #1051 (Continued) **S112141495**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	20-Jun-2013 00:00:00
Trans1 Recv Date:	20-Jun-2013 00:00:00
Trans2 Recv Date:	24-Jun-2013 00:00:00
TSD Site Recv Date:	03-Jul-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	005534078FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	20-Jun-2013 00:00:00
Trans1 Recv Date:	20-Jun-2013 00:00:00
Trans2 Recv Date:	24-Jun-2013 00:00:00
TSD Site Recv Date:	03-Jul-2013 00:00:00
Part A Recv Date:	Not reported

RITE AID #1051 (Continued) **S112141495**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	005534078FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	02-Jan-2013 00:00:00
Trans1 Recv Date:	02-Jan-2013 00:00:00
Trans2 Recv Date:	08-Jan-2013 00:00:00
TSD Site Recv Date:	11-Jan-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	005967346FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

RITE AID #1051 (Continued) **S112141495**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	2012-09-05
Trans1 Recv Date:	2012-09-05
Trans2 Recv Date:	2012-09-17
TSD Site Recv Date:	2012-09-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005196613FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	2012-06-18
Trans1 Recv Date:	2012-06-18
Trans2 Recv Date:	2012-06-27
TSD Site Recv Date:	2012-07-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported

RITE AID #1051 (Continued) **S112141495**

Quantity:	3.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005417333FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	2012-09-05
Trans1 Recv Date:	2012-09-05
Trans2 Recv Date:	2012-09-17
TSD Site Recv Date:	2012-09-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005196613FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

RITE AID #1051 (Continued) **S112141495**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJD054126164
Generator Ship Date:	2012-11-28
Trans1 Recv Date:	2012-11-28
Trans2 Recv Date:	2012-12-07
TSD Site Recv Date:	2012-12-14
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005403387FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	2012-06-18
Trans1 Recv Date:	2012-06-18
Trans2 Recv Date:	2012-06-27
TSD Site Recv Date:	2012-07-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000189977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	3.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1.0

RITE AID #1051 (Continued) **S112141495**

Year:	2012
Manifest Tracking Num:	005417333FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

D33 **RITE AID #1051** **RCRA-CESQG** **1014927206**
SSE **614-616 COLUMBIA TNPK** **NYR000189977**
1/8-1/4 **EAST GREENBUSH, NY 12061**
0.132 mi.
695 ft. **Site 5 of 5 in cluster D**

Relative:
Higher

Actual:
269 ft.

RCRA-CESQG:

Date form received by agency:	11/04/2011
Facility name:	RITE AID #1051
Facility address:	614-616 COLUMBIA TNPK EAST GREENBUSH, NY 12061
EPA ID:	NYR000189977
Mailing address:	HUNTER LANE CAMP HILL, PA 17011
Contact:	STEPHANIE A CAIATI
Contact address:	HUNTER LANE CAMP HILL, PA 17011
Contact country:	US
Contact telephone:	(717) 730-8225
Contact email:	SSCAIATI@RITEAID.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	RITE AID CORP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported

RITE AID #1051 (Continued) **1014927206**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/18/1998
Owner/Op end date: Not reported

Owner/operator name: RITE AID CORP
Owner/operator address: HUNTER LANE
CAMP HILL, PA 17011
Owner/operator country: US
Owner/operator telephone: (717) 761-2633
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/18/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D009
Waste name: MERCURY

RITE AID #1051 (Continued) **1014927206**

Waste code: D010
Waste name: SELENIUM

Waste code: D024
Waste name: M-CRESOL

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste code: P075
Waste name: NICOTINE, & SALTS

Violation Status: No violations found

F34 **EDR US Hist Auto Stat** **1015575218**
SSE **611 COLUMBIA TPKE** **N/A**
1/8-1/4 **EAST GREENBUSH, NY 12061**
0.156 mi.
825 ft. **Site 1 of 4 in cluster F**

Relative:
Higher

Actual:
272 ft.

EDR Historical Auto Stations:

Name: EAST GREENBUSH SUNOCO
Year: 2002
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2003
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2005
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2006
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2007
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2008
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2009
Address: 611 COLUMBIA TPKE

Name: EAST GREENBUSH SUNOCO
Year: 2010
Address: 611 COLUMBIA TPKE

F35 **SUNOCO RT 9 & RT 20 DAN ROWE COLUMBIA TNPK** **NY LTANKS** **S102960049**
SSE **611 COLUMBIA TNPK RT 9 & 20** **NY Spills** **N/A**
1/8-1/4 **EAST GREENBUSH, NY**
0.156 mi.
825 ft. **Site 2 of 4 in cluster F**

Relative:
Higher

Actual:
272 ft.

LTANKS:

Site ID:	186054
Spill Number/Closed Date:	8704640 / 11/18/1987
Spill Date:	9/3/1987
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station
Spill Class:	Known release that creates potential for fire or hazard. (Minimal Occurrence)
Cleanup Ceased:	11/18/1987
Cleanup Meets Standard:	True
SWIS:	4224
Investigator:	MCDONALD
Referred To:	Not reported
Reported to Dept:	9/3/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/4/1987
Spill Record Last Update:	6/22/2011
Spiller Name:	Not reported
Spiller Company:	PETERSON PETROLEUM RGLL
Spiller Address:	RT 9 & RT 20
Spiller City,St,Zip:	E. GREENBUSH, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	358549
DEC Memo:	Not reported
Remarks:	ULTRA UNLEADED 6K UGT, REG. UNLEADED 10K UGT : BOTH FAILED @ UNREADABLE RATES. WILL UNCOVER, ISOLATE AND RETEST

Material:

Site ID:	186054
Operable Unit ID:	908355
Operable Unit:	01
Material ID:	467267
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

SUNOCO RT 9 & RT 20 DAN ROWE COLUMBIA TNPK (Continued) **S102960049**

Tank Test:

Site ID:	186054
Spill Tank Test:	1531553
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

SPILLS:

Facility ID:	9400516
DER Facility ID:	353449
Facility Type:	ER
Site ID:	186055
DEC Region:	4
Spill Date:	4/11/1994
Spill Number/Closed Date:	9400516 / 4/15/1994
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	PNBENTIE
Referred To:	Not reported
Reported to Dept:	4/12/1994
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Responsible Party
Cleanup Ceased:	4/12/1994
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/15/1994
Spill Record Last Update:	6/22/2011
Spiller Name:	DAN ROWE(CUSTOMER/SPILLR)
Spiller Company:	D. ROWE @ PETERSON PET RGLL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BENTIEN"8704640, 9708451
Remarks:	NOZZLE @ PUMP DIDN'T SHUT-OFF. CALLER CALLED TO RPT EQ FAILURE, TURNS OUT HE JAMMED NOZZLE OPEN W/GAS CAP, CAUSED SPILL HIMSELF. NO FURTHER DEC RESPONSE.

Material:

Site ID:	186055
Operable Unit ID:	994222
Operable Unit:	01

SUNOCO RT 9 & RT 20 DAN ROWE COLUMBIA TNPK (Continued) **S102960049**

Material ID:	387829
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9708451
DER Facility ID:	353449
Facility Type:	ER
Site ID:	186056
DEC Region:	4
Spill Date:	10/20/1997
Spill Number/Closed Date:	9708451 / 9/7/2000
Spill Cause:	Housekeeping
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	10/20/1997
CID:	297
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	4/10/1998
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/20/1997
Spill Record Last Update:	6/22/2011
Spiller Name:	ROBERT METZ, PETERSON PETR RGLL
Spiller Company:	PETERSON PETROLEUM (RGLL)
Spiller Address:	RT 9 & 20 @ ELLIOT RD
Spiller City,St,Zip:	NH
Spiller Company:	999
Contact Name:	BOB METZ
Contact Phone:	(603) 476-2253
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"PBS # 4-429651, SEE 8704640, 9400516.APPPROX 450 YARDS DUG OUT. ERM HIRED TO INVESTIGATE. SAMPLES SHOW THAT THERE IS A BAND OF CONTAMINATED SOIL AT THE 14 FOOT LEVEL. UNSURE OF THE NEXT STEP. ROBERT METZ WAS TOLD NOT TO INSTALL TANKS UNTIL THE CLEANUP IS FINALIZED. Letter from Geisendorfer to that effect sent. FOLDERReport submitted documenting that contamination still exists underneath the site. More detail needs to be developed on the Rte. 20 side of the property, but no groundwater exists on the site to a depth of around 30 feet.12/5/97 Blain met Marty Rowan at the site. Screened and

SUNOCO RT 9 & RT 20 DAN ROWE COLUMBIA TNPK (Continued) **S102960049**

sampled soils to characterize. PID readings generally in the 100 to 200ppm range. Samples were taken a foot or so beneath the pile's surface, but not very far into the pile. Strong petro odors.4/9/98 Blain onsite. Soil pile gone. Letter inquiring whereabouts of soil sent to R. Fierstein. ECO's asked to investigate.6/2/98 Response rec'd. Soil receipts enclosed. This closed the soil disposal portion of the spill. Acknowledgement letter sent to R.Feirstein, RP's atty.12/98 Report submitted.SUMMARY: There still exists significant amounts of contaminated soil underneath the site. No groundwater was encountered to depth of over 20 feet. Excavated soil accounted for. Closed, does not meet standards.

Remarks: SITE PH#477-9129 / CALLER COMPANY REMOVING TANKS AND PUMP AND DISCOVERED CONTAMINATED SOIL UNDER THE PUMPS

Material:

Site ID:	186056
Operable Unit ID:	1054985
Operable Unit:	01
Material ID:	330426
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

G36
NW
1/8-1/4
0.169 mi.
894 ft.

MOUNT VERNON MOTEL RT 20 COLUMBIA TNPK **NY LTANKS** **S102232872**
576 COLUMBIA TNPK RT 9 & 20 **N/A**
EAST GREENBUSH, NY

Site 1 of 9 in cluster G

Relative:
Higher

Actual:
265 ft.

LTANKS:

Site ID:	198375
Spill Number/Closed Date:	9600817 / 5/9/1996
Spill Date:	4/17/1996
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/30/1996
Cleanup Meets Standard:	True
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	4/17/1996
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	4/18/1996
Recommended Penalty:	False
UST Involvement:	False

MOUNT VERNON MOTEL RT 20 COLUMBIA TNPK (Continued) **S102232872**

Remediation Phase:	0
Date Entered In Computer:	4/17/1996
Spill Record Last Update:	6/22/2011
Spiller Name:	JIM MATIAS
Spiller Company:	MOUNT VERNON MOTEL
Spiller Address:	576 COLUMBIA TNPK
Spiller City,St,Zip:	EAST GREENBUSH, NY
Spiller County:	001
Spiller Contact:	JIM
Spiller Phone:	(518) 477-9352
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	165101
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"BLAIN ONSITE 4/18/96. ROUTINE TANK PULL WITH CONTAMINATED SOIL. FIRST ROUND OF CONFIRMATORY SAMPLES SHOWED THAT A PORTION OF THE EXCAVATION FAILED TCLP. THAT AREA, UNDER A CONCRETE PAD, WAS REEXCAVATED. RESULTS PASSED. TOTAL OF 65 TON OF SOIL DISPOSED. REPORT DOCUMENTING SAMPLING AND DISPOSAL RECEIVED MAY,96. REPORT RESIDES WITH THE PBS FILE. WB.AREA OF PUBLIC WATER. MEETS ALL STDS. PROJECT CAME ABOUT DUE TO A REAL ESTATE TRANSACTION. FACILITY WAS NOT REGISTERED WITH PBS.
Remarks:	going to exavate and retest

Material:

Site ID:	198375
Operable Unit ID:	1032248
Operable Unit:	01
Material ID:	354211
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

G37 **BEST VALUE INN** **NY UST U003066040**
NW **576 COLUMBIA TPK** **NY HIST UST N/A**
1/8-1/4 **EAST GREENBUSH, NY 12061** **NY AST**
0.169 mi.
894 ft. **Site 2 of 9 in cluster G**

Relative:
Higher

Actual:
265 ft.

UST:

Id/Status:	4-600415 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	4
Expiration Date:	N/A
UTM X:	605526.89713000006
UTM Y:	4717435.5276499996
Site Type:	Other

BEST VALUE INN (Continued) **U003066040**

Affiliation Records:

Site Id:	37749
Affiliation Type:	Mail Contact
Company Name:	YOGINI INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	576 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	37749
Affiliation Type:	On-Site Operator
Company Name:	MT. VERNON MOTEL
Contact Type:	Not reported
Contact Name:	YOGINI INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005

Site Id:	37749
Affiliation Type:	Emergency Contact
Company Name:	YOGINI INC.
Contact Type:	Not reported
Contact Name:	BEN PATEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005

Site Id:	37749
Affiliation Type:	Facility Owner
Company Name:	YOGINI INC.
Contact Type:	MANAGER
Contact Name:	BEN PATEL

BEST VALUE INN (Continued) **U003066040**

Address1:	576 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005

Tank Info:

Tank Number:	2
Tank ID:	96207
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	04/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser

HIST UST:

PBS Number:	4-600415
SPDES Number:	Not reported
Emergency Contact:	BEN PABEL
Emergency Telephone:	(518) 477-9352
Operator:	YOGINI INC.
Operator Telephone:	(518) 477-9352
Owner Name:	YOGINI INC.
Owner Address:	576 COLUMBIA TURNPIKE
Owner City,St,Zip:	EAST GREENBUSH, NY 12061
Owner Telephone:	(518) 477-9352
Owner Type:	Corporate/Commercial

BEST VALUE INN (Continued) **U003066040**

Owner Subtype:	Not reported
Mailing Name:	YOGINI INC.
Mailing Address:	576 COLUMBIA TURNPIKE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	EAST GREENBUSH, NY 12061
Mailing Contact:	Not reported
Mailing Telephone:	(518) 477-9352
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	3824
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/11/1999
Expiration Date:	03/10/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	EAST GREENBUSH
County Code:	38
Town or City:	24
Region:	4

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	FIBERGLASS COATED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	04/07/2001
Next Test Date:	04/07/2006
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported

BEST VALUE INN (Continued) **U003066040**

Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	2
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	FIBERGLASS COATED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	04/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	4
Site Status:	Unregulated
Facility Id:	4-600415
Program Type:	PBS
UTM X:	605526.89713000006
UTM Y:	4717435.5276499996
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	37749
Affiliation Type:	Mail Contact
Company Name:	YOGINI INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	576 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported

BEST VALUE INN (Continued) **U003066040**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	37749
Affiliation Type:	On-Site Operator
Company Name:	MT. VERNON MOTEL
Contact Type:	Not reported
Contact Name:	YOGINI INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005
Site Id:	37749
Affiliation Type:	Emergency Contact
Company Name:	YOGINI INC.
Contact Type:	Not reported
Contact Name:	BEN PATEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005
Site Id:	37749
Affiliation Type:	Facility Owner
Company Name:	YOGINI INC.
Contact Type:	MANAGER
Contact Name:	BEN PATEL
Address1:	576 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RJSCHOWE
Date Last Modified:	5/25/2005

Tank Info:

BEST VALUE INN (Continued) **U003066040**

Tank Number:	1
Tank Id:	96206
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
I00 - Overfill - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	03
Date Test:	04/07/2001
Next Test Date:	Not reported
Date Tank Closed:	05/25/2005
Register:	True
Modified By:	RJSCHOWE
Last Modified:	05/25/2005
Material Name:	#2 Fuel Oil (On-Site Consumption)

38
ESE
1/8-1/4
0.173 mi.
911 ft.

Relative:
Higher

Actual:
267 ft.

E. GREENBUSH SCHOOL BUS GARAGE ELLIOTT RD **NY LTANKS** **S100163731**
ELLIOTT RD SCHOOL BUS GARAGE **N/A**
EAST GREENBUSH, NY

LTANKS:

Site ID:	256101
Spill Number/Closed Date:	8703456 / 11/18/1987
Spill Date:	7/28/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. (Minimal Occurrence)
Cleanup Ceased:	11/18/1987
Cleanup Meets Standard:	True
SWIS:	4224
Investigator:	MCDONALD
Referred To:	Not reported
Reported to Dept:	7/28/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

E. GREENBUSH SCHOOL BUS GARAGE ELLIOTT RD (Continued) **S100163731**

Remediation Phase:	0
Date Entered In Computer:	7/30/1987
Spill Record Last Update:	6/18/2013
Spiller Name:	Not reported
Spiller Company:	E. GREENBUSH SCHOOL GARAG
Spiller Address:	ELLIOTT RD
Spiller City,St,Zip:	EAST GREENBUSH, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	209731
DEC Memo:	8703456, 8904352, 9301915, 9707729, 9906165, 0010924, 0212029, 0611089; PBS 4-075825?
Remarks:	10K UGT FAILURE - COULDN'T DETERMINE LEAKRATE. TO UNCOVER/EXCAVATE/ RETEST

Material:

Site ID:	256101
Operable Unit ID:	907338
Operable Unit:	01
Material ID:	469693
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	256101
Spill Tank Test:	1531212
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

F39 **VALVOLINE INSTANT OIL CHANGE** **RCRA NonGen / NLR** **1004758798**
SSE **618 COLUMBIA TNPK** **FINDS** **NYD987023736**
1/8-1/4 **EAST GREENBUSH, NY 12061** **NY MANIFEST**
0.174 mi. **NY CBS**
920 ft. **Site 3 of 4 in cluster F**

Relative: RCRA NonGen / NLR:
Higher Date form received by agency: 01/01/2007
Facility name: VALVOLINE INSTANT OIL CHANGE
Actual: Facility address: 618 COLUMBIA TNPK
272 ft. EAST GREENBUSH, NY 12061

VALVOLINE INSTANT OIL CHANGE (Continued) **1004758798**

EPA ID: NYD987023736
Mailing address: COLUMBIA TNPK
EAST GREENBUSH, NY 12061
Contact: LANA SHANLEY
Contact address: COLUMBIA TNPK
EAST GREENBUSH, NY 12061
Contact country: US
Contact telephone: (606) 264-2271
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: J P & N J PETALAS VIA R M JACON
Owner/operator address: 726 COLUMBIA TNPK PO BOX 415
EAST GREENBUSH, NY 12061
Owner/operator country: US
Owner/operator telephone: (518) 477-5945
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: J P & N J PETALAS VIA R M JACON
Owner/operator address: 726 COLUMBIA TNPK PO BOX 415
EAST GREENBUSH, NY 12061
Owner/operator country: US
Owner/operator telephone: (518) 477-5945
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VALVOLINE INSTANT OIL CHANGE
Classification: Not a generator, verified

VALVOLINE INSTANT OIL CHANGE (Continued) **1004758798**

Date form received by agency: 12/10/1992
Facility name: VALVOLINE INSTANT OIL CHANGE
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004498856

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD987023736
Country: USA
Mailing Name: VALVOLINE INSTANT OIL CHANGE
Mailing Contact: TOM LAVIOLETTE
Mailing Address: 618 COLUMBIA TPKE
Mailing Address 2: Not reported
Mailing City: EAST GREENBUSH
Mailing State: NY
Mailing Zip: 12061
Mailing Zip4: 1610
Mailing Country: USA
Mailing Phone: 518-477-4805

Document ID: NYB1189296
Manifest Status: Completed copy
Trans1 State ID: OHIOPYN95
Trans2 State ID: Not reported
Generator Ship Date: 931122
Trans1 Recv Date: 931122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 931124
Part A Recv Date: 931207
Part B Recv Date: 931206
Generator EPA ID: NYD987023736
Trans1 EPA ID: KYD981807274
Trans2 EPA ID: Not reported
TSDF ID: WVD005005509
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 93

VALVOLINE INSTANT OIL CHANGE (Continued) **1004758798**

Document ID:	INA0863705
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	AB20327PA
Trans2 State ID:	Not reported
Generator Ship Date:	940216
Trans1 Recv Date:	940216
Trans2 Recv Date:	940224
TSD Site Recv Date:	940228
Part A Recv Date:	940228
Part B Recv Date:	940404
Generator EPA ID:	NYD987023736
Trans1 EPA ID:	KYD981807274
Trans2 EPA ID:	KYD981807274
TSDF ID:	IND098958283
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	94

CBS:

CBS Number:	4-000247
Program Type:	CBS
Facility Status:	Unregulated
Expiration Date:	N/A
Dec Region:	4
UTMX:	605975.87242999
UTMY:	4716875.5832200

F40 **VALVOLINE INSTANT OIL CHANGE** **NY AST S104562222**
SSE **618 COLUMBIA TURNPIKE** **NY CBS AST N/A**
1/8-1/4 **EAST GREENBUSH, NY 12061**
0.174 mi.
920 ft. **Site 4 of 4 in cluster F**

Relative:
Higher

Actual:
272 ft.

CBS AST:

CBS Number:	4-000247
ICS Number:	Not reported
PBS Number:	4-600388
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	ACTIVE FACILITY
Facility Type:	FARM
Telephone:	(518) 477-4805
Facility Town:	EAST GREENBUSH
Region:	STATE
Expiration Date:	06/28/2002
Total Capacity of All Active Tanks(gal):	0
Operator:	SERVICE CENTER MANAGER
Emergency Contact:	BILL MULTINAS
Emergency Phone:	(517) 785-7813
Owner Name:	GALENA ASSOCIATES/VALVOLINE INSTANT OIL
Owner Address:	1082 FARMINGTON AVE.
Owner City,St,Zip:	BRISTOL, CT 06010

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Owner Telephone:	(860) 582-5320
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	GALENA ASSOCIATES/VALVOLINE INSTANT OIL CHANGE
Mail Contact Addr:	1082 FARMINGTON AVE.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	MICHAEL FERRI
Mail Contact City,St,Zip:	BRISTOL, CT 06010
Mail Phone:	(860) 582-5320

Tank Id:	5
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/99
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Ethylene glycol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Painted/Asphalt Coating
Tank Error Status:	No Missing Data
Date Entered:	06/27/2000
Certified Date:	05/31/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	PLASTIC
Pipe Internal:	None
Pipe External:	00
Pipe Containment:	None,Painted/Asphalt Coating
Pipe Flag:	None,Painted/Asphalt Coating
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	False
Pre-Printed Renewal App Last Printed:	/ /

Tank Id:	6
CAS Number:	67561
Federal ID:	Not reported

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Tank Status:	0
Install Date:	10/99
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Methanol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Painted/Asphalt Coating
Tank Error Status:	No Missing Data
Date Entered:	06/27/2000
Certified Date:	05/31/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	PLASTIC
Pipe Internal:	None
Pipe External:	00
Pipe Containment:	None,Painted/Asphalt Coating
Pipe Flag:	None,Painted/Asphalt Coating
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	30
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	False
Pre-Printed Renewal App Last Printed:	/ /

Tank Id:	7
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	0
Install Date:	08/00
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Ethylene glycol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Other
Tank Error Status:	No Missing Data
Date Entered:	05/31/2001
Certified Date:	05/31/2001

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	00
Pipe Containment:	None,Other
Pipe Flag:	None,Other
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	False
Pre-Printed Renewal App Last Printed:	/ /

AST:

Region:	STATE
DEC Region:	4
Site Status:	Active
Facility Id:	4-600388
Program Type:	PBS
UTM X:	606018.96985999995
UTM Y:	4716816.5755500002
Expiration Date:	2015/08/21
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	37722
Affiliation Type:	On-Site Operator
Company Name:	VALVOLINE INSTANT OIL CHANGE
Contact Type:	Not reported
Contact Name:	SERVICE CENTER MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-4805
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG
Date Last Modified:	6/5/2013

Site Id:	37722

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Affiliation Type:	Emergency Contact
Company Name:	GALENA ASSOCIATES-DBA VALVOLINE INSTANT OIL CHANGE
Contact Type:	Not reported
Contact Name:	RONALD WILLIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 859-0159
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG
Date Last Modified:	6/5/2013

Site Id:	37722
Affiliation Type:	Facility Owner
Company Name:	GALENA ASSOCIATES-DBA VALVOLINE INSTANT OIL CHANGE
Contact Type:	DIR. OF ENVIRONMENTAL COMPLIANCE
Contact Name:	GLENN HOLDERBACH
Address1:	25 MAIN STREET
Address2:	Not reported
City:	HARTFORD
State:	CT
Zip Code:	06106
Country Code:	001
Phone:	(860) 244-9352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDUTBERG
Date Last Modified:	6/5/2013

Site Id:	37722
Affiliation Type:	Mail Contact
Company Name:	GALENA ASSOC.- DBA VALVOLINE INSTANT OIL CHANGE
Contact Type:	Not reported
Contact Name:	GLENN HOLDERBACH
Address1:	25 MAIN ST. - 4TH FLOOR
Address2:	Not reported
City:	HARTFORD
State:	CT
Zip Code:	06106
Country Code:	001
Phone:	(860) 244-9352
EMail:	GLENNH@SYNPOWER.NET
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	7/14/2010

Tank Info:

Tank Number:	10
Tank Id:	211995
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Used Oil (Heating, On-Site Consumption)

Tank Number:	2
Tank Id:	96034
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E02 - Piping Secondary Containment - Vault (with Access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1992
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Motor Oil

Tank Number:	3
Tank Id:	96035
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E02 - Piping Secondary Containment - Vault (with Access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1992
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Lube Oil

Tank Number:	4
Tank Id:	96036
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E02 - Piping Secondary Containment - Vault (with Access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1992
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Waste Oil/Used Oil

Tank Number:	5
Tank Id:	99824
Material Code:	0021
Common Name of Substance:	Transmission Fluid

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/27/2003
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Transmission Fluid

Tank Number:	6
Tank Id:	99825
Material Code:	0013
Common Name of Substance:	Lube Oil

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/27/2003
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Lube Oil

Tank Number:	7
Tank Id:	181630
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/2004
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Date Tank Closed: Not reported
Register: True
Modified By: rjschowe
Last Modified: 07/14/2010
Material Name: Motor Oil

Tank Number: 8
Tank Id: 211993
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/2006
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: rjschowe
Last Modified: 07/14/2010
Material Name: Lube Oil

Tank Number: 9
Tank Id: 211994
Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:

D00 - Pipe Type - No Piping
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	07/14/2010
Material Name:	Motor Oil

CBS AST:

CBS Number:	4-000247
ICS Number:	Not reported
PBS Number:	4-600388
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	ACTIVE FACILITY
Facility Type:	FARM
Telephone:	(518) 477-4805
Facility Town:	EAST GREENBUSH
Region:	STATE
Expiration Date:	06/28/2002
Total Capacity of All Active Tanks(gal):	0
Operator:	SERVICE CENTER MANAGER
Emergency Contact:	BILL MULTINAS
Emergency Phone:	(517) 785-7813
Owner Name:	GALENA ASSOCIATES/VALVOLINE INSTANT OIL
Owner Address:	1082 FARMINGTON AVE.
Owner City,St,Zip:	BRISTOL, CT 06010
Owner Telephone:	(860) 582-5320
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	GALENA ASSOCIATES/VALVOLINE INSTANT OIL CHANGE
Mail Contact Addr:	1082 FARMINGTON AVE.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	MICHAEL FERRI
Mail Contact City,St,Zip:	BRISTOL, CT 06010
Mail Phone:	(860) 582-5320

Tank Id:	5
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/99
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Ethylene glycol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Painted/Asphalt Coating
Tank Error Status:	No Missing Data
Date Entered:	06/27/2000
Certified Date:	05/31/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	PLASTIC
Pipe Internal:	None
Pipe External:	00
Pipe Containment:	None,Painted/Asphalt Coating
Pipe Flag:	None,Painted/Asphalt Coating
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	False
Pre-Printed Renewal App Last Printed:	/ /

Tank Id:	6
CAS Number:	67561
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/99
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Methanol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Painted/Asphalt Coating
Tank Error Status:	No Missing Data
Date Entered:	06/27/2000
Certified Date:	05/31/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	PLASTIC
Pipe Internal:	None
Pipe External:	00

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Pipe Containment:	None,Painted/Asphalt Coating
Pipe Flag:	None,Painted/Asphalt Coating
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	30
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	False
Pre-Printed Renewal App Last Printed:	/ /

Tank Id:	7
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	0
Install Date:	08/00
Tank Closed:	08/01
Capacity (Gal):	200
Chemical:	Ethylene glycol
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None,Other
Tank Error Status:	No Missing Data
Date Entered:	05/31/2001
Certified Date:	05/31/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	00
Pipe Containment:	None,Other
Pipe Flag:	None,Other
Leak Detection:	None,None
Overfill Protection:	09
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3824
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False

VALVOLINE INSTANT OIL CHANGE (Continued) **S104562222**

Date Expired: Not reported
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: False
Pre-Printed Renewal App Last Printed: / /

G41 **HAMILTON PRINTING RT 20 COLUMBIA TNPK** **NY LTANKS** **S102960048**
NW **579 COLUMBIA TNPK RT 9 & 20** **N/A**
1/8-1/4 **EAST GREENBUSH, NY**
0.191 mi.
1011 ft. **Site 3 of 9 in cluster G**

Relative:
Higher

Actual:
269 ft.

LTANKS:
Site ID: 288932
Spill Number/Closed Date: 8704867 / 10/22/1987
Spill Date: 9/11/1987
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 10/22/1987
Cleanup Meets Standard: True
SWIS: 4224
Investigator: MCDONALD
Referred To: Not reported
Reported to Dept: 9/11/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 9/14/1987
Spill Record Last Update: 6/22/2011
Spiller Name: Not reported
Spiller Company: HAMILTON PRINTING
Spiller Address: 579 COLUMBIA TNPK
Spiller City,St,Zip: EAST GREENBUSH, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 4
DER Facility ID: 234006
DEC Memo: Not reported
Remarks: 2K UGT FAILURE @ -.489 GPH. TO PUMP TANK. FURTHER ACTION UNDECIDED.

Material:
Site ID: 288932
Operable Unit ID: 908576
Operable Unit: 01
Material ID: 467481
Material Code: 0008
Material Name: Diesel
Case No.: Not reported

HAMILTON PRINTING RT 20 COLUMBIA TNPK (Continued) **S102960048**

Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	288932
Spill Tank Test:	1531602
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	288931
Spill Number/Closed Date:	8704579 / 10/22/1987
Spill Date:	9/2/1987
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	10/22/1987
Cleanup Meets Standard:	True
SWIS:	4224
Investigator:	MCDONALD
Referred To:	Not reported
Reported to Dept:	9/2/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/4/1987
Spill Record Last Update:	6/22/2011
Spiller Name:	Not reported
Spiller Company:	HAMILTON PRINTING
Spiller Address:	579 COLUMBIA TNPK
Spiller City,St,Zip:	EAST GREENBUSH, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	353442
DEC Memo:	Not reported
Remarks:	2K UGT. LEAK RATE IS UNKNOWN. PLAN TO DIG AND RETEST

Material:

HAMILTON PRINTING RT 20 COLUMBIA TNPK (Continued) **S102960048**

Site ID: 288931
Operable Unit ID: 911068
Operable Unit: 01
Material ID: 467209
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 288931
Spill Tank Test: 1531537
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

G42 **HAMILTON PRINTING** **RCRA NonGen / NLR** **1000554406**
NW **579 COLUMBIA TNPK** **FINDS** **NYD986968691**
1/8-1/4 **EAST GREENBUSH, NY 12061** **NY Spills**
0.191 mi.
1011 ft. **Site 4 of 9 in cluster G**

Relative:
Higher

Actual:
269 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: HAMILTON PRINTING
Facility address: 579 COLUMBIA TNPK
EAST GREENBUSH, NY 12061
EPA ID: NYD986968691
Contact: Not reported
Contact address: Not reported
NY
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

HAMILTON PRINTING (Continued) **1000554406**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: HAMILTON PRINTING
Classification: Not a generator, verified

Date form received by agency: 10/09/1991
Facility name: HAMILTON PRINTING
Classification: Not a generator, verified

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/01/1991
Date achieved compliance: 11/26/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/01/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/26/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/26/1991
Evaluation lead agency: State

FINDS:

Registry ID: 110004475327

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

HAMILTON PRINTING (Continued) **1000554406**

SPILLS:

Facility ID:	9802539
DER Facility ID:	103388
Facility Type:	ER
Site ID:	119006
DEC Region:	4
Spill Date:	5/28/1998
Spill Number/Closed Date:	9802539 / 8/23/1999
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	5/28/1998
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/28/1998
Spill Record Last Update:	6/22/2011
Spiller Name:	Not reported
Spiller Company:	HAMILTON PRINTING
Spiller Address:	579 COLUMBIA TURNPIKE
Spiller City,St,Zip:	EAST GREENUSH [SP], NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"SEE 8704579, 8704867.8/99 Several UGT's removed at the site. Unregistered tanks closed at the facility. Spillage was trivial.Needs closure report. Referred to PBS. closed
Remarks:	CONTAMINATED SOIL DISCOVERED DURING TANK PULL

Material:

Site ID:	119006
Operable Unit ID:	1063182
Operable Unit:	01
Material ID:	320865
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

G43
NW
1/8-1/4
0.197 mi.
1042 ft.

O'SULLIVAN'S GARAGE
577 COLUMBIA TURNPIKE
EAST GREENBUSH, NY 12061

NY HIST UST **U001845077**
NY AST **N/A**
NY HIST AST

Site 5 of 9 in cluster G

Relative:
Higher

Actual:
270 ft.

HIST UST:

PBS Number:	4-086045
SPDES Number:	Not reported
Emergency Contact:	W. MALONE
Emergency Telephone:	(518) 477-8042
Operator:	W.MALONE
Operator Telephone:	(518) 477-8042
Owner Name:	DOROTHY MALONE
Owner Address:	577 COLUMBIA TPK
Owner City,St,Zip:	E. GREENBUSH, NY 12061
Owner Telephone:	(518) 477-6082
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	W. MALONE
Mailing Address:	577 COLUMBIA TPK
Mailing Address 2:	Not reported
Mailing City,St,Zip:	E. GREENBUSH, NY 12061
Mailing Contact:	Not reported
Mailing Telephone:	(518) 477-8042
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	3824
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	09/07/2000
Inspector:	D.S.
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	11/06/2000
Expiration Date:	11/06/2005
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	9550
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	EAST GREENBUSH
County Code:	38
Town or City:	24
Region:	4
Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000

O'SULLIVAN'S GARAGE (Continued) **U001845077**

Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	08/01/1987
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/1990
Test Method:	Petro-Tite
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	2
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	08/01/1987
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/1990
Test Method:	Petro-Tite
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	3
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None

O'SULLIVAN'S GARAGE (Continued) **U001845077**

Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	03/01/1992
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	08/01/1992
Test Method:	Petro-Tite
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	4
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	03/01/1992
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	08/01/1992
Test Method:	Petro-Tite
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	5D
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL

O'SULLIVAN'S GARAGE (Continued) **U001845077**

Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	10/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	4
Site Status:	Active
Facility Id:	4-086045
Program Type:	PBS
UTM X:	605526.89713000006
UTM Y:	4717435.5276499996
Expiration Date:	2015/01/14
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	35488
Affiliation Type:	Mail Contact
Company Name:	577 AUTO CARE
Contact Type:	Not reported
Contact Name:	RAY LAHERA
Address1:	577 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-5772
EMail:	577AUTOCARE@GMAIL.COM
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	On-Site Operator
Company Name:	577 AUTO CARE
Contact Type:	Not reported
Contact Name:	RAY LAHERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-5772
EMail:	Not reported

O'SULLIVAN'S GARAGE (Continued) **U001845077**

Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	Emergency Contact
Company Name:	GUNTHARP AND LAHERA ENTERPRISES, LLC DBA 577 AUTO
Contact Type:	Not reported
Contact Name:	ALFRED GUNTHARP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 786-8843
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	Facility Owner
Company Name:	GUNTHARP AND LAHERA ENTERPRISES, LLC DBA 577 AUTO
Contact Type:	OWNER
Contact Name:	RAMON R. LAHERA
Address1:	577 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-5772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Tank Info:

Tank Number:	3D
Tank Id:	97258
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

O'SULLIVAN'S GARAGE (Continued) **U001845077**

B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	02/01/1998
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	01/14/2010
Material Name:	Diesel

Tank Number:	4K
Tank Id:	97259
Material Code:	2722
Common Name of Substance:	Kerosene [#1 Fuel Oil] (Resale/Redistribute)

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	RJSCHOWE
Last Modified:	10/18/2004
Material Name:	Kerosene [#1 Fuel Oil] (Resale/Redistribute)

Tank Number:	5W
Tank Id:	98471
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

O'SULLIVAN'S GARAGE (Continued) **U001845077**

I00 - Overfill - None
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	rjschowe
Last Modified:	01/14/2010
Material Name:	Waste Oil/Used Oil

Tank Number:	W
Tank Id:	96756
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Waste Oil/Used Oil

O'SULLIVAN'S GARAGE (Continued) **U001845077**

HIST AST:

PBS Number:	4-086045
SWIS Code:	3824
Operator:	W.MALONE
Facility Phone:	(518) 477-8042
Facility Addr2:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Emergency:	W. MALONE
Emergency Tel:	(518) 477-8042
Old PBSNO:	Not reported
Date Inspected:	09/07/2000
Inspector:	D.S.
Result of Inspection:	Not reported
Owner Name:	DOROTHY MALONE
Owner Address:	577 COLUMBIA TPK
Owner City,St,Zip:	E. GREENBUSH, NY 12061
Federal ID:	Not reported
Owner Tel:	(518) 477-6082
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	W. MALONE
Mailing Address:	577 COLUMBIA TPK
Mailing Address 2:	Not reported
Mailing City,St,Zip:	E. GREENBUSH, NY 12061
Mailing Telephone:	(518) 477-8042
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	11/06/2000
Expiration:	11/06/2005
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	9550
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	EAST GREENBUSH
County Code:	38
Town or City Code:	24
Region:	4
Tank ID:	W
Tank Location:	ABOVEGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (Gal):	275
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	0
Pipe Location:	None

O'SULLIVAN'S GARAGE (Continued) **U001845077**

Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	0
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	0
Dispenser Method:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	10/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

G44 **577 AUTO CARE** **NY UST** **U004063889**
NW **577 COLUMBIA TURNPIKE** **N/A**
1/8-1/4 **EAST GREENBUSH, NY 12061**
0.197 mi.
1042 ft. **Site 6 of 9 in cluster G**

Relative:
Higher

Actual:
270 ft.

UST:

Id/Status:	4-086045 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	4
Expiration Date:	2015/01/14
UTM X:	605526.89713000006
UTM Y:	4717435.5276499996
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	35488
Affiliation Type:	Mail Contact
Company Name:	577 AUTO CARE
Contact Type:	Not reported
Contact Name:	RAY LAHERA
Address1:	577 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-5772
EMail:	577AUTOCARE@GMAIL.COM
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	On-Site Operator
Company Name:	577 AUTO CARE
Contact Type:	Not reported
Contact Name:	RAY LAHERA
Address1:	Not reported
Address2:	Not reported

577 AUTO CARE (Continued) **U004063889**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 477-5772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	Emergency Contact
Company Name:	GUNTHARP AND LAHERA ENTERPRISES, LLC DBA 577 AUTO
Contact Type:	Not reported
Contact Name:	ALFRED GUNTHARP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 786-8843
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Site Id:	35488
Affiliation Type:	Facility Owner
Company Name:	GUNTHARP AND LAHERA ENTERPRISES, LLC DBA 577 AUTO
Contact Type:	OWNER
Contact Name:	RAMON R. LAHERA
Address1:	577 COLUMBIA TURNPIKE
Address2:	Not reported
City:	EAST GREENBUSH
State:	NY
Zip Code:	12061
Country Code:	001
Phone:	(518) 477-5772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rjschowe
Date Last Modified:	1/14/2010

Tank Info:

Tank Number:	1
Tank ID:	89615
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	09/01/1992
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

577 AUTO CARE (Continued) **U004063889**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: 11/01/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: rjschowe
Last Modified: 01/14/2010

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
I01 - Overfill - Float Vent Valve
E04 - Piping Secondary Containment - Double-Walled (Underground)
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 1-A
Tank ID: 89616
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 08/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 2

577 AUTO CARE (Continued) **U004063889**

Tank ID:	89619
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	09/01/1992
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	11/01/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	rjschowe
Last Modified:	01/14/2010

Equipment Records:

C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D11 - Pipe Type - Flexible Piping
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
I01 - Overfill - Float Vent Valve
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Number:	2-A
Tank ID:	89631
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	04/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	08/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser

577 AUTO CARE (Continued) **U004063889**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	3
Tank ID:	86458
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	08/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	03/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	4
Tank ID:	86459
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	08/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	03/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported

577 AUTO CARE (Continued) **U004063889**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Number: 5D
Tank ID: 86460
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 10/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None

G45 **SULLIVAN FUELS GAS STATION RT 20 COLUMBIA TNPK** **NY LTANKS S100133991**
NW **577 COLUMBIA TNPK RT 9 & 20** **NY Spills N/A**
1/8-1/4 **EAST GREENBUSH, NY**
0.197 mi.
1042 ft. **Site 7 of 9 in cluster G**

Relative: **Higher**

Actual: **270 ft.**

LTANKS:
Site ID: 275828
Spill Number/Closed Date: 8911174 / 4/5/1990
Spill Date: 2/23/1990
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.

SULLIVAN FUELS GAS STATION RT 20 COLUMBIA TNPK (Continued) **S100133991**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/5/1990
Cleanup Meets Standard:	True
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	2/23/1990
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	4/5/1990
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	4/11/1990
Spill Record Last Update:	6/22/2011
Spiller Name:	Not reported
Spiller Company:	SULLIVAN FUELS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	224258
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"SEE 8909597, 8911174, 9003274, 9206275, 9708226.7/11/08 - FOIL 08/217
Remarks:	2-2K UGTS FAILED PETROTITE, STOPPED BOTH TESTS. 1 REG UNL, 1 UNL+. 4/5-EXCAVATION OF BOTH TANKS COMPLETE. SM AMT. CONT. SOIL TO BE AERATED ON SITE. FINAL INSP. SHOWS SATISFACTORY.

Material:

Site ID:	275828
Operable Unit ID:	936700
Operable Unit:	01
Material ID:	564966
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	275828
Spill Tank Test:	1536800
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported

SULLIVAN FUELS GAS STATION RT 20 COLUMBIA TNPK (Continued) **S100133991**

Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

SPILLS:

Facility ID:	9206275
DER Facility ID:	224258
Facility Type:	ER
Site ID:	253188
DEC Region:	4
Spill Date:	8/31/1992
Spill Number/Closed Date:	9206275 / 12/7/1992
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	8/31/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	8/31/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	9/2/1992
Spill Record Last Update:	6/22/2011
Spiller Name:	Not reported
Spiller Company:	SULLIVAN FUEL
Spiller Address:	577 COLUMBIA TNPK
Spiller City,St,Zip:	EAST GREENBUSH, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"SEE 8909597, 8911174, 9003274, 9206275, 9708226.7/11/08 - FOIL 08/217
Remarks:	ANDERSON REMOVED 2 4K UGTS & 3 TRUCKLOADS CONT. SOIL, PUBLIC WATER.

Material:

Site ID:	253188
Operable Unit ID:	973507
Operable Unit:	01
Material ID:	410450
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

SULLIVAN FUELS GAS STATION RT 20 COLUMBIA TNPK (Continued) **S100133991**

Oxygenate: False

Tank Test:

Facility ID:	9708226
DER Facility ID:	224258
Facility Type:	ER
Site ID:	61245
DEC Region:	4
Spill Date:	10/14/1997
Spill Number/Closed Date:	9708226 / 12/4/1998
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4224
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	10/14/1997
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	10/14/1997
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/14/1997
Spill Record Last Update:	6/22/2011
Spiller Name:	ABOVE CALLER
Spiller Company:	SULLIVAN FUEL OIL SVC
Spiller Address:	577 COLUMBIA TURNPIKE
Spiller City,St,Zip:	EAST GREENBUSH, ZZ
Spiller Company:	001
Contact Name:	ABOVE CALLER
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BLAIN"10/14/97 BLAIN ONSITE, MET WITH JIM GRIFFEN, OWNER, AND JOHN DRUMM, CONTRACTOR. ROUTINE TANK PULL WITH CONTAMINATED SOIL.PUBLIC WATER AREA. VERY HEAVY SOIL, LIMITED EXTENT OF CONTAMINATION. WILL TREAT SOIL ONSITE. WB SEE 8909597, 8911174, 9003274, 9206275, 9708226.10/97 Sample results- meets STARS stds., but still has odors. Soils can be reused onsite.7/11/08 - FOIL 08/217
Remarks:	TANK PULL WILL EXCAVATE SOIL AND STAGE ON SITE - BILL BLAINE REG-4 AWARE OF TANK PULL - AND WILL BE ON SITE TODAY

Material:

Site ID:	61245
Operable Unit ID:	1054876
Operable Unit:	01
Material ID:	330209
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum