



NO	Revision	Date	Initial

LEGEND

- GT-12 EXISTING GROUND WATER MONITORING WELL
- U8-SB-1 2001 SOIL BORING LOCATION
- VRI-1 2001 GROUND WATER MONITORING WELL
- B16-SS-1 SURFACE SOIL SAMPLE LOCATION
- SMH ○ MANHOLE
- CB □ CATCH BASIN
- PROPERTY BOUNDARY LINE
- - - CHAIN LINK FENCE
- J ESTIMATED VALUE

LOCATION ID: VRI-4

PARAMETER	CONCENTRATION (µg/L)	NO EXCEEDANCE OF CRITERIA/NOT ANALYZED
Metals	5,990	300
Iron	384	300
Manganese	384	300

SAMPLE DATE: 10/16/01

NYSDEC GROUND WATER CLASS GA CRITERIA EXCEEDANCES (µg/L)

SCALE VERIFICATION

THIS BAR MEASURES 1" ON ORIGINAL. ADJUST SCALE ACCORDINGLY.

Approved

DRAWING STATUS

Status	Date	Initial

**VRI-RIVERVIEW FACILITY
Schenectady, New York**

**GROUNDWATER QUALITY DATA
NYSDEC CLASS GA EXCEEDANCES**



Source Reference:

Project Manager: J.K.P.	Reviewed By: MARCH 2002	Date:
Scale: 1"=100'	Project No: 18631-50	Report No: 005
		Drawing No: PLAN 2