

No.	Revision	Date	Initial

LEGEND

- GT-12 EXISTING GROUND WATER MONITORING WELL
- U6-SB-1 2001 SOIL BORING LOCATION
- ⊕ VRI-1 2001 GROUNDWATER MONITORING WELL
- ⊕ B16-SS-1 SURFACE SOIL SAMPLE LOCATION
- SMH ○ MANHOLE
- CB □ CATCH BASIN
- PROPERTY BOUNDARY LINE
- - - CHAIN LINK FENCE
- J ESTIMATED VALUE
- NE NO EXCEEDANCES OF NYSDEC TAGM # 4046 CRITERIA

LOCATION ID	SAMPLE DATE	NYSDEC TAGM #4046 CRITERIA EXCEEDANCES (pp/kg)
U6-SB-1	09/27/01	224 or MDL
B16-SS-1	09/27/01	61 or MDL
B16-SS-1	09/27/01	14 or MDL

PARAMETER

CONCENTRATION (pp/kg) (ppb)

SCALE VERIFICATION

THIS BAR MEASURES 1" ON ORIGINAL. ADJUST SCALE ACCORDINGLY.


Approved

DRAWING STATUS

Status	Date	Initial

VRI-RIVERVIEW FACILITY
Schenectady, New York

2001 SOIL QUALITY DATA
NYSDEC TAGM EXCEEDANCES



Source Reference:

Project Manager: J.K.P.	Reviewed By:	Date: JULY 2002
Scale: 1"=100'	Project No: 18631-50	Report No: 006
		Drawing No: PLAN 2