


Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Rocket Test Site (Malta Test Station)		Class: 2	Number: 5-46-022
O&M Funding Source: ☐ State Superfund ☐ Federal Superfund ☐ Municipal ☒ Responsible Party			
O&M Information: O&M Start: 4/95, 1/98, 3/98 End: Annual Cost: \$ ☐ Estimated			
Interim Remedial Measures/Operable Units in O&M Phase: ☐ Drum Removal ☒ Soil Removal (WE #3) ☐ Tank Removal ☐ Cap/Cover ☐ Containment Structure ☐ Fence/Security ☐ Groundwater Treatment ☐ Leachate Collection/Treatment ☐ Vapor Extraction/Treatment ☒ Air Stripper System (WE #1) ☐ Treatment/Filtration Plant/System ☐ Potable Water Supply/System ☒ Other: Long-term Monitoring (WE #2) and an Early Warning Monitoring System			
Institutional Controls: ☐ Deed Restriction ☐ Discharge Permit ☐ Department of Health Sampling ☒ Other: Institutional Controls Report 7/99 (Work Element #4)			
O&M Review Information: Reports: 01/99 Semiannual Drinking Water Sampling Results (Work Element (WE) #1); 06/99 Groundwater Long Term Monitoring Report (WE # 2); 02/99 Soil Removal Report (WE #3); 07/99 Institutional Controls Report (WE #4); 05/99 Semiannual Report on Early Warning Monitoring System. Reports are sent to the USEPA and NYSDEC. Inspection: _____ Sampling: _____ Other: _____			
Conclusions: Remedy Effective? ☒ Yes ☐ No: _____ ROD Compliance? ☒ Yes ☐ No: _____ Consent Order Compliance? ☒ Yes ☐ No: _____ Other: _____			
Recommendations: <u>Arrange a site inspection in 2000.</u> _____ Next Review Report 09/2000 _____ _____ _____ _____			
ROD/Consent Order Modifications? ☒ No ☐ Yes (per above) Reclassify the Site? ☒ No ☐ Yes → Class:			
Comments: <u>NPL Site. The Federal Projects Section (Central Office) continues to coordinate the remedial side of this project. Region Five receives copies of the reports. O&M has not been officially transferred to the Region.</u> <u>There are several O&M programs associated with this site. Work Element #1 is the site drinking water system and is an air stripper that provides groundwater treatment for water used by the Malta Test Station. Monitoring includes sampling of influent and effluent with semiannual reporting. Work Element #2 is a groundwater monitoring program that incorporates the Early Warning Monitoring System (EWMS) data and influent data from WE #1 to track VOC concentrations over time and to monitor natural attenuation and degradation. The EWMS is a semiannual monitoring program that monitors groundwater and surface water between the site and the Luther Forest water supply well field. Work Element #3 is the soil removal project that was completed and Work Element #4 deals with institutional controls for the site.</u> _____ _____			
Project Manager:  Signature John R. Strang Name 12/17/99 Date Haz. Site Control Region or Bureau (518) 457-0927 Telephone		Reviewer:  Signature Gerald J. Rider, Jr. Name 12/28/99 Date Haz. Site Control Region or Bureau (518) 457-0927 Telephone	