)8) NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION
INSPECTOR'S DAILY REPORT

Site Code No. E878 Date 06/05/00 I.R. No. 635

Site Name: NYSEG MECH'VILLE MGP IRM Sheet 1 of

Location: MECHANICVILLE (C), SARATOGA (Co.)

Engineer: NYSEG

Contractor: CLEAN WATERS OF AMERICA

Job Phone: ( )

	AM	PM
Weather	OVERCAST	
Temperature	50°F	
Wind (Dir./Vel.)	LITE/VAR.	

Health & Safety:

Level of protective clothing used: ~~LEVEL "D"~~ N/A

Is the level of protection in conformance with the approved Health & Safety Plan?

Yes N/A No___ If no, list the deviations under Items of Concern.

Are atmospheric monitoring results at acceptable levels? Yes N/A No___

Attach a copy of the monitoring log. N/A

Description of work performed during this report period: I MADE AN EARLY MORNING SITE VISIT TO THE SITE. IT APPEARS THAT ALL THE SITE GRADING AND PREP WORK IS COMPLETE.

I SAW TWO MAJOR AREAS OF EROSION WHERE STORM WATER COMES ON TO THE SITE ① IN THE NORTH EAST CORNER OF THE SITE APPROX ±7' SOUTH OF THE CONCRETE WALL WATER FROM CENTRAL AVE (SURFACE) HAS ERODED A CHANNEL IN THE BANK. IN THE CHANNEL I OBSERVED PURIFIER WOOD CHIPS. SOME OF THE CHIPS WERE CARRIED DOWN ONTO THE AREA TO BE PAVED.

② IN THE SOUTH END OF THE SITE ALONG FERRIS LANE, EAST OF THE GAS REGULATOR SHED, WATER FROM FERRIS LANE HAS ERODED AND AREA UNDER THE FENCE.

IN GENERAL, FROM THE LOOKS OF THE SITE, THEIR GRADING PLAN IS WORKING.

ANOTHER SIGNIFICANT OBSERVATION IS THAT THE CAISSON IN THE HOLDER (WHICH IS TO BE USED DURING THE R.I.) HAS BEEN COMPLETELY COVERED OVER. I DONT KNOW IF NYSEG TOOK ACCURATE NOTES RE: ITS LOCATION.

Site Visitors Representing Entered exclusion zone

THE FORECAST IS FOR RAIN FOR THE NEXT TWO DAYS WHICH SHOULD ADVERSELY AFFECT THE PLACEMENT OF THE ASPHALT.

)(8/88)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION
INSPECTOR'S DAILY REPORT

Subcontractor A: _____ worked from _____ to _____

Subcontractor B: _____ worked from _____ to _____

Contractors' Equipment	Prime	A	B	Not Used
N/A				

Work Force	Prime	A	B
N/A			

Prime Contractor worked from _____ to _____

Comments:

Items of concern:

Attachments to this report:

Inspector's Name (Print): WILLIAM ZEPPETELLI

Inspector's Signature: William Zeppetelli Date: 06/05/08

Reviewed by: _____ Date: _____