I (10/00)

Scanned & eDoced

INSPECTOR'S DAILY REPORT
New York State Department of Environmental Conservation
Division of Environmental Remediation

I.R. No. _____
Date 11/14/02

Site Name:	NYSEG MECHANICVILLE (CENTRAL AVE) FORMER MGP SITE
Site Code:	——— T & A Code: E877
Location:	MECHANICVILLE, SARATOGA COUNTY
DEC Project Manager:	GARDINER CROSS
Engineer / Consultant:	URS
Contractor:	AMERICAN AUGER
Health & Safety: PPE Level	D X C ___ B ___ P. SUNNY, 50°

Description of Work Performed:

DEVELOPED BOTH MW-43D AND MW-31D.

IN MW-43D, WATER LEVEL AT 17' BGS. PUMPED WELL DRY TWICE; RECOVERED ABOUT HALF BOTH TIMES. SULFUR ODOR PRESENT IN WATER. NO SHEEN PRESENT. REMOVED ABOUT 300 GALS.

M. GUTMAN (URS) ON SITE.
G. CROSS ON SITE.

IN MW-31D, WATER LEVEL AT 17' BGS. PUMPED DRY ONCE; RECOVERED ONLY 2' IN ABOUT 90 MINUTES. PUMPED DRY AGAIN. NO SHEENS OR ODORS DETECTED. REMOVED ABOUT 110 GALS.

I.R. No.

Description of Work Performed:

Items of Concern:

Inspector's Name:	R. SCOTT DEYETTE
Inspector's Signature:	Date: 11/14/02

Form # BCS-01 (10/00)

INSPECTOR'S DAILY REPORT
New York State Department of Environmental Conservation
Division of Environmental Remediation

I.R. No. _____
Date 11/13/02

Site Name:	NYSEG MECHANICVILLE FORMER MGP SITE (CENTRAL AVE)
Site Code:	——— T & A Code: E877
Location:	MECHANICVILLE, SARATOGA COUNTY
DEC Project Manager:	GARDINER GROSS
Engineer / Consultant:	LMS
Contractor:	AMERICAN AUGER
Health & Safety: PPE Level	D X C ____ B ____ LT. RAIN, 45°

Description of Work Performed:

COMPLETED MW-43D (6" CASING AND OPEN HOLE) TO 150' BGS. LOCATED IN STREET BETWEEN # 16 AND 22 BRUNDAGE ST.

DRILLING COMPLETED WITH VERSADRILL V-2000 DRILL RIG.

ASSUMED WEATHERED BEDROCK AT 12.5' BGS. COMPETENT BEDROCK AT 14.8' BGS.

6" STEEL CASING SET TO 19.5' BGS; THEN USED 4" ROLLERBIT TO COMPLETE OPEN HOLE TO 150' BGS.

MODERATE SHEEN NOTED IN WASH TUB AT ~30', 70', AND 100' BGS. NO ODOR DETECTED.

PLACED 12" MANHOLE COVER AND J-PLUG ON WELL.

I.R. No.

Description of Work Performed:

Items of Concern:

Inspector's Name: R. Scott DeYette

Inspector's Signature: R. Scott

Date: 11/13/02

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	June 12, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech061202
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 3:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	65F/74F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-37D Well to 165.2'. Packer Test 145.2'-165.2'. No water. Run#31 165.2'-170.2'. Run#32 170.2'-175.2'. Run#33 175.2'-180.2'. Run#34 180.2'-185.2'. Packer Test 165.2'-185.2' Did produce water.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	June 13, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech061302
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 3:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	57F/72F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-37D Reaming out MW-37D to 185.2'..

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: **Signature:** **Date:**
Raymond Crawford

Reviewed By: **Date:**

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	June 10, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech061002
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:30 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/Sunny
CONT. REP.		**TEMP.**	57F/71F
SITE PHONE		**WIND DIR.**	Calm/NW@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-37D at B&D Tavern Rock at 16.2'. Casing to 20'. Run#1 20.2'-23.0'. Run#2 23.0'-25.2'. Run#3 25.2'-30.2'. Run#4 30.2'-35.2'. Run#5 35.2'-40.2'. Run#6 40.2'-45.2'. Packer Test 20'-45'. Run#7 45.2'-50.2'. Run#8 50.2'-55.2'. Run#9 55.2-60.2'. Run#10 60.2'-65.2'. Packer Test 45'-65'. Run#11 65.2'-70.2'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	June 6, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech060602
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Rain/PtlyCldy
CONT. REP.		**TEMP.**	48F/60F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Flushing out MW-39D.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford **Signature:** **Date:**

Reviewed By: **Date:**

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	June 5, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech060502
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	8:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlyCldy/PtlyCldy
CONT. REP.		**TEMP.**	60F/78F
SITE PHONE		**WIND DIR.**	SE@2/SE@3

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Installing flush mount well caps at MW-1D, 1I and 40D.
Flushing out MW-38D.
Reaming out MW-36I.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 31, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech053102
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 3:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/PtlySun
CONT. REP.		**TEMP.**	69F/81F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-39I
Overburden is +/- 30'.
Drilled to 18' and found resistance. Will try to drill through w/6" core bit. May have been a piece of steel.
Spoon 18'-20' Wet sand w/some gravel.
Spoon 20'-22' Silt going into course sand, wet.
Spoon 22'-24' Wet, more gravel than sand.
Spoon 24-26' 4" recovery, some rock.
Spoon 26'-28' Wet, shale, grey gravel.
Spoon 28'-30' Wet, some shale, course sand and silt.
Spoon 30'-32' Wet, grey gravel and shale.
Spoon 32'-34' TOR at 33'.
Backfilled with bentite.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 30, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech053002
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/CldyLtRain
CONT. REP.		**TEMP.**	64F/78F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-38I Opening up hole 90'-120'. Expect tar at 95'-100'. Oh, yes tar found at 102'. Completed well construction.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 29, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052902
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	57F/68F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-41D Flushing well Pulling drilling rods. Grouted in approximately 115' of 4" PVC well casing. Open well from 115' to 140'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 28, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052802
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	53F/64F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Reamed out MW-41D Samples came back clean.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 24, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052402
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 2:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/PtlySun
CONT. REP.		**TEMP.**	46F/67F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-38D Roller bit used instead of air hammer. Roller bit to 90'. Grouted in 4" PVC casing.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 23, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052302
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/Sunny
CONT. REP.		**TEMP.**	48F/71F
SITE PHONE		**WIND DIR.**	Calm/W@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-41D Run#18 104.6'-109.6' Run#19 109.6'-114.6' Run#20 114.6'-119.6' Run#21 119.6'-124.6' Packer Test 100'-120' Run#22 124.6'-129.6' Run#23 129.6'-134.6' Run#24 134.6'-139' Packer Test 120'-139' Sampled, will stop at 139' and wait for sample results.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 22, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052202
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	11:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	/Sunny
CONT. REP.		**TEMP.**	/58F
SITE PHONE		**WIND DIR.**	/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-41D Packer Test 40'-60' Clear water, no tar. Packer Test 60'-80' Clear water, no tar. Run#13 79.6'-84.6' Run#14 84.6'-89.6' Run#15 89.6'-94.6' Run#16 94.6'-99.6' Packer Test 80'-100'

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 20, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052002
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	9:50 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/Cldy
CONT. REP.		**TEMP.**	47F/57F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-1I Reaming down from 45' to 75'. While flushing well heavy tar present. Quick recovery of product. URS well probably put this well on their weekly sampling list.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 21, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech052102
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/Cldy
CONT. REP.		**TEMP.**	44F/55F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-41 on Williams Street. While moving drill rig front tire broke through sidewalk pavement. Starting drilling 3' center to center from 6" gas main. 14' to TOR. Set temp casing to 19'.
Run#1 19.2'-24.2' Very fractured and broken rock. Run#2 24.2'-29.6' Some crystal formation. Very broken rock. Run#3 29.6'-34.6' Run#4 34.6'-39.6'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 16, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech051602
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	8:30 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	8:45 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/PtlySun
CONT. REP.		**TEMP.**	442F/68F
SITE PHONE		**WIND DIR.**	Calm/W@3

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Setting temp casing on MW-1I. Last night to 17.5'. Tar at 16.5'. Drilled to 45'. Grouted in 4" PVC pipe to 44.6'.
Back on MW-36D Reaming out 6" casing to 140'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: **Signature:** **Date:**
Raymond Crawford

Reviewed By: **Date:**

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 15, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech051502
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:25 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/PtlySun
CONT. REP.		**TEMP.**	42F/58F
SITE PHONE		**WIND DIR.**	NW@2/NW@3

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-36D
Checked water in well. Came up 1/10" over night.
Run#27 145.9'-150.9'.
Run#28 150.9'-155.9'.
Run#29 155.9'-160.9'.
Packer test 145'-160'. Numerous fractures in Run#29. Water recovery fast. Sending out samples. Waiting for results to continue work on well.

Setting up on MW-1I.

Spoon#1	0'-2'	Sand, pebbles, gravel.
Spoon#2	2'-4'	Dark soil, coal fragments.
Spoon#3	4'-6'	Dark soil, musty smell.
Spoon#4	6'-8'	No recovery.
Spoon#5	8'-10'	Water table, musty, broken rock, sand and gravel.
Spoon#6	10'-11.5'	TOR.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 14, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech051402
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:30 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	LtRain/Cldy
CONT. REP.		**TEMP.**	47F/54F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Set up on MW-36D Run#18 100.9'-105.9'. Run#19 105.9'-110.9'. Run#20 110.9'-115.9'. Run#21 !15.9'-120.9'. Packer test 100'-120'. No water, no sample. Run#22 120.9'-125.9'. Run#23 125.9'-130.9'. Run#24 130.9'-135.9'. Run#25 135.9'-140.9'. Packer test 120'-140'. No water, no sample. Run#26 140.9'-145.9'. Packer test. Problem with pump. Hand pumped well dry.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 13, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech051302
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	10:00 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	LtRain/Rain
CONT. REP.		**TEMP.**	43F/49F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Driller arrived at 2:00 pm and deconned drill rig brought to site.
No drilling activity.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 10, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech051002
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 12:30 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/
CONT. REP.		**TEMP.**	49F/
SITE PHONE		**WIND DIR.**	Calm/

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

De-conned both drilling rigs and all equipment
Drillers left at 12:30 pm.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 9, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech050902
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	51F/62F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		3							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-36D Packer test 80'-100'. Eric was called by URS and told to get off site due to lawsuit brought by property owner.
Grouted top of MW-40D in pm. Pulled casing.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 8, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech050802
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	11:30 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/Cldy
CONT. REP.		**TEMP.**	45F/52F
SITE PHONE		**WIND DIR.**	NW@3/NW@3

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		3							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

De-conning drill rig.
Starting MW-36D. Rock at 5'. Casing to 18.5'.
Run#10 60.9'-65.9'. Packer test 40'-60'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: **Signature:** **Date:**
Raymond Crawford

Reviewed By: **Date:**

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 7, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech050702
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Cldy/Cldy
CONT. REP.		**TEMP.**	56F/72F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		3							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

De-conning drill rig.
Setting up on MW-36D
Pulling casing on MW-39D. Having trouble with keeping 4" PVC well pipe down in well when pulling casing. Finally pulled casing in mid pm.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 6, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech050602
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sunny/PtlySun
CONT. REP.		**TEMP.**	51F/70F
SITE PHONE		**WIND DIR.**	Calm/W@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-38D
Casing set to 150'.

Started boring at 150'.

Run#27 150'-155.1'.
Run#28 155.1'-160.1'.
Run#29 160.1'-165.1'.
Run#30 165.1'-170.1'.
Pumped out water from 150'-170' and sampled.

Done with this well.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	May 1, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech050102
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlyCldy/PtlySun
CONT. REP.		**TEMP.**	33F/50F
SITE PHONE		**WIND DIR.**	Calm/W@1

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-38D Late yesterday came up with tar in core sample at 98.1', 98.5' and 99.3'. Run#21 115.3'-120.3'. Packer test at 105'-115'. Pumping tars. Did not complete pumping down. Run#22 120.3'-124.8'. Run#23 124.8'-130.1'. Run#24 130.1'-134.9'. Run#25 134.9'-140.2'. Run#26 140.2'-145.5'. Packer test. Mineute tar and sheen at 124'-145'.
MW-38D Reaming out well to 150.5'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 30, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech043002
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 4:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:15 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/PtlySun
CONT. REP.		**TEMP.**	38F/48F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-38D
Bore down to 40.3'.
Inner core barrel stuck in outer core barrel. Pulled barrel.
Packer test 20-40'.
Bore quickly filled with water. Took sample. Sulfur odor.
Run#6 40.3'-45.3'.
Run#7 45.3'-50.3'.
Run#8 50.3-55.3'.
Run#9 55.3'-60.3'.
Packer test 40'-60'. Sample taken.
Run#10 60.3'-65.3'.
Run#11 65.3'-70.3'.
Run#12 70.3'-75.3' On Run#12 bore is losing water.
Run#13 75.3'-80.3'.
Packer test 60'-80'. Sample taken.
Run#14 80.3'-85.3'.
Run#15 85.3'-90.3'.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 29, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech042902
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 3:30 pm
DEC ENG.	R. Shick	**ARRIVED**	10:45 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	LtRain/Cldy
CONT. REP.		**TEMP.**	41F/47F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

De-conned rig from Friday's work.
Setting up on MW-38D.
Casing down to 18.5'. Rock at 12.5',

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 26, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech042602
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 4:30 pm
DEC ENG.	R. Shick	**ARRIVED**	9:45 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	Sun/PtlyCldy
CONT. REP.		**TEMP.**	36F/44F
SITE PHONE		**WIND DIR.**	W@1/W@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		1		
URS	1				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-1D
Casing down to 120.2'.
Run#23 118.2'-120.2'
Packer Test 100.0'-120.2'.
Run#24 120.2'-125.2'.
Run#25 125.2'-130.2'.
Run#26 130.2'-135.2'.
Run#27 135.2'-140.2'.
Run#28 140.2'-141.2'.
Run#29 141.2'-146.2'.
Run#30 146.2'-151.2'.
Run#31 151.2'-155.0'.
Pumped off as much water as possible to see what recovery is over weekend.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 25, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech042502
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 3:30 pm
DEC ENG.	R. Shick	**ARRIVED**	7:05 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	American Auger	**WEATHER**	PtlySun/Rain
CONT. REP.		**TEMP.**	41F/48F
SITE PHONE		**WIND DIR.**	W@2/W@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	2				Truck		1		
AA		2							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

MW-39D Casing down to 33'. Packer Test done at 35'-50' 70'-90' 90'-110' No re-charge from 50'-70' Run #17 - 110.4'-115.4' Fault line at 114'. Run #18 - 115.4'-120.4' Run #19 - 120.4'-125.4' Run #20 - 125.4'-130.4' Packer Test done 110'-130' Run #21 - 130.4'-135.4' Run #22 - 135.4'-140.4' Run #23 - 140.4'-145.4' Run #24 - 145.4'-150.4' Packer Test done 130'-150'
Deconning and setting up on MW-1C

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 15, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech041502
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:30 am to 3:30 pm
DEC ENG.	R. Shick	**ARRIVED**	9:40 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	ADT Drilling	**WEATHER**	Cldy/PtlyCldy
CONT. REP.		**TEMP.**	62F/72F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		3							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Driller arrived at 10:40 am.
Measured water level in MW-40D. 72.75' from top of casing. Casing about 1.5' above grade. Will pump out water and allow to return before taking sample.
Pumped out about +/- 6 gallons of water. No evidence of product or odor.
Driller left core tube on other drill rig. Will return home tonite to get. Installed rock cutting rods.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 12, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech041202
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	7:00 am to 3:30 pm
DEC ENG.	R. Shick	**ARRIVED**	7:20 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	ADT Drilling	**WEATHER**	Sunny/Sunny
CONT. REP.		**TEMP.**	42F/57F
SITE PHONE		**WIND DIR.**	Calm/Calm

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
AA	Drilling	
	De-coning	

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig		2		
URS	1				Truck		1		
AA		3							

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

Eric brought me up-to-date: Set 6' casing 40D 26.25' TOR 36D 9' TOR 1D 11' TOR 38D 12' TOR Connected to Anthony Kill 5" into rock 39D 32" TOR
Data logger(4) set up around MW-40D.
MW-40D Air hammer from +/- 30' to 80'. 20' rods with 5.7' above surface. 1st rod would equal 45'. 2nd rod would equal 65'. 3rd rod went down to 80' at 9:16 am. No presence of product or odor were as well 20' away had product at 67'.
De-conned equipment at end of day.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date:

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Bureau of Construction Services

John P. Cahill
Commissioner

DAILY INSPECTION REPORT

SITE NUMBER	5-46-033	**DATE**	April 9, 2002
SITE NAME	Mechanicville MGP.	**REPORT #**	mech040902
LOCATION	Mech'le(cy)Saratoga(cty)	**HRS WORKED**	6:45 am to 12:00 pm
DEC ENG.	R. Shick	**ARRIVED**	7:45 am
DEC PROJ. ENG	G. Cross	**T&A CODE**	B517
CONSULTANT	URS		**AM/PM**
CONTRACTOR	ADT Drilling	**WEATHER**	PtlyCldy/PtlyCldy
CONT. REP.		**TEMP.**	55F/58F
SITE PHONE		**WIND DIR.**	SW@2/SW@2

CONTRACTOR INFORMATION:

	WORK ACTIVITY	**HOURS WORKED**
Mobilizing		

PERSONNEL	**G**	**1**	**2**	**3**	**EQUIP.**	**G**	**1**	**2**	**3**
NYSE&G					Drill rig				
URS	2				Truck				
ADT									

(@) - Hrs used

HEALTH & SAFETY:

Level of protective used - Level D
Is level of protection in conformance with the approved Health & Safety Plan?
Yes ✔ No If no, list the deviation(s).
Are atmospheric monitoring results at an acceptable level? Yes No
Attach a copy of the monitoring log.

DESCRIPTION OF WORK PERFORMED DURING THIS REPORT PERIOD:

URS on site at 9:10 am. URS tech doing normal Tuesday/Friday recovery well sampling. Sampled RH-1S and MW-10I.
Porta-john delivered. Twenty-five reconditioned 55 gallon drums delivered to site.
Driller expected to be on site in pm. Will start drilling on Wednesday in pm.

COMMENTS:

ITEMS OF CONCERN:

Site Visitors	Representing	Entered exclusion zone

Site Representative: Raymond Crawford

Signature:

Date:

Reviewed By:

Date: