Appendix C

Project Photographic Log

Daily Photograph Log for October 30, 2008



Mechanicville MGP RA 001	NYSEG line crew removing power poles.	Direction: E



Mechanicville MGP RA 002	Setup of site trailers.	Direction: NW



Mechanicville MGP RA 003	Setup of site trailers.	Direction: W



Mechanicville MGP RA 004	Testing of Community Air Monitoring.	Direction: NW

Daily Photograph Log for October 31, 2008



Mechanicville MGP RA 005	Removal of power poles.	Direction: E



Mechanicville MGP RA 006	Backfilling of holes from power poles.	Direction: E



Mechanicville MGP RA 007	Backfilling of holes from power poles.	Direction:



Mechanicville MGP RA 008	Stockpiling of stubs of power poles.	Direction:



Mechanicville MGP RA 009	Removal of unused soil storage pad.	Direction:



Mechanicville MGP RA 010	Removal of unused soil storage pad.	Direction:

Daily Photograph Log for November 03, 2008



Mechanicville MGP RA 011	Power lines over Ferris Ln. flagged for visibility.	Direction: W



Mechanicville MGP RA 012	Installing temporary fence panels.	Direction: W



Mechanicville MGP RA 013	Installing temporary fence panels.	Direction: N



Mechanicville MGP RA 014	Power pole anchors that will need to be moved.	Direction: NW



Mechanicville MGP RA 015	Power pole anchors that will need to be moved.	Direction: NW

Daily Photograph Log for November 04, 2008



Mechanicville MGP RA 016	Foggy conditions affecting CAMP.	Direction: E



Mechanicville MGP RA 017	Foggy conditions affecting CAMP.	Direction: E



Mechanicville MGP RA 018	Foggy conditions affecting CAMP.	Direction: E




Mechanicville MGP RA 019	Foggy conditions affecting CAMP.	Direction: E



Mechanicville MGP RA 020	NEYSEG line crew installing	Direction: SE



Mechanicville MGP RA 021	Installation of silt fence.	Direction: NE

	weather station.				
					
Mechanicville MGP RA 022	Installation of silt fence.	Direction: NE	Mechanicville MGP RA 023	Pole anchors that will have to be moved.	Direction: NW
					
Mechanicville MGP RA 024	Pole anchors that will have to be moved.	Direction: NW	Mechanicville MGP RA 025	Pole anchors that will have to be moved.	Direction: NW

					
Mechanicville MGP RA 026	Installation of silt fence.	Direction: E	Mechanicville MGP RA 027	Installation of silt fence.	Direction: W

Daily Photograph Log for November 05, 2008



Mechanicville MGP RA 029	Foggy conditions affecting CAMP.	Direction: SE



Mechanicville MGP RA 031	Removal of existing fencing along Central Ave.	Direction: N



Mechanicville MGP RA 032	Bongiavanni equipment setup.	Direction: SE



Mechanicville MGP RA 034	Bongiavanni equipment setup.	Direction: SE



Mechanicville MGP RA 036	Bongiavanni setting up materials.	Direction: NE



Mechanicville MGP RA 037	Landscaping work along Ferris Ln that may affect CAMP.	Direction: E

					
Mechanicville MGP RA 038	Removal of stone fill along Central Ave.	Direction: N	Mechanicville MGP RA 039	Removal of stone fill along Central Ave.	Direction: N
					
Mechanicville MGP RA 040	Removal of stone fill along Central Ave.	Direction: N	Mechanicville MGP RA 041	Bongiavanni threading sheets together for sizing..	Direction: N
					
Mechanicville MGP RA 026	Sheet pile that encountered contamination.	Direction: N	Mechanicville MGP RA 027	Underground steel tank that was found east of the building.	Direction: S

Daily Photograph Log for November 06, 2008



Mechanicville MGP RA 053	Delivery of steel sheet piles.	Direction: SE



Mechanicville MGP RA 056	Removal of trees and planting boxes along Central Ave.	Direction: N



Mechanicville MGP RA 060	Removal of trees and planting boxes along Central Ave.	Direction: NE



Mechanicville MGP RA 063	Excavation of bank along Central Ave to install sheet piles.	Direction: S



Mechanicville MGP RA 070	Excavation of bank along Central Ave to install sheet piles.	Direction: S



Mechanicville MGP RA 074	Segregation of spent coal material.	Direction: N

					
Mechanicville MGP RA 079	Grading of cut material to level area 3A.	Direction: E	Mechanicville MGP RA 080	EPS pumping liquid from underground steel tank.	Direction:
					
Mechanicville MGP RA 085	Excavation of the underground Steel Tank.	Direction: N	Mechanicville MGP RA 091	Excavation of the underground Steel Tank.	Direction: N
					
Mechanicville MGP RA 093	Excavation of the underground Steel Tank.	Direction: N	Mechanicville MGP RA 099	Decommissioning of the underground Steel Tank.	Direction:

Daily Photograph Log for November 07, 2008



Mechanicville MGP RA 108	Delivery of steel sheet piles.	Direction: SE



Mechanicville MGP RA 109	Steel sheet piles.	Direction: W



Mechanicville MGP RA 111	Grading of area east of building for WWTP.	Direction: NE



Mechanicville MGP RA 113	Grading of excavation area 3A to install sheet piles.	Direction: SE



Mechanicville MGP RA 114	Grading of excavation area 3A to install sheet piles.	Direction: N



Mechanicville MGP RA 115	Grading of excavation area 3A to install sheet piles.	Direction: W

					
Mechanicville MGP RA 118	Grading of cut material to level area 3A.	Direction: NW	Mechanicville MGP RA 119	Survey work to stake out excavation area 3A.	Direction: E
					
Mechanicville MGP RA 120	Survey work to stake out excavation area 3A.	Direction: E	Mechanicville MGP RA 124	Grading of cut material to level area 3A.	Direction: SE
					
Mechanicville MGP RA 126	Grading of cut material to level area 3A.	Direction: NW	Mechanicville MGP RA 131	Decontamination of steel H-pile after spudding to map top of bedrock.	Direction: W

Daily Photograph Log for November 10, 2008



Mechanicville MGP RA 134	Grading of area 3A.	Direction: SE



Mechanicville MGP RA 135	Verizon installing phone lines to trailers.	Direction: S



Mechanicville MGP RA 137	Grading of Ferris Lane in preparation of improving road.	Direction: SW



Mechanicville MGP RA 138	Grading of Ferris Lane in preparation of improving road.	Direction: SW



Mechanicville MGP RA 139	Bongiavanni assembling the whaler for area 3A.	Direction: E



Mechanicville MGP RA 140	Bongiavanni assembling the whaler for area 3A.	Direction: SE

					
Mechanicville MGP RA 141	Connection detail of whaler.	Direction:	Mechanicville MGP RA 142	Bongiavanni assembling the whaler for area 3A.	Direction:
					
Mechanicville MGP RA 144	Sediment monitoring.	Direction: NE	Mechanicville MGP RA 145	Sediment monitoring.	Direction: NE
					
Mechanicville MGP RA 146	Sediment monitoring.	Direction: N	Mechanicville MGP RA 150	Bongiavanni building an access ramp into excavation area 3A.	Direction: SE

Daily Photograph Log for November 11, 2008



Mechanicville MGP RA 154	Grading of area Ferris Lane.	Direction: SW



Mechanicville MGP RA 155	Preparation of sheet piles for sealant.	Direction: NE



Mechanicville MGP RA 156	Compaction of frac tank pad area.	Direction: SW



Mechanicville MGP RA 158	Grading of area Ferris Lane.	Direction: W



Mechanicville MGP RA 160	Compaction of crushed stone on Ferris Lane.	Direction: SW



Mechanicville MGP RA 161	Frac tank pad area compacted in preparation for construction of the pad.	Direction: SW

					
Mechanicville MGP RA 162	Construction of haul road.	Direction: W	Mechanicville MGP RA 163	Compacted crushed stone on Ferris Lane.	Direction: SW
					
Mechanicville MGP RA 166	Temporary sign for NYSDEC contact number.	Direction: W	Mechanicville MGP RA 168	Sealant applied to sheet pile pair.	Direction:
					
Mechanicville MGP RA 174	Liner placed for frac tank pad.	Direction: W	Mechanicville MGP RA 175	Installation of steel sheet piling.	Direction: NE

Daily Photograph Log for November 12, 2008



Mechanicville MGP RA 177	Bank cracking from sheet pile driving operations.	Direction: N



Mechanicville MGP RA 178	Crushed stone being placed for frac tank pad.	Direction: SW



Mechanicville MGP RA 180	Grading of crushed stone in frac tank pad area.	Direction: SW



Mechanicville MGP RA 181	Sheet piles driven on previous day.	Direction: SW



Mechanicville MGP RA 182	Sheetpiles being prepared for sealant.	Direction: NW



Mechanicville MGP RA 183	Grading of crushed stone in frac tank pad area.	Direction: SW

					
Mechanicville MGP RA 184	Completed interior portion of frac tank pad.	Direction: E	Mechanicville MGP RA 186	Bank cracking from sheet pile driving operations.	Direction: N
					
Mechanicville MGP RA 187	Bank cracking from sheet pile driving operations.	Direction: N	Mechanicville MGP RA 189	Bank cracking from sheet pile driving operations.	Direction: N
					
Mechanicville MGP RA 174	Placing of frac tank on pad.	Direction: W	Mechanicville MGP RA 175	Backfilling behind sheet piles.	Direction: N

Daily Photograph Log for November 13, 2008



Mechanicville MGP RA 193	Redriving sheet piles singally.	Direction: E



Mechanicville MGP RA 194	Installing sheet piles.	Direction: SW



Mechanicville MGP RA 197	Cracking from sheet pile driving operations.	Direction: S



Mechanicville MGP RA 198	Cracking from sheet pile driving operations.	Direction: S



Mechanicville MGP RA 199	Sheetpiles being prepared for sealant.	Direction: N



Mechanicville MGP RA 200	Grading of crushed stone in frac tank pad area.	Direction: NW

					
Mechanicville MGP RA 201	Installing sheet piles.	Direction: E	Mechanicville MGP RA 202	Delivery of frac tank.	Direction: N
					
Mechanicville MGP RA 203	Depression formed in Ferris Lane during pile driving operations.	Direction: E	Mechanicville MGP RA 204	Depression formed in Ferris Lane during pile driving operations.	Direction: E
					
Mechanicville MGP RA 205	Sheet piles that have been redriven singally.	Direction: NE	Mechanicville MGP RA 206	Sheet piles that have been redriven singally.	Direction: NE

Daily Photograph Log for November 14, 2008



Mechanicville MGP RA 207	Progress of sheet pile installation.	Direction: E



Mechanicville MGP RA 208	Installing sheet piles.	Direction: S



Mechanicville MGP RA 209	Delivery of frac tank.	Direction: W



Mechanicville MGP RA 210	Installing sheet piles.	Direction: N



Mechanicville MGP RA 211	Installing sheet piles. Note plate welded on to protect leading edge female interlock.	Direction:



Mechanicville MGP RA 212	Installing sheet piles. Note plate welded on to protect leading edge female interlock.	Direction:

					
Mechanicville MGP RA 214	Installing sheet piles.	Direction: SE	Mechanicville MGP RA 220	Installing sheet piles.	Direction:
					
Mechanicville MGP RA 221	Installed sheet piles. Note female interlock is clean.	Direction:	Mechanicville MGP RA 222	Installed sheet piles. Note female interlock is clean.	Direction:
					
Mechanicville MGP RA 223	Sheet pile sealant.	Direction:	Mechanicville MGP RA 224	Installed frac tanks.	Direction: SW

Daily Photograph Log for November 17, 2008



Mechanicville MGP RA 227	Completing the berm around WWTP.	Direction: S



Mechanicville MGP RA 228	Completed berm around WWTP.	Direction: S



Mechanicville MGP RA 229	Completed berm around WWTP.	Direction: W



Mechanicville MGP RA 231	Installing sheet piles.	Direction: N



Mechanicville MGP RA 236	NAPL brought to surface by pile driving.	Direction:



Mechanicville MGP RA 237	NAPL brought to surface by pile driving.	Direction:

					
Mechanicville MGP RA 240	Spraying of biosolve..	Direction: S	Mechanicville MGP RA 242	Cover of NAPL.	Direction:
					
Mechanicville MGP RA 243	NAPL brought to surface by pile driving.	Direction:	Mechanicville MGP RA 244	Backfilling against sheet piles to prevent odor from NAPL.	Direction: E
					
Mechanicville MGP RA 247	NAPL brought to surface by pile driving.	Direction:	Mechanicville MGP RA 250	Backfilling against sheet piles to prevent odor from NAPL.	Direction: E

Daily Photograph Log for November 18, 2008



Mechanicville MGP RA 252	Delivery of Komatsu PC300LC excavator.	Direction: NE	Mechanicville MGP RA 253	Komatsu PC200LC excavator loaded to go offsite.	Direction:



Mechanicville MGP RA 254	Komatsu PC200LC excavator loaded to go offsite.	Direction: NE	Mechanicville MGP RA 255	Fabricated transition sheet pile from Larsen to ball and socket interlock.	Direction: N



Mechanicville MGP RA 256	Fabricated transition sheet pile from Larsen to ball and socket interlock.	Direction:	Mechanicville MGP RA 257	Fabricated transition sheet pile from Larsen to ball and socket interlock.	Direction:

					
Mechanicville MGP RA 258	Installing sheet piles.	Direction: W	Mechanicville MGP RA 259	Installing sheet piles.	Direction: W

Daily Photograph Log for November 19, 2008



Mechanicville MGP RA 260	Preparation of sheet piles for installation.	Direction: NE



Mechanicville MGP RA 261	Preparation of sheet piles for installation.	Direction: NE



Mechanicville MGP RA 262	Preparation of sheet piles for installation.	Direction: SW



Mechanicville MGP RA 263	Preparation of sheet piles for installation.	Direction: SW



Mechanicville MGP RA 264	Delivery of Godwin hydraulic pump.	Direction: NW



Mechanicville MGP RA 265	Delivery of Godwin hydraulic pump.	Direction: NW

					
Mechanicville MGP RA 266	Installation of sheet piles.	Direction: W	Mechanicville MGP RA 267	Installation of sheet piles.	Direction: W
					
Mechanicville MGP RA 268	Installation of sheet piles.	Direction: NE	Mechanicville MGP RA 269	Sampling of water/liquid collected from UST.	Direction: NW
					
Mechanicville MGP RA 270	Installation of sheet piles.	Direction: NE			

Daily Photograph Log for November 20, 2008



Mechanicville MGP RA 271	Preparation of sheet piles for installation.	Direction: NE



Mechanicville MGP RA 272	Sevenson preparing to remove fencing in excavation area 2.	Direction: S



Mechanicville MGP RA 273	Progression of sheet pile installation.	Direction: NW



Mechanicville MGP RA 274	Progression of sheet pile installation.	Direction: E



Mechanicville MGP RA 275	Progression of sheet pile installation.	Direction:



Mechanicville MGP RA 276	Sevenson removing fencing in excavation area 2.	Direction: E

					
Mechanicville MGP RA 277	Installation of sheet piles in area 3A.	Direction: NE	Mechanicville MGP RA 278	Installation of sheet piles in area 3A.	Direction: NE
					
Mechanicville MGP RA 279	Installation of sheet piles in area 3A.	Direction: NE			

Daily Photograph Log for November 21, 2008



Mechanicville MGP RA 280	Installation of sheet piles in excavation area 3A.	Direction: E



Mechanicville MGP RA 281	Completed berm around WWTP.	Direction: N



Mechanicville MGP RA 282	Installation of sheet piles in excavation area 3A.	Direction:



Mechanicville MGP RA 283	Installation of sheet piles in excavation area 3A.	Direction: W

Daily Photograph Log for November 24, 2008



Mechanicville MGP RA 285	Thomas D&B's drill rig being delivered.	Direction: SW



Mechanicville MGP RA 286	Installation of sheet piles in area 3A.	Direction: SE



Mechanicville MGP RA 287	Installation of last sheet pile pair in area 3A.	Direction: NE



Mechanicville MGP RA 288	Installation of last sheet pile pair in area 3A.	Direction: E



Mechanicville MGP RA 292	Last sheet pile pair in area 3A note welded transition of interlocks.	Direction:



Mechanicville MGP RA 293	Toe pin operations.	Direction: SE

					
Mechanicville MGP RA 294	Toe pin operations.	Direction: SE	Mechanicville MGP RA 295	Toe pin operations.	Direction: SE
					
Mechanicville MGP RA 296	Toe pin operations.	Direction: SE	Mechanicville MGP RA 297	Toe pin operations.	Direction: E
					
Mechanicville MGP RA 299	Toe pin operations.	Direction: E	Mechanicville MGP RA 300	Toe pin operations. Note spraying of biosolve for odor.	Direction: E

Daily Photograph Log for November 25, 2008



Mechanicville MGP RA 303	Brush and cut trees being lifted off the bank of area 2.	Direction: NE



Mechanicville MGP RA 304	Toe pinning operations.	Direction: SE



Mechanicville MGP RA 305	Toe pinning operations.	Direction: E



Mechanicville MGP RA 306	Toe pinning operations.	Direction: E

Daily Photograph Log for November 26, 2008



Mechanicville MGP RA 307	Toe pinning operations.	Direction: N



Mechanicville MGP RA 311	Toe pinning operations.	Direction: E



Mechanicville MGP RA 316	Toe pinning operations. Note pin being incerted.	Direction: E




Mechanicville MGP RA 317	Toe pinning operations. Note pin being dropped in.	Direction: E



Mechanicville MGP RA 318	Hole from completed toe pin. Note NAPL in hole.	Direction:



Mechanicville MGP RA 319	Hole from completed toe pin. Note NAPL in hole.	Direction:

					
Mechanicville MGP RA 320	Hole from completed toe pin. Note NAPL in hole.	Direction:	Mechanicville MGP RA 322	Clearing operations along the Anthony Kill.	Direction: E
					
Mechanicville MGP RA 323	Clearing operations along the Anthony Kill.	Direction: E	Mechanicville MGP RA 324	High water in the Anthony Kill.	Direction: E
					
Mechanicville MGP RA 325	High water in the Anthony Kill.	Direction: E	Mechanicville MGP RA 326	High water in the Anthony Kill.	Direction: NW

Daily Photograph Log for December 01, 2008



Mechanicville MGP RA 328	Toe pinning operations. Note the thick diesel smoke from the drill rig.	Direction:	SE



Mechanicville MGP RA 329	Elevated water levels in the Anthony Kill.	Direction:	W



Mechanicville MGP RA 330	Toe pinning operations.	Direction:	E




Mechanicville MGP RA 331	Consolidating brush from area 2.	Direction:	NE



Mechanicville MGP RA 332	Consolidating brush from area 2.	Direction:	NE



Mechanicville MGP RA 333	Cleared are of area 2.	Direction:	N

					
Mechanicville MGP RA 334	Chipping of brush.	Direction: SE	Mechanicville MGP RA 335	Clean up of drilling area.	Direction: NWE
					
Mechanicville MGP RA 336	Clean up of drilling area.	Direction: E	Mechanicville MGP RA 337	Chipping of brush.	Direction: E

Daily Photograph Log for December 02, 2008



Mechanicville MGP RA 338	Chipping of brush.	Direction: W



Mechanicville MGP RA 339	Rip-rap placed as diverter in the Anthony Kill.	Direction: N

Daily Photograph Log for December 03, 2008



Mechanicville MGP RA 340	Removal of decorative trees for excavation area 3A.	Direction: E



Mechanicville MGP RA 341	Removal of decorative trees for excavation area 3A.	Direction: E



Mechanicville MGP RA 342	Installation of toe pins in area 3A.	Direction: W



Mechanicville MGP RA 343	Decommissioning of 1550 HDPE tank.	Direction: W



Mechanicville MGP RA 344	Turbidity curtain installed along excavation area 2.	Direction: W



Mechanicville MGP RA 345	Turbidity curtain installed along excavation area 2.	Direction: W

					
Mechanicville MGP RA 346	Decommissioning of 1550 HDPE tank.	Direction: NW	Mechanicville MGP RA 348	Grading of Ferris Lane for truck route.	Direction: E
					
Mechanicville MGP RA 349	Toe pin operations.	Direction: W	Mechanicville MGP RA 350	Burring of sediment from poly tank inside of excavation area 3A.	Direction: N
					
Mechanicville MGP RA 351	Burring of sediment from poly tank inside of excavation area 3A.	Direction: N	Mechanicville MGP RA 352	Grading of Ferris Lane for truck route.	Direction: W

Daily Photograph Log for December 04, 2008



Mechanicville MGP RA 353	Installation of toe pins on area 3A.	Direction: E	Mechanicville MGP RA 354	Installation of toe pins on area 3A.	Direction: E



Mechanicville MGP RA 355	Placing of material from UST removal in area 3A for future treatment at ESMI.	Direction: W	Mechanicville MGP RA 356	Placing of material from UST removal in area 3A for future treatment at ESMI.	Direction: W



Mechanicville MGP RA 357	Removal of sampling tubing from monitor wells.	Direction: W	Mechanicville MGP RA 358	Decommissioning of deep monitor wells in excavation areas.	Direction: W

					
Mechanicville MGP RA 359	Decommissioning of deep monitor wells in excavation areas.	Direction: NW	Mechanicville MGP RA 360	Decommissioning of deep monitor wells in excavation areas.	Direction: E
					
Mechanicville MGP RA 361	Decommissioning of deep monitor wells in excavation areas.	Direction: W	Mechanicville MGP RA 362	Decommissioning of deep monitor wells in excavation areas.	Direction: N

Daily Photograph Log for December 05, 2008



Mechanicville MGP RA 340	Installation of toe pins in excavation area 3A.	Direction: NW



Mechanicville MGP RA 341	Installation of toe pins in excavation area 3A.	Direction: E



Mechanicville MGP RA 342	Decommissioned deep bedrock monitor well inside of holder.	Direction:



Mechanicville MGP RA 343	Decommissioned deep bedrock monitor well inside of holder.	Direction:

Daily Photograph Log for December 08, 2008



Mechanicville MGP RA 367	Construction of haul road.	Direction: S



Mechanicville MGP RA 369	Construction of haul road.	Direction: SE



Mechanicville MGP RA 370	Installation of toe pins in area 3A.	Direction: SE



Mechanicville MGP RA 371	Adjusting turbidity curtain.	Direction: NW



Mechanicville MGP RA 372	Adjusting turbidity curtain.	Direction: NW



Mechanicville MGP RA 374	Installation of silt fence along area 2.	Direction: N

					
Mechanicville MGP RA 375	Installation of silt fence along area 2.	Direction: NW	Mechanicville MGP RA 376	Installation of exclusion zone fencing.	Direction: E
					
Mechanicville MGP RA 377	Installation of silt fence along area 2.	Direction: NW	Mechanicville MGP RA 378	Installation of silt fence along area 2.	Direction: E
					
Mechanicville MGP RA 379	Burring of sediment from poly tank inside of excavation area 3A.	Direction: S	Mechanicville MGP RA 380	Grading of Ferris Lane for truck route.	Direction: W

Daily Photograph Log for December 09, 2008

					
Mechanicville MGP RA 382	Excavation and load out of material from excavation area 2.	Direction: E	Mechanicville MGP RA 383	Excavation of material from excavation area 2.	Direction: NE
					
Mechanicville MGP RA 384	Excavation of material from excavation area 2.	Direction: NE	Mechanicville MGP RA 385	Excavation of material from excavation area 2.	Direction: E
					
Mechanicville MGP RA 387	Excavation of material from excavation area 2.	Direction: NE	Mechanicville MGP RA 388	Excavation of material from excavation area 2.	Direction: NE

					
Mechanicville MGP RA 389	Excavation of material from excavation area 2.	Direction: NE	Mechanicville MGP RA 390	Excavation of material from excavation area 2.	Direction: NE
					
Mechanicville MGP RA 391	Installation of toe pins in area 3A.	Direction: E	Mechanicville MGP RA 392	Excavation of material from excavation area 2.	Direction: NE
					
Mechanicville MGP RA 393	Excavation of material from excavation area 2.	Direction: NE	Mechanicville MGP RA 394	Installation of toe pins in area 3A.	Direction: N

Daily Photograph Log for December 10, 2008



Mechanicville MGP RA 396	Water collected in excavation area 2.	Direction: N



Mechanicville MGP RA 397	Setting of sump and Godwin pump in excavation area 2.	Direction: N



Mechanicville MGP RA 398	Setting of sump and Godwin pump in excavation area 2.	Direction: N




Mechanicville MGP RA 399	Excavation of material from excavation area 2.	Direction: E



Mechanicville MGP RA 400	Excavation of material from excavation area 2.	Direction: E



Mechanicville MGP RA 401	Excavation of material from excavation area 2.	Direction: E

					
Mechanicville MGP RA 402	Resetting of sump and pump in excavation area 2.	Direction: NE	Mechanicville MGP RA 403	End of the day cover of excavation area 2.	Direction: NW
					
Mechanicville MGP RA 406	End of the day cover of excavation area 2.	Direction: N	Mechanicville MGP RA 407	End of the day cover of excavation area 2.	Direction: NE
					
Mechanicville MGP RA 408	Installation of toe pins in area 3A.	Direction: NE	Mechanicville MGP RA 409	Installation of toe pins in area 3A.	Direction: NE

Daily Photograph Log for December 11, 2008



Mechanicville MGP RA 410	Excavation progress in excavation area 2.	Direction: N



Mechanicville MGP RA 411	Excavation progress in excavation area 2.	Direction: N




Mechanicville MGP RA 412	Excavation progress in excavation area 2.	Direction: N




Mechanicville MGP RA 413	Tar saturated material in excavation area 2 along Anthony Kill.	Direction: E



Mechanicville MGP RA 415	Southwest corner of excavation area 2A. Note clean IRM backfill above bedrock.	Direction: E



Mechanicville MGP RA 417	Western sidewall of excavation area 2. Note tar stained layer above soft bedrock.	Direction: E

					
Mechanicville MGP RA 418	Western sidewall of excavation area 2. Note tar stained layer above soft bedrock.	Direction: NE	Mechanicville MGP RA 420	Western sidewall of excavation area 2. Note crushed brick layer above tar stained layer.	Direction: NW
					
Mechanicville MGP RA 423	Southwest corner of excavation area 2A. Note clean IRM backfill above bedrock.	Direction: N	Mechanicville MGP RA 427	South sidewall of area 2A. Note void in bedrock.	Direction: NE
					
Mechanicville MGP RA 429	Western sidewall of area 2 covered with poly-sheeting.	Direction: NE	Mechanicville MGP RA 435	Backfilling of southwest corner of area 2A.	Direction: NE

Daily Photograph Log for December 12, 2008



Mechanicville MGP RA 440	Toe pin operations shut down due to icy conditions.	Direction: E



Mechanicville MGP RA 441	Excavation progress in excavation area 2.	Direction: E



Mechanicville MGP RA 442	Excavation progress in excavation area 2.	Direction: NE



Mechanicville MGP RA 443	Excavation progress in excavation area 2. Note high water in Anthony Kill.	Direction: NE



Mechanicville MGP RA 444	Icy conditions onsite due to ice storm overnight.	Direction: NW



Mechanicville MGP RA 445	Load out of material from excavation area 2.	Direction: E

					
Mechanicville MGP RA 446	Icy conditions onsite due to ice storm overnight.	Direction: NE	Mechanicville MGP RA 447	Excavation progress in excavation area 2.	Direction: NE
					
Mechanicville MGP RA 449	Excavation progress in excavation area 2. Note tar saturated layer continuing south of proposed limits.	Direction: SE	Mechanicville MGP RA 450	Excavation progress in excavation area 2. Note tar saturated layer continuing south of proposed limits.	Direction: SE
					
Mechanicville MGP RA 451	Icy conditions onsite due to ice storm overnight.	Direction: W	Mechanicville MGP RA 453	Load out of material from excavation area 2.	Direction: E

Daily Photograph Log for December 15, 2008



Mechanicville MGP RA 455	Water in excavation area 2 from weekend.	Direction: NE



Mechanicville MGP RA 457	Toe pin operations in excavation area 3A.	Direction: N



Mechanicville MGP RA 458	Load out of material from excavation area 2.	Direction: E



Mechanicville MGP RA 459	Load out of material from excavation area 2.	Direction: E



Mechanicville MGP RA 460	Excavation operations in area 2.	Direction: NE



Mechanicville MGP RA 463	Excavation operations in area 2.	Direction: W

					
Mechanicville MGP RA 465	Establishing grade of cut in area 2B.	Direction: S	Mechanicville MGP RA 466	Odor control during excavations.	Direction: SW
					
Mechanicville MGP RA 471	Excavation operations in area 2.	Direction: SW	Mechanicville MGP RA 472	Excavation operations in area 2.	Direction: E
					
Mechanicville MGP RA 473	Excavation operations in area 2.	Direction: E	Mechanicville MGP RA 477	Cover of excavation and stockpile in area 2.	Direction: NE

Daily Photograph Log for December 16, 2008



Mechanicville MGP RA 479	South sidewall of area 2A backfilled with IRM backfill.	Direction: NE



Mechanicville MGP RA 482	Dam of debris from ice storm under railway trestle.	Direction: N



Mechanicville MGP RA 487	Dam of debris from ice storm under railway trestle.	Direction: E



Mechanicville MGP RA 489	Thomas Drilling and Blasting drill rig decontaminated.	Direction: E



Mechanicville MGP RA 490	West sidewall of area 2 with IRM backfill.	Direction: NE



Mechanicville MGP RA 491	West sidewall of area 2 with IRM backfill.	Direction: W

					
Mechanicville MGP RA 495	Thomas Drilling and Blasting drill rig decontaminated.	Direction: S	Mechanicville MGP RA 500	Sevenson 220 excavator being decon'd for swap out.	Direction: SW
					
Mechanicville MGP RA 504	Excavation operations in area 2.	Direction: SW	Mechanicville MGP RA 509	Excavation operations in area 2.	Direction: E
					
Mechanicville MGP RA 512	Excavation operations in area 2. Note tar under concrete pad does not penetrate bedrock.	Direction: E	Mechanicville MGP RA 515	ESMI backfill in area 2 along western sidewall.	Direction: NE

Daily Photograph Log for December 17, 2008



Mechanicville MGP RA 517	Load out of material from excavation area 2A.	Direction: E



Mechanicville MGP RA 518	Load out of material from excavation area 2A.	Direction: NE



Mechanicville MGP RA 523	Load of material from area 2A covered with poly-sheeting.	Direction: SE



Mechanicville MGP RA 525	Excavations in excavation area 3A.	Direction: S



Mechanicville MGP RA 527	Excavations in excavation area 3A.	Direction: S




Mechanicville MGP RA 528	Excavations in excavation area 3A.	Direction: N

					
Mechanicville MGP RA 531	Excavations in excavation area 3A.	Direction: NE	Mechanicville MGP RA 533	Excavations in excavation area 3A.	Direction: SW
					
Mechanicville MGP RA 535	Excavations in excavation area 2B.	Direction: S	Mechanicville MGP RA 536	Excavations in excavation area 2B.	Direction:
					
Mechanicville MGP RA 537	Excavations in excavation area 2B.	Direction:	Mechanicville MGP RA 538	Excavations in excavation area 2B.	Direction:

Daily Photograph Log for December 18, 2008

					
Mechanicville MGP RA 543	Pipes exposed in south sidewall of area 2A.	Direction: S	Mechanicville MGP RA 545	Pipes exposed in south sidewall of area 2A.	Direction: SE
					
Mechanicville MGP RA 547	Pipes exposed in south sidewall of area 2A.	Direction: S	Mechanicville MGP RA 549	Excavations in excavation area 3A.	Direction: NE
					
Mechanicville MGP RA 551	Final extent of deep excavation in southeast corner of area 2A Note bedrock sidewalls.	Direction: S	Mechanicville MGP RA 552	Final extent of deep excavation in southeast corner of area 2A Note tar stain above bedrock.	Direction: SE

					
Mechanicville MGP RA 553	Hard bedrock ridge at bottom of south end of area 2A.	Direction: S	Mechanicville MGP RA 558	IRM backfill from area 3A being placed in area 2A.	Direction: W
					
Mechanicville MGP RA 559	IRM backfill from area 3A being placed in area 2A.	Direction: NW	Mechanicville MGP RA 561	IRM backfill from area 3A being placed in area 2A.	Direction: NW
					
Mechanicville MGP RA 562	Excavation operations in area 3A of IRM backfill.	Direction: N	Mechanicville MGP RA 563	Excavation operations in area 3A of IRM backfill.	Direction: NE

Daily Photograph Log for December 19, 2008



Mechanicville MGP RA 564	Load out of material from excavation area 2A.	Direction: E



Mechanicville MGP RA 565	Load out of material from excavation area 2A.	Direction: SE



Mechanicville MGP RA 566	Load out of material from excavation area 2A.	Direction: SE



Mechanicville MGP RA 567	Excavations in excavation area 3A.	Direction: N



Mechanicville MGP RA 568	Site prepared for the weekend.	Direction: E



Mechanicville MGP RA 569	Site prepared for the weekend.	Direction: E

					
Mechanicville MGP RA 570	Site prepared for the weekend.	Direction: SE			

Daily Photograph Log for December 22, 2008



Mechanicville MGP RA 571	Snow conditions onsite.	Direction: E



Mechanicville MGP RA 572	Snow conditions onsite.	Direction: NE



Mechanicville MGP RA 573	Snow conditions onsite.	Direction: E



Mechanicville MGP RA 574	Snow conditions onsite.	Direction: NE



Mechanicville MGP RA 575	Snow conditions onsite.	Direction: NW



Mechanicville MGP RA 576	Snow conditions onsite.	Direction: W

					
Mechanicville MGP RA 577	Hard bedrock ridge at bottom of south end of area 2A.	Direction: N	Mechanicville MGP RA 578	IRM backfill from area 3A being placed in area 2A.	Direction: NE
					
Mechanicville MGP RA 579	IRM backfill from area 3A being placed in area 2A.	Direction: E	Mechanicville MGP RA 580	IRM backfill from area 3A being placed in area 2A.	Direction: E

Daily Photograph Log for December 23, 2008



Mechanicville MGP RA 581	Load out of material from excavation area 3A.	Direction: NW



Mechanicville MGP RA 582	Load out of material from excavation area 3A.	Direction: W



Mechanicville MGP RA 583	Excavations in area 3A.	Direction:



Mechanicville MGP RA 584	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 585	Load out of material from excavation area 3A.	Direction: NW



Mechanicville MGP RA 586	Excavation area 3A.	Direction: N

Daily Photograph Log for December 24, 2008



Mechanicville MGP RA 587	Excavation and load out of material from excavation area 3A.	Direction: SW	Mechanicville MGP RA 588	Excavation and load out of material from excavation area 3A.	Direction: S



Mechanicville MGP RA 589	Excavation and load out of material from excavation area 3A.	Direction: SW	Mechanicville MGP RA 590	Excavation and load out of material from excavation area 3A.	Direction: W



Mechanicville MGP RA 591	Excavation of material in excavation area 3A.	Direction: SE	Mechanicville MGP RA 592	Excavation of material in excavation area 3A.	Direction: NW

Daily Photograph Log for December 29, 2008



Mechanicville MGP RA 593	Delivery of “Super Sack” sandbags..	Direction: NE



Mechanicville MGP RA 596	Wet conditions in excavation area 3A.	Direction: N



Mechanicville MGP RA 597	Wet conditions in excavation area 2A.	Direction: N



Mechanicville MGP RA 598	Wet conditions in excavation area 2A.	Direction: N



Mechanicville MGP RA 601	Excavations for installation of dewatering sump in area 3A.	Direction: N



Mechanicville MGP RA 602	Excavations for installation of dewatering sump in area 3A.	Direction: NW

					
Mechanicville MGP RA 603	Excavations for installation of dewatering sump in area 3A.	Direction: NW	Mechanicville MGP RA 606	IRM backfill from area 3A being placed in area 2A.	Direction: NW
					
Mechanicville MGP RA 607	IRM backfill from area 3A being placed in area 2A.	Direction: NW	Mechanicville MGP RA 613	Progress of excavations in area 3A.	Direction: NW
					
Mechanicville MGP RA 617	Excavation operations in area 3A.	Direction: E	Mechanicville MGP RA 625	Delivery of mini-excavator, jersey barriers and sump basket..	Direction: E

Daily Photograph Log for December 30, 2008



Mechanicville MGP RA 626	Setup of load out operations.	Direction: E



Mechanicville MGP RA 627	White material in area 3A.	Direction: S



Mechanicville MGP RA 628	White material in area 3A.	Direction: SE



Mechanicville MGP RA 629	Dewatering sump in area 3A.	Direction: N



Mechanicville MGP RA 630	Dewatering sump in area 3A.	Direction: N



Mechanicville MGP RA 631	Dewatering sump in area 3A.	Direction: N

					
Mechanicville MGP RA 632	Temporary dewatering sump inside of gas holder.	Direction: W	Mechanicville MGP RA 633	Temporary dewatering sump inside of gas holder.	Direction: W
					
Mechanicville MGP RA 634	Cover of stockpiled material in area 3A.	Direction: W	Mechanicville MGP RA 635	Cover of stockpiled material in area 3A.	Direction: W
					
Mechanicville MGP RA 636	Cover of stockpiled material and excavations in area 3A.	Direction: N	Mechanicville MGP RA 637	Cover of stockpiled material and excavations in area 3A.	Direction: NE

Daily Photograph Log for December 31, 2008



Mechanicville MGP RA 639	Excavation and load out of material from area 3A.	Direction: NE	Mechanicville MGP RA 640	Excavation and load out of material from area 3A.	Direction: NW



Mechanicville MGP RA 641	Snowy conditions on site.	Direction: W	Mechanicville MGP RA 642	Snowy conditions on site.	Direction: NE



Mechanicville MGP RA 644	Snowy conditions on site.	Direction: N	Mechanicville MGP RA 646	Excavation and load out of material from area 3A.	Direction: SW

					
Mechanicville MGP RA 647	Snowy conditions on site.	Direction: NE	Mechanicville MGP RA 648	Cover of stockpiled material in area 3A.	Direction: N
					
Mechanicville MGP RA 649	Snowy conditions on site.	Direction: NE	Mechanicville MGP RA 650	Cover of stockpiled material in area 3A.	Direction: W
					
Mechanicville MGP RA 651	Cover of stockpiled material in area 3A.	Direction: NW	Mechanicville MGP RA 652	Cover of stockpiled material in area 3A.	Direction: NW

Daily Photograph Log for January 05, 2009



Mechanicville MGP RA 653	Excavation in area 3A.	Direction: SE



Mechanicville MGP RA 655	Water management in area 2A.	Direction: NE



Mechanicville MGP RA 656	Excavation in area 3A.	Direction: N



Mechanicville MGP RA 657	Excavation in area 3A.	Direction: NW




Mechanicville MGP RA 660	Excavation in area 3A.	Direction: SE



Mechanicville MGP RA 662	Excavation in area 3A.	Direction: E

					
Mechanicville MGP RA 663	Excavation in area 3A.	Direction: NE	Mechanicville MGP RA 665	Excavation in area 3A.	Direction: NE
					
Mechanicville MGP RA 668	Water management in area 3A.	Direction: N	Mechanicville MGP RA 669	Water management in area 3A.	Direction: N
					
Mechanicville MGP RA 670	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 671	Apparent upwelling of water in area 3A.	Direction: SE

Daily Photograph Log for January 06, 2009



Mechanicville MGP RA 680	Load out of material from area 3A.	Direction: S



Mechanicville MGP RA 681	Load out of material from area 3A.	Direction: SE



Mechanicville MGP RA 682	Load out of material from area 3A.	Direction: E



Mechanicville MGP RA 684	Excavation in area 3A.	Direction: N



Mechanicville MGP RA 685	Excavation in area 3A.	Direction: N



Mechanicville MGP RA 686	Excavation in area 3A.	Direction: N

					
Mechanicville MGP RA 687	Excavation in area 3A.	Direction: NE	Mechanicville MGP RA 688	Excavation in area 3A.	Direction: N
					
Mechanicville MGP RA 689	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 690	Excavation in area 3A.	Direction: NE
					
Mechanicville MGP RA 693	Collection of WWTP Effluent Batch 1.	Direction: E	Mechanicville MGP RA 694	Collection of WWTP Effluent Batch 1.	Direction: W

Daily Photograph Log for January 07, 2009



Mechanicville MGP RA 696	Excavation in area 3A.	Direction: W



Mechanicville MGP RA 697	Excavation in area 3A.	Direction: NW



Mechanicville MGP RA 699	Excavation in area 3A.	Direction: N



Mechanicville MGP RA 700	Excavation in area 3A.	Direction: SE



Mechanicville MGP RA 701	Excavation in area 3A.	Direction: S



Mechanicville MGP RA 703	Excavation in area 3A.	Direction: E

					
Mechanicville MGP RA 704	Installation of the upper whaler in area 3A.	Direction: SW	Mechanicville MGP RA 706	Installation of the upper whaler in area 3A.	Direction: S
					
Mechanicville MGP RA 707	Installation of the upper whaler in area 3A.	Direction: NE	Mechanicville MGP RA 709	Installation of the upper whaler in area 3A.	Direction: NE
					
Mechanicville MGP RA 712	Installation of the upper whaler in area 3A.	Direction: SW	Mechanicville MGP RA 713	Installation of the upper whaler in area 3A.	Direction: SW

Daily Photograph Log for January 08, 2009



Mechanicville MGP RA 714	Excavation in area 2.	Direction: W



Mechanicville MGP RA 723	Preparations in area 2 for coffer dam construction.	Direction: NW



Mechanicville MGP RA 724	Construction of coffer dam in area 2.	Direction: N



Mechanicville MGP RA 725	Construction of coffer dam in area 2.	Direction: SE



Mechanicville MGP RA 726	Excavation in area 3A.	Direction: S



Mechanicville MGP RA 727	Construction of coffer dam in area 2.	Direction: E

					
Mechanicville MGP RA 729	Excavation in area 3A.	Direction: SW	Mechanicville MGP RA 730	Excavation in area 3A.	Direction: S
					
Mechanicville MGP RA 731	Excavation in area 3A.	Direction: NE	Mechanicville MGP RA 733	Installation of the upper whaler in area 3A.	Direction: NE
					
Mechanicville MGP RA 739	Installation of the upper whaler in area 3A.	Direction: SW	Mechanicville MGP RA 744	Coffer dam in area 2.	Direction: SW

Daily Photograph Log for January 09, 2009



Mechanicville MGP RA 745	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 746	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 747	Excavations in area 3A.	Direction: W



Mechanicville MGP RA 750	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 751	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 752	Excavations in area 3A.	Direction: W

					
Mechanicville MGP RA 753	Excavations in area 3A.	Direction: SW	Mechanicville MGP RA 754	Excavation in area 2.	Direction: NE
					
Mechanicville MGP RA 755	Excavation in area 2.	Direction: NE	Mechanicville MGP RA 756	Installation of the upper whaler in area 2.	Direction: E
					
Mechanicville MGP RA 758	Demolition of the holder foundation in area 3A.	Direction: E	Mechanicville MGP RA 759	Demolition of the holder foundation in area 3A.	Direction: E

Daily Photograph Log for January 12, 2009



Mechanicville MGP RA 760	Conditions in area 3A.	Direction: NE



Mechanicville MGP RA 761	Load out of material from area 3A.	Direction: NW



Mechanicville MGP RA 762	Demolition of the holder foundation in area 3A.	Direction: N



Mechanicville MGP RA 765	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 767	Load out of material from area 3A.	Direction: NW



Mechanicville MGP RA 768	Excavations in area 3A.	Direction: E

					
Mechanicville MGP RA 769	Excavations in area 3A.	Direction: E	Mechanicville MGP RA 771	Load out of material from area 3A.	Direction: SE
					
Mechanicville MGP RA 772	Excavation in area 3A.	Direction: E	Mechanicville MGP RA 773	Excavation in area 3A.	Direction: N
					
Mechanicville MGP RA 774	Excavation in area 3A.	Direction: W	Mechanicville MGP RA 775	Excavation in area 3A.	Direction: S

Daily Photograph Log for January 13, 2009



Mechanicville MGP RA 779	Load out of material from area 3A.	Direction: SE



Mechanicville MGP RA 781	Amendment of soils in area 3A.	Direction: NW



Mechanicville MGP RA 782	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 783	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 784	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 785	Excavations in area 3A.	Direction: E

					
Mechanicville MGP RA 787	Excavations in area 3A.	Direction: W	Mechanicville MGP RA 790	Excavations in area 3A.	Direction: S
					
Mechanicville MGP RA 791	Excavation in area 3A.	Direction: W	Mechanicville MGP RA 792	Excavation in area 3A.	Direction: E
					
Mechanicville MGP RA 794	Excavation in area 3A.	Direction: E	Mechanicville MGP RA 797	Excavation and water management in area 3A.	Direction: N

Daily Photograph Log for January 14, 2009



Mechanicville MGP RA 798	Load out of material from area 3A.	Direction: S



Mechanicville MGP RA 800	Installation of Effluent pipe for WWTP.	Direction: E



Mechanicville MGP RA 801	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 802	Excavations in area 3A.	Direction: S



Mechanicville MGP RA 803	Amendment of soils in area 3A.	Direction: SW



Mechanicville MGP RA 805	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 806	Amendment of soils in area 3A.	Direction: W



Mechanicville MGP RA 807	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 808	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 814	Load out of material from area 3A.	Direction: NW



Mechanicville MGP RA 815	Excavation in area 3A.	Direction: W



Mechanicville MGP RA 816	Installation of Effluent pipe for WWTP.	Direction: E

Daily Photograph Log for January 15, 2009



Mechanicville MGP RA 817	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 819	Amendment of soils in area 3A.	Direction: SE



Mechanicville MGP RA 820	Load out of material from area 3A.	Direction: W



Mechanicville MGP RA 821	Delivery of Calciment for soil amendment	Direction: NE



Mechanicville MGP RA 823	Amendment of soils in area 3A.	Direction: NE



Mechanicville MGP RA 824	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 826	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 827	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 829	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 832	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 833	Excavation in area 3A.	Direction: E



Mechanicville MGP RA 835	Excavations in area 3A.	Direction: E

Daily Photograph Log for January 16, 2009



Mechanicville MGP RA 836	Load out of material from area 3A.	Direction: SE



Mechanicville MGP RA 837	Load out of material from area 3A.	Direction: E



Mechanicville MGP RA 838	Ice-fog conditions onsite.	Direction: E



Mechanicville MGP RA 839	Ice-fog conditions onsite.	Direction: SE



Mechanicville MGP RA 840	Clearing of ice-fog conditions onsite.	Direction: S



Mechanicville MGP RA 841	Clearing of ice-fog conditions onsite.	Direction: E

					
Mechanicville MGP RA 842	Ice formed from biosolve spray in area 3A.	Direction: E	Mechanicville MGP RA 843	Excavations in area 3A.	Direction: E
					
Mechanicville MGP RA 844	Excavations in area 3A covered with poly-sheeting.	Direction: SE	Mechanicville MGP RA 845	Excavations in area 3A covered with poly-sheeting.	Direction: SE
					
Mechanicville MGP RA 846	Excavations in area 3A covered with poly-sheeting.	Direction: E			

Daily Photograph Log for January 19, 2009



Mechanicville MGP RA 847	Delivery of Calciment for soil amendment.	Direction: N



Mechanicville MGP RA 849	Excavations and load out of material from area 3A.	Direction: W



Mechanicville MGP RA 850	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 851	Excavations of grouted material in area 3A.	Direction:



Mechanicville MGP RA 853	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 854	Excavations in area 3A.	Direction: E

					
Mechanicville MGP RA 855	Excavations in area 3A.	Direction: E	Mechanicville MGP RA 858	Excavations in area 3A.	Direction: NE
					
Mechanicville MGP RA 859	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 860	Collection of WWTP Effluent Batch 3 sample.	Direction:
					
Mechanicville MGP RA 861	Collection of WWTP Effluent Batch 3 sample.	Direction:	Mechanicville MGP RA 862	Collection of WWTP Effluent Batch 3 sample.	Direction:

Daily Photograph Log for January 20, 2009



Mechanicville MGP RA 863	Load out of material from area 3A.	Direction: SE



Mechanicville MGP RA 864	Excavations of the center of the holder foundation – "Dumpling".	Direction: E



Mechanicville MGP RA 865	Excavations of the center of the holder foundation – "Dumpling".	Direction: E



Mechanicville MGP RA 866	Excavations of the center of the holder foundation – "Dumpling".	Direction:



Mechanicville MGP RA 867	Excavations of the "Dumpling".	Direction: SE



Mechanicville MGP RA 868	Excavations of the "Dumpling".	Direction:

					
Mechanicville MGP RA 869	Excavations of the “Dumpling”.	Direction:	Mechanicville MGP RA 870	Excavations of the “Dumpling”.	Direction:
					
Mechanicville MGP RA 871	Excavations of the “Dumpling”.	Direction:			

Daily Photograph Log for January 21, 2009



Mechanicville MGP RA 872	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 873	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 874	Excavations in area 3A.	Direction: W



Mechanicville MGP RA 875	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 876	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 877	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 878	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 879	Excavations in area 3A.	Direction: SE
					
Mechanicville MGP RA 880	Excavations in area 3A.	Direction: E	Mechanicville MGP RA 881	Excavations in area 3A.	Direction: SE

Daily Photograph Log for January 22, 2009



Mechanicville MGP RA 883	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 885	Water treatment.	Direction:



Mechanicville MGP RA 886	Water treatment.	Direction:



Mechanicville MGP RA 889	Odor control in area 3A.	Direction: N



Mechanicville MGP RA 890	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 891	Excavations in area 3A.	Direction: SW

					
Mechanicville MGP RA 895	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 897	Excavations in area 3A.	Direction: NW
					
Mechanicville MGP RA 898	Excavations in area 3A.	Direction: SW	Mechanicville MGP RA 902	Installation of blocking in lower whaler in area 3A.	Direction: NW
					
Mechanicville MGP RA 903	Upwelling of groundwater through bedrock at west edge of area 3A.	Direction: N	Mechanicville MGP RA 935	Area of contamination continuing outside of area 3A to the west.	Direction: NW


Daily Photograph Log for January 23, 2009



Mechanicville MGP RA 942	Excavations in area 3A.	Direction: SW



Mechanicville MGP RA 943	Excavations in area 3A.	Direction: W



Mechanicville MGP RA 946	Upwelling of groundwater through bedrock at west edge of area 3A.	Direction: SW



Mechanicville MGP RA 948	Upwelling of groundwater through bedrock at west edge of area 3A.	Direction: E



Mechanicville MGP RA 949	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 951	Soil amendment in area 3A.	Direction: E

					
Mechanicville MGP RA 953	Soil amendment in area 3A.	Direction: NE	Mechanicville MGP RA 956	Soil amendment in area 3A.	Direction: SE
					
Mechanicville MGP RA 957	Transfer of IRM backfill to area 2.	Direction: NW	Mechanicville MGP RA 959	Excavations in area 3A.	Direction: E
					
Mechanicville MGP RA 960	Upwelling of groundwater through bedrock at west edge of area 3A.	Direction: S	Mechanicville MGP RA 965	Stockpiling of amended soils in area 3A.	Direction: S

Daily Photograph Log for January 26, 2009



Mechanicville MGP RA 968	Ice conditions in the Anthony Kill.	Direction: NE



Mechanicville MGP RA 969	Ice conditions in the Anthony Kill.	Direction: NW



Mechanicville MGP RA 970	Ice conditions in area 3A.	Direction: S



Mechanicville MGP RA 971	Ice conditions in area 3A.	Direction: S



Mechanicville MGP RA 976	Demolition of the holder foundation in area 3A.	Direction: W



Mechanicville MGP RA 978	Excavations in area 3A.	Direction: SE

					
Mechanicville MGP RA 979	Demolition of the holder foundation in area 3A.	Direction: E	Mechanicville MGP RA 980	Demolition of the holder foundation in area 3A.	Direction: S
					
Mechanicville MGP RA 981	Demolition of the holder foundation in area 3A.	Direction: SE	Mechanicville MGP RA 983	Demolition of the holder foundation in area 3A.	Direction: S
					
Mechanicville MGP RA 987	Demolition of the holder foundation in area 3A.	Direction: W	Mechanicville MGP RA 988	Demolition of the holder foundation in area 3A.	Direction: W

Daily Photograph Log for January 27, 2009



Mechanicville MGP RA 990	Water management in area 2.	Direction: NW



Mechanicville MGP RA 992	Demolition of the holder foundation in area 3A.	Direction: E



Mechanicville MGP RA 993	Excavations in area 3A.	Direction: N




Mechanicville MGP RA 995	Excavations in area 2 along the Anthony Kill.	Direction: W



Mechanicville MGP RA 996	Excavations in area 2 along the Anthony Kill.	Direction: W



Mechanicville MGP RA 997	Backfilling in area 2 along the Anthony Kill.	Direction: S

					
Mechanicville MGP RA 998	Backfilling in area 2 along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1000	Backfilling in area 2 along the Anthony Kill.	Direction: SW
					
Mechanicville MGP RA 1001	Backfilling in area 2 along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1003	Excavations in area 2 along the Anthony Kill.	Direction: E
					
Mechanicville MGP RA 1005	Excavations in area 2 along the Anthony Kill.	Direction: E	Mechanicville MGP RA 1018	Backfilling in area 2 along the Anthony Kill.	Direction: NE

Daily Photograph Log for January 28, 2009



Mechanicville MGP RA 1021	Conditions in area 2.	Direction: N



Mechanicville MGP RA 1022	Conditions in area 2.	Direction: NW



Mechanicville MGP RA 1023	Water management in area 3A.	Direction: E



Mechanicville MGP RA 1024	Demolition of the holder foundation in area 3A.	Direction: S



Mechanicville MGP RA 1025	Water management in area 3A.	Direction: SE



Mechanicville MGP RA 1026	Demolition of the holder foundation in area 3A.	Direction: S

					
Mechanicville MGP RA 1027	Demolition of the holder foundation in area 3A.	Direction: SE	Mechanicville MGP RA 1028	Demolition of the holder foundation in area 3A.	Direction: S
					
Mechanicville MGP RA 1029	Water management in area 3A.	Direction: SE	Mechanicville MGP RA 1030	Demolition of the holder foundation in area 3A.	Direction: E
					
Mechanicville MGP RA 1031	Demolition of the holder foundation in area 3A.	Direction: SW	Mechanicville MGP RA 1032	Demolition of the holder foundation in area 3A.	Direction: SW

Daily Photograph Log for January 29, 2009



Mechanicville MGP RA 1033	Excavations in area 3A.	Direction: SE




Mechanicville MGP RA 1034	Water management in area 3A.	Direction: E



Mechanicville MGP RA 1036	Load out of soil from area 2.	Direction: E





Mechanicville MGP RA 1037	Excavations in area 2.	Direction: E



Mechanicville MGP RA 1039	Excavations in area 2.	Direction: E



Mechanicville MGP RA 1040	Excavations in area 2.	Direction: SE

					
Mechanicville MGP RA 1041	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 1043	Excavations in area 2.	Direction: E
					
Mechanicville MGP RA 1045	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 1046	Excavations in area 2.	Direction: SE
					
Mechanicville MGP RA 1047	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 1049	Excavations in area 3A.	Direction: SE

Daily Photograph Log for January 30, 2009



Mechanicville MGP RA 1050	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 1051	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 1052	Excavations in area 3A.	Direction: S



Mechanicville MGP RA 1054	Soil amendment in area 3A.	Direction: W



Mechanicville MGP RA 1057	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 1058	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 1059	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1060	Excavations in area 3A.	Direction: N
					
Mechanicville MGP RA 1061	Soil stratification in area 3A.	Direction: NE	Mechanicville MGP RA 1063	Visible NAPL in soil in area 3A.	Direction: N
					
Mechanicville MGP RA 1064	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 1065	Excavations in area 3A.	Direction: E

Daily Photograph Log for February 02, 2009



Mechanicville MGP RA 1067	Water collected in area 3A after the weekend.	Direction: E



Mechanicville MGP RA 1068	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 1069	Soil amendment in area 3A.	Direction: N



Mechanicville MGP RA 1070	Soil amendment in area 3A.	Direction: N



Mechanicville MGP RA 1072	Water management in area 3A.	Direction: NE



Mechanicville MGP RA 1080	Moving of main sump in area 3A.	Direction: SNE

					
Mechanicville MGP RA 1081	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 1083	Load out of material from area 3A.	Direction: N
					
Mechanicville MGP RA 1085	Extent of excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1086	Extent of excavations in area 3A.	Direction: S
					
Mechanicville MGP RA 1090	Soil stratification in area 3A.	Direction: EE	Mechanicville MGP RA 1098	Solidified soils in area 3A.	Direction: N

Daily Photograph Log for February 03, 2009



Mechanicville MGP RA 1101	Water collected in area 3A overnight.	Direction: SE



Mechanicville MGP RA 1102	Water collected in area 3A overnight.	Direction: SE



Mechanicville MGP RA 1103	Water collected in area 3A overnight.	Direction: N



Mechanicville MGP RA 1104	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 1105	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 1106	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 1107	Excavations in area 3A.	Direction: N			

Daily Photograph Log for February 04, 2009



Mechanicville MGP RA 1112	Water collected in area 3A overnight.	Direction: SE



Mechanicville MGP RA 1114	Demolition of the holder and excavations in area 3A.	Direction: N



Mechanicville MGP RA 1115	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 1117	Demolition of the holder in area 3A.	Direction: E



Mechanicville MGP RA 1118	Amended soils in area 3A.	Direction: S



Mechanicville MGP RA 1120	Demolition of the holder in area 3A.	Direction: SE

					
Mechanicville MGP RA 1124	Demolition of the holder in area 3A.	Direction: N	Mechanicville MGP RA 1125	Demolition of the holder in area 3A.	Direction: N
					
Mechanicville MGP RA 1126	Demolition of the holder in area 3A.	Direction:	Mechanicville MGP RA 1127	Icy conditions onsite.	Direction: SW

Daily Photograph Log for February 05, 2009



Mechanicville MGP RA 1128	Conditions in are 2.	Direction: NE



Mechanicville MGP RA 1131	Biosolve icing in area 3A.	Direction: E



Mechanicville MGP RA 1132	Biosolve icing in area 3A.	Direction: E



Mechanicville MGP RA 1133	Biosolve icing in area 3A.	Direction: E



Mechanicville MGP RA 1134	Stockpiling of excavated soils in area 3A.	Direction: SW



Mechanicville MGP RA 1136	Stockpiling of excavated soils in area 3A.	Direction: S

					
Mechanicville MGP RA 1138	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1139	Stockpiling of excavated soils in area 3A.	Direction: N
					
Mechanicville MGP RA 1141	Excavations in area 3A.	Direction: E	Mechanicville MGP RA 1142	Excavations in area 3A.	Direction:
					
Mechanicville MGP RA 1143	Excavations in area 3A.	Direction:	Mechanicville MGP RA 1144	Excavations in area 3A.	Direction: SW

Daily Photograph Log for February 06, 2009



Mechanicville MGP RA 1147	Conditions in are 2.	Direction: E



Mechanicville MGP RA 1148	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 1150	Soil amendment in area 3A.	Direction: SW



Mechanicville MGP RA 1151	Holder demolition in area 3A.	Direction: NE



Mechanicville MGP RA 1153	Holder demolition in area 3A.	Direction: SW



Mechanicville MGP RA 1154	Soil amendment in area 3A.	Direction: S

					
Mechanicville MGP RA 1155	Load out of soils from area 3A.	Direction: S	Mechanicville MGP RA 1156	Holder demolition in area 3A.	Direction: NE
					
Mechanicville MGP RA 1157	Nightly cover of area 3A.	Direction: W	Mechanicville MGP RA 1158	Nightly cover of area 3A.	Direction: W
					
Mechanicville MGP RA 1159	Nightly cover of area 3A.	Direction: SW	Mechanicville MGP RA 1160	Nightly cover of area 3A.	Direction: SW

Daily Photograph Log for February 09, 2009



Mechanicville MGP RA 1161	Weekend water in area 3A.	Direction: SE



Mechanicville MGP RA 1164	Weekend water in area 2.	Direction: N



Mechanicville MGP RA 1168	Holder demolition in area 3A.	Direction: E



Mechanicville MGP RA 1169	Holder demolition in area 3A.	Direction: E



Mechanicville MGP RA 1170	Load out of cut trees.	Direction: N



Mechanicville MGP RA 1172	Cleared area between areas 2 and 4.	Direction: W

					
Mechanicville MGP RA 1174	Ice conditions in the Anthony Kill.	Direction: W	Mechanicville MGP RA 1175	Ice conditions in the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1176	Ice conditions in the Anthony Kill.	Direction: W	Mechanicville MGP RA 1179	Excavations in area 3A.	Direction: SW
					
Mechanicville MGP RA 1181	Excavations in area 3A.	Direction: S	Mechanicville MGP RA 1183	Excavations in area 3A.	Direction: SE

Daily Photograph Log for February 10, 2009



Mechanicville MGP RA 1185	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 1187	Soil amendment in area 3A.	Direction: N



Mechanicville MGP RA 1188	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 1190	Holder demolition in area 3A.	Direction: N



Mechanicville MGP RA 1191	NAPL collecting from soil in area 3A.	Direction: E



Mechanicville MGP RA 1193	Water management in area 3A.	Direction:

					
Mechanicville MGP RA 1194	Water management in area 3A.	Direction: SE	Mechanicville MGP RA 1199	Excavations to bedrock in area 3A.	Direction: E
					
Mechanicville MGP RA 1201	Apparent clay seal around holder in area 3A.	Direction: SE	Mechanicville MGP RA 1202	Water management in area 3A.	Direction: NW
					
Mechanicville MGP RA 1203	NAPL in bedrock cracks in area 3A.	Direction: NW	Mechanicville MGP RA 1211	Top of fault in area 3A.	Direction: N

Daily Photograph Log for February 11, 2009



Mechanicville MGP RA 1222	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 1223	Bedrock cracks in area 3A.	Direction: NE



Mechanicville MGP RA 1224	Bedrock cracks in area 3A.	Direction: NE



Mechanicville MGP RA 1226	Bedrock cracks in area 3A.	Direction: N



Mechanicville MGP RA 1229	Holder wall in area 3A.	Direction: W



Mechanicville MGP RA 1231	Holder inner wall in area 3A.	Direction: W

					
Mechanicville MGP RA 1233	Holder footing pad removal in area 3A.	Direction: NE	Mechanicville MGP RA 1235	Holder footing pad removal in area 3A.	Direction: S
					
Mechanicville MGP RA 1237	Holder footing pad removal in area 3A.	Direction: NE	Mechanicville MGP RA 1240	Holder inner wall/floor removal in area 3A.	Direction: SW
					
Mechanicville MGP RA 1243	Holder inner wall/floor removal in area 3A.	Direction: W	Mechanicville MGP RA 1248	Nightly cover in area 3A.	Direction: S

Daily Photograph Log for February 12, 2009



Mechanicville MGP RA 1252	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 1254	Power washing of concrete in area 3A.	Direction: E



Mechanicville MGP RA 1255	Power washing of concrete in area 3A.	Direction: E



Mechanicville MGP RA 1256	Power washing of concrete in area 3A.	Direction: N



Mechanicville MGP RA 1257	Power washing of concrete in area 3A.	Direction: N



Mechanicville MGP RA 1258	Power washing of concrete in area 3A.	Direction: E

					
Mechanicville MGP RA 1259	Power washing of concrete in area 3A.	Direction: E	Mechanicville MGP RA 1260	Delivery of medium stone fill in area 2.	Direction: W
					
Mechanicville MGP RA 1261	Power washing of concrete in area 3A.	Direction: SE	Mechanicville MGP RA 1262	Power washing of concrete in area 3A.	Direction: SE
					
Mechanicville MGP RA 1263	Power washing of concrete in area 3A.	Direction: NE	Mechanicville MGP RA 1264	Power washing of concrete in area 3A.	Direction: N

Daily Photograph Log for February 13, 2009

					
Mechanicville MGP RA 1265	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1266	Amending of soils in area 3A.	Direction: S
					
Mechanicville MGP RA 1267	Amending of soils in area 3A.	Direction: SE	Mechanicville MGP RA 1268	Excavations in area 3A.	Direction: SE
					
Mechanicville MGP RA 1269	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1270	Excavations in area 3A.	Direction: SE

					
Mechanicville MGP RA 1271	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1272	Delivery of Rusmar foamer.	Direction: NW
					
Mechanicville MGP RA 1273	Stockpiled soils in area 3A.	Direction: SW	Mechanicville MGP RA 1274	Excavations in area 3A.	Direction: SE

Daily Photograph Log for February 16, 2009

					
Mechanicville MGP RA 1275	Weekend water in area 3A.	Direction: E	Mechanicville MGP RA 1276	Weekend water in area 3A.	Direction: SE
					
Mechanicville MGP RA 1277	Weekend water in area 3A.	Direction: SE	Mechanicville MGP RA 1278	Weekend water in area 3A.	Direction: E
					
Mechanicville MGP RA 1279	Load out of soils from area 3A.	Direction: SE	Mechanicville MGP RA 1280	Load out of soils from area 3A.	Direction: S

					
Mechanicville MGP RA 1281	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1282	Excavations in area 3A.	Direction: SE
					
Mechanicville MGP RA 1283	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1289	Application of odor suppressant foam in area 3A.	Direction: N
					
Mechanicville MGP RA 1290	Application of odor suppressant foam in area 3A.	Direction: N	Mechanicville MGP RA 1291	Application of odor suppressant foam in area 3A.	Direction: NE

Daily Photograph Log for February 17, 2009



Mechanicville MGP RA 1292	Water level in area 3A.	Direction: SE



Mechanicville MGP RA 1293	Water level in area 3A.	Direction: SE



Mechanicville MGP RA 1295	Load out of soils from area 3A.	Direction: SW



Mechanicville MGP RA 1296	Load out of soils from area 3A.	Direction: SW



Mechanicville MGP RA 1298	Removal of sump basket in area 3A.	Direction: SE



Mechanicville MGP RA 1299	Load out of soils from area 3A.	Direction: S

					
Mechanicville MGP RA 1300	Removal of sump basket in area 3A.	Direction: SE	Mechanicville MGP RA 1301	Installation of erosion matting and stone fill in area 2.	Direction: W
					
Mechanicville MGP RA 1302	Installation of erosion matting and stone fill in area 2.	Direction: W	Mechanicville MGP RA 1303	Water level in area 3A.	Direction: NE
					
Mechanicville MGP RA 1304	Nightly odor suppressant foam cover in area 3A.	Direction: N	Mechanicville MGP RA 1305	Nightly odor suppressant foam cover in area 3A.	Direction: N

Daily Photograph Log for February 18, 2009



Mechanicville MGP RA 1307	Water level in area 3A.	Direction: NE



Mechanicville MGP RA 1308	Cleaning of sheets in area 3A with impact hammer.	Direction: NW



Mechanicville MGP RA 1310	Medium stone fill installed along Anthony Kill.	Direction: W



Mechanicville MGP RA 1313	Demolition of holder foundation in area 3A.	Direction: NW



Mechanicville MGP RA 1314	Cleaning of WWTP vessels.	Direction:



Mechanicville MGP RA 1315	Cleaning of WWTP vessels.	Direction:

					
Mechanicville MGP RA 1316	Solidification of WWTP media.	Direction: NW	Mechanicville MGP RA 1319	Cleaning of baffle tank.	Direction: E
					
Mechanicville MGP RA 1324	Cleaning of baffle tank.	Direction:	Mechanicville MGP RA 1329	Dumping of sludge from baffle tank.	Direction: N
					
Mechanicville MGP RA 1331	Dumping of sludge from baffle tank.	Direction: N	Mechanicville MGP RA 1336	Solidification of sludge from baffle tank.	Direction: NE

Daily Photograph Log for February 19, 2009



Mechanicville MGP RA 1341	Solidification of sludge from baffle tank.	Direction: NE



Mechanicville MGP RA 1343	Cofferdam construction along the Anthony Kill.	Direction: W



Mechanicville MGP RA 1345	Solidification of sludge from baffle tank.	Direction: W



Mechanicville MGP RA 1346	Water level in area 3A.	Direction: SW



Mechanicville MGP RA 1348	Water level in area 3A.	Direction: NE



Mechanicville MGP RA 1349	Water level in area 3A.	Direction: N

					
Mechanicville MGP RA 1350	Water level in area 3A.	Direction: NE	Mechanicville MGP RA 1355	Cofferdam construction along the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1357	Cofferdam construction along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1359	Water level in area 3A.	Direction: E
					
Mechanicville MGP RA 1360	Nightly odor suppressant foam cover.	Direction: E	Mechanicville MGP RA 1361	Nightly odor suppressant foam cover.	Direction: NE

Daily Photograph Log for February 20, 2009



Mechanicville MGP RA 1362	Load out of soils form area 3A.	Direction: S



Mechanicville MGP RA 1363	Demolition of holder foundation in area 3A.	Direction: S



Mechanicville MGP RA 1364	Water level in area 3A.	Direction: SW



Mechanicville MGP RA 1366	Demolition of holder foundation in area 3A.	Direction: S



Mechanicville MGP RA 1370	Demolition of holder foundation in area 3A.	Direction: E



Mechanicville MGP RA 1371	Excavations in area 3A.	Direction: NW

					
Mechanicville MGP RA 1372	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1373	Water level in area 3A.	Direction: E
					
Mechanicville MGP RA 1374	Water level in area 3A.	Direction: E	Mechanicville MGP RA 1375	Excavations in area 3A.	Direction: N
					
Mechanicville MGP RA 1382	Nightly\weekend odor suppressant foam cover.	Direction: S	Mechanicville MGP RA 1385	Nightly\weekend odor suppressant foam cover.	Direction: S

Daily Photograph Log for February 23, 2009

					
Mechanicville MGP RA 1386	Water level in area 3A.	Direction: SE	Mechanicville MGP RA 1387	Water level in area 3A.	Direction: SE
					
Mechanicville MGP RA 1388	Water level in area 3A.	Direction: SE	Mechanicville MGP RA 1391	Water level in area 3A.	Direction: N
					
Mechanicville MGP RA 1392	Water level in area 3A.	Direction: NE	Mechanicville MGP RA 1393	Water level in area 3A.	Direction: NE

					
Mechanicville MGP RA 1395	Excavations in area 2.	Direction: E	Mechanicville MGP RA 1396	Excavations in area 2.	Direction: E
					
Mechanicville MGP RA 1397	Reinstallation of sump basket in area 3A.	Direction: SE	Mechanicville MGP RA 1398	Nightly odor suppressant foam cover.	Direction: NE
					
Mechanicville MGP RA 1402	Nightly odor suppressant foam cover.	Direction: NE	Mechanicville MGP RA 1405	Water level in area 3A.	Direction: NE

Daily Photograph Log for February 24, 2009



Mechanicville MGP RA 1406	Water level in area 3A.	Direction: NE



Mechanicville MGP RA 1407	Water level in area 3A.	Direction: NW



Mechanicville MGP RA 1409	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 1411	Excavations in area 2.	Direction: E



Mechanicville MGP RA 1415	Excavations in area 2.	Direction: SW



Mechanicville MGP RA 1416	Excavations in area 2.	Direction: SW

					
Mechanicville MGP RA 1418	Excavations in area 2.	Direction: W	Mechanicville MGP RA 1420	Backfilling in area 2.	Direction: SW
					
Mechanicville MGP RA 1421	Backfilling in area 2.	Direction: SW	Mechanicville MGP RA 1429	Progress of backfilling in area 2.	Direction: NW
					
Mechanicville MGP RA 1430	Progress of backfilling in area 2.	Direction: N	Mechanicville MGP RA 1431	Progress of excavations in area 2.	Direction: NW

Daily Photograph Log for February 25, 2009



Mechanicville MGP RA 1432	Water level in area 3A.	Direction: E



Mechanicville MGP RA 1433	Water level in area 3A.	Direction: NE



Mechanicville MGP RA 1435	Water level in area 3A.	Direction: NE



Mechanicville MGP RA 1437	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 1439	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 1440	Excavations in area 2.	Direction: SE

					
Mechanicville MGP RA 1441	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 1442	Excavations in area 2.	Direction: S
					
Mechanicville MGP RA 1443	Excavations in area 2.	Direction: S	Mechanicville MGP RA 1445	Excavations in area 2.	Direction: N
					
Mechanicville MGP RA 1446	Excavations in area 2.	Direction: E	Mechanicville MGP RA 1452	Backfilling in area 2.	Direction: NE

Daily Photograph Log for February 26, 2009



Mechanicville MGP RA 1453	Delivery of backfill in area 2..	Direction: NW



Mechanicville MGP RA 1454	Power washing of concrete in area 3A.	Direction: N



Mechanicville MGP RA 1455	Power washing of concrete in area 3A.	Direction: N



Mechanicville MGP RA 1456	Power washing of concrete in area 3A.	Direction: N

					
Mechanicville MGP RA 1457	Transfer of concrete block from area 2 to area 3A.	Direction: NW	Mechanicville MGP RA 1458	Amending of soils in area 3A.	Direction: N

Daily Photograph Log for February 27, 2009



Mechanicville MGP RA 1459	Exposing of monitor well for decommissioning.	Direction: SW




Mechanicville MGP RA 1460	Decommissioning of monitor well.	Direction: N



Mechanicville MGP RA 1462	Excavation to bedrock in area 3A.	Direction: SE



Mechanicville MGP RA 1463	Excavation to bedrock in area 3A.	Direction: SE



Mechanicville MGP RA 1464	Excavation to bedrock in area 3A.	Direction: SE



Mechanicville MGP RA 1469	Decommissioning of monitor wells.	Direction: E

					
Mechanicville MGP RA 1471	Transfer of IRM rip rap to area 3A as backfill.	Direction: SW	Mechanicville MGP RA 1472	Power washing of concrete in area 3A.	Direction: SW
					
Mechanicville MGP RA 1475	Moving sheet piles for access to area 4.	Direction: NE	Mechanicville MGP RA 1477	Power washing of concrete in area 3A.	Direction: SW
					
Mechanicville MGP RA 1478	Moved sheet piles for access to area 4.	Direction: NWE	Mechanicville MGP RA 1484	Weekend cover in area 3A.	Direction: SW

Daily Photograph Log for March 02, 2009



Mechanicville MGP RA 1487	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 1488	Excavations in area 3A.	Direction: NE



Mechanicville MGP RA 1489	Excavations in area 3A.	Direction: NW



Mechanicville MGP RA 1490	Excavations in area 3A.	Direction: N



Mechanicville MGP RA 1494	Water management in area 2.	Direction: E



Mechanicville MGP RA 1495	Load out of soils from area 3A.	Direction: S

					
Mechanicville MGP RA 1496	Demolition of the holder foundation in area 3A.	Direction: SE	Mechanicville MGP RA 1499	Water management in area 3A.	Direction: NE
					
Mechanicville MGP RA 1500	Demolition of the holder foundation in area 3A.	Direction: NE	Mechanicville MGP RA 1501	Excavations in area 2.	Direction: E
					
Mechanicville MGP RA 1502	Excavations in area 2.	Direction: E	Mechanicville MGP RA 1503	Demolition of the holder foundation in area 3A.	Direction: NE

Daily Photograph Log for March 03, 2009



Mechanicville MGP RA 1505	Demolition of the holder foundation in area 3A.	Direction: N



Mechanicville MGP RA 1506	Valve box assembly removed from the holder foundation.	Direction: E



Mechanicville MGP RA 1507	Excavations in area 2.	Direction: E



Mechanicville MGP RA 1508	Excavations in area 3A.	Direction: SE



Mechanicville MGP RA 1509	Load out of soils from area 3A.	Direction: S



Mechanicville MGP RA 1510	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 1514	Demolition of the holder foundation in area 3A.	Direction: SW	Mechanicville MGP RA 1515	Demolition of the holder foundation in area 3A.	Direction: SW
					
Mechanicville MGP RA 1516	Amending of soils in area 3A.	Direction: W	Mechanicville MGP RA 1517	Excavations in area 2.	Direction: SW
					
Mechanicville MGP RA 1518	Excavations in area 2.	Direction: W	Mechanicville MGP RA 1520	Boiler house foundation uncovered in area 2/4.	Direction: SE

Daily Photograph Log for March 04, 2009



Mechanicville MGP RA 1522	Water management in area 3A.	Direction: E



Mechanicville MGP RA 1524	Soil amending in area 3A.	Direction: N



Mechanicville MGP RA 1525	Excavations in area 2/4.	Direction: W



Mechanicville MGP RA 1527	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 1528	Excavations to bedrock in area 3A.	Direction: SW



Mechanicville MGP RA 1529	Excavations to bedrock in area 3A.	Direction: SW

					
Mechanicville MGP RA 1530	Excavations to bedrock in area 3A.	Direction: SW	Mechanicville MGP RA 1531	Excavations to bedrock in area 3A.	Direction: SW
					
Mechanicville MGP RA 1532	Excavations in area 2.	Direction: SW	Mechanicville MGP RA 1533	Power washing of concrete in area 3A.	Direction: SE
					
Mechanicville MGP RA 1534	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 1535	Excavation progress in area 3A.	Direction: N

Daily Photograph Log for March 05, 2009



Mechanicville MGP RA 1537	Load out of material from area 2/4 and 4.	Direction: E



Mechanicville MGP RA 1538	Power washing of concrete in area 3A.	Direction: E



Mechanicville MGP RA 1539	Power washing of concrete in area 3A.	Direction: SE



Mechanicville MGP RA 1540	Power washing of concrete in area 3A.	Direction: E




Mechanicville MGP RA 1541	Load out of material from area 2/4 and 4.	Direction: E



Mechanicville MGP RA 1545	Infiltration of water under sheet piles in area 3A.	Direction:

					
Mechanicville MGP RA 1546	Exposed toe pin in area 3A.	Direction:	Mechanicville MGP RA 1551	Progress of excavations in area 3A.	Direction: S
					
Mechanicville MGP RA 1552	Power washing of concrete in area 3A.	Direction: SE	Mechanicville MGP RA 1553	Water management in area 3A.	Direction: E
					
Mechanicville MGP RA 1554	Progress of excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1555	Progress of excavations in area 3A.	Direction: NE

Daily Photograph Log for March 06, 2009

					
Mechanicville MGP RA 1556	Cofferdam work along the Anthony Kill.	Direction: N	Mechanicville MGP RA 1557	Excavations in area 3A.	Direction: N
					
Mechanicville MGP RA 1558	Cofferdam work along the Anthony Kill.	Direction: NW	Mechanicville MGP RA 1559	Water management in area 3A.	Direction: E
					
Mechanicville MGP RA 1560	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 1561	Water management in area 3A.	Direction: N

					
Mechanicville MGP RA 1562	Cofferdam work along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1563	Water management in area 3A.	Direction: NE
					
Mechanicville MGP RA 1564	Cofferdam work along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1565	Demolition of the holder ‘dumpling’ in area 3A.	Direction: N

Daily Photograph Log for March 09, 2009



Mechanicville MGP RA 1568	High water conditions in the Anthony Kill.	Direction: NE



Mechanicville MGP RA 1569	High water conditions in the Anthony Kill.	Direction: E



Mechanicville MGP RA 1570	High water conditions in the Anthony Kill.	Direction: NW



Mechanicville MGP RA 1571	High water conditions in the Anthony Kill.	Direction: W



Mechanicville MGP RA 1573	High water conditions in area 3A.	Direction: SE



Mechanicville MGP RA 1577	High water conditions in area 3A.	Direction: NE

					
Mechanicville MGP RA 1578	High water conditions in area 3A.	Direction: NE	Mechanicville MGP RA 1579	High water conditions in the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1595	High water conditions in the Anthony Kill.	Direction: N	Mechanicville MGP RA 1604	Load out of material from area 3A.	Direction: NW
					
Mechanicville MGP RA 1605	Water management in area 3A.	Direction: NE	Mechanicville MGP RA 1606	Excavations in area 3A.	Direction: NE

Daily Photograph Log for March 10, 2009



Mechanicville MGP RA 1611	High water conditions in the Anthony Kill.	Direction: NE



Mechanicville MGP RA 1614	High water conditions in the Anthony Kill.	Direction: E



Mechanicville MGP RA 1617	Water management in area 3A.	Direction: NW



Mechanicville MGP RA 1619	Excavations in area 3A.	Direction: W



Mechanicville MGP RA 1621	Amending of soils in area 3A.	Direction: SE



Mechanicville MGP RA 1624	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 1625	Tar collector unearthed in area 3A.	Direction: NE	Mechanicville MGP RA 1626	Tar collector unearthed in area 3A.	Direction: W
					
Mechanicville MGP RA 1631	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1632	Excavations in area 3A.	Direction: NW
					
Mechanicville MGP RA 1635	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1646	Demolition of holder foundations in area 3A.	Direction: NE

Daily Photograph Log for March 11, 2009



Mechanicville MGP RA 1649	Demolition of holder foundations in area 3A.	Direction: E



Mechanicville MGP RA 1650	Demolition of holder foundations in area 3A.	Direction: E



Mechanicville MGP RA 1651	Demolition of holder foundations in area 3A.	Direction: NE



Mechanicville MGP RA 1652	Excavations in area 4.	Direction: E



Mechanicville MGP RA 1653	Former gas main uncovered in area 4.	Direction: SE



Mechanicville MGP RA 1655	Demolition of holder foundations in area 3A.	Direction: N

					
Mechanicville MGP RA 1656	Former gas main uncovered in area 4.	Direction: SE	Mechanicville MGP RA 1657	Removal of former gas main uncovered in area 4.	Direction: S
					
Mechanicville MGP RA 1660	Removal of former gas main uncovered in area 4.	Direction: E	Mechanicville MGP RA 1661	Demolition of holder foundations in area 3A.	Direction: N
					
Mechanicville MGP RA 1662	Excavations in area 4.	Direction: E	Mechanicville MGP RA 1663	Excavations in area 4.	Direction: E

Daily Photograph Log for March 12, 2009

					
Mechanicville MGP RA 1664	Progress of excavations in area 3A.	Direction: W	Mechanicville MGP RA 1667	Demolition of holder foundations in area 3A.	Direction: N
					
Mechanicville MGP RA 1668	Demolition of holder foundations in area 3A.	Direction: N	Mechanicville MGP RA 1669	High water conditions in the Anthony Kill.	Direction: N
					
Mechanicville MGP RA 1670	High water conditions in the Anthony Kill.	Direction: N	Mechanicville MGP RA 1671	High water conditions in the Anthony Kill.	Direction: NE


					
Mechanicville MGP RA 1673	Excavations in area 3A.	Direction: SE	Mechanicville MGP RA 1674	Demolition of holder foundations in area 3A.	Direction: S
					
Mechanicville MGP RA 1675	Demolition of holder foundations in area 3A.	Direction: NE	Mechanicville MGP RA 1676	Demolition of holder foundations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1677	Demolition of holder foundations in area 3A.	Direction: NE	Mechanicville MGP RA 1678	Demolition of holder foundations in area 3A.	Direction: N

Daily Photograph Log for March 13, 2009

					
Mechanicville MGP RA 1679	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1680	Load out of soils to ESMI in area 3A.	Direction: NW
					
Mechanicville MGP RA 1681	Demolition of holder foundations in area 3A.	Direction: W	Mechanicville MGP RA 1682	Excavations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1683	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1684	Excavations in area 3A.	Direction: N

					
Mechanicville MGP RA 1685	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1687	Excavations in area 3A.	Direction: E
					
Mechanicville MGP RA 1688	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1689	High water conditions in the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1690	High water conditions in the Anthony Kill.	Direction: W	Mechanicville MGP RA 1692	High water conditions in the Anthony Kill.	Direction: W

Daily Photograph Log for March 16, 2009

					
Mechanicville MGP RA 1693	Excavations in area 3A.	Direction: N	Mechanicville MGP RA 1694	Excavations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1697	High water conditions in the Anthony Kill.	Direction: W	Mechanicville MGP RA 1701	High water conditions in the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1703	High water conditions in the Anthony Kill.	Direction: W	Mechanicville MGP RA 1705	Debris dam under RR bridge.	Direction: N

					
Mechanicville MGP RA 1710	Excavations in area 3A.	Direction: NE	Mechanicville MGP RA 1711	Excavations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1713	Excavations in area 3A.	Direction: E	Mechanicville MGP RA 1715	Power washing of concrete in area 3A.	Direction: NE
					
Mechanicville MGP RA 1717	Power washing of concrete in area 3A.	Direction: S	Mechanicville MGP RA 1718	Power washing of concrete in area 3A.	Direction: S

Daily Photograph Log for March 17, 2009



Mechanicville MGP RA 1724	Excavations in area 3A.	Direction: E



Mechanicville MGP RA 1725	Repairs to erosion controls along the Anthony Kill.	Direction: W



Mechanicville MGP RA 1726	Repairs to erosion controls along the Anthony Kill.	Direction: W




Mechanicville MGP RA 1727	Power washing of concrete in area 3A.	Direction:



Mechanicville MGP RA 1728	Amending of soils in area 3A.	Direction: NE



Mechanicville MGP RA 1729	Excavations in area 3A.	Direction: NE

					
Mechanicville MGP RA 1730	Repairs to erosion controls along the Anthony Kill.	Direction: W	Mechanicville MGP RA 1731	Repairs to erosion controls along the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1732	Checking grades along the Anthony Kill.	Direction: NW			

Daily Photograph Log for March 18, 2009



Mechanicville MGP RA 1733	Delivery of pond fill backfill.	Direction: NW



Mechanicville MGP RA 1734	Backfilling with washed concrete in area 3A.	Direction: SE



Mechanicville MGP RA 1736	Final excavations in area 3A.	Direction: SW



Mechanicville MGP RA 1737	Final excavations in area 3A.	Direction: SW




Mechanicville MGP RA 1739	Backfilling with washed concrete in area 3A.	Direction: SE



Mechanicville MGP RA 1741	Backfilling with washed concrete in area 3A.	Direction: NW

					
Mechanicville MGP RA 1748	Cobble backfill in area 3A.	Direction: NE	Mechanicville MGP RA 1749	Re-installation of cofferdam along the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1765	Large block of concrete being placed into area 3A.	Direction: W	Mechanicville MGP RA 1773	Re-installation of cofferdam along the Anthony Kill.	Direction: W
					
Mechanicville MGP RA 1779	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1780	Backfilling operations in area 3A.	Direction: N

Daily Photograph Log for March 19, 2009

					
Mechanicville MGP RA 1782	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1783	Backfilling operations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1784	Decontamination of equipment in area 3A.	Direction: NE	Mechanicville MGP RA 1786	Decontamination of equipment in area 3A.	Direction: NE
					
Mechanicville MGP RA 1787	Decontamination of equipment in area 3A.	Direction: N	Mechanicville MGP RA 1788	Backfilling operations in area 3A.	Direction: W

					
Mechanicville MGP RA 1789	Backfilling operations in area 3A.	Direction: NW	Mechanicville MGP RA 1791	Construction of #1 stone sump in area 3A.	Direction: NW
					
Mechanicville MGP RA 1792	Construction of #1 stone sump in area 3A.	Direction: SE	Mechanicville MGP RA 1793	Construction of #1 stone sump in area 3A.	Direction: S
					
Mechanicville MGP RA 1794	Construction of #1 stone sump in area 3A.	Direction: SE	Mechanicville MGP RA 1795	Construction of #1 stone sump in area 3A.	Direction: E

Daily Photograph Log for March 20, 2009

					
Mechanicville MGP RA 1796	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1797	Backfilling operations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1798	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1802	Backfilling operations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1803	Mini-excavator exiting area 3A.	Direction: N	Mechanicville MGP RA 1804	Installation of geotextile in area 3A.	Direction: W

					
Mechanicville MGP RA 1809	Backfilling operations in area 3A.	Direction: NW	Mechanicville MGP RA 1814	Backfilling operations in area 3A.	Direction: NW
					
Mechanicville MGP RA 1831	Backfilling operations in area 3A.	Direction: SE	Mechanicville MGP RA 1832	Backfilling operations in area 3A.	Direction: S
					
Mechanicville MGP RA 1833	Backfill in area 2.	Direction: SE	Mechanicville MGP RA 1834	Backfill in area 2.	Direction: E

Daily Photograph Log for March 23, 2009

					
Mechanicville MGP RA 1836	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1837	Backfilling operations in area 3A.	Direction: NE
					
Mechanicville MGP RA 1842	Backfilling operations in area 3A.	Direction: NE	Mechanicville MGP RA 1843	Water control in area 2.	Direction: NE
					
Mechanicville MGP RA 1845	Backfilling operations in area 3A.	Direction: N	Mechanicville MGP RA 1846	Backfilling operations in area 3A.	Direction: W

					
Mechanicville MGP RA 1848	Excavations in area 2.	Direction: NW	Mechanicville MGP RA 1853	Backfilling operations in area 2.	Direction: NW
					
Mechanicville MGP RA 1860	Placing rip-rap in area 2.	Direction: SE	Mechanicville MGP RA 1862	Progress in area 2.	Direction: S
					
Mechanicville MGP RA 1864	Backfilling operations in area 3A.	Direction: SE	Mechanicville MGP RA 1866	Backfilling operations in area 3A.	Direction: E

Daily Photograph Log for March 24, 2009



Mechanicville MGP RA 1867	Loadout of soils from area 4.	Direction: NE



Mechanicville MGP RA 1868	Excavations in area 2.	Direction: E



Mechanicville MGP RA 1869	Backfilling operations in area 2.	Direction: E



Mechanicville MGP RA 1870	Water control in area 2.	Direction: N



Mechanicville MGP RA 1871	Backfilling operations in area 2.	Direction: NE



Mechanicville MGP RA 1872	Backfilling operations in area 2.	Direction: NW

					
Mechanicville MGP RA 1873	Excavations in area 2.	Direction: NW	Mechanicville MGP RA 1874	Backfilling operations in area 2.	Direction: E
					
Mechanicville MGP RA 1876	Water control in area 2.	Direction: N	Mechanicville MGP RA 1877	Backfilling operations in area 2.	Direction: SW
					
Mechanicville MGP RA 1878	Backfilling operations in area 2.	Direction: SW	Mechanicville MGP RA 1881	Backfilling operations in area 2.	Direction: E

Daily Photograph Log for March 25, 2009



Mechanicville MGP RA 1886	Loadout of soils from area 2/4.	Direction: N



Mechanicville MGP RA 1887	Backfilling operations in area 3A.	Direction: SW



Mechanicville MGP RA 1888	Backfilling operations in area 3A.	Direction: W



Mechanicville MGP RA 1889	Backfilling operations in area 3A.	Direction: NW



Mechanicville MGP RA 1890	Excavations in area 2.	Direction: W



Mechanicville MGP RA 1892	Excavations in area 2.	Direction: NW

					
Mechanicville MGP RA 1894	Water control in area 2.	Direction: N	Mechanicville MGP RA 1899	Backfilling operations in area 2.	Direction: SW
					
Mechanicville MGP RA 1901	Backfilling operations in area 2.	Direction: NW	Mechanicville MGP RA 1904	Backfilling operations in area 2.	Direction: N
					
Mechanicville MGP RA 1906	Backfilling operations in area 2.	Direction: W	Mechanicville MGP RA 1908	Backfilling operations in area 2.	Direction: W

Daily Photograph Log for March 26, 2009

					
Mechanicville MGP RA 1918	Excavations in area 2.	Direction: W	Mechanicville MGP RA 1921	Excavations in area 2.	Direction: W
					
Mechanicville MGP RA 1923	Sediment monitoring in the Anthony Kill.	Direction: NW	Mechanicville MGP RA 1926	Sediment monitoring in the Anthony Kill.	Direction: E
					
Mechanicville MGP RA 1936	Excavations in area 2.	Direction: E	Mechanicville MGP RA 1938	Excavations in area 2.	Direction: E

					
Mechanicville MGP RA 1941	Backfilling operations in area 2.	Direction: SW	Mechanicville MGP RA 1943	Backfilling operations in area 2.	Direction: SE
					
Mechanicville MGP RA 1944	Backfilling operations in area 2.	Direction: NE	Mechanicville MGP RA 1947	Excavations in area 2.	Direction: E
					
Mechanicville MGP RA 1952	Backfilling operations in area 2.	Direction: SW	Mechanicville MGP RA 1954	Backfilling operations in area 2.	Direction: W

Daily Photograph Log for March 27, 2009

					
Mechanicville MGP RA 1961	Excavations in area 4.	Direction: SW	Mechanicville MGP RA 1964	Excavations in area 4.	Direction: SW
					
Mechanicville MGP RA 1970	Excavations in area 4.	Direction: SE	Mechanicville MGP RA 1972	Excavations in area 4.	Direction: SE
					
Mechanicville MGP RA 1973	Excavations in area 4.	Direction: SE	Mechanicville MGP RA 1975	Excavations in area 4.	Direction: SW

					
Mechanicville MGP RA 1976	Backfilling operations in area 4.	Direction: E	Mechanicville MGP RA 1978	Backfilling operations in area 4.	Direction: W
					
Mechanicville MGP RA 1984	Installation of geo-fabric in area 4.	Direction: SW	Mechanicville MGP RA 1986	Installation of geo-fabric in area 4.	Direction: W
					
Mechanicville MGP RA 1991	Installation of rip-rap in area 4.	Direction: W	Mechanicville MGP RA 1992	Installation of rip-rap in area 4.	Direction: SW

Daily Photograph Log for March 30, 2009



Mechanicville MGP RA 1993	Excavations in area 4.	Direction: W



Mechanicville MGP RA 1994	Excavations in area 4.	Direction: W



Mechanicville MGP RA 1995	Excavations in area 4.	Direction: W



Mechanicville MGP RA 1996	Excavations in area 4.	Direction: W



Mechanicville MGP RA 1997	Excavations in area 4.	Direction: NE



Mechanicville MGP RA 1999	Excavations in area 4.	Direction: SW

					
Mechanicville MGP RA 2000	Backfilling operations in area 4.	Direction: NE	Mechanicville MGP RA 2002	Backfilling operations in area 4.	Direction: W
					
Mechanicville MGP RA 2003	Installation of geo-fabric in area 4.	Direction: W	Mechanicville MGP RA 2004	Installation of geo-fabric in area 4.	Direction: NE

Daily Photograph Log for March 31, 2009

					
Mechanicville MGP RA 2014	Demolition of foundations in area 4.	Direction: SE	Mechanicville MGP RA 2021	Demolition of foundations in area 4.	Direction: SW
					
Mechanicville MGP RA 2023	Demolition of foundations in area 4.	Direction: SW	Mechanicville MGP RA 2024	Demolition of foundations in area 4.	Direction: E
					
Mechanicville MGP RA 2025	Demolition of foundations in area 4.	Direction: NE	Mechanicville MGP RA 2029	Demolition of foundations in area 4.	Direction: SW

					
Mechanicville MGP RA 2030	Cleaning of "surge" tank.	Direction:	Mechanicville MGP RA 2031	Demolition of foundations in area 4.	Direction: NE
					
Mechanicville MGP RA 2032	Demolition of foundations in area 4.	Direction: W	Mechanicville MGP RA 2033	Fracture in bedrock near "point" in streambank.	Direction: S
					
Mechanicville MGP RA 1935	Moving "surge" tank.	Direction: E	Mechanicville MGP RA 1936	Staging of "surge" tank for demobilization.	Direction: NE

Daily Photograph Log for April 01, 2009



Mechanicville MGP RA 2041	Demolition of foundations in area 4.	Direction: W



Mechanicville MGP RA 2042	Demolition of foundations in area 4.	Direction: SW



Mechanicville MGP RA 2044	Demolition of foundations in area 4.	Direction: NW



Mechanicville MGP RA 2045	Odor suppressant foam in area 4.	Direction: NE



Mechanicville MGP RA 2047	Excavations in area 4.	Direction: NE



Mechanicville MGP RA 2049	Excavations in area 4.	Direction: N

					
Mechanicville MGP RA 2051	Excavations in area 4.	Direction: E	Mechanicville MGP RA 2052	Excavations in area 4.	Direction: SE
					
Mechanicville MGP RA 2054	Excavations in area 4.	Direction: N	Mechanicville MGP RA 2059	Excavations in area 4.	Direction: N
					
Mechanicville MGP RA 1962	Backfilling in area 4.	Direction: NE	Mechanicville MGP RA 1965	Backfilling in area 4.	Direction: NE

Daily Photograph Log for April 02, 2009

					
Mechanicville MGP RA 2068	Demolition of foundations in area 4.	Direction: W	Mechanicville MGP RA 2071	Demolition of foundations in area 4.	Direction: SW
					
Mechanicville MGP RA 2073	Demolition of foundations in area 4.	Direction: NW	Mechanicville MGP RA 2076	Odor suppressant foam in area 4.	Direction: NE
					
Mechanicville MGP RA 2077	Excavations in area 4.	Direction: NE	Mechanicville MGP RA 2080	Excavations in area 4.	Direction: N

					
Mechanicville MGP RA 2084	Excavations in area 4.	Direction: E	Mechanicville MGP RA 2085	Excavations in area 4.	Direction: SE
					
Mechanicville MGP RA 2087	Excavations in area 4.	Direction: N	Mechanicville MGP RA 2088	Excavations in area 4.	Direction: N
					
Mechanicville MGP RA 2092	Backfilling in area 4.	Direction: NE	Mechanicville MGP RA 2093	Backfilling in area 4.	Direction: NE

Daily Photograph Log for April 03, 2009



Mechanicville MGP RA 2096	Excavations in area 2.	Direction: S



Mechanicville MGP RA 2098	Excavations in area 2.	Direction: SW



Mechanicville MGP RA 2100	Excavations in area 2.	Direction: E



Mechanicville MGP RA 2104	Excavations in area 2.	Direction: S



Mechanicville MGP RA 2106	Excavations and backfilling in area 2.	Direction: SW



Mechanicville MGP RA 2108	Excavations in area 2.	Direction: S

					
Mechanicville MGP RA 2110	Excavations in area 2.	Direction: W	Mechanicville MGP RA 2112	Ridge in bedrock in area 2.	Direction: W
					
Mechanicville MGP RA 2113	Backfilling in area 2.	Direction: NW	Mechanicville MGP RA 2114	Demolition of foundations in area 2/4.	Direction: S
					
Mechanicville MGP RA 2119	Excavations and demolition of foundations in area 2/4.	Direction: NW	Mechanicville MGP RA 2121	Progress in areas 2, 2/4, and 4.	Direction: SW

Daily Photograph Log for April 06, 2009



Mechanicville MGP RA 2131	Excavations in area 2/4.	Direction: SW



Mechanicville MGP RA 2136	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 2138	Mark out of west side wall of area 3B for pretrench.	Direction: N



Mechanicville MGP RA 2140	Progress in areas 2, 2/4, and 4.	Direction: SW



Mechanicville MGP RA 2141	Excavation of west sidewall of area 3B.	Direction: N



Mechanicville MGP RA 2142	Excavation of west sidewall of area 3B.	Direction: N

					
Mechanicville MGP RA 2143	Excavation of west sidewall of area 3B.	Direction: W	Mechanicville MGP RA 2145	Excavation of west sidewall of area 3B.	Direction: W
					
Mechanicville MGP RA 2146	Excavation of west sidewall of area 3B.	Direction: W	Mechanicville MGP RA 2148	Excavation of west sidewall of area 3B.	Direction: W
					
Mechanicville MGP RA 2149	Excavation of west sidewall of area 3B.	Direction: W	Mechanicville MGP RA 2150	Progress in areas 2, 2/4, and 4.	Direction: SW

Daily Photograph Log for April 07, 2009



Mechanicville MGP RA 2151	Progress in areas 2, 2/4, and 4.	Direction: W



Mechanicville MGP RA 2153	Cleanout of WWTP baffle tank.	Direction: SW



Mechanicville MGP RA 2154	Cleanout of WWTP baffle tank.	Direction: E



Mechanicville MGP RA 2156	Cleanout of WWTP baffle tank.	Direction: NE



Mechanicville MGP RA 2157	Cleanout of WWTP baffle tank.	Direction: NE



Mechanicville MGP RA 2159	Loadout of soil from area 2.	Direction: N

					
Mechanicville MGP RA 2161	Progress in areas 2, 2/4, and 4.	Direction: SW	Mechanicville MGP RA 2164	Excavation in area 2.	Direction: S
					
Mechanicville MGP RA 2168	Excavation in area 2.	Direction: S	Mechanicville MGP RA 2170	Odor suppressant foam on stockpiled soil in area 2.	Direction: E
					
Mechanicville MGP RA 2171	Backfilling operations in areas2, 2/4, and 4.	Direction: E	Mechanicville MGP RA 2172	Backfilling operations in areas2, 2/4, and 4.	Direction: W

Daily Photograph Log for April 08, 2009

					
Mechanicville MGP RA 2179	Installation of geo-textile and rip-rap in area 4.	Direction: SW	Mechanicville MGP RA 2180	Installation of silt fence along the Anthony Kill.	Direction: SW
					
Mechanicville MGP RA 2187	Cleanout of WWTP organo-clay vessel.	Direction: E	Mechanicville MGP RA 2188	Cleanout of WWTP organo-clay vessel.	Direction: E
					
Mechanicville MGP RA 2195	Excavation in area 2.	Direction: S	Mechanicville MGP RA 2196	Excavation in area 2.	Direction: SE

					
Mechanicville MGP RA 2197	Excavation in area 2.	Direction: SE	Mechanicville MGP RA 2199	Excavation in area 2.	Direction: S
					
Mechanicville MGP RA 2201	Excavation in area 2.	Direction: S	Mechanicville MGP RA 2203	Demobilization of circular whaler sections.	Direction: N
					
Mechanicville MGP RA 2204	Mobilization of ABI.	Direction: SW	Mechanicville MGP RA 2205	Demobilization of circular whaler sections.	Direction: S

Daily Photograph Log for April 09, 2009



Mechanicville MGP RA 2206	Excavation in area 2.	Direction: W



Mechanicville MGP RA 2207	Backfilling in area 2.	Direction: NW



Mechanicville MGP RA 2209	Removal of sheet piles in area 3A.	Direction: E



Mechanicville MGP RA 2210	Backfilling in area 2.	Direction: W



Mechanicville MGP RA 2212	Excavation in area 2.	Direction: E



Mechanicville MGP RA 2213	Excavation in area 2.	Direction: SE

					
Mechanicville MGP RA 2214	Survey in area 2.	Direction: S	Mechanicville MGP RA 2215	Survey in area 2.	Direction: S
					
Mechanicville MGP RA 2216	Survey in area 2.	Direction: S	Mechanicville MGP RA 2217	Survey in area 2.	Direction: S
					
Mechanicville MGP RA 2218	Progress in areas 2 and 4.	Direction: NW	Mechanicville MGP RA 2219	Progress in areas 2 and 4.	Direction: E

Daily Photograph Log for April 10, 2009

					
Mechanicville MGP RA 2220	Removal of sheet piles in area 3A.	Direction: W	Mechanicville MGP RA 2221	Removal of sheet piles in area 3A.	Direction: NE
					
Mechanicville MGP RA 2224	Installation of temporary fence near area 3A.	Direction: S	Mechanicville MGP RA 2225	Excavations in area 2.	Direction: S
					
Mechanicville MGP RA 2227	Backfilling in area 2.	Direction: W	Mechanicville MGP RA 2230	Damage to sheet piles from area 3A.	Direction: SW

					
Mechanicville MGP RA 2232	Damage to sheet piles from area 3A.	Direction: SW	Mechanicville MGP RA 2233	Damage to sheet piles from area 3A.	Direction: SW
					
Mechanicville MGP RA 2234	Excavations in area 2.	Direction: S	Mechanicville MGP RA 2236	Dust control.	Direction: SE
					
Mechanicville MGP RA 2240	Backfilling in area 2.	Direction: NW	Mechanicville MGP RA 2241	Backfilling in area 2.	Direction: SW

Daily Photograph Log for April 13, 2009



Mechanicville MGP RA 2243	Clearing of brush for area 3B.	Direction: N



Mechanicville MGP RA 2244	Removal decorative trees in area 3B.	Direction: W



Mechanicville MGP RA 2246	Progress of backfill in area 2.	Direction: S



Mechanicville MGP RA 2247	Progress of backfill in area 2.	Direction: W



Mechanicville MGP RA 2249	Survey-layout of area 3B.	Direction: W



Mechanicville MGP RA 2253	Removal decorative trees in area 3B.	Direction: SW

					
Mechanicville MGP RA 2254	Removal decorative trees in area 3B.	Direction: NE	Mechanicville MGP RA 2255	Moving of guy wires over area 1.	Direction: N
					
Mechanicville MGP RA 2257	Removal decorative trees in area 3B.	Direction: N	Mechanicville MGP RA 2259	Dust control.	Direction: N
					
Mechanicville MGP RA 2260	Backfilling in area 2.	Direction: NW	Mechanicville MGP RA 2262	Spudding to verify depth to bedrock in area 3B.	Direction: SW

Daily Photograph Log for April 14, 2009



Mechanicville MGP RA 2266	Test excavation in area 1.	Direction: SW



Mechanicville MGP RA 2267	Test excavation in area 1.	Direction: SW



Mechanicville MGP RA 2268	Tar and water in test excavation in area 1.	Direction: W



Mechanicville MGP RA 2269	Tar and water in test excavation in area 1.	Direction: NW



Mechanicville MGP RA 2270	Tar and water in test excavation in area 1.	Direction: W



Mechanicville MGP RA 2271	Tar and water in test excavation in area 1.	Direction: W

					
Mechanicville MGP RA 2272	Backfill of test excavation in area 1.	Direction: N	Mechanicville MGP RA 2274	Sheet pile preparations for area 3B.	Direction: SW
					
Mechanicville MGP RA 2275	Sheet pile preparations for area 3B.	Direction: E	Mechanicville MGP RA 2276	Turbidity curtain installed for excavations in area 1.	Direction: W
					
Mechanicville MGP RA 2278	Excavations with NYSEG gas dept. to find gas main.	Direction: N	Mechanicville MGP RA 2279	Excavations with NYSEG gas dept. to find gas main.	Direction: NE

Daily Photograph Log for April 15, 2009



Mechanicville MGP RA 2287	Installation of HDPE pipe under haul road.	Direction: W



Mechanicville MGP RA 2296	Excavations in area 1.	Direction: NW



Mechanicville MGP RA 2297	Excavations in area 1.	Direction: N



Mechanicville MGP RA 2298	Excavations in area 1.	Direction: N



Mechanicville MGP RA 2299	Excavations in area 1.	Direction: N



Mechanicville MGP RA 2307	Clean-out of WWTP baffle tank.	Direction:

					
Mechanicville MGP RA 2309	Clean-out of WWTP baffle tank.	Direction:	Mechanicville MGP RA 2312	Excavations in area 1.	Direction: N
					
Mechanicville MGP RA 2313	Sheet pile installations in area 3B.	Direction: S	Mechanicville MGP RA 2314	Sheet pile installations in area 3B.	Direction: SW
					
Mechanicville MGP RA 2315	Piian system installed along the Anthony Kill.	Direction: NE	Mechanicville MGP RA 2316	Piian system installed along the Anthony Kill.	Direction: NW

Daily Photograph Log for April 16, 2009



Mechanicville MGP RA 2333	Dark tarry spot in North sidewall of area 1.	Direction: N



Mechanicville MGP RA 2339	Streambank adjacent to area 1.	Direction: S



Mechanicville MGP RA 2350	Clean-out of WWTP baffle tank.	Direction: E



Mechanicville MGP 2351	Clean-out of WWTP baffle tank.	Direction:



Mechanicville MGP RA 2353	Collection of confirmation samples in area 1.	Direction: NE



Mechanicville MGP RA 2357	Collection of confirmation samples in area 1.	Direction: NW

					
Mechanicville MGP RA 2358	Collection of confirmation samples in area 1.	Direction: N	Mechanicville MGP RA 2360	Collection of confirmation samples in area 1.	Direction: N
					
Mechanicville MGP RA 2361	Collection of confirmation samples in area 1.	Direction: W	Mechanicville MGP RA 2362	Collection of confirmation samples in area 1.	Direction: W
					
Mechanicville MGP RA 2366	Installation of sheet piles in area 3B.	Direction: NE	Mechanicville MGP RA 2367	Installation of sheet piles in area 3B.	Direction: N

Daily Photograph Log for April 17, 2009

					
Mechanicville MGP RA 2368	NAPL in test pit in area 3B.	Direction: E	Mechanicville MGP RA 2371	Waste characterization test pitting in area 3B.	Direction: SE
					
Mechanicville MGP RA 2374	Waste characterization test pitting in area 3B.	Direction: S	Mechanicville MGP 2382	House fire SW of site that affected CAMP readings for the rest of workday.	Direction: SW
					
Mechanicville MGP RA 2384	Installation of sheet piles in area 3B.	Direction: N	Mechanicville MGP RA 2386	Installation of sheet piles in area 3B.	Direction: NW

					
Mechanicville MGP RA 2387	Installation of sheet piles in area 3B.	Direction: E	Mechanicville MGP RA 2393	Backfilling in area 1.	Direction: E
					
Mechanicville MGP RA 2394	Backfilling in area 1.	Direction: SE	Mechanicville MGP RA 2396	Backfilling in area 1.	Direction: E
					
Mechanicville MGP RA 2398	Backfilling in area 1.	Direction: NE	Mechanicville MGP RA 2399	Backfilling in area 1.	Direction: E

Daily Photograph Log for April 20, 2009



Mechanicville MGP RA 2400	Water management in area 1.	Direction: E



Mechanicville MGP RA 2401	Water management in area 1.	Direction: E



Mechanicville MGP RA 2402	Water management in area 1.	Direction: E



Mechanicville MGP 2403	Excavation in area 1.	Direction: SE



Mechanicville MGP RA 2404	Installation of sheet piles in area 3B.	Direction: NE



Mechanicville MGP RA 2408	Excavation in area 1.	Direction: SW

					
Mechanicville MGP RA 2409	Excavation in area 1.	Direction: SW	Mechanicville MGP RA 2410	Odor control in area 1.	Direction: SE
					
Mechanicville MGP RA 2411	Water management in area 1.	Direction: S	Mechanicville MGP RA 2412	Water management in area 1.	Direction: SE
					
Mechanicville MGP RA 2414	Installation of sheet piles in area 3B.	Direction: E	Mechanicville MGP RA 2415	Installation of sheet piles in area 3B.	Direction: E

Daily Photograph Log for April 21, 2009



Mechanicville MGP RA 2417	Excavation in area 1.	Direction: E



Mechanicville MGP RA 2419	Installation of sheet piles in area 3B.	Direction: W



Mechanicville MGP RA 2420	Excavation in area 1.	Direction: W



Mechanicville MGP RA 2423	Relocation of Sevenson container for excavation in area 1.	Direction: NW



Mechanicville MGP RA 2426	Welding of sheet pile interlock tee's for area 3B.	Direction: E



Mechanicville MGP RA 2427	Endpoint sampling in area 1.	Direction: N

					
Mechanicville MGP RA 2428	Excavation in area 1.	Direction: S	Mechanicville MGP RA 2429	Excavation in area 1.	Direction: SW
					
Mechanicville MGP RA 2431	Installation of sheet piles in area 3B.	Direction: N	Mechanicville MGP RA 2432	Installation of sheet piles in area 3B.	Direction: NE
					
Mechanicville MGP RA 2434	Progress in area 1.	Direction: E	Mechanicville MGP RA 2435	Progress in area 1.	Direction: N

Daily Photograph Log for April 22, 2009

					
Mechanicville MGP RA 2436	Western Limits of Area 1 Excavation	Direction: NW	Mechanicville MGP RA 2437	Eastern Limits of Area 1 Excavation	Direction: NE
					
Mechanicville MGP RA 2438	ABI Broke Down	Direction: N	Mechanicville MGP RA 2439	Backfilling of Area 1, Test Trench Area in front of Sevenson Trailer	Direction: S
					
Mechanicville MGP RA 2440	Backfilling Area 1	Direction: W	Mechanicville MGP RA 2441	MAB repairing ABI	Direction: E

					
Mechanicville MGP RA 2442	Sevenson taking PID Readings at Area 1 Limits	Direction:	Mechanicville MGP RA 2444	ABI repaired and installing sheets.	Direction: E
					
Mechanicville MGP RA 2445	Area 1 Confirmation Sample: MCEXBM06009	Direction:	Mechanicville MGP RA 2446	Area 1 Confirmation Sample: MCEXSW04010	Direction:
					
Mechanicville MGP RA 2447	Placing fill against southern limit of Area 1 for stability	Direction: NE	Mechanicville MGP RA 2448	Placing fill against southern limit of Area 1 for stability	Direction: W

Daily Photograph Log for April 23, 2009



Mechanicville MGP RA 2450	Sevenson unloading materials in GA Bove area	Direction: SW



Mechanicville MGP RA 2451	Sandbag berm around Area 1 to divert stormwater	Direction: N



Mechanicville MGP RA 2452	ABI Installing sheets in Area 3b	Direction: SE



Mechanicville MGP RA 2453	Sheet pile template. Driving North wall of Area 3b	Direction: NE



Mechanicville MGP RA 2454	Sheet Pile operations	Direction: W



Mechanicville MGP RA 2455	Sheet Pile staging area	Direction: SW

					
Mechanicville MGP RA 2456	Installation of Fin walls on North wall of Area 3	Direction: E	Mechanicville MGP RA 2457	Stock pile of backfill materials, pending Area 1 Sample results	Direction: W
					
Mechanicville MGP RA 2458	Area 3b sheet pile installation	Direction: E	Mechanicville MGP RA 2459	Sheet Pile Installation, Area 3b	Direction: W
					
Mechanicville MGP RA 2460	Area 3 Fin wall	Direction: W			

Daily Photograph Log for April 24, 2009

					
Mechanicville MGP RA 2461	Safety Fence around Area 1 Perimeter	Direction: NE	Mechanicville MGP RA 2462	Area 1 slope protection	Direction: NE
					
Mechanicville MGP RA 2463	ABI Installing sheets in Area 3b	Direction: E	Mechanicville MGP RA 2464	Sevenson installing Odor suppression system around area 3b	Direction: E
					
Mechanicville MGP RA 2465	Area 2 cleaned up and ready for guy wires to be moved	Direction: N	Mechanicville MGP RA 2466	Backfill stockpile	Direction: NE

					
Mechanicville MGP RA 2470	Sevenson building ramp for ABI access to east wall of Area 3b	Direction: NE	Mechanicville MGP RA 2471	Sheet Pile Installation, Area 3b	Direction: N
					
Mechanicville MGP RA 2472	Sevenson backfilling and tracking in area 1	Direction: NE	Mechanicville MGP RA 2473	Sevenson backfilling and tracking in area 1	Direction: SW
					
Mechanicville MGP RA 2474	Sevenson backfilling and tracking in area 1	Direction: W	Mechanicville MGP RA 2475	Sevenson backfilling and tracking in area 1.	Direction: W

Daily Photograph Log for April 27, 2009



Mechanicville MGP RA 2476	Roller compaction in area 1.	Direction: W



Mechanicville MGP RA 2479	NYSEG relocating guy wires to original positions.	Direction: W



Mechanicville MGP RA 2481	NYSDEC investigation across Central Ave at Getty Station	Direction: SW



Mechanicville MGP RA 2487	Excavations in area 2.	Direction: W



Mechanicville MGP RA 2489	Spreading of crushed stone surface in area 1.	Direction: NW



Mechanicville MGP RA 2491	Excavations in area 2.	Direction: W

					
Mechanicville MGP RA 2492	Excavations in area 2.	Direction: W	Mechanicville MGP RA 2494	Sheet Pile Installation, Area 3B	Direction: S
					
Mechanicville MGP RA 2497	Building ramp for ABI access to east wall of Area 3B	Direction: E	Mechanicville MGP RA 2498	Building ramp for ABI access to east wall of Area 3B	Direction: W
					
Mechanicville MGP RA 2499	Building ramp for ABI access to east wall of Area 3B	Direction: SE	Mechanicville MGP RA 2500	Installation of sheet piles in area 3B.	Direction: E

Daily Photograph Log for April 28, 2009



Mechanicville MGP RA 2507	Roller compaction in area 1.	Direction: SW



Mechanicville MGP RA 2508	NYSEG relocating guy wires to original positions.	Direction: SW



Mechanicville MGP RA 2510	NYSDEC investigation across Central Ave at Getty Station	Direction: SW



Mechanicville MGP RA 2514	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 2515	Spreading of crushed stone surface in area 1.	Direction: SW



Mechanicville MGP RA 2516	Excavations in area 2.	Direction: NW

					
Mechanicville MGP RA 2518	# 1 stone sump in area 2covered with geo-fabric and ESMI treated fill.	Direction: E	Mechanicville MGP RA 2519	# 1 stone sump in area 2covered with geo-fabric and ESMI treated fill.	Direction: E
					
Mechanicville MGP RA 2521	Apllication of sealant to sheet piles.	Direction: SW	Mechanicville MGP RA 2524	Backfilling in area 2	Direction: W
					
Mechanicville MGP RA 2526	Backfilling in area 2	Direction: NW	Mechanicville MGP RA 2530	Installation of sheet piles in area 3B.	Direction: N

Daily Photograph Log for April 29, 2009



Mechanicville MGP RA 2532	Construction of ramp for ABI in area 3B.	Direction: W



Mechanicville MGP RA 2534	Toe pin installation in area 3B.	Direction: SW



Mechanicville MGP RA 2535	Toe pin installation in area 3B.	Direction: SW



Mechanicville MGP RA 2541	Backfilling operations in area 2.	Direction: NE



Mechanicville MGP RA 2546	Installation of sheet piles in area 3B.	Direction: NE



Mechanicville MGP RA 2547	Delivery of #3 washed stone for surface in area 1.	Direction: NE

					
Mechanicville MGP RA 2548	Crushed stone surface in area 1.	Direction: W	Mechanicville MGP RA 2550	Toe pin operations in area 3B.	Direction: W
					
Mechanicville MGP RA 2551	Finished surface in area 1.	Direction: NW	Mechanicville MGP RA 2554	Toe pin operations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2555	Installation of sheet piles in area 3B.	Direction: E	Mechanicville MGP RA 2556	Installation of sheet piles in area 3B.	Direction: N

Daily Photograph Log for April 30, 2009



Mechanicville MGP RA 2559	Excavations south of area 2 for NAPL in area 2 south sidewall.	Direction: S



Mechanicville MGP RA 2561	Excavations south of area 2 for NAPL in area 2 south sidewall.	Direction: S



Mechanicville MGP RA 2562	Excavations south of area 2 for NAPL in area 2 south sidewall.	Direction: S



Mechanicville MGP RA 2571	Excavations in area 3B to allow sheet pile installation	Direction: E



Mechanicville MGP RA 2576	Excavations in expanded area 2.	Direction: SE



Mechanicville MGP RA 2578	Excavations in expanded area 2.	Direction: SE

					
Mechanicville MGP RA 2580	Excavations in expanded area 2.	Direction: E	Mechanicville MGP RA 2582	Toe pin operations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2584	Finished surface in area 1.	Direction: S	Mechanicville MGP RA 2585	Excavations in expanded area 2.	Direction: S
					
Mechanicville MGP RA 2587	Installation of sheet piles in area 3B.	Direction: E	Mechanicville MGP RA 2589	Installation of sheet piles in area 3B.	Direction: S

Daily Photograph Log for May 01, 2009



Mechanicville MGP RA 2593	Excavations in area 2.	Direction: E



Mechanicville MGP RA 2595	Toe pin installations in area 3B.	Direction: W



Mechanicville MGP RA 2596	Sheet pile installations in area 3B.	Direction: W



Mechanicville MGP RA 2597	Excavations in area 2.	Direction: E



Mechanicville MGP RA 2598	Excavations in area 2.	Direction: SE



Mechanicville MGP RA 2599	Backfilling in area 2.	Direction: N

					
Mechanicville MGP RA 2602	Backfilling in area 2.	Direction: N	Mechanicville MGP RA 2603	Odor-suppressant foam used in area 2.	Direction: SE
					
Mechanicville MGP RA 2604	Backfilling in area 2.	Direction: N	Mechanicville MGP RA 2606	Backfilling in area 2.	Direction: W
					
Mechanicville MGP RA 2607	Backfilling in area 2.	Direction: W	Mechanicville MGP RA 2610	Installation of sheet piles in area 3B.	Direction: E

Daily Photograph Log for May 04, 2009

					
Mechanicville MGP RA 2612	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 2631	Confirmation sampling in area 2.	Direction: SE
					
Mechanicville MGP RA 2632	Backfilling in area 2.	Direction: NE	Mechanicville MGP RA 2633	Backfilling in area 2.	Direction: NE
					
Mechanicville MGP RA 2639	Excavations in area 2.	Direction: W	Mechanicville MGP RA 2640	Confirmation sample location in area 2.	Direction: S

					
Mechanicville MGP RA 2643	Backfilling in area 2.	Direction: N	Mechanicville MGP RA 2644	Backfilling in area 2.	Direction: W
					
Mechanicville MGP RA 2645	Toe pin installation in area 3B.	Direction: E	Mechanicville MGP RA 2647	Installation of sheet piles in area 3A as tie backs in area 3B.	Direction: W
					
Mechanicville MGP RA 2648	Odor-suppressant foam in area 2.	Direction: SW	Mechanicville MGP RA 2649	Installation of sheet piles in area 3A as tie backs in area 3B.	Direction: E

Daily Photograph Log for May 05, 2009

					
Mechanicville MGP RA 2656	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 2658	Excavations in area 2.	Direction: SE
					
Mechanicville MGP RA 2659	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 2661	Water management in area 2.	Direction: S
					
Mechanicville MGP RA 2665	Installation of toe pins in area 3B.	Direction: E	Mechanicville MGP RA 2668	Installation of toe pins in area 3B.	Direction: S

					
Mechanicville MGP RA 2669	Backfilling in area 2.	Direction: W	Mechanicville MGP RA 2670	Excavation and load out of soils in area 2.	Direction: S
					
Mechanicville MGP RA 2671	Backfilling in area 2.	Direction: SW	Mechanicville MGP RA 2673	Backfilling in area 2.	Direction: SW
					
Mechanicville MGP RA 2675	Installation of toe pins in area 3B.	Direction: E	Mechanicville MGP RA 2676	Backfilling in area 2.	Direction: S

Daily Photograph Log for May 06, 2009

					
Mechanicville MGP RA 2679	Excavations in area 2.	Direction: S	Mechanicville MGP RA 2682	Excavations in area 2.	Direction: S
					
Mechanicville MGP RA 2701	Excavations in area 3B to install upper whaler.	Direction: E	Mechanicville MGP RA 2703	Excavations in area 3B to install upper whaler.	Direction: W
					
Mechanicville MGP RA 2709	Excavations in area 2.	Direction: S	Mechanicville MGP RA 2710	Brick structures holding pipes in area 2.	Direction: S

					
Mechanicville MGP RA 2711	Brick structures holding pipes in area 2.	Direction: S	Mechanicville MGP RA 2717	Backfilling in area 2.	Direction: E
					
Mechanicville MGP RA 2720	Excavations in area 3B to install upper whaler.	Direction: NE	Mechanicville MGP RA 2721	Excavations in area 3B to install upper whaler.	Direction: NE
					
Mechanicville MGP RA 2725	Grouting of pipe in area 2 sidewall.	Direction: W	Mechanicville MGP RA 2726	Grouting of pipe in area 2 sidewall.	Direction: W

Daily Photograph Log for May 07, 2009



Mechanicville MGP RA 2732	Break down of ABI for demobilization.	Direction: E



Mechanicville MGP RA 2733	Excavations and load out of soils in area 2.	Direction: S



Mechanicville MGP RA 2734	Installation of toe pins in area.	Direction: SW



Mechanicville MGP RA 2737	Excavations in area 2.	Direction: SW






Mechanicville MGP RA 2739	Installation of toe pins in area.	Direction: E



Mechanicville MGP RA 2740	Excavations and load out of soils in area 2.	Direction: S

					
Mechanicville MGP RA 2743	Backfilling in area 2.	Direction: E	Mechanicville MGP RA 2744	Backfilling in area 2.	Direction: E
					
Mechanicville MGP RA 2745	Excavations in area 2.	Direction: W	Mechanicville MGP RA 2748	Excavations in area 2 in collapsing water-saturated area.	Direction: SW
					
Mechanicville MGP RA 2749	Installation of toe pins in area.	Direction: NW	Mechanicville MGP RA 2750	Backfilling in area 2.	Direction: S

Daily Photograph Log for May 08, 2009

					
Mechanicville MGP RA 2772	Confirmation sampling in area 2.	Direction: SE	Mechanicville MGP RA 2776	Confirmation sampling in area 2.	Direction: SE
					
Mechanicville MGP RA 2778	Confirmation sampling in area 2.	Direction: SE	Mechanicville MGP RA 2780	South sidewall of excavations in area 2.	Direction: SE
					
Mechanicville MGP RA 2782	Excavations in area 2.	Direction: SE	Mechanicville MGP RA 2783	Preparations for backfill in area 2.	Direction: SE

					
Mechanicville MGP RA 2785	Preparations for backfill in area 2.	Direction: SE	Mechanicville MGP RA 2787	Backfilling in area 2.	Direction: NW
					
Mechanicville MGP RA 2788	Backfilling in area 2.	Direction: NW	Mechanicville MGP RA 2789	Backfilling in area 2.	Direction: NW
					
Mechanicville MGP RA 2792	Backfilling in area 2.	Direction: NW	Mechanicville MGP RA 2793	Backfilling in area 2.	Direction: SE

Daily Photograph Log for May 11, 2009

					
Mechanicville MGP RA 2796	Geo-textile placed for reconstruction of site road.	Direction: NW	Mechanicville MGP RA 2825	Reconstruction of site road with crushed stone and #3 washed stone surface.	Direction: SE
					
Mechanicville MGP RA 2827	Reconstruction of site road.	Direction: N	Mechanicville MGP RA 2828	Ferris Lane with #3 washed stone surface for dust control.	Direction: E
					
Mechanicville MGP RA 2829	Ferris Lane with #3 washed stone surface for dust control.	Direction: S	Mechanicville MGP RA 2830	Progress on site.	Direction: SW

					
Mechanicville MGP RA 2831	Installation of toe pins in area 3B.	Direction: SW	Mechanicville MGP RA 2832	Installation of tie-backs in area 3A for area 3B.	Direction: W
					
Mechanicville MGP RA 2834	Ferris Lane with #3 washed stone surface for dust control.	Direction: E	Mechanicville MGP RA 2835	Reconstruction of site road.	Direction: N
					
Mechanicville MGP RA 2836	Odor-supressant foam in area 3B.	Direction: W	Mechanicville MGP RA 2837	Installation of toe pins in area 3B.	Direction: W

Daily Photograph Log for May 12, 2009



Mechanicville MGP RA 2838	Installation of tie-backs in area 3A for area 3B.	Direction: E



Mechanicville MGP RA 2839	Installation of tie-backs in area 3A for area 3B.	Direction: N



Mechanicville MGP RA 2840	Backfill of tie-backs in area 3A.	Direction: W



Mechanicville MGP RA 2848	Installation of last toe pin in area 3B.	Direction: E



Mechanicville MGP RA 2850	Excavation in area 3B.	Direction: N



Mechanicville MGP RA 2852	Load out of soils from area 3B to ESMI.	Direction: NW

					
Mechanicville MGP RA 2854	Preparation of whalers for area 3B.	Direction: E	Mechanicville MGP RA 2856	Excavation in area 3B.	Direction: NW
					
Mechanicville MGP RA 2859	Excavation and load out of soils in area 3B.	Direction: NW	Mechanicville MGP RA 2860	Excavation in area 3B.	Direction: N
					
Mechanicville MGP RA 2861	Installation of upper whaler in area 3B.	Direction: NE	Mechanicville MGP RA 2862	Installation of upper whaler in area 3B.	Direction: E

Daily Photograph Log for May 13, 2009

					
Mechanicville MGP RA 2868	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 2870	Excavations in area 3B.	Direction: SW
					
Mechanicville MGP RA 2875	Installation of upper whaler in area 3B.	Direction: NE	Mechanicville MGP RA 2879	Installation of upper whaler in area 3B.	Direction: NE
					
Mechanicville MGP RA 2880	Excavations in area 3B.	Direction: NW	Mechanicville MGP RA 2881	Excavations in area 3B.	Direction: NW

					
Mechanicville MGP RA 2883	Excavations in area 3B.	Direction: NE	Mechanicville MGP RA 2884	Excavation in area 3B.	Direction: SW
					
Mechanicville MGP RA 2885	Demobilization of Thomas D&B drill.	Direction: S	Mechanicville MGP RA 2887	Excavation in area 3B.	Direction: SW
					
Mechanicville MGP RA 2888	Installation of upper whaler in area 3B.	Direction: E	Mechanicville MGP RA 2889	Excavation in area 3B.	Direction: E

Daily Photograph Log for May 14, 2009

					
Mechanicville MGP RA 2891	Load out of soils from area 3B.	Direction: NW	Mechanicville MGP RA 2899	Excavations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2901	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 2902	Installation of dewatering sump in area 3B.	Direction: S
					
Mechanicville MGP RA 2905	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 2907	Installation of upper whaler in area 3B.	Direction: SW

					
Mechanicville MGP RA 2908	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 2909	Installation of upper whaler in area 3B.	Direction: S
					
Mechanicville MGP RA 2910	Excavations in area 3B.	Direction: NW	Mechanicville MGP RA 2911	Installation of upper whaler in area 3B.	Direction: E
					
Mechanicville MGP RA 2912	Poly sheeting cover in area 3B for odor control.	Direction: NE	Mechanicville MGP RA 2913	Installation of upper whaler in area 3B.	Direction: W

Daily Photograph Log for May 15, 2009



Mechanicville MGP RA 2919	Installation of upper whaler in area 3B.	Direction: E



Mechanicville MGP RA 2921	Excavations in area 3B.	Direction: E



Mechanicville MGP RA 2924	Excavations in area 3B.	Direction: N



Mechanicville MGP RA 2925	Excavations in area 3B.	Direction: N



Mechanicville MGP RA 2926	Excavations in area 3B.	Direction: N



Mechanicville MGP RA 2928	Excavations in area 3B.	Direction: N

					
Mechanicville MGP RA 2929	Excavations in area 3B.	Direction: N	Mechanicville MGP RA 2931	Excavations in area 3B.	Direction: NW
					
Mechanicville MGP RA 2933	Excavations in area 3B.	Direction: NW	Mechanicville MGP RA 2934	Excavations in area 3B.	Direction: NW
					
Mechanicville MGP RA 2936	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 2938	Odor-suppressant foam and poly sheeting weekend odor control.	Direction: W

Daily Photograph Log for May 18, 2009



Mechanicville MGP RA 2949	Excavations in area 3B.	Direction: S



Mechanicville MGP RA 2953	Excavations in area 3B.	Direction: SW



Mechanicville MGP RA 2956	Visible NAPL in area 3B.	Direction: SW



Mechanicville MGP RA 2958	Excavations in area 3B.	Direction: W



Mechanicville MGP RA 2962	Excavations in area 3B.	Direction: E



Mechanicville MGP RA 2969	Demolition of concrete foundations in area 3B.	Direction: N

					
Mechanicville MGP RA 2970	Repair of washouts on stream bank.	Direction: W	Mechanicville MGP RA 2971	Demolition of concrete foundations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2972	Demolition of concrete foundations in area 3B.	Direction: W	Mechanicville MGP RA 2974	Odor-suppressant foam on stockpile in area 3B.	Direction: SE
					
Mechanicville MGP RA 2975	Demolition of concrete foundations in area 3B.	Direction: S	Mechanicville MGP RA 2976	Demolition of concrete foundations in area 3B.	Direction: E

Daily Photograph Log for May 19, 2009



Mechanicville MGP RA 2982	Water management in area 3B.	Direction: S



Mechanicville MGP RA 2983	Excavations in area 3B.	Direction: SW



Mechanicville MGP RA 2984	Excavations in area 3B.	Direction: SW



Mechanicville MGP RA 2985	Excavations in area 3B.	Direction: W



Mechanicville MGP RA 2986	Excavations in area 3B.	Direction: E



Mechanicville MGP RA 2987	Excavations in area 3B.	Direction: N

					
Mechanicville MGP RA 2989	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 2990	Excavations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2991	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 2996	Excavations in area 3B.	Direction: SE
					
Mechanicville MGP RA 2997	Installation of lower whaler in area 3B.	Direction: S	Mechanicville MGP RA 2998	Installation of lower whaler in area 3B.	Direction: E

Daily Photograph Log for May 20, 2009



Mechanicville MGP RA 2999	Odor management in area 3B.	Direction: E



Mechanicville MGP RA 3001	Installation of lower whaler in area 3B.	Direction: SW



Mechanicville MGP RA 3002	Installation of lower whaler in area 3B.	Direction: SW



Mechanicville MGP RA 3004	Excavations in area 3B.	Direction: SW



Mechanicville MGP RA 3005	Installation of lower whaler in area 3B.	Direction: NE



Mechanicville MGP RA 3007	Excavations in area 3B.	Direction: SW

					
Mechanicville MGP RA 3008	Installation of lower whaler in SE corner of area 3B.	Direction:	Mechanicville MGP RA 3010	Excavations in area 3B.	Direction: E
					
Mechanicville MGP RA 3011	Excavations in area 3B.	Direction: SE	Mechanicville MGP RA 3012	Water flowing under southern sheet pile wall in area 3B.	Direction: W
					
Mechanicville MGP RA 3017	Water flowing under southern sheet pile wall in area 3B.	Direction: N	Mechanicville MGP RA 3021	Odor suppressant foam in area 3B.	Direction: SW

Daily Photograph Log for May 21, 2009

					
Mechanicville MGP RA 3022	High water in area 3B.	Direction: E	Mechanicville MGP RA 3026	Water management in area 3B.	Direction: NE
					
Mechanicville MGP RA 3030	Excavations in area 3B.	Direction: N	Mechanicville MGP RA 3031	Electric Power Research Institute personnel and equipment.	Direction: N
					
Mechanicville MGP RA 3033	Excavations in area 3B.	Direction: SE	Mechanicville MGP RA 3035	Excavations in area 3B.	Direction:

					
Mechanicville MGP RA 3036	Excavations in SE corner of area 3B.	Direction: SE	Mechanicville MGP RA 3038	Excavations in SE corner of area 3B.	Direction: SE
					
Mechanicville MGP RA 3039	Excavations in SE corner of area 3B.	Direction: SE	Mechanicville MGP RA 3042	Excavations in SE corner of area 3B.	Direction: SE
					
Mechanicville MGP RA 3043	Clay plug of water flowing under southern sheet pile wall in area 3B.	Direction: W	Mechanicville MGP RA 3044	Installation of lower whaler in area 3B.	Direction: E

Daily Photograph Log for May 22, 2009

					
Mechanicville MGP RA 3045	Excavations in area 3B.	Direction: NE	Mechanicville MGP RA 3046	Excavations in area 3B.	Direction: E
					
Mechanicville MGP RA 3047	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 3048	Excavations in area 3B.	Direction: E
					
Mechanicville MGP RA 3049	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 3050	Excavations in area 3B.	Direction: E

					
Mechanicville MGP RA 3051	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 3052	Excavations in area 3B.	Direction: E
					
Mechanicville MGP RA 3053	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 3054	Excavations in area 3B.	Direction: N
					
Mechanicville MGP RA 3055	Excavations in area 3B.	Direction: N	Mechanicville MGP RA 3056	Electric Power Research Institute personnel and odor experiment equipment.	Direction: N

Daily Photograph Log for May 26, 2009

					
Mechanicville MGP RA 3057	Weekend water accumulation in area 3B.	Direction: E	Mechanicville MGP RA 3058	Weekend water accumulation in area 3B.	Direction: SE
					
Mechanicville MGP RA 3059	Weekend water accumulation in area 3B.	Direction: NE	Mechanicville MGP RA 3061	Water flowing under south sheet pile wall in area 3B.	Direction: N
					
Mechanicville MGP RA 3062	Calcimente delivery.	Direction: W	Mechanicville MGP RA 3064	Excavations in area 3B.	Direction: SW

					
Mechanicville MGP RA 3066	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 3067	Excavations in area 3B.	Direction: N
					
Mechanicville MGP RA 3069	NYSEG gas personnel marking gas main under Ferris Lane.	Direction: W	Mechanicville MGP RA 3070	Mark-out of gas main under Ferris Lane	Direction: SW
					
Mechanicville MGP RA 3073	Mark-out of gas main under Ferris Lane	Direction: NW	Mechanicville MGP RA 3079	Odor-suppressant foam in area 3B.	Direction: E

Daily Photograph Log for May 27, 2009



Mechanicville MGP RA 3080	Mark-out of gas mains in area 5.	Direction: S



Mechanicville MGP RA 3097	Odor control in area 3B.	Direction: E



Mechanicville MGP RA 3098	Odor control during soil amendment in area 3B.	Direction: SE



Mechanicville MGP RA 3099	Soil amendment in area 3B.	Direction: NW



Mechanicville MGP RA 3103	Excavations in area 3B.	Direction: SE



Mechanicville MGP RA 3104	Excavations in area 3B.	Direction: W

					
Mechanicville MGP RA 3105	Soil amendment in area 3B.	Direction: NW	Mechanicville MGP RA 3108	Excavations in area 3B.	Direction: SE
					
Mechanicville MGP RA 3109	Excavations in area 3B.	Direction: E	Mechanicville MGP RA 3110	Area 5.	Direction: SE
					
Mechanicville MGP RA 3111	Mark-out of gas mains in area 5.	Direction: NW	Mechanicville MGP RA 3112	Excavations in area 3B.	Direction: NE

Daily Photograph Log for May 28, 2009



Mechanicville MGP RA 3123	Excavations in the SE corner of area 3B.	Direction: SE



Mechanicville MGP RA 3126	Bolder under sheet piles in NE corner of area 3B.	Direction: NE



Mechanicville MGP RA 3128	Excavations in the SE corner of area 3B.	Direction: E



Mechanicville MGP RA 3129	Excavations in the SE corner of area 3B.	Direction: E



Mechanicville MGP RA 3133	Excavations in the SE corner of area 3B.	Direction: S



Mechanicville MGP RA 3136	Excavations in the SE corner of area 3B.	Direction: S

					
Mechanicville MGP RA 3137	Excavations in the SE corner of area 3B.	Direction: S	Mechanicville MGP RA 3138	Excavations in area 3B.	Direction: NE
					
Mechanicville MGP RA 3141	Excavations in area 3B.	Direction: NW	Mechanicville MGP RA 3143	Sediment washing in under the SE corner of area 3B.	Direction: SE
					
Mechanicville MGP RA 3144	Excavations in the SE corner of area 3B.	Direction: SE	Mechanicville MGP RA 3145	Excavations in the SE corner of area 3B.	Direction: SE

Daily Photograph Log for May 29, 2009

					
Mechanicville MGP RA 3155	Boulders placed to hold cobble fill in area 3B.	Direction: SE	Mechanicville MGP RA 3161	Backfill in area 3B with cobbles.	Direction: E
					
Mechanicville MGP RA 3162	Excavations in area 3B.	Direction: SE	Mechanicville MGP RA 3163	Backfill in area 3B with cobbles.	Direction: NE
					
Mechanicville MGP RA 3164	Backfill in the SE corner of area 3B.	Direction: E	Mechanicville MGP RA 3165	Backfill in area 3B.	Direction: W

					
Mechanicville MGP RA 3166	Backfill in the SE corner of area 3B.	Direction: W	Mechanicville MGP RA 3167	Backfill in the SE corner of area 3B.	Direction: SW
					
Mechanicville MGP RA 3169	Excavations in area 3B.	Direction: W	Mechanicville MGP RA 3170	Backfill in area 3B.	Direction: NE
					
Mechanicville MGP RA 3171	Water level in the Anthony Kill.	Direction: NE	Mechanicville MGP RA 3172	Backfill in area 3B.	Direction: SE

Daily Photograph Log for June 01, 2009



Mechanicville MGP RA 3173	Site odor control systems.	Direction: NE



Mechanicville MGP RA 3174	Weekend water in area 3B.	Direction: NE



Mechanicville MGP RA 3175	Weekend water in area 3B.	Direction: NE



Mechanicville MGP RA 3176	Weekend water in area 3B.	Direction: NE



Mechanicville MGP RA 3178	Decontamination of PC-220 excavator.	Direction: NE



Mechanicville MGP RA 3179	Backfilling in area 3B.	Direction: E

					
Mechanicville MGP RA 3180	Backfill in the SW corner of area 3B.	Direction: S	Mechanicville MGP RA 3181	Water management in area 3B.	Direction: NE
					
Mechanicville MGP RA 3183	Backfilling in area 3B.	Direction: E	Mechanicville MGP RA 3184	Backfill in area 3B.	Direction: SE
					
Mechanicville MGP RA 3186	Backfilling in area 3B.	Direction: N	Mechanicville MGP RA 3187	Backfilling in area 3B.	Direction: E

Daily Photograph Log for June 02, 2009

					
Mechanicville MGP RA 3193	Washed #1 stone sump in NE corner of area 3B.	Direction: NE	Mechanicville MGP RA 3204	Geotextile cover over cobble fill in area 3B.	Direction: SE
					
Mechanicville MGP RA 3205	Water management in area 3B.	Direction: N	Mechanicville MGP RA 3212	Backfilling operations in area 3B.	Direction: NE
					
Mechanicville MGP RA 3213	Removing the lower whaler in area 3B.	Direction: NE	Mechanicville MGP RA 3215	Removing the lower whaler in area 3B.	Direction: NE

					
Mechanicville MGP RA 3221	Undermined sheet pile pair in the north wall of area 3B.	Direction: N	Mechanicville MGP RA 3224	Removing the upperr whaler in area 3B.	Direction: SE
					
Mechanicville MGP RA 3226	Backfilling in area 3B.	Direction: NE	Mechanicville MGP RA 3228	Backfilling in area 3B.	Direction: NE
					
Mechanicville MGP RA 3229	Backfilling in area 3B.	Direction: E	Mechanicville MGP RA 3230	Backfilling in area 3B.	Direction: SE

Daily Photograph Log for June 03, 2009



Mechanicville MGP RA 3231	Backfilling operations in area 3B.	Direction: NW



Mechanicville MGP RA 3232	Backfilling operations in area 3B.	Direction: NW



Mechanicville MGP RA 3233	Backfilling operations in area 3B.	Direction: NE



Mechanicville MGP RA 3235	Backfilling operations in area 3B.	Direction: E



Mechanicville MGP RA 3236	Backfilling in area 3B.	Direction: E



Mechanicville MGP RA 3237	Demobilization of whalers.	Direction: SE

					
Mechanicville MGP RA 3238	Backfilling in area 3B.	Direction: NE	Mechanicville MGP RA 3239	Backfilling in area 3B.	Direction: NE
					
Mechanicville MGP RA 3240	Backfilling in area 3B.	Direction: NE	Mechanicville MGP RA 3241	Backfilling in area 3B.	Direction: NE

Daily Photograph Log for June 04, 2009



Mechanicville MGP RA 3246	Backfilling operations in area 3B.	Direction: SW



Mechanicville MGP RA 3252	Decontamination of WWTP Fractionation tank.	Direction:



Mechanicville MGP RA 3253	Decontamination of WWTP Fractionation tank.	Direction:



Mechanicville MGP RA 3255	Backfilling operations in area 3B.	Direction: SW



Mechanicville MGP RA 3258	Backfilling operations in area 3B.	Direction: SW



Mechanicville MGP RA 3259	Backfilling operations in area 3B.	Direction: SW

					
Mechanicville MGP RA 3261	Backfilling operations in area 3B.	Direction: W	Mechanicville MGP RA 3263	Demobilization of unnecessary equipment.	Direction: E
					
Mechanicville MGP RA 3264	Backfilling operations in area 3B.	Direction: SW	Mechanicville MGP RA 3265	Backfilling operations in area 3B.	Direction: SW
					
Mechanicville MGP RA 3266	Backfilling operations in area 3B.	Direction: NW	Mechanicville MGP RA 3267	Backfilling operations in area 3B.	Direction: N

Daily Photograph Log for June 05, 2009



Mechanicville MGP RA 3268	Moving of turbidity curtain to area 2.	Direction: NW



Mechanicville MGP RA 3272	Removal of load out ramp from area 3B.	Direction: S



Mechanicville MGP RA 3273	Removal of tie backs from area 3A/B.	Direction: S



Mechanicville MGP RA 3275	New location of turbidity curtain.	Direction: W



Mechanicville MGP RA 3276	Removal of tie backs from area 3A/B.	Direction: NE



Mechanicville MGP RA 3277	Removal of tie backs from area 3A/B.	Direction:

					
Mechanicville MGP RA 3278	Cleaning of WWTP fractionation tank.	Direction:	Mechanicville MGP RA 3279	Cleaning of WWTP fractionation tank.	Direction:
					
Mechanicville MGP RA 3283	Draw down of water in WWTP baffle tank.	Direction:	Mechanicville MGP RA 3287	Removal of load out ramp from area 3B.	Direction: NE
					
Mechanicville MGP RA 3288	Removal of tie backs from area 3A/B.	Direction: E	Mechanicville MGP RA 3290	Backfilling/grading along Central Ave.	Direction: S

Daily Photograph Log for June 08, 2009

					
Mechanicville MGP RA 3291	Dust control.	Direction: E	Mechanicville MGP RA 3295	MAB receives APE pile driving hammer for pile removal.	Direction: NE
					
Mechanicville MGP RA 3296	MAB receives APE pile driving hammer for pile removal.	Direction: W	Mechanicville MGP RA 3297	Exposing of sheet piles for removal.	Direction: SW
					
Mechanicville MGP RA 3298	MAB receives their crane for pile removal.	Direction: NE	Mechanicville MGP RA 3299	Sheet pile removal operations in area 3B.	Direction: W

					
Mechanicville MGP RA 3300	Sheet pile removal operations in area 3B.	Direction: SE	Mechanicville MGP RA 3301	Sevenson demobilizing decontamination mats.	Direction: E
					
Mechanicville MGP RA 3303	Sheet pile removal operations in area 3B.	Direction: W	Mechanicville MGP RA 3304	Excavations in area 3D.	Direction: SW
					
Mechanicville MGP RA 3305	Excavations in area 3D.	Direction: S	Mechanicville MGP RA 3306	Sheet pile removal operations in area 3B.	Direction: W

Daily Photograph Log for June 09, 2009



Mechanicville MGP RA 3314	Excavations in area 3D.	Direction: S



Mechanicville MGP RA 3317	Sheet pile removal operations in area 3B.	Direction: SW



Mechanicville MGP RA 3318	Excavations in area 3D.	Direction: SE



Mechanicville MGP RA 3320	Excavations in area 3C.	Direction: S



Mechanicville MGP RA 3323	Confirmation samples in area 3D.	Direction: SE



Mechanicville MGP RA 3327	Excavations in area 3D.	Direction: S

					
Mechanicville MGP RA 3328	Excavations and backfilling in area 3D.	Direction: S	Mechanicville MGP RA 3329	Sheet pile removal operations in area 3B.	Direction: SE
					
Mechanicville MGP RA 3330	Excavations in area 3C.	Direction: S	Mechanicville MGP RA 3331	Sheet pile removal operations in area 3B.	Direction: SE
					
Mechanicville MGP RA 3332	Excavations in area 3D.	Direction: NW	Mechanicville MGP RA 3333	Backfilling in area 3D.	Direction: S

Daily Photograph Log for June 10, 2009

					
Mechanicville MGP RA 3336	Excavations in area 3C.	Direction: S	Mechanicville MGP RA 3337	Excavations in area 3C.	Direction: S
					
Mechanicville MGP RA 3339	Excavations in area 3C.	Direction: SW	Mechanicville MGP RA 3340	Excavations in area 3C.	Direction: W
					
Mechanicville MGP RA 3341	Backfilling in area 3D.	Direction: N	Mechanicville MGP RA 3342	Backfilling in area 3D.	Direction: S

					
Mechanicville MGP RA 3343	Backfilling in area 3D.	Direction: S	Mechanicville MGP RA 3344	Sheet pile removal operations in area 3B.	Direction: E
					
Mechanicville MGP RA 3345	Excavations in area 3C.	Direction: S	Mechanicville MGP RA 3346	Excavations in area 3C.	Direction: S
					
Mechanicville MGP RA 3347	Sheet pile removal operations in area 3B.	Direction: E	Mechanicville MGP RA 3348	Sheet pile removal operations in area 3B.	Direction: E

Daily Photograph Log for June 11, 2009



Mechanicville MGP RA 3351	Cleanout of WWTP baffle tank.	Direction: NE



Mechanicville MGP RA 3364	Cleanout of WWTP baffle tank.	Direction: W



Mechanicville MGP RA 3365	Cleanout of WWTP baffle tank.	Direction:



Mechanicville MGP RA 3368	Excavations in area 3C.	Direction: N



Mechanicville MGP RA 3371	Excavations in area 3C.	Direction: S



Mechanicville MGP RA 3376	Backfilling in area 3C.	Direction: SW

					
Mechanicville MGP RA 3377	Excavations in area 3C.	Direction: SW	Mechanicville MGP RA 3378	Backfilling in area 3C.	Direction: S
					
Mechanicville MGP RA 3379	Excavations in area 3C.	Direction: SW	Mechanicville MGP RA 3380	Sheet pile removal operations in area 3B.	Direction: SW
					
Mechanicville MGP RA 3383	Backfilling operations in area 3B.	Direction: NE	Mechanicville MGP RA 3384	Sheet pile removal operations in area 3B.	Direction: N

Daily Photograph Log for June 12, 2009

					
Mechanicville MGP RA 3385	Demobilization of whalers from area 3B shoring system.	Direction: S	Mechanicville MGP RA 3388	Excavations in area 3C.	Direction: SW
					
Mechanicville MGP RA 3389	Sheet pile removal operations in area 3B.	Direction: N	Mechanicville MGP RA 3390	Excavations in area 3C.	Direction: SW
					
Mechanicville MGP RA 3391	Excavations in area 3C.	Direction: W	Mechanicville MGP RA 3394	Load out to ESMI of soils from area 3C.	Direction: W

					
Mechanicville MGP RA 3395	Backfilling operations in area 3C.	Direction: N	Mechanicville MGP RA 3396	Cleanout of WWTP baffle tank.	Direction:
					
Mechanicville MGP RA 3397	Excavations in area 3C.	Direction: E	Mechanicville MGP RA 3400	Grading east of the WWTP.	Direction: SE
					
Mechanicville MGP RA 3405	MAB Demobilization.	Direction: SE	Mechanicville MGP RA 3406	Grading in area 3.	Direction: E

Daily Photograph Log for June 15, 2009



Mechanicville MGP RA 3410	Demobilization MAB's equipment.	Direction: S



Mechanicville MGP RA 3411	Grading in area 3/2.	Direction: SW



Mechanicville MGP RA 3412	Cleanout of WWTP baffle tank.	Direction: W



Mechanicville MGP RA 3413	Cleanout of WWTP baffle tank.	Direction: W



Mechanicville MGP RA 3414	Delivery of biodegradable erosion control matting.	Direction: NE



Mechanicville MGP RA 3415	Delivery of environmental roll-off container.	Direction: NE

					
Mechanicville MGP RA 3416	Removal of WWTP pad.	Direction: SW	Mechanicville MGP RA 3418	PC-220 excavator decontaminated and cleaned for demobilization.	Direction: NE
					
Mechanicville MGP RA 3419	Removal of WWTP pad.	Direction: SW	Mechanicville MGP RA 3420	Removal of WWTP pad.	Direction: SW
					
Mechanicville MGP RA 3421	Removal of WWTP pad.	Direction: W	Mechanicville MGP RA 3422	Grading on stream bank slope.	Direction: NE

Daily Photograph Log for June 16, 2009

					
Mechanicville MGP RA 3425	Demobilization of A-Verdi container.	Direction: S	Mechanicville MGP RA 3426	Demobilization of MAB's loader.	Direction: SW
					
Mechanicville MGP RA 3427	Staging of WWTP baffle tank for demobilization.	Direction: NW	Mechanicville MGP RA 3428	Cleanout of WWTP effluent tank.	Direction:
					
Mechanicville MGP RA 3429	Removal of WWTP pad.	Direction: SW	Mechanicville MGP RA 3430	Removal of WWTP pad.	Direction: NE

					
Mechanicville MGP RA 3431	Removal of WWTP pad.	Direction: SE	Mechanicville MGP RA 3432	Removal of WWTP pad.	Direction: S
					
Mechanicville MGP RA 3433	Removal of WWTP effluent discharge line.	Direction: NW	Mechanicville MGP RA 3435	Demobilization of jersey barriers and HDPE pipe.	Direction: SE
					
Mechanicville MGP RA 3436	Removal of WWTP pad.	Direction: SE	Mechanicville MGP RA 3437	Staging of WWTP effluent tank for demobilization.	Direction: SE

Daily Photograph Log for June 17, 2009

					
Mechanicville MGP RA 3444	Cleanout of WWTP media.	Direction: E	Mechanicville MGP RA 3445	Grading in the former WWTP pad.	Direction: SE
					
Mechanicville MGP RA 3447	Grading and compaction.	Direction: SE	Mechanicville MGP RA 3448	Grading and compaction.	Direction: E
					
Mechanicville MGP RA 3452	Grading and compaction.	Direction: S	Mechanicville MGP RA 3453	Grading and compaction.	Direction: W

					
Mechanicville MGP RA 3455	Rework of MW-2.	Direction: SE	Mechanicville MGP RA 3456	Rework of MW-2 and MW-21.	Direction: SE
					
Mechanicville MGP RA 3457	Dust control along Central Ave.	Direction: SE	Mechanicville MGP RA 3458	Solidification of WWTP media and sludge.	Direction: E
					
Mechanicville MGP RA 3460	Rework of monitor well tops along Central Ave.	Direction: N	Mechanicville MGP RA 3461	Rework of monitor well tops along Central Ave.	Direction: N

Daily Photograph Log for June 18, 2009



Mechanicville MGP RA 3462	Grading in area 3.	Direction: E



Mechanicville MGP RA 3464	Demobilization of WWTP baffle tank.	Direction: SE



Mechanicville MGP RA 3465	Rework of tops of MW-2 and MW-21.	Direction: NW



Mechanicville MGP RA 3466	Grading in area 3.	Direction: N



Mechanicville MGP RA 3467	Rework of monitor well tops along Central Ave.	Direction: N

Daily Photograph Log for June 19, 2009

					
Mechanicville MGP RA 3470	Sheen on surface water from G.A Bove Fuels site.	Direction: SW	Mechanicville MGP RA 3472	G.A Bove Fuels personnel cleaning up sheen.	Direction: NW
					
Mechanicville MGP RA 3475	Jack hammering to install bollards around MW-2, -21.	Direction: N	Mechanicville MGP RA 3476	Jack hammering to install bollards around MW-2, -21.	Direction: SE
					
Mechanicville MGP RA 3477	Jack hammering to install bollards around MW-2, -21.	Direction: E	Mechanicville MGP RA 3478	Rework of monitor well tops along Central Ave.	Direction: NE

					
Mechanicville MGP RA 3479	Rework of monitor well tops along Central Ave.	Direction: NE	Mechanicville MGP RA 3481	Installations of stone fill in eastern swale.	Direction: E
					
Mechanicville MGP RA 3482	Jack hammering to install bollards around MW-2, -21.	Direction: S	Mechanicville MGP RA 3483	Installations of stone fill in eastern swale.	Direction: E
					
Mechanicville MGP RA 3484	Grading and compaction in area 3.	Direction: E	Mechanicville MGP RA 3485	Rework of MW-2 and MW-21.	Direction: SE

Daily Photograph Log for June 22, 2009



Mechanicville MGP RA 3499	Marking final elevation of Rip-rap.	Direction: E



Mechanicville MGP RA 3506	Cutting Rip-rap to finish elevation.	Direction: E



Mechanicville MGP RA 3511	Grading and compaction along Central Ave.	Direction: S



Mechanicville MGP RA 3513	Sheen encountered during grading along the Anthony Kill.	Direction: N



Mechanicville MGP RA 3516	Saturated conditions encountered in stream bank.	Direction: NE



Mechanicville MGP RA 3518	Installations of stone fill in eastern swale.	Direction: NE

					
Mechanicville MGP RA 3523	Rework of monitor well tops along Central Ave.	Direction: SW	Mechanicville MGP RA 3524	Installations of stone fill in eastern swale.	Direction: SW
					
Mechanicville MGP RA 3527	Jack hammering to install bollards around MW-2, -21.	Direction: NE	Mechanicville MGP RA 3528	Installations of stone fill in eastern swale.	Direction: N
					
Mechanicville MGP RA 3529	Grading and compaction in area 3.	Direction: S	Mechanicville MGP RA 3530	Rework of MW-2 and MW-21.	Direction: NW

Daily Photograph Log for June 23, 2009



Mechanicville MGP RA 3532	Mixing of rip-rap into below grade soils in stream bank.	Direction: NW



Mechanicville MGP RA 3546	Construction of central drainage swale.	Direction: NE



Mechanicville MGP RA 3548	Saturated conditions encountered in stream bank.	Direction: W



Mechanicville MGP RA 3551	Construction of eastern drainage swale.	Direction: W



Mechanicville MGP RA 3553	Grading of stream bank.	Direction: W



Mechanicville MGP RA 3555	Grading of stream bank.	Direction: W

					
Mechanicville MGP RA 3557	Construction of eastern drainage swale.	Direction: S	Mechanicville MGP RA 3559	Grading of stream bank.	Direction: W
					
Mechanicville MGP RA 3560	Placement of topsoil on stream bank.	Direction: E	Mechanicville MGP RA 3562	Placement of topsoil on stream bank.	Direction: W
					
Mechanicville MGP RA 3563	Construction of eastern drainage swale.	Direction: N	Mechanicville MGP RA 3564	Grading of topsoil on stream bank.	Direction: W

Daily Photograph Log for June 24, 2009



Mechanicville MGP RA 3567	Grading of topsoil on stream bank.	Direction: W



Mechanicville MGP RA 3569	Construction of central drainage swale.	Direction: NW



Mechanicville MGP RA 3570	Construction of central drainage swale.	Direction: N



Mechanicville MGP RA 3571	Installation of erosion control matting.	Direction: E



Mechanicville MGP RA 3573	Saturated soils at bottom of stream bank slope.	Direction: E



Mechanicville MGP RA 3575	Removal of saturated soils at bottom of stream bank slope.	Direction: NE

					
Mechanicville MGP RA 3576	Removal of saturated soils at bottom of stream bank slope.	Direction: E	Mechanicville MGP RA 3578	Removal of saturated soils at bottom of stream bank slope.	Direction: E
					
Mechanicville MGP RA 3579	Reinstallation of turbidity along saturated area.	Direction: E	Mechanicville MGP RA 3580	Removal of saturated soils at bottom of stream bank slope.	Direction: E
					
Mechanicville MGP RA 3581	Removal of saturated soils at bottom of stream bank slope. Note flow of water from the bank.	Direction: N	Mechanicville MGP RA 3582	Groundwater erosion of cover soils exposing NAPL at bedrock along stream bank.	Direction: W

					
Mechanicville MGP RA 3583	Groundwater erosion of cover soils exposing NAPL at bedrock along stream bank.	Direction: NW	Mechanicville MGP RA 3584	Placement of backfill over bedrock.	Direction: W
					
Mechanicville MGP RA 3585	Placement of backfill over bedrock.	Direction: W	Mechanicville MGP RA 3588	Flow conditions from stream bank.	Direction: E
					
Mechanicville MGP RA 3591	Construction of subsurface drain in stream bank.	Direction: W	Mechanicville MGP RA 3593	Construction of subsurface drain in stream bank.	Direction: W

					
Mechanicville MGP RA 3594	Construction of subsurface drain in stream bank.	Direction: NW	Mechanicville MGP RA 3599	Construction of rip-rap erosion controls.	Direction: NW
					
Mechanicville MGP RA 3602	Installation of trees and plants on stream bank.	Direction: W	Mechanicville MGP RA 3604	Installation of trees and plants on stream bank.	Direction: W
					
Mechanicville MGP RA 3605	Restoration of edge of Ferris Lane.	Direction: SE	Mechanicville MGP RA 3608	Installation of trees and plants on stream bank.	Direction: E

Daily Photograph Log for June 25, 2009

					
Mechanicville MGP RA 3610	Restoration of the edge of Ferris Lane.	Direction: E	Mechanicville MGP RA 3613	Restoration of the edge of Ferris Lane.	Direction: W
					
Mechanicville MGP RA 3623	Grading in area 3.	Direction: NE	Mechanicville MGP RA 3624	Restoration of the edge of Ferris Lane.	Direction: SW
					
Mechanicville MGP RA 3627	Final grading in area 3.	Direction: SW	Mechanicville MGP RA 3628	Stream bank restoration plantings.	Direction: W

					
Mechanicville MGP RA 3630	Restoration of the edge of Ferris Lane.	Direction: SE	Mechanicville MGP RA 3631	Restoration of the edge of Ferris Lane.	Direction: SE
					
Mechanicville MGP RA 3635	Final grading in area 3.	Direction: SE	Mechanicville MGP RA 3636	Final grading and compaction in area 3.	Direction: E
					
Mechanicville MGP RA 3637	Final grading in area 3.	Direction: E	Mechanicville MGP RA 3638	Final grading and compaction in area 3.	Direction: SW

Daily Photograph Log for June 26, 2009

					
Mechanicville MGP RA 3639	Hydro-seeding of stream bank.	Direction: E	Mechanicville MGP RA 3640	Hydro-seeding of stream bank.	Direction: E
					
Mechanicville MGP RA 3642	Demobilization of diesel tank.	Direction: NW	Mechanicville MGP RA 3646	Final grading in the WWTP pad area.	Direction: SE
					
Mechanicville MGP RA 3647	Complete stream bank restoration plantings.	Direction: E	Mechanicville MGP RA 3648	Complete stream bank restoration plantings.	Direction: NE

					
Mechanicville MGP RA 3650	Final grading and compaction in area 3.	Direction: W	Mechanicville MGP RA 3651	Final grading and compaction in area 3.	Direction: W
					
Mechanicville MGP RA 3652	Complete grading and compaction in area 3.	Direction: W	Mechanicville MGP RA 3653	Complete stream bank restoration.	Direction: SW
					
Mechanicville MGP RA 3654	Complete grading and compaction in area 3.	Direction: SW	Mechanicville MGP RA 3655	Complete grading and compaction in area 3.	Direction: W

Daily Photograph Log for June 29, 2009

					
Mechanicville MGP RA 3656	Completed restoration of east side of site.	Direction: W	Mechanicville MGP RA 3657	Completed restoration of east side of site.	Direction: W
					
Mechanicville MGP RA 3658	Completed restoration of east side of site.	Direction: W	Mechanicville MGP RA 3659	Completed restoration of east side of site.	Direction: W
					
Mechanicville MGP RA 3660	Demobilization of DH-50 excavator and equipment trailer.	Direction: SE	Mechanicville MGP RA 3661	Site trailers staged for demobilization.	Direction: W

					
Mechanicville MGP RA 3662	Demobilization of water truck.	Direction: SE			

Daily Photograph Log for June 30, 2009



Mechanicville MGP RA 3663	Moving of Sevenson trailer for final grading.	Direction: W



Mechanicville MGP RA 3664	Final grading of west side of site.	Direction: S



Mechanicville MGP RA 3672	Final grading of west side of site.	Direction: NE



Mechanicville MGP RA 3673	Final grading of west side of site.	Direction: NE



Mechanicville MGP RA 3676	Complete stream bank restoration plantings.	Direction: E



Mechanicville MGP RA 3677	Complete stream bank restoration plantings.	Direction: W

					
Mechanicville MGP RA 3678	Saturated conditions at bottom of stream bank.	Direction: W	Mechanicville MGP RA 3679	Saturated conditions at bottom of stream bank.	Direction: W
					
Mechanicville MGP RA 3682	Complete stream bank restoration plantings.	Direction: E	Mechanicville MGP RA 3685	Final grading of west side of site.	Direction: NE
					
Mechanicville MGP RA 3686	Final grading and compaction of west side of site.	Direction: N	Mechanicville MGP RA 3687	Complete grading and compaction of west side of site.	Direction: NE