

Fort Edward Landfill Visit

DER Site Management, 03/13/2013

Photos with Notes

Photo

Description



Payson Long and Will Welling visited the Ft. Edward Landfill to inspect the recent concrete pour. We found that it had not been done yet.



Payson stands where one of the corners of the pad will be



Some of the pieces of equipment have been moved here from American Thermostat. This is the base for the "clarifier catch" tank (plastic).



Back



Back



Back view of the equipment



Front where the pour will happen



View of the cap from near the gate



View of the cap from near the gate



View of the cap from near the gate



Payson at the gate



Blue marking for the water meter is seen in the foreground



Utility shot



Another utility shot:

Electricity, phone and water.