



REPLY TO
ATTENTION OF

**DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT DRUM
10000 10TH MOUNTAIN DIVISION DRIVE
FORT DRUM, NEW YORK 13602-5046**

April 26, 2022

Environmental Division
Public Works

Heather Bishop
Project Manager
Division of Environmental Remediation
NYSDEC
625 Broadway, 12th Floor
Albany, New York 12233

Subject:
Draft Final 2021 Annual Basewide Monitoring Report
Fort Drum Installation Restoration Program
Fort Drum, Jefferson County, New York

Dear Ms. Bishop:

Enclosed with this letter is Fort Drum's draft final 2021 Annual Basewide Monitoring Report for your review. As captured in the 2019 and 2020 Annual Basewide Monitoring Reports, Fort Drum is requesting to discontinue the environmental monitoring program at the Airfield Sanitary Landfill based on stable groundwater conditions over the past several decades. This recommendation can be found in Section 5.2 BWM Program Recommendations of the report.

If you have any questions or concerns, please contact Ms. Amy Dixon at (315) 286-7334.

Sincerely,

James M. Miller
Chief, Environmental Division
Public Works

Enclosure