

NEWYORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation Operation Maintenance and Monitoring Review Report Period covered by -- 2002

Site / Spill Number : 633027		Site Name: Primoshield, Inc.		Class: 04	
Program Lead: Hazardous Waste Program			OM&M Funding Source: Title3		
Start Date : 08/01/1998		ACT			
Annual IC/EC Certification :					
DEC Inspection Date: 11/30/2000		--- Last Date of DEC Inspection			
Report Used for Evaluation: Quarterly reports					
ROD Compliance ? YES		Consent order/Decree Compliance ? YES			
LongTerm Monitoring(effectiveness of remedy): No		Frequency:		Act. Date: / /	
Treatment System(Monitoring performance of remedy): Yes		Frequency: Quarterly		Pln. Date: / / #wells : 0	
PROBLEM STATUS : 01F		None			
Evaluation : The Remedy is performing properly and effectiveness will be evaluated					
Comments/ Changes/ Attachments: 2002: 2001: Sump pump to be replaced in spring and the carbon drums will be disconnected with the ability to reconnect them. There is question whether the sump pumps' in addition to the drum's failing will cause high level alarms. There is also question whether shutting down the pump will cause flooding in the basement.					
ROD/Consent Order Modifications?		NO			
reclassification recommended :		None			
Contaminant of concern	OU	Contaminant of concern	Media/Receptor		
	01	CYANIDE SALTS			
	01	HYDROFLUORIC ACID			
	01	CORROSIVE LIQUIDS			
	01	SOLVENTS			
	01				
	01				
	01				
Remedies	OU	Remedies	Size of Treatment	Date in Place	Remedy Effective
	01		Small (<10gpm or < 5 acres)	/ /	Yes

Next Review 03/01/2003			Priority: 0		
Subject Manager Lasdin			Reviewer: Rider		
Signature		Date	Signature		Date
Name	Region or Bureau	Telephone	Name	Region or Bureau	Telephone