

DAILY OBSERVATION REPORT

Pg. 1 of 9

NYSDEC

10/18/2023

Remedial Bureau C

Division of Environmental Remediation

Site: Ogdensburg MGP

Phase: Site Management

Site No.: 645053

Contractor PM: Devin Shay/GES

NYSDEC PM: Bradley Demo

Construction Manager: N/A

Project Engineers: N/A

Remedial Contractor: N/A

Air Monitoring: N/A

Health & Safety: N/A

Weather Conditions

General Description	Cloudy	am	N/A	pm
Temperature	50°F	am	N/A	pm
Wind Direction	N/A	am	N/A	pm

HEALTH & SAFETY:

(*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).

Were there any changes to the Health & Safety Plan?	*Yes ()	No (x)	NA ()
Were there any exceedances at the perimeter action level reported on this date?	Air: *Yes ()	No ()	NA (x)
Were there any Noise /Vibration exceedances reported on this date?	Noise: *Yes ()	No ()	NA (x)
	Vibration: *Yes ()	No ()	NA (x)
Were there any breaches to the tent structure or silt fence reported/observed on this date?	*Yes ()	No ()	NA (x)
Were there any dust/odor issues reported or observed on this date?	*Yes ()	No ()	NA (x)

WASTE HAULING :

(*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes ()	No ()	NA (x)
Were there any vehicles which were not lined or tarped?	*Yes ()	No ()	NA (x)
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes ()	No ()	NA (x)

DAILY OBSERVATION REPORT

Materials Removed From Site: N/A

Disposal Facility's:

Total Loads: (on this date)

Total Loads: (to date)

Total Daily Weight: (est.)

Total Weight: (*approx.)

*Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.

Summary of Events:

- NYSDEC onsite to observe Groundwater Environmental Services (GES) conduct required quarterly site inspection and biannual groundwater sampling
- Site cover system and perimeter fencing in good conditions, no signs of erosion
- All monitoring wells in good physical condition. Per Kevin of GES the city of Ogdensburg previously began demolition activities at the former cheese factory building across the street and were previously unaware of monitoring wells onsite
- All monitoring wells were purged for 30 minutes per National Grid procedures and sampled for parameters and contaminants specified by the Site Management Plan
- Of note was MW14R showing a pH of 3.07 during purging and was emitting a strong sulfur odor and MW20R showing a pH of 4.7 during purging

VISITORS TO SITE:

NAME	Representing	Entered Exclusion/CRZ Zone	
Kevin, Pete, Greg	GES	Yes (x)	No ()
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()

PROJECT SCHEDULE:

•

ISSUES PENDING:

ITEMS OF CONCERN:

SITE REPRESENTATIVE /
CONSTRUCTION INSPECTOR:
Bradley Demo

Name: (*signature*)

Bradley Demo

Date: 10/18/2023

DAILY OBSERVATION REPORT



Site cover/fence conditions

DAILY OBSERVATION REPORT



Site cover/fence conditions

DAILY OBSERVATION REPORT



Minor signs of burrowing animal activity

DAILY OBSERVATION REPORT



Site conditions across King St./ downgradient

DAILY OBSERVATION REPORT



Site conditions across King St./ building demolition

DAILY OBSERVATION REPORT



Site conditions at monitoring well MW14R

DAILY OBSERVATION REPORT



Monitoring wells MW15 and MW 15RS