## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

## **Inactive Hazardous Waste Site Operations and Maintenance Review Report**

Ŷ			Form Date 96.10.0
Site Name: Conklin Dumps	С	lass: 4	lumber: 704013
O&M Funding Source:	perfund   Federal Superfu	und X Municipal	☐ Responsible Party
O&M Information: O&M Start: 1/96	End:	Annual Cost:	\$ Estimated
Interim Remedial Measures/Operable L	Jnits in O&M Phase:		
☐ Drum Removal	□ Soil Removal	☐ Tank Rer	
X Cap/Cover	☐ Containment Structure	☐ Fence/Se	
☐ Groundwater Recovery/Treatment	X Leachate Collection/Treatm		traction/Treatment
<ul><li>☐ Air Sparging/Stripper System</li><li>☐ Other:</li></ul>	☐ Treatment/Filtration Plant/S	System D Potable V	Vater Supply/System
Institutional Controls: Deed Restr	iction   Discharge Pe	rmit Depart	ment of Health Sampling
☐ Other:			
O&M Review Information:			
Reports: 1,2,3 & 4 Quarter Conklin Landf	ill MW sampling & analysis repor	rts receive by this office.	
Inspection: Inspection made John May 12			
Sampling:			
Other:			
Conclusions:			
Remedy Effective? X Yes ☐ No: _			
ROD Compliance? X Yes  No:			
NOD Compliance: X Tes Li No			
Consent Order Compliance?   Yes	□ No:		
Other:			
Recommendations: Continue to monitor	or wells and collect & treat leach	ate. Continue to maintai	n landfill cap.
ROD/Consent Order Modifications?	No ☐ Yes (per above) Recla	assify the Site?   No	☐ Yes → Class:
Comments: Total leachate collected in 2			
City Sewage Treatment Plant. Leachate	samples were collected by the E	S.J.C. STP as part of the	ir pretreatment program.
No leachate seeps observed during my in and gates in tact and locked. Future lead			
Superintendent, Dennis Shimmer 607-77			
		0.	
Project Metagor: 4 - 47	/ / Reviewer:	Har int	01
Project Manager: A Manager:	12/8/00 \	Suarypu	ery 163/01
Signature Rep 7		nature DIRINER JR BH	Date SC 451 0927
Name Region or Buggau	Telephone Telephone	Name Region or Burea	