

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP062915 Date:June 29, 2015

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (X) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which did not display proper D.O.T ^{*Yes () No () NA (X)} numbers and placards?
Were there any vehicles which were not lined or tarped? *Yes () No () NA (X)

Were there any vehicles which were not decontaminated * Yes () No () NA (X) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP062915 Date: June 29, 2015

Contractor Severson continued to work installing siltation fence for erosion control along northern edge of site. Contractor worked on various site preparation activities, including clearing, grading, and receiving supplies and equipment. Contractor installed an absorbent boom in the Owasco Outlet along the northern edge of the site.

Subcontractor Thew Associates on site to provide surveying services.

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP062515 Date:June 25, 2015

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (X) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which did not display proper D.O.T ^{*Yes () No () NA (X)} numbers and placards?

Were there any vehicles which were not lined or tarped? *Yes () No () NA (X)

Were there any vehicles which were not decontaminated * Yes () No () NA (X) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP062515 Date: June 25, 2015

Contractor Severson continued to work installing siltation fence for erosion control along northern edge of site. Contractor worked on various site preparation activities, including clearing, grading, and receiving supplies and equipment.

Subcontractor Thew Associates on site to provide surveying services.

Inspector: Eric Knapp

Siltation fence beginning install – northern edge of site near Owasco Outlet





Looking southeast toward site entrance

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP062415 Date:June 24, 2015

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (X) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which did not display proper D.O.T ^{*Yes () No () NA (X)} numbers and placards?
Were there any vehicles which were not lined or tarped? *Yes () No () NA (X)

Were there any vehicles which were not decontaminated * Yes () No () NA (X) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP062415 Date: June 24, 2015

Contractor Severson continued to work installing siltation fence for erosion control along northern edge of site. Contractor worked on various site preparation activities, including clearing, grading, and receiving supplies and equipment. Contractor added gravel alongside the access road to widen roadway and cleared brush to improve sight distance.

Subcontractor Thew Associates on site to provide surveying services.

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP062215 Date:June 22, 2015

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (X) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which did not display proper D.O.T ^{*Yes () No () NA (X)} numbers and placards?

Were there any vehicles which were not lined or tarped? *Yes () No () NA (X)

Were there any vehicles which were not decontaminated * Yes () No () NA (X) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP062215 Date: June 22, 2015

Contractor Severson worked installing siltation fence for erosion control along eastern and northern edges of site. Contractor worked on various site preparation activities, including clearing, grading, and receiving supplies and equipment.

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP061915 Date:June 19, 2015

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (X) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which did not display proper D.O.T ^{*Yes () No () NA (X)} numbers and placards?

Were there any vehicles which were not lined or tarped? *Yes () No () NA (X)

Were there any vehicles which were not decontaminated * Yes () No () NA (X) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP061915 Date: June 19, 2015

Contractor Severson pulled existing wooden posts from ground along southern edge of site. Contractor received gravel which was spread along southern edge of site and compacted for job trailers.

Inspector: Eric Knapp



South edge of site – prepping location for job trailers