

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP052616 Date: May 26, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP052616 Date: May 26, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP052316 Date: May 23, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP052316 Date: May 23, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP052016 Date: May 20, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP052016 Date: May 20, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP051916 Date: May 19, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP051916 Date: May 19, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP051316 Date: May 13, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP051316 Date: May 13, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP051216 Date: May 12, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP051216 Date: May 12, 2016

Contractor Severson worked excavating southern portion of Phase 2 cell, segregating material for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP051116 Date: May 11, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP051116 Date: May 11, 2016

Contractor Severson worked on equipment maintenance and general housekeeping.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP050916 Date: May 9, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP050916 Date: May 9, 2016

Contractor Severson excavated soils from south-central portion of Phase 2 cell and loaded onto trucks for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp







DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP050616 Date: May 6, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP050616 Date: May 6, 2016

Contractor Severson excavated soils from east end of Phase 2 cell and loaded onto trucks for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP050516 Date: May 5, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP050516 Date: May 5, 2016

Contractor Severson excavated soils from east end of Phase 2 cell and loaded onto trucks for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Water pumped from excavation as needed and treated.

-

Inspector: Eric Knapp





DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP050316 Date: May 3, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP050316 Date: May 3, 2016

Contractor Severson excavated soils from east end of Phase 2 cell and loaded onto trucks for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Inspector: Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: ACSMGP050216 Date: May 2, 2016

Auburn Clark Street
MGP
Remedial Action Site
706008

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: ACSMGP050216 Date: May 2, 2016

Contractor Severson excavated soils from east end of Phase 2 cell and loaded onto trucks for disposal at ESMI or Seneca Meadows.

Contractor filled excavation with imported backfill.

Inspector: Eric Knapp