

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP072916    Date: July 29, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP072916      Date: July 29, 2016

Contractor Severson   worked on storm sewer, placing a riser on manhole.

Contractor backfilled excavation with imported fill.

Inspector: Eric Knapp |  
|



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP072816    Date: July 28, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?



**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP072816      Date: July 28, 2016

Contractor Severson   worked on storm sewer, replacing pipe from manhole to outfall. Contractor placed rebar for outfall wingwalls.

Contractor backfilled excavation with imported fill.

Inspector: Eric Knapp|















DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP072216    Date: July 22, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?



**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP072216      Date: July 22, 2016

Contractor Severson   worked on storm sewer, adding a manhole near the south edge of Phase 3 cell.

Contractor backfilled excavation with imported fill.

Inspector: Eric Knapp|











DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP072116    Date: July 21, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP072116      Date: July 21, 2016

Contractor Severson worked on storm sewer, temporarily replacing outfall portion of pipe and cutting south end of existing pipe for the addition of a manhole.

Inspector: Eric Knapp|













DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP071516    Date: July 15, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP071516      Date: July 15, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI. Contractor excavated for replacement of storm sewer.



**Inspector:** Eric Knapp





DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP071416    Date: July 14, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP071416      Date: July 14, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Contractor placed forms for footer of sewer oufall.

Contractor broke up concrete/stone wall for former holder in northwest corner of phase 3 cell.

**Inspector:** Eric Knapp

















DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP071316 Date: July 13, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan? \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X)

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP071316      Date: July 13, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Contractor constructed forms for footer for storm sewer outfall.   Contractor set final grades for footer of sewer outfall..

**Inspector:** Eric Knapp|



**DAILY OBSERVATION REPORT** Pg. 1 of 2

Report No.: AMSMGP071216    Date: July 12, 2016

**Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010**

**Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services**

***Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )***

**Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?**

**Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )**

**Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )**

**Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )**

**WASTE HAULING :**  
***( \*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).***

**Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()**

**Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?**

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP071216      Date: July 12, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Contractor constructed forms for footer for storm sewer outfall. Contractor broke concrete and excavated for footer of sewer outfall.



**Inspector:** Eric Knapp















DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP071116 Date: July 11, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan? \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X)

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP071116      Date: July 11, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Contractor constructed forms for footer for storm sewer outfall.



Inspector:




















Eric Knapp

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP070816    Date: July 8, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X)

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?



**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP070816      Date: July 8, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

**Inspector:** Eric Knapp|

**DAILY OBSERVATION REPORT** Pg. 1 of 2

Report No.: AMSMGP070716    Date: July 7, 2016

**Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010**

**Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services**

***Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )***

**Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?**

**Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )**

**Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )**

**Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )**

**WASTE HAULING :**  
***( \*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).***

**Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()**

**Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?**

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP070716      Date: July 7, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Inspector: Eric Knapp|



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP070616    Date: July 6, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP070616      Date: July 6, 2016

Contractor Severson   excavated in Phase 3 area, loading soils on to trucks for disposal at ESMI.

Contractor constructed cofferdam in outlet preparatory to replacing storm sewer outfall.



**Inspector:** Eric Knapp













DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP063016    Date: June 30, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP063016      Date: June 30, 2016

Contractor Severson   worked on site preparations and equipment mobilization to site

Inspector: Eric Knapp|



**DAILY OBSERVATION REPORT** Pg. 1 of 2

Report No.: AMSMGP062916    Date: June 29, 2016

**Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010**

**Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services**

***Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )***

**Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?**

**Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )**

**Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )**

**Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )**

**WASTE HAULING :**  
***( \*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).***

**Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()**

**Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?**

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP062916      Date: June 29, 2016

Contractor Severson    worked on site preparations and equipment mobilization to site

Inspector: Eric Knapp|



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP062816    Date: June 28, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP062816      Date: June 28, 2016

Contractor Severson   worked on site preparations and equipment mobilization to site

Inspector: Eric Knapp|

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP062716    Date: June 27, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?



**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP062716      Date: June 27, 2016

Contractor Severson stripped topsoil from railroad embankment and dug test pit to determine size of stormsewer.

**Inspector:** Eric Knapp











DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP062316    Date: June 23, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP062316      Date: June 23, 2016

Contractor Severson   worked preparing wastewater treatment system.





**Inspector:** Eric Knapp