

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP100516    Date: October 5, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP100516      Date: October 5, 2016

Contractor Severson not working on site. Photos of site at end of Phase 3 work.

Inspector: Eric Knapp











DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP092816    Date: September 28, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP092816      Date: September 28, 2016

Contractor Severson worked winterizing site and performing general site housekeeping.

Inspector: Eric Knapp





DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP092716    Date: September 27, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP092716      Date: September 27, 2016

Contractor Severson worked paving dredge-spoils containment area and performing general site housekeeping.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP092216    Date: September 22, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP092216      Date: September 22, 2016

Contractor Severson worked constructing dredge-spoils containment area and performing general site housekeeping.

Inspector: Eric Knapp



**DAILY OBSERVATION REPORT** Pg. 1 of 2

Report No.: AMSMGP092116    Date: September 21, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

*Were there any changes to the Health & Safety Plan?*    \*Yes ( ) No (X) NA ( )

*Were there any exceedances at the perimeter Air:*    \*Yes ( ) No ( ) NA (x) action level reported on this date?

*Were there any Noise /Vibration exceedances Noise:*    \*Yes ( ) No ( ) NA (X) reported on this date?  
*Vibration:*    \*Yes ( ) No ( ) NA (X)

*Were there any breaches to the silt fence reported/observed on this date ?*    \*Yes ( ) No (x) NA ( )

*Were there any dust/odor issues reported or observed on this date?*    \*Yes ( ) No (X) NA ( )

**WASTE HAULING :**  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

*Were there any vehicles which were not lined or tarped?*    \*Yes ( ) No (x ) NA()

*Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?*


DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP092116      Date: September 21, 2016

Contractor Severson worked constructing dredge-spoils containment area and performing general site housekeeping.

Inspector: Eric Knapp





DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP092016    Date: September 20, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()


Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP092016      Date: September 20, 2016

Contractor Severson worked constructing dredge-spoils containment area and performing general site housekeeping.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP091416    Date: September 14, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP091416      Date: September 14, 2016

Contractor Severson worked de-contaminating equipment and performing general site housekeeping.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP091316    Date: September 13, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()


Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP091316      Date: September 13, 2016

Contractor Severson worked preparing dredge-spoils containment area and performing general site housekeeping.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP090916    Date: September 9, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP090916      Date: September 9, 2016

Contractor Severson began preparing dredge-spoils containment area..

Inspector: Eric Knapp





**DAILY OBSERVATION REPORT** Pg. 1 of 2

Report No.: AMSMGP090716    Date: September 7, 2016

**Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010**

**Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services**

***Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )***

**Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?**

**Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )**

**Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )**

**Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )**

**WASTE HAULING :**  
***( \*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).***

**Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()**

**Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?**

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP090716      Date: September 7, 2016

Contractor Severson performed general housekeeping duties and surveyed site.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP090116    Date: September 1, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP090116      Date: September 1, 2016

Contractor Severson disposed of sediments from cleaning water treatment plant.

Inspector: Eric Knapp



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP083016    Date: August 30, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP083016      Date: August 30, 2016

Contractor Severson worked cleaning water treatment plant.

Inspector: Eric Knapp|







DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP081816    Date: August 18, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP081816      Date: August 18, 2016

Contractor Severson worked dressing area near sewer outfall.

Inspector: Eric Knapp|



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP081716    Date: August 17, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP081716      Date: August 17, 2016

Contractor Severson removed material from eastern end of phase 3 and loaded onto trucks for disposal.

Contractor backfilled other portions of excavation with imported fill.

Contractor worked dressing area near sewer outfall.

Inspector: Eric Knapp|









DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP080516    Date: August 5, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP080516      Date: August 5, 2016

Contractor Severson backfilled holder.

Contractor backfilled other portions of excavation with imported fill.

Contractor worked building forms for sewer outfall wingwalls.

Inspector: Eric Knapp |

|





DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP080416    Date: August 4, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP080416      Date: August 4, 2016

Contractor Severson worked excavating contents from within old holder near northwest corner of Phase 3 cell. Contractor broke up portions of holder floor. Contractor backfilled holder.

Contractor backfilled other portions of excavation with imported fill.

Contractor worked building forms for sewer outfall wingwalls.

Inspector: Eric Knapp|



DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP080316    Date: August 3, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?   \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP080316      Date: August 3, 2016

Contractor Severson worked excavating contents from within old holder near northwest corner of Phase 3 cell. Contractor broke up portions of holder floor.

Contractor backfilled other portions of excavation with imported fill.

Contractor worked building forms for sewer outfall wingwalls.

Inspector: Eric Knapp|







DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP080216    Date: August 2, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ?    \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date?    \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped?    \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP080216      Date: August 2, 2016

Contractor Severson worked excavating contents from within old holder near northwest corner of Phase 3 cell. Contractor broke up portions of holder floor.

Contractor backfilled other portions of excavation with imported fill.

Inspector: Eric Knapp |  
|







DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP080116    Date: August 1, 2016

Auburn MacMaster  
Street MGP  
Remedial Action Site  
# 706010

Consultant: Parsons Engineering  
Contractor: Severson Environmental  
Services

Were there any changes to the Health & Safety Plan?    \*Yes ( ) No (X) NA ( )

Were there any exceedances at the perimeter Air: \*Yes ( ) No ( ) NA (x ) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: \*Yes ( ) No ( ) NA (X ) reported on this date?  
Vibration: \*Yes ( ) No ( ) NA (X )

Were there any breaches to the silt fence reported/observed on this date ? \*Yes ( ) No (x) NA ( )

Were there any dust/odor issues reported or observed on this date? \*Yes ( ) No (X) NA ( )

WASTE HAULING :  
*(\*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? \*Yes ( ) No (x ) NA()

Were there any vehicles which were not decontaminated \* Yes ( ) No ( x) NA ( ) prior to exiting the work site?

**DAILY OBSERVATION REPORT** Pg. 2 of 2

Report No.: AMSMGP080116      Date: August 1, 2016

Contractor Severson   worked excavating contents from within old holder near northwest corner of Phase 3 cell..

Contractor backfilled other portions of excavation with imported fill.

Inspector: Eric Knapp|

