

DAILY OBSERVATION REPORT Pg. 1 of 2

Report No.: AMSMGP010417 Date: January 4, 2017

Auburn MacMaster
Street MGP
Remedial Action Site
706010

Consultant: Parsons Engineering
Contractor: Severson Environmental
Services

Were there any changes to the Health & Safety Plan? *Yes () No (X) NA ()

Were there any exceedances at the perimeter Air: *Yes () No () NA (x) action level reported on this date?

Were there any Noise /Vibration exceedances Noise: *Yes () No () NA (X) reported on this date?
Vibration: *Yes () No () NA (X)

Were there any breaches to the silt fence reported/observed on this date ? *Yes () No (x) NA ()

Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA ()

WASTE HAULING :
*(*If any box(s) below are checked “Yes”, list the deviation under the “Items of Concern” section of this report).*

Were there any vehicles which were not lined or tarped? *Yes () No (x) NA()

Were there any vehicles which were not decontaminated * Yes () No (x) NA () prior to exiting the work site?

DAILY OBSERVATION REPORT Pg. 2 of 2

Report No.: AMSMGP010417 Date: January 4, 2017

Contractor Severson not working on site. Photos of sewer outfall.

Inspector: Eric Knapp

