

New York State Department of Environmental Conservation
Division of Environmental Remediation – Central Office
Remedial Bureau C
Field Support Unit



Basil Seggos
Commissioner

DAILY INSPECTION REPORT

Site Code #: 706010	Date: 20 September 2018	Report #:
----------------------------	--------------------------------	------------------

Site Name: Auburn McMaster St. MGP

Location: Auburn, Cayuga County

Consultant Proj. Mgr.: Heather Phillips, Parsons

Proj. Contr.: Severson

Site Phone & Fax: N/A

	AM	PM
Weather		Mostly Sunny
Temperature		70s
Wind Direction		Calm

On-site at 1:00 pm

Temporary dam is out. Water is flowing through stream. Bypass pipes remain. No sign of remnant dam – prison dam. The staging area and water treatment system remain on site.

At 1:30 a 3 man Severson crew arrives. Moving a Cat excavator in the area of the bypass piping at the W side of Auburn Tank. Chain saw observed. Probably going to cut up pipe.

Off site at 1:40 pm

Ron Prohaska – Parsons

Anthony – Severson

3 operators, 1 labor, possible larger crew

Site Representative: John Spellman

Representative's signature:

Date: Sept. 21, 2018