NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

	Form Dale 96 10 0
O&M Funding Source: A State Superfund D Fee	Class: Z Number: 7-09-009
Own Funding Source: A state Superiord D Fee	leral Superfund Municipal Responsible Party
O&M Information: O&M Start: 70 7 90 End.	On Joing Annual Cost: \$ 500 & Estimated
Interim Remedial Measures/Operable Units in O&M Phase Drum Removal Soil Removal Cap/Cover Containment S Groundwater Recovery/Treatment Leachate Coll Air Sparging/Stripper System Treatment/Filt X Other: CAC SYSTEM South	Tank Removal Tank Removal Fence/Security Contraction/Treatment Vapor Extraction/Treatment
	ischarge Permit Department of Health Sampling
O&M Review Information:	
Reports: None-	
Inconcession Arrest Arrest	5
Inspection: <u>Annual by BC</u> Sampling: <u>Annual by BC</u>	2.5
Other:	
Conclusions: Remedy Effective? 🖸 Yes 💆 No:	
ROD Compliance? Yes No:	
Consent Order Compliance? Yes No:	
Other:	
Recommendations: <u>O+M Section assume responsibility for monitoring</u> <u>this GAC system or assign it to THMS under</u> <u>WIA & D003060-14</u> .	
ROD/Consent Order Modifications? I No I Yes (per abo	
The GAC system seems not to treat the water	
going to the lunch room / kitchen. Employees use	
be the water	
Is needed.	
The system does pot, and is not intended to, treat the	
Woter going to the touts.	
Project Manager: Thomas Vickunon 10/1/98	Reviewer:
Signature Date Thomas Wickerson BCS 7-7678	Signature Date
Name Region or Bureau Telephone	Name Region or Bureau Telephone