NYSDEC

Division of Environmental Remediation





# NYSDEC Contract No. D009804

Superintendent:

NYSDEC PM: Payson Long

Arcadis PM: Andy Vitolins, P.G.

Arcadis Site Inspectors: Jasmine Mullins, Kimberly Stilson

Site Location: South Otselic, New York

Weather Conditions					
<b>General Description</b>	Sunny	AM	Sunny	PM	
Temperature 55°F		AM	52°F	PM	
Wind Not Recorded		AM	Not Recorded	PM	
		_			

#### **Health & Safety**

If any box below is checked "Yes", provide explanation under "Health & Safety Comments".

Were there any changes to the Health & Safety Plan?	*Yes	No	NA
Were there any exceedances of the perimeter air monitoring reported on this date?	*Yes	No	NA
Were there any nuisance issues reported/observed on this date?	*Yes	No	NA

#### **Health & Safety Comments**

Arcadis personnel adhered to covid policies during groundwater sampling practices.

Summary of Work Perfo	ormed	Arriv	ed at site:	0930	De	parted	Site:	1830	

Arcadis personnel arrived onsite to conduct groundwater sampling, monthly treatment system sampling, and municipal well sampling. All samples will be analyzed for per- and polyfluoroalkyl substances (PFAS), 1,4-dioxane, and volatile organic compounds (VOCs).

### **Equipment/Material Tracking**

If any box below is checked "Yes", provide explanation under "Material Tracking Comments".

Were there any vehicles which did not display proper D.O.T numbers and placards?	*Yes	No	NA
Were there any vehicles which were not tarped?	* Yes	No	NA
Were there any vehicles which were not decontaminated prior to exiting the work site?	* Yes	No	NA

#### **Personnel and Equipment**

Individual	Company	Trade	Total Hours
Jasmine Mullins, EIT	Arcadis	Staff Environmental Engineer	9.0
Kimberly Stilson	Arcadis	Geologist 1	9.0
·		· ·	



Equipment Description	on		Contractor/Vendor		Quantity	Use	ed
Horiba – Water Quality M	1eter		Eco-Rental Solutions		2	Ye	s
MiniRAE 3000 PID – VOC r	monitor		Eco-Rental Solutions		1	Ye	:S
200 Foot Oil/Water Interface	e probe		Eco-Rental Solutions		2	Ye	S
Peristaltic pump – groundwate	r sampler		Eco-Rental Solutions		2	Ye	S
					<u> </u>		D-!!-
Material Description	Imported/ Delivered to Site	Exported off Site	Waste Profile (If Applicable)	Source of Facility (If	r Disposal Applicable)	Daily Loads	Daily Weight (tons)*
						1	
						1	
*On-Site scale for off-site shipm	nent, delivery t	ticket for mater	ial received				
Equipment/Material Track	ing Comme	nts:					

Visitors to Site						
Name	Re	presenting	Entered Exclusion/CRZ Zone			
	-	<u>,                                    </u>	Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
			Yes	No		
Site Representatives			<u> </u>			
Name		Representing				
Project Schedule Comments						
Issues Pending						
Interaction with Public, Property O	wners, Media, et	c.				

# Include (insert) figures with markups showing location of work and job progress



## **Site Photographs (Descriptions Below)**





View of Treatment System HOA panel door.



View of TW-7 well cluster.

View of TW-12 well cluster.

**DAILY INSPECTION REPORT** Report No. 1 Gladding Cordage - NYSDEC Site No. 709009 Date: 10/12/2020 Comments

Date: 10/12/2020

Site Inspector(s): Jasmine Mullins and Kimberly Stilson

Is social distancing being practiced?	Yes ⊠	No □
Is the tail gate safety meeting held outdoors?	Yes ⊠	No □
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes ⊠	No □
Were personal protective gloves, masks, and eye protection being used?	Yes ⊠	No □
Are sanitizing wipes, wash stations or spray available?	Yes ⊠	No □
Have any workers/visitors been excluded based on close contact with individuals diagnosed with COVID-19, have recently traveled to restricted areas or countries, or are symptomatic (fever, chills, cough/shortness of breath)?	Yes □	No ⊠
Comments:		

DAILY HEALTH CHECKLIST

## REMEDIAL ACTIVITIES AT PROPERTIES

1.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
2.	Is anyone at this location isolated or quarantined for COVID-19?	Yes □	No ⊠
3.	Has anyone at this location had contact with anyone known to have COVID-19 in the past 14 days?	Yes □	No ⊠
4.	Does anyone at this locaton have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
5.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
•	If it is <u>not</u> critical that service/entry be carried out immediately and can be postponed until the risk of COVID-19 is lower, or can be accomplished remotely/without entry, postpone or conduct service without entry.  If it <u>is</u> critical that service/entry be carried out immediately, advise occupants that as a precaution and for our own protection, project personnel will be donning appropriate PPE* (including respiratory protection) - and do so prior to entry.	Yes □	No □
Comm	ents:		

# **NUISANCE CHECKLIST**

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No ⊠	N/A□
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No □	N/A⊠
Was turbidity checked at the Montauk Highway outfall?	AM □	РМ□	N/A⊠



# **DAILY INSPECTION REPORT**

Page 8 of 8

Report No. 1 Gladding Cordage - NYSDEC Site No. 709009 Date: 10/12/2020

Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No ⊠	N/A□
Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			