


New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau E



Alexander B. Grannis
Commissioner

DAILY INSPECTION REPORT

Site Code #: 712009	Date: 4/30/09	Report #: 1
----------------------------	----------------------	--------------------

Site Name: South Hill Dump
Location: Cortlandville, NY
PRP Proj. Mgr.: N/A
DEC Proj. Mgr.: Gerard Burke
Consultant Proj. Mgr.: Tim Zabol
Proj. Contr.: Aztech Technologies Inc.
Site Phone & Fax:

	AM	PM
Weather	Cloudy	Same
Temperature	60° F	
Wind Direction	SW	

Description of work performed by contr. this report period:

Inspected and sampled drums for off-site disposal. There were 26 drums. One was empty. Six contained PPE. Six contained drum carcasses. The remaining drums contained various liquids and sludges. Two drums had oily residue which were not sampled. A composite sample was collected from three drums that contained a similar watery oily liquid in each drum. . A composite sample was collected from three drums that contained a similar oily watery liquid in each drum. . A composite sample was collected from two drums that contained a similar liquid in each drum. A grab sample was collected of one drum that contained a liquid different from the others. A grab sample was collected of one drum that contained a sludge different from the others.

Description of inspections performed by engr. this report period:

Oversaw the drum sampling.

Discussions/comments regarding visitors, contractor and/or engineer:

Health and Safety meeting was held at the site prior to beginning of work.

Sampling and Analyses:

Discussed above. Samples collected were for TCLP, VOCs, SVOCs and PCBs.

Major Issues	Description & Reason

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Y

List deviations:

Are atmospheric monitoring results acceptable? N/A

Contractor's Information:

Prime contractor worked from:

[illegible]

Site Representative: Gerard Burke

Date: 4/30/09

Representative's signature: *Gerard Burke*

Drum Numbering by Contractor:

19	16	11	5	4	3	
18	15	12	10	6	2	
17	14	13	9	8	7	1

Drum Contents/Samples:

1&2	Residue,	No Samples
3,4,5	Composite	(watery oil)
6,7,8	Composite	(oily water)
9,10	Composite	oil?
12	Grab	liquid
19	grab	solid
11,13,14,16,17,18	Drum Carcasses	
15	Could not open	Unknown

