

**Operations & Maintenance Inc.**

Riverview Business Park  
1850 Route 57  
Fulton, NY 13069

**Gary Mullen, Jr.**  
Project Manager  
gmullenomi@gmail.com

August 7, 2019

Michael Belveg, Assistant Engineer (Environmental)  
New York State Department of Environmental Conservation  
Division of Environmental Remediation  
615 Erie Boulevard West  
Syracuse, NY 13204  
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029  
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for June 2019.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.  
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO  
Eamonn O'Neil, NYSDOH, Troy, NY  
Val Murakami, DYSDEC, Syracuse, NY  
Bill Buchan, OMI, Constantia, NY  
Dean Merritt, OMI, Syracuse, NY  
Maureen Schuck, NYSDOH

# SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

## GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: June 12, 2019

Report No.: 1908848

### GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<0.5	<0.5	<b>3.2</b>	<b>1.8</b>	<b>18</b>	<0.5	<2	<b>26</b>	<0.5	<b>1.5</b>	<b>5.6</b>	<1
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<2	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	<b>1200</b>

**NOTES:** VOC data presented in µg/l. Oil & grease data presented in mg/l.

---



---

Last updated: July 15, 2019

---



---

**OPERATIONS AND MAINTENANCE INC.**