

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

October 22, 2019

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for July 2019. Also attached is a table of the analytical results from the sampling of the active recovery wells.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: July 10, 2019

Report No.: 1910950

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Location	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<0.5	<0.5	4.3	1.8	21	<0.5	<2	23	<0.5	1.8	6.3	0.5
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<2	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1300

NOTES: VOC data presented in µg/l. Oil & grease data presented in mg/l.

Last updated: October 22, 2019

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029
QUARTERLY RECOVERY WELL SAMPLING
DATE: July 17, 2019
Report #: 1911591

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloromethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<2	<2	15	6.3	66	0.51	<2	<4	100	<2	5.6	37	7.2	<2
RW-3	<0.5	<0.5	1.20	1.4	28	<0.5	<0.5	<1	46	<0.5	2.7	5.8	<0.5	<0.5
RW-4	<0.5	<0.5	9.4	4.7	50	<0.5	<0.5	<1	99	<0.5	12	7.1	6.9	<0.5
RW-5R	<0.5	<0.5	2.0	2.6	10.0	<0.5	<0.5	<0.5	90	<0.5	2.3	7.1	<0.5	<0.5
RW-8	<0.5	<0.5	7.1	3.8	56	<0.5	<0.5	<1	16	<0.5	3.0	3.4	3.4	<0.5
RW-9	<0.5	<0.5	38	28	310	1.6	<0.5	<1	29	<0.5	4.6	42	3.2	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	1.6	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.61	<0.5	<0.5	<0.5	<0.5	<1	2.0	<0.5	0.56	<0.5	<0.5	<0.5
RW-13	<0.5	<0.5	2.2	1.9	2.2	<0.5	<0.5	<1	0.82	<0.5	0.64	3.1	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

OPERATIONS AND MAINTENANCE INC.