

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

October 25, 2019

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for August 2019.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: August 8, 2019

Report No.: 1913017

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Location	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<0.5	<0.5	4.7	2.1	28	<0.5	<2	29	<0.5	2.1	6.4	1.5
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<2	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	2000

NOTES: VOC data presented in µg/l. Oil & grease data presented in mg/l.

Last updated: October 22, 2019

OPERATIONS AND MAINTENANCE INC.