

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

May 18, 2020

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for January 2020. Also attached is a table of the analytical data from the sampling of the active recovery wells.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: January 9, 2020

Report No.: 2000530

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Location	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<0.5	<0.5	6.5	2.6	33	<0.5	<2	38	<0.5	2.9	11	2.5
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<2	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	2100

NOTES: VOC data presented in µg/l. Oil & grease data presented in mg/l.

Last updated: February 14, 2020

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029
QUARTERLY RECOVERY WELL SAMPLING
DATE: January 10, 2020
Report #: 2000531

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloromethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<2	<2	17	7.3	65	<2	<2	<4	110	<2	7.1	37	8.8	<2
RW-3	<0.5	<0.5	2.2	2.4	53	0.50	<0.5	<1	52	<0.5	4.5	11	1.5	<0.5
RW-4	<0.5	<0.5	6.9	4.4	66	0.71	<0.5	<1	97	<0.5	12	8.1	11	<0.5
RW-5R	<2	<2	<2	<2	12	<2	<2	<2	73	<2	<2	7.2	<2	<2
RW-8	<0.5	<0.5	6.4	3.1	48	<0.5	<0.5	<1	11	<0.5	2.9	3.2	3.7	<0.5
RW-9	<0.5	<0.5	54	29	520	2.3	<0.5	<1	32	<0.5	5.7	50	8.9	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	1.00	<0.5	<0.5	<1	1.6	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.70	0.50	<0.5	<0.5	<0.5	<1	1.9	<0.5	0.65	<0.5	<0.5	<0.5
RW-13	<0.5	<0.5	3.7	4.0	2.6	<0.5	<0.5	<1	2.6	<0.5	2.3	5.7	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

OPERATIONS AND MAINTENANCE INC.