## **Operations & Maintenance Inc.**

Gary Mullen, Jr.
Project Manager
gmullenomi@gmail.com

Riverview Business Park 1850 Route 57 Fulton, NY 13069

May 28, 2020

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029 Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for March 2020.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr. Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

## SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

## NYSDEC SITE #7-38-029 GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: March 11, 2020 Report No.: 2003724

## **GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones**

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl- benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<0.5	<0.5	5.3	2.4	32	<0.5	<2	45	<0.5	3.0	12	1.5
FINAL EFF	<5.0	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5	<2	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5

Location	TDS				
Location	mg/l				
FINAL EFF	1800				

**NOTES:** VOC data presented in  $\mu$ g/l. Oil & grease data presented in mg/l.

Last updated: May 1, 2020