

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

February 1, 2021

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for October 2020. Also attached is a table of the results from the sampling of the active recovery wells.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: October 28, 2020

Report No.: 2017803

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	4.6	2.6	23	<1	<2	42	<1	2.9	8.5	1.2
FINAL EFF	<5.0	<1	<1	<1	<1	<1	<1	<2	<1	<1	<1	<1	<1

Location	TDS mg/l
FINAL EFF	2000

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: February 1, 2021

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029
QUARTERLY RECOVERY WELL SAMPLING
DATE: October 27, 2020
Report #: 2017801

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<2	0.51	12	8.4	49	0.63	<2	<4	120	<2	9.0	30	4.9	<2
RW-3	<0.5	<0.5	0.86	1.3	14	<0.5	<0.5	<1	58	<0.5	3.1	6.8	<0.5	<0.5
RW-4	<0.5	<0.5	3.4	3.1	61	0.66	<0.5	<1	93	<0.5	8.4	11	7.2	<0.5
RW-5R	<2	<2	<2	<2	12	<2	<2	<5	67	<2	<2	5.3	<2	<2
RW-8	<0.5	<0.5	3.4	1.5	21	<0.5	<0.5	<1	8	<0.5	1.7	2.0	1.7	<0.5
RW-9	<0.5	<0.5	40	17	470	2.0	<0.5	<1	32	<0.5	4.1	50	5.8	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	0.84	<0.5	<0.5	<1	1.8	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.64	<0.5	<0.5	<0.5	<0.5	<1	2.2	<0.5	0.50	<0.5	<0.5	<0.5
RW-13	<0.5	<0.5	3.9	4.0	7.2	<0.5	<0.5	<1	<0.5	<0.5	2.6	3.4	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

OPERATIONS AND MAINTENANCE INC.