

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

February 23, 2021

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for January 2021. Also attached is a table of the analytical results from the sampling of the active recovery wells.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: January 13, 2021

Report No.: 2100677

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	6.0	3.6	26	<1	<2	43	<1	4.2	12.0	1.70
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1900

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: February 3, 2021

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029
QUARTERLY RECOVERY WELL SAMPLING
DATE: January 13, 2021
Report #: 2100676

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<2	0.58	17	12	60	0.79	<2	<4	120	<2	13	37	6.0	<2
RW-3	<0.5	<0.5	1.1	1.5	19	<0.5	<0.5	<1	48	<0.5	3.6	9.6	0.63	<0.5
RW-4	<0.5	<0.5	5.1	4.7	85	1.1	<0.5	<1	93	<0.5	13	14	14	<0.5
RW-5R	<0.5	<0.5	2.3	1.8	17	<0.5	<0.5	<5	66	<0.5	2.1	7.4	<0.5	<0.5
RW-8	<0.5	<0.5	2.3	1.2	10.0	<0.5	<0.5	<1	4.8	<0.5	1.5	1.3	1.00	<0.5
RW-9	<0.5	<0.5	22	9.6	240	2.9	<0.5	<1	16	<0.5	2.7	28	13	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	2.0	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.94	0.60	<0.5	<0.5	<0.5	<1	2.4	<0.5	0.70	<0.5	<0.5	<0.5
RW-13	<0.5	<0.5	5.2	5.4	9.8	<0.5	<0.5	<1	<0.5	<0.5	3.4	4.8	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

OPERATIONS AND MAINTENANCE INC.