

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.

Project Manager
gmullenomi@gmail.com

November 15, 2021

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find a table of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for May through August 2021. Also attached is a table of the results from the sampling of the active recovery wells in July.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: May 12, 2021

Report No.: 2107134

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	3.6	2.4	18	<1	<2	47	<1	2.6	8.4	0.88
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1800

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: July 9, 2021

OPERATIONS AND MAINTENANCE INC.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: June 9, 2021

Report No.: 2108821

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	3.3	2.9	16	<1	<2	41	<1	2.6	7.0	0.57
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1700

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: July 9, 2021

OPERATIONS AND MAINTENANCE INC.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: July 12, 2021

Report No.: 2111014

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	3.2	2.3	15	<1	<2	37	<1	2.4	6.5	0.74
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1800

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: September 14, 2021

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029
QUARTERLY RECOVERY WELL SAMPLING
DATE: July 12, 2021
Report #: 2111019

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<0.5	<0.5	10.0	9.3	48	0.56	<0.5	<2	82	<0.5	9.1	27	3.6	<0.5
RW-3	<0.5	<0.5	0.83	1.6	9.2	<0.5	<0.5	<1	78	<0.5	3.5	6.9	<0.5	<0.5
RW-4	<0.5	<0.5	3.0	3.4	51	0.58	<0.5	<1	73	<0.5	9.3	10.0	5.1	<0.5
RW-5R	<0.5	<0.5	1.6	1.5	12	<0.5	<0.5	<5	75	<0.5	1.5	4.5	<0.5	<0.5
RW-8	<0.5	<0.5	1.8	0.91	5.7	<0.5	<0.5	<1	3.9	<0.5	1.00	0.85	0.58	<0.5
RW-9	<0.5	<0.5	20	13	150	0.59	<0.5	<1	23	<0.5	3.1	39	1.7	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	1.7	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.69	0.58	<0.5	<0.5	<0.5	<1	2.0	<0.5	0.51	<0.5	<0.5	<0.5
RW-13	<0.5	<0.5	3.9	4.6	5.4	<0.5	<0.5	<1	0.69	<0.5	2.1	3.8	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

OPERATIONS AND MAINTENANCE INC.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: August 26, 2021

Report No.: 2114396

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	2.8	2.0	12	<1	<2	31	<1	2.2	5.4	0.68
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1500

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: September 22, 2021

OPERATIONS AND MAINTENANCE INC.