

Operations & Maintenance Inc.

Riverview Business Park
1850 Route 57
Fulton, NY 13069

Gary Mullen, Jr.
Project Manager
gmullenomi@gmail.com

January 24, 2022

Michael Belveg, Assistant Engineer (Environmental)
New York State Department of Environmental Conservation
Division of Environmental Remediation
615 Erie Boulevard West
Syracuse, NY 13204
michael.belveg@dec.ny.gov

Subject: Former Miller Container Site, No. 7-38-029
Oswego County

Dear Mr. Belveg

Attached please find the tables of the analytical data from the sampling at the Miller Brewing, Ground Water Treatment Facility for September through December 2021. Also attached is a table of the results from the sampling of the active recovery wells in October.

If you have any questions or need any additional information, please contact me at (315) 378-5088.

Respectfully,

Operations & Maintenance Inc.

Gary W. Mullen Jr.
Project Manager

Attachments

cc: Jay Eversman, Anhauser-Busch, St Louis, MO
Eamonn O'Neil, NYSDOH, Troy, NY
Val Murakami, DYSDEC, Syracuse, NY
Bill Buchan, OMI, Constantia, NY
Dean Merritt, OMI, Syracuse, NY
Maureen Schuck, NYSDOH

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: September 29, 2021

Report No.: 2116596

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	3.0	2.1	14	<1	<2	31	<1	2.2	5.8	0.81
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1800

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: January 24, 2022

OPERATIONS AND MAINTENANCE INC.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: October 26, 2021

Report No.: 2118262

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	2.6	1.8	11	<1	<2	26	<1	1.8	4.8	<0.5
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1500

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: January 24, 2022

OPERATIONS AND MAINTENANCE INC.

GROUNDWATER SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE # 7-38-029

QUARTERLY RECOVERY WELL SAMPLING

DATE: October 26, 2021

Report #: 2118262

RECOVERY WELLS - USEPA Method 8260C

WELL	Benzene	Chloethane	1,1-DCA	1,1-DCE	c-1,2-DCE	trans-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride	Total Xylenes
RW-2	<0.5	<0.5	7.7	7.3	34	<0.5	<0.5	<2	98	<0.5	6.4	20	3.8	<0.5
RW-3	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	1.5	<0.5	<0.5	<0.5	<0.5	<0.5
RW-4	<0.5	<0.5	1.6	1.6	42	<0.5	<0.5	<1	55	<0.5	4.0	5.8	2.9	<0.5
RW-5R	<0.5	<0.5	1.6	1.7	12	<0.5	<0.5	<5	71	<0.5	1.6	4.7	<0.5	<0.5
RW-8	<0.5	<0.5	0.73	<0.5	2.2	<0.5	<0.5	<1	1.5	<0.5	<0.5	<0.5	<0.5	<0.5
RW-9	<0.5	<0.5	7.0	5.0	74	<0.5	<0.5	<1	9.0	<0.5	1.1	13	2.6	<0.5
RW-11	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	1.5	<0.5	<0.5	<0.5	<0.5	<0.5
RW-12	<0.5	<0.5	0.79	0.74	<0.5	<0.5	<0.5	<1	1.8	<0.5	0.53	<0.5	<0.5	<0.5

NOTES: All data presented in µg/l unless otherwise specified.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: November 19, 2021

Report No.: 2119736

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	3.1	<0.5	16	<1	<2	29	<1	2.0	6.1	0.69
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1700

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: January 24, 2022

OPERATIONS AND MAINTENANCE INC.

SAMPLING RESULTS-FORMER MILLER CONTAINER FACILITY

NYSDEC SITE #7-38-029

GROUNDWATER TREATMENT FACILITY SAMPLING

DATE: December 29, 2021

Report No.: 2121615

GROUNDWATER TREATMENT FACILITY - USEPA Method 8260C + Xylenes, Keytones

Locattion	Oil & Grease	Benzene	Chloroform	1,1-DCA	1,1-DCE	c-1,2-DCE	Ethyl-benzene	Methylene Chloride	PCE	Toluene	1,1,1-TCA	TCE	Vinyl Chloride
AST-INF	n/a	<1	<1	2.4	1.4	16	<1	<2	29	<1	1.9	5.9	<1.0
FINAL EFF	<5.0	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<1	<0.5	<0.5	<0.5	<0.5	<0.5

Location	TDS mg/l
FINAL EFF	1700

NOTES: VOC data presented in µg/l. Oil & Grease and TDS data presented in mg/l.

Last updated: January 24, 2022

OPERATIONS AND MAINTENANCE INC.