
New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Remedial Bureau C Section D



DAILY INSPECTION REPORT

Site Code #: 7-55-08

Site Name: NYSEG Ithaca Court St. Location: Ithaca, Chemung County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

Proj. Contr.: Sevenson Environmental

Site Phone & Fax:

	AM	PM
Weather	P. Sunny	P. Sunny
Temperature	30 degrees	45 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Continued removal of Duct #2.
- Staining extended 1 foot north by 7 feet bgs; 7 feet bgs under duct; and 7 feet south by 7 feet bgs. Impacts still present in south wall (ran out of trucks).
- Impacts also present around and under sanitary sewer and waterline service to #616 Court St. Contractor leaves material in place, and will remove when service is replaced.

Description of inspections performed by engr. this report period:

_

<u>Discussions/comments regarding visitors, contractor and/or engineer:</u>

•

Change Orders:

•

Sampling and Analyses:

•

Major Issues	Description & Reason	

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 4:30P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	3			

Site Representative: R. Scott Deyette Date: November 10, 2003

Representative's signature:

Reviewed By:	Date:	

REVISED 5/99 @BLANK.wpd