

INSPECTOR'S DAILY REPORT
 New York State Department of Environmental Conservation
 Division of Environmental Remediation

I.R. No. _____
 Date 11/13/03

Site Name: Ithaca Court St.

Site Code: 7-55-008

T & A Code: A 381

Location: Court St. Ithaca NY

Mostly Cloudy 40%

DEC Project Manager: Bill Ottaway

Winds WSW 4 mph

Engineer / Consultant:

light snow, windy Variable

Contractor: Sevenson


@ 13¹³ hrs 30-40 mph

Health & Safety: PPE Level D ☒ C ☐ B ☐

modified in trench AK onsite 0820

Description of Work Performed:

Excavating between # 614 & # 612 Court St.
 Removed 14' of small wooden duct, starting @ SE
 corner of # 614 property running 14' due east. Cut to 9' - 4" depth
 dense clay material (Brown/Green) with lenses of dark
 grey clay with mcp odor. Skipped over utility line to
 start removing soil above duct work @ # 612
 Court St. This work started after lunch. Water gathered
 in second pit # 612 area. Sevenson pumped out & contained.
 Two trailer dumps loaded by 12:00 noon.
 Four (total) trucks loaded by 2:55 pm



← Court Street → Skipped over utility Line → EAST

Komatsu PW170 RTire Excavator

Hertz 1 Ton Dump w trailer (vapor control vacuum unit)

Sevenson 1 Ton Flat Bed 159E

Komatsu WA 250 RTire FELoader

2 - Laborers

1 - Foreman

1 - Operator

1 - H&S person

Ithaca Court St.

I.R. No.

Description of Work Performed:

Only small wood duct removed today. Clay soil in bottom of each pit had MGP odor. Clay had brown/green color with dark gray speckles/hair-like stringers.

Odors seemed minimal due to cold temps and high winds.

Bert Finch on site with Walt Savichky.

Items of Concern:

MGP odor in clay soil @ bottom of excavation in front of #614 Court St. Depth is ~ 9'4" bg. Also small hair-like stringers of tar in clayey soil.

Inspector's Name:

Anthony Barwell

Inspector's Signature:

Anthony Barwell

Date:

11/13/03