


New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty
Commissioner

DAILY INSPECTION REPORT

Site Code #: 7-55-08	Date: December 12, 2003	Report #: NYSEG121203
-----------------------------	--------------------------------	------------------------------

Site Name: NYSEG Ithaca Court St.

Location: Ithaca, Chemung County

NYSEG Proj. Mgr.: Bert Finch

DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

Proj. Contr.: Severson Environmental

Site Phone & Fax:

	AM	PM
Weather	P. Sunny	P. Sunny
Temperature	22 degrees	30 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Removed 29 feet of clay tile pipe. Removed material down to 3.5 feet bgs over first 8 north of sewer main; then 7 feet bgs over last 6 feet north to Duct #2 excavation.
- Sent 4 trucks to ESML.

Description of inspections performed by engr. this report period:

-

Discussions/comments regarding visitors, contractor and/or engineer:

-

Change Orders:

-

Sampling and Analyses:

- NYSEG sampled bottom (BM-23, 4.5 feet bgs, on water line) and sidewall (SW-24, 4.5 feet bgs, south wall) from clay tile excavation.

Major Issues	Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 5:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	3			

Site Representative: R. Scott Deyette

Date: December 12, 2003

Representative's signature:

Reviewed By:

Date:

