New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Remedial Bureau C Section D



DAILY INSPECTION REPORT

Site Code #: 7-55-08	Date: December 16, 2003	Report #: NYSEG121603
2100 20010 , 22 33	2 2 10, 2002	110port v 1 (1 2 2 3 1 2 1 3 3 3

Site Name: NYSEG Ithaca Court St. Location: Ithaca, Chemung County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway Consultant Proj. Mgr.:

Proj. Contr.: Sevenson Environmental

Site Phone & Fax:

	AM	PM
Weather	P. Sunny	P. Sunny
Temperature	38 degrees	50 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Removed 20 feet of Duct #1. Removed material down to 7 feet bgs 2 foot north of duct, and 1 foot south.
- Removed 20 feet of Duct #2. Removed material down to 7 feet bgs 7 feet south to clay tile pipe excavation; and 4 feet north to within 1 foot south of Duct #1.
- According to Tracy B. (NYSEG), contractor excavated a 15 foot by 25 foot long by 7.5 feet bgs along the clay tile pipe on 12/15/03.
- Sent 4 trucks to ESMI.

Description of inspections performed by engr. this report period:

•

Discussions/comments regarding visitors, contractor and/or engineer:

•

Change Orders:

.

Sampling and Analyses:

•

Major Issues	Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 5:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	3			

Site Representative: R. Scott Deyette

Date: December 16, 2003

Representative's signature:

Reviewed By:	Date:	

REVISED 5/99 @BLANK.wpd