

# New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty  
Commissioner

## DAILY INSPECTION REPORT

|                             |                                |                              |
|-----------------------------|--------------------------------|------------------------------|
| <b>Site Code #:</b> 7-55-08 | <b>Date:</b> December 18, 2003 | <b>Report #:</b> NYSEG121803 |
|-----------------------------|--------------------------------|------------------------------|

**Site Name:** NYSEG Ithaca Court St.

**Location:** Ithaca, Chemung County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson Environmental

**Site Phone & Fax:**

|                       | AM         | PM         |
|-----------------------|------------|------------|
| <b>Weather</b>        | Overcast   | Flurries   |
| <b>Temperature</b>    | 25 degrees | 30 degrees |
| <b>Wind Direction</b> | NW         | NW         |

### Description of work performed by contr. this report period:

- Removed 10 feet of Duct #1. Removed material down to 6.5 feet bgs 2 foot north of duct, and 1 foot south.
- Removed 10 feet of Duct #2. Removed material down to 6.5 feet bgs 7 feet south to clay tile pipe excavation; and 4 feet north to within 1 foot south of Duct #1.
- Removed 10 feet of clay tile pipe. Removed material down to 3.5 feet bgs south to sewer main, and to 2 feet north of water main.
- Sent 3 trucks to ESML.

### Description of inspections performed by engr. this report period:

- 

### Discussions/comments regarding visitors, contractor and/or engineer:

- 

### Change Orders:

-

**Sampling and Analyses:**

•

| Major Issues | Description & Reason |
|--------------|----------------------|
|              |                      |

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

| Site Visitors | Representing | Entered Exclusion Zone |
|---------------|--------------|------------------------|
|               |              |                        |

**Contractor's Information:**

Prime contractor worked from 7:00A to 6:00P.

| Subcontractor | Activity | Hours Worked |
|---------------|----------|--------------|
|               |          |              |

| Equipment              | P | 1 | 2 | 3 | Personnel       | P | 1 | 2 | 3 |
|------------------------|---|---|---|---|-----------------|---|---|---|---|
| Daewoo 135 Backhoe     | 1 |   |   |   | Site Supervisor | 1 |   |   |   |
| Air Handling Equipment | 1 |   |   |   | Operator        | 2 |   |   |   |
|                        |   |   |   |   | Laborer         | 3 |   |   |   |

**Site Representative:** R. Scott Deyette

**Date:** December 18, 2003

**Representative's signature:**

**Reviewed By:**

**Date:**