


New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Section D



Erin Crotty
Commissioner

DAILY INSPECTION REPORT

Site Code #: 7-55-08	Date: January 5, 2004	Report #: NYSEG010504
-----------------------------	------------------------------	------------------------------

Site Name: NYSEG Ithaca Court St.
Location: Ithaca, Tompkins County
NYSEG Proj. Mgr.: Bert Finch
DEC Proj. Mgr.: Bill Ottaway
Consultant Proj. Mgr.:
Proj. Contr.: Severson Environmental
Site Phone & Fax:

	AM	PM
Weather	Overcast	Overcast
Temperature	30 degrees	38 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Removed 12 feet of Duct #1. Removed material down to 6 feet bgs 2 foot north of duct, and 2 feet south.
- Removed 12 feet of Duct #2. Removed material down to 7 feet bgs 5 feet south to clay tile pipe excavation; and 3 feet north to within 2 feet south of Duct #1.
- Removed 12 feet of storm sewer.
- Sent 2 trucks to ESML.

Description of inspections performed by engr. this report period:

•

Discussions/comments regarding visitors, contractor and/or engineer:

•

Change Orders:

•

Sampling and Analyses:

•

Major Issues	Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 6:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	2			

Site Representative: R. Scott Deyette

Date: January 5, 2004

Representative's signature:

Reviewed By:

Date: